



Non-taxable items/sublet charges:

To ream in bushes *

TBD

* sublet item

Labor (charged at \$170/hour)

To strip front suspension (both sides), replace suspension pins (if required), replace king pin and trunnion bushes. To repair bent spring seats, replace spring rubbers, replace wheel bearings and reassemble.

\$ 5,950.00

\$ 8,359.60

Tax \$ 228.91

ESTIMATE TOTAL \$ 8,588.51

This estimate is valid for 14 days after date of estimate.

I hereby authorize the above work to be completed with the necessary parts. An express mechanic's lien is acknowledged on the above items to secure the amount of repairs thereto. Work not picked up within 7 days following notification will be charged storage at a daily rate of \$85. All items left over 30 days will be sold or discarded.

Print Name:

Date: 5/20/19

Sign:

BAR Registration Name: GTO Engineering LA LLC

BAR License Number: ARD00286121

Page 2 of 2

the classic Ferrari specialists

telephone +1 424 303 7005 email la@gtoengineering.com url www.gtoengineering.com

1450 S La Cienega Boulevard | Los Angeles | CA 90035 | USA