

Friday, September 13, 2019

Re: Ferrari 330 GT 2+2, Chassis# 6077, Blue, 82393 miles JN1281

ESTIMATE

Taxa	ble Parts:	
12	Valve Guide	\$299.40
12	Valve Stem Oil Seal 8mm	\$23.40
1	Cylinder Head Gasket	\$499.99
1	Timing Case Square Section Seal	\$15.85
1	O-Ring	\$3.25
1	Angle Drive O Ring	\$3.72
1	Cover Gasket	\$9.95
1	O Ring Seal 144	\$3.89
1	Cam Cover Gasket 330/365	\$36.50
12	O-Ring Intake	\$83.40
2	Exhaust Gasket Single Flange 365	\$36.76
2	Exhaust Manifold Gasket Double 365 Daytona	\$41.78
		\$1,057.89

All parts are new, unless otherwise stated

Non-taxable parts/sublet items:

Machining Charge \$1,990.0

To:

Valve Guide Seals Initial Inspection: To remove valve cover, pull off chain cap, remove rocker assembly, clean gasket, remove breather. To attempt to compress the springs, not possible. Cylinder head removal required.

\$1,020.00

the classic Ferrari specialists



Bank 1 to 6 Valve Guide Seal replacement: To remove cylinder head, disassemble and send for machine work. To reassemble cylinder head, refit cylinder head to block, adjust valve and tappet clearances. To refit valve cover, distributor/angle drive assembly and carburetor/inlet manifold assembly.

Sub Total \$11,207.89
Sales Tax \$100.50

TOTAL \$11,308.39

This estimate is valid for 14 days after date of estimate.

Compression check and possibly leak down:

I hereby authorize the above work to be completed with the necessary parts. An express mechanic's lien is acknowledged on the above items to secure the amount of repairs thereto. Work not picked up within 7 days following notification will be charged storage at a daily rate of \$85. All items left over 30 days will be sold or discarded.

Print Name:	
Signature:	
Date:	
D 410.	

BAR Registration Name: GTO Engineering LA LLC

BAR License Number: ARD00286121

