Bay Bridge Bimmers & Minis

3425 Ettie st

Oakland, CA 94608-0000 Shop Phone: (510) 208-3273 Fax: (510) 208-3226

Email: info@baybridgemotors.com
Web Address: www.baybridge-bimmers-minis.com

Invoice

22665

Estimate Ref #0

Date Printed: 02/11/2021 Printed Time: 2:24 pm EPA#: CAL000292047 SR CH 100-072528 BAR #: ARD00249928

Time Promised:

Hat/Ref

1999 BMW Z3 M COUPE L6 3.2L 3152CC FI GAS N S52

VIN: WBSCM9338XLC61098

License: Unit #: Mileage In: 80,124

Date Written:

02/08/2021

Mileage Out: 80,135

Written By:

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
Job #1	instal drive shaft guibo				
Labor 1	Work Requested - instal drive shaft guibo		2.00	160.00	320.00
Part	shift shaft seal		1.00	23.00	23.00
Part	drive shaft guibo		1.00	135.00	135.00
				Job Total:	478.00

Cars that are older than 5 years may have regular wear and tear that could require additional repairs during assembly or disassembly of quoted repairs.

There is a 12 month warranty on labor and 2 year warranty on NEW parts. All parts listed are new unless otherwise noted. Any Vehicle left here will be subject to a storage charge of: \$65 per day.

Payment Date	Type	Method	Amount
2/11/2021	Cash		496.12
		Payment Totals:	\$496.12

 Parts:
 \$158.00

 Labor:
 \$320.00

 Sublet:
 \$0.00

 Misc:
 \$0.00

 Hazmat:
 \$0.00

 Supplies:
 \$3.50

Tax Total:

\$14.62

Invoice Total: Less Paid:

\$496.12 496.12

Balance Due:

\$0.00

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Authorized By

Date

Time

110 Auto Care

1406 S Pacific Ave San Pedro, CA. 90731 Phone: 310-531-8085

All Roads Lead to 110 Auto Care

INVOICE

8072

Org. Est. # 008208 ARD00289417 CAL000431771

Date: 01/13/2021

1999 BMW - M Coupe - 3.2L, In-Line6 (192CI) VIN(3)

Lic #: 019LUS

Odometer In: 79739

VIN #: WBSCM9338 XLC61098

	VIN # : WBSCM9338 XLC61098						
Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext	
Oil Filter 51160	1.00	23.71	23.71	Engine Oil - Volume: 6.90 QTS. (6.5L) - SAE 5W-30 Synthetic Engine Oil may be used, but it is not required.; All Applicable Mode			
Full Synthetic Motor Oil XXXX	6.90	11.00	75.90				
				Change Motor Oil Lube Chassis Changed Motor Oil & Replaced Filter, Adde Oil, Check all Fluid Levels, Air Pressure Ch Rotation as Needed Change your engine oil every 5,000 miles t car. [Discount] EARLY BIRD OIL CHANGE SPI TECH NOTED VEHICLE WAS LOW ON E BROUGHT IN.	eck, Full Inspection o extend the life of y	, Tire your	

Org. Estimate 102.65 Revisions 0.00 Current Estimate 102.65	Labor:	10.00
	Parts:	99.61
	Discount:	-15.00
	SubTotal:	94.61
	Tax:	8.04
	Total:	102.65
[Payments - Elec - Credit Card - \$102.65]	Bal Due:	\$0.00

BENZ'N BEAMERS

26122 S. WESTERN AVE Lomita, CA. 90717

Phone: 310-326-1034 Fax: 310-325-4169

FOLLOW US ON FACEBOOK

INVOICE

25739

Org. Est. # 092216 EPA# CAL000267928 BAR#ARD237257

Work Completed:

06/11/2020

Date: 06/12/2020

1999 BMW - M Coupe - 3.2L, In-Line6 (192CI) VIN(3)

Lic #: 019 LUS

Odometer In: 78012

Odometer Out: 78012

VIN #: WBSCM9338 XLC61098

	VIII # . WD3CIVI9330 ALCO 1096				
Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Engine Mount 22 92 2 798	2.00	105.60	211.20	51. ENGINE MOUNT - Remove & Replace - Front - Both	195.00
Transmission Mount 22 43 7 977	2.00	29.91	59.82	52. TRANSMISSION MOUNT - Remove & Replace - Both	65.00
Strut Mount-Front Left	1.00	110.00	110.00	53. STRUT ASSEMBLY - Remove & Replace - Both - [DOES NOT include disassemble or alignment.]	260.00
22 44 2 897 Strut Mount-Front Right	1.00	110.00	110.00	53. SHOCK &/OR STRUT ASSEMBLY - Remove & Replace - Both - [DOES NOT include alignment.]	130.00
22 44 2 898				54. ALIGHNMENT	145.00
Strut Assembly-Front Left 22 44 3 937	1.00	425.00	425.00	54. POWER STEERING HOSE - Remove & Replace - Return - [Includes: Bleed System.]	104.00
Strut Assembly-Front Right 22 44 3 938	1.00	425.00	425.00	Hazardous Materials	4.95
Shock Absorber-Rear 24-027182	2.00	214.98	429.96		
Shock Mount-Rear 22 52 2 362	2.00	32.33	64.66		
Power Steering Reservoir Line Hose-Reservoir To Pump 22 51 2 419	1.00	54.96	54.96		
Power Steering Fluid 22 51 2 410	1.00	23.50	23.50		

Org. Estimate 62.50 Revisions 3,006.10 Current Estimate 3,068.60

Revision # 1, Previous Estimate Amount: 62.50, Additional Cost: 3006.10, Revised Estimate: 3068.60, Parts: \$2014.88 Labor: \$780.00 Sublet: \$0.00 Taxes & Fees: \$211.22 Authorized by - RIGGIN, MITCH, Date - 6/11/2020, Time - 1:37 PM, Initiated By - Shop, Written By - STEVE, Reason - fOR RECOMMENDED REPAIRS. Phone Number - Cellular: 415-860-9278

 Labor:
 899.00

 Parts:
 1,914.10

 HazMat:
 4.95

 SubTotal:
 2,818.05

 Tax:
 181.84

 Total:
 2,999.89

[Payments -]

Signature

VISIT US AT *** WWW.BENZNBEAMERS.COM ***

Vehicle Received: 6/11/2020

Customer Number: 11293

\$2,999.89

I authorize the above repair work to be done with the necessary materials and grant you and/or your employees permission to operate vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles (Excluding Electrical Parts) whichever comes first. All warranty repairs done by other facilities require prior authorization by Benz N' Beamers. RMF is an abbreviation for remanufactured.

Visit us on the web: www.benznbeamers.org

Date

Email Address: benznbeamers@yahoo.com

Bal Due: