



# Restoration & Performance Motorcars

462 Monkton Road  
Vergennes, VT 05491

802-877-2645

# Invoice

| Date     | Invoice # |
|----------|-----------|
| 7/7/2015 | 7667      |

Bill To



**PAID**  
07-17-2015

Customer Phone



Customer Alt. Phone



| Yr/Make/Model                  | Serial Number: | Odometer Reading: | Project/Job | Terms  |
|--------------------------------|----------------|-------------------|-------------|--------|
| 1975 Lambo Countach Perisco... | 1120064        |                   |             | Net 30 |

| Item               | Qty | Description  | List | Rate     | Amount   |
|--------------------|-----|--|------|----------|----------|
| Insurance Premi... | 1   | Additional Insurance Coverage While Intransit for high value vehicle.  |      | 2,843.75 | 2,843.75 |
| Storage            | 3   | Storage, car arrived March 2015, no storage charge as we have been working on the car  |      | 0.00     | 0.00     |
| Parts              | 1   | Clutch slave cylinder & master cylinder  |      | 250.00   | 250.00   |
| Parts              | 4   | Spherical bearings LH and RH thread on the rear suspension points  |      | 150.00   | 600.00   |
| Parts              | 2   | Tie Rod end  |      | 180.00   | 360.00   |
| Parts              | 2   | Needle Bearings for front wheel bearings outer   |      | 150.00   | 300.00   |
| Parts              | 2   | Inner front wheel bearing  |      | 120.00   | 240.00   |
| Parts              | 2   | Wheel bearing oil seals  |      | 15.00    | 30.00    |
| Parts              | 1   | Key blanks   |      | 38.05    | 38.05    |
| Parts              | 1   | 82 Series Rebuilt Shocks   |      | 1,300.00 | 1,300.00 |
| Parts              | 1   | O Rings  |      | 20.00    | 20.00    |
| Parts              | 1   | Bump Stop Poly   |      | 200.00   | 200.00   |
| Parts              | 1   | Guide 82 New Type  |      | 285.00   | 285.00   |
| Parts              | 12  | Rubber spring shackle to be modified to fit the Koni   |      | 68.00    | 816.00   |
| Parts              | 1   | 82 Series Gland Nut  |      | 250.00   | 250.00   |
| Parts              | 1   | Shop Service material at Shock overhaul shop   |      | 24.00    | 24.00    |
| Sublet Repairs/... | 2   | Cut brake rotors   |      | 20.00    | 40.00    |
| Sublet Repairs/... |     | Overhaul all brake calipers, master cylinder.  |      | 2,000.00 | 2,000.00 |
| Transport          |     | Transport the car from NJ to the shop  |      | 700.00   | 700.00   |
| Labor              | 8   | 3-25-15. Try to move the car, brakes are stuck, get the car situated in the shop to remove the calipers. Check the other things on the car. remove, package all calipers and send off for overhaul   |      | 95.00    | 760.00   |
| Labor              | 6   | 3-26-15. Front wheel bearings look bad. disassemble and measure bearings as Lambo parts are horribly expensive. Measure and order from local bearing house. Send discs off to be surfaced. Shocks are stuck or leaking. Remove fronts  |      | 95.00    | 570.00   |
| Labor              | 6   | 3-27-15. Finish removing the shocks. Package and send off for rebuild. Clean the springs, sand blast a bunch of little stuff to be painted. The rear susp link bearings are loose and very noisy. remove and look for new ones. At this time, we have not done any re-assembly, just costs to date. We are waiting for a few last minute parts |      | 95.00    | 570.00   |

**Total**

\$12,196.80

**Payments/Credits**

-\$12,196.80

**Balance Due**

\$0.00



# Restoration & Performance Motorcars

462 Monkton Road  
Vergennes, VT 05491

# Invoice

802-877-2645

| Date      | Invoice # |
|-----------|-----------|
| 9/17/2015 | 7771      |

Bill To



**PAID**  
07-17-2015

Customer Phone



Customer Alt. Phone



| Yr/Make/Model                  | Serial Number: | Odometer Reading: | Project/Job | Terms  |
|--------------------------------|----------------|-------------------|-------------|--------|
| 1975 Lambo Countach Perisco... | 1120064        |                   |             | Net 30 |

| Item               | Qty | Description   | List | Rate   | Amount |
|--------------------|-----|---|------|--------|--------|
| Sublet Repairs/... | 2   | Machine Rotor   |      | 15.00  | 30.00  |
| Labor              | 2   | Deal with keys, get duplicates cut and fine tune with a file to make them work.   |      | 95.00  | 190.00 |
| Labor              | 8   | 6-12-15. Modify a commonly available silent block bushing to work with the shock absorbers eliminating the metal ball joints. We had to turn down the OD and shorten them |      | 95.00  | 760.00 |
| Labor              | 6   | 7-15-15. Assembly of the suspension and brakes.   |      | 95.00  | 570.00 |
| Labor              | 7   | 7-16-15. Further assembly of the brakes and clutch hydraulics   |      | 95.00  | 665.00 |
| Labor              | 5   | 7-27-15. Make a few new brake lines, install shocks after new bushings were installed   |      | 95.00  | 475.00 |
| Labor              | 4   | 8-13-15. Further assembly and bleed brakes. Modify one line to keep from rubbing  |      | 95.00  | 380.00 |
| Labor              | 4   | 8-14-15. Further bleeding, working to get the shocks to fit well  |      | 95.00  | 380.00 |
| Labor              | 4   | 8-17-15. Get car on the wheels, drive, test, tune.  |      | 95.00  | 380.00 |
| Labor              | 4   | 8-25-15. Double check the car, look for leaks and tighten up one fitting. Change all o-rings on idle jets. Run the engine, check for overheat. Fill with gas              |      | 95.00  | 380.00 |
| Labor              | 6   | 8-26-15. Change the oil, make a license plate bracket. Make an aux cell charger port. Check the charging system and check all lights and levels.                          |      | 95.00  | 570.00 |
| Labor              | 3   | Detailing the car   |      | 95.00  | 285.00 |
| Parts              | 1   | Cell charger with bracket   |      | 15.00  | 15.00  |
| Parts              | 4   | Brake hoses   |      | 75.00  | 300.00 |
| Parts              | 12  | Engine oil  |      | 5.00   | 60.00  |
| Parts              | 1   | Oil filter element  |      | 18.00  | 18.00  |
| Parts              |     | O-Rings for carb jets   |      | 15.00  | 15.00  |
| Parts              |     | Brake fluid   |      | 25.00  | 25.00  |
| Parts              |     | Transaxle oil   |      | 45.00  | 45.00  |
| Parts              |     | Battery   |      | 118.00 | 118.00 |
| Gas, Oil & Gre...  |     | Gas, for test driving and filling up for the rally day.   |      | 75.00  | 75.00  |
| Transport          |     | Transport the car to RI   |      | 600.00 | 600.00 |

**Total** \$6,336.00

**Payments/Credits** -\$6,336.00

**Balance Due** \$0.00



# Restoration & Performance Motorcars

462 Monkton Road  
Vergennes, VT 05491

# Invoice

802-877-2645

|           |           |
|-----------|-----------|
| Date      | Invoice # |
| 10/5/2016 | 8252      |

Bill To

**PAID**

Customer Phone

Customer Alt. Phone

|                                |                |                   |             |        |
|--------------------------------|----------------|-------------------|-------------|--------|
| Yr/Make/Model                  | Serial Number: | Odometer Reading: | Project/Job | Terms  |
| 1975 Lambo Countach Perisco... | 1120064        | 20951             |             | Net 30 |

| Item               | Qty | Description   | List | Rate   | Amount   |
|--------------------|-----|---|------|--------|----------|
| Sublet Repairs/... | 1   | Repair dents and paint hood.  |      | 810.00 | 810.00   |
| Transport          | 1   | Transport Fees from RI to VT, April 2016.   |      | 650.00 | 650.00   |
| Gas, Oil & Grea... |     | Gas,  |      | 25.00  | 25.00    |
| Labor              | 8   | Remove and install front hood. Get the car checked out for the Greenwich Show. One of the fuel tanks leaks, cap off that tank and set up to run on the other tank only. |      | 105.00 | 840.00   |
| Labor              | 4   | Detail the car prior to the shop  |      | 105.00 | 420.00   |
| Labor              |     | Transport the car to and from Greenwich CT. Show June 2 2016. Spend the day with the car.   |      | 800.00 | 800.00   |
| Storage            | 8   | Storage April 2016 to January 1, 2017   |      | 125.00 | 1,000.00 |
| Storage            | 12  | Storage January 1, 2016 to January 1, 2017  |      | 125.00 | 1,500.00 |

|                         |             |
|-------------------------|-------------|
| <b>Total</b>            | \$6,045.00  |
| <b>Payments/Credits</b> | -\$6,045.00 |
| <b>Balance Due</b>      | \$0.00      |



# Restoration & Performance Motorcars

462 Monkton Road  
Vergennes, VT 05491

# Invoice

802-877-2645

|           |           |
|-----------|-----------|
| Date      | Invoice # |
| 11/1/2018 | 14860     |

Bill To



**PAID**  
11/03/2018

Customer Phone



Customer Alt. Phone



|                                |                |                   |             |        |
|--------------------------------|----------------|-------------------|-------------|--------|
| Yr/Make/Model                  | Serial Number: | Odometer Reading: | Project/Job | Terms  |
| 1975 Lambo Countach Perisco... | 1120064        | 20951             |             | Net 30 |

| Item               | Qty | Description   | List | Rate     | Amount   |
|--------------------|-----|---|------|----------|----------|
| Labor              | 8   | Try and get the car running to clean out the back corner of the building. It won't start. Installed new spark plugs. No start. Jets in the carburetors are plugged. Remove all jets and clean out float chambers. Add Aviation gas  |      | 115.00   | 920.00   |
| Labor              | 8   | Get the car running and found a fuel hose leaking. Replace the hose. The car runs but not well. Found the fuel pressure regulator is leaking as well. Remove the distributor caps and found the points corroded and lots of green corrosion in the advance mechanism. Removed distributors and send off to be repaired. |      | 115.00   | 920.00   |
| Labor              | 6   | Install new oil seals in the distributor drive areas. Replace the fuel pressure regulator diaphragm which is a bear to get to.  |      | 115.00   | 690.00   |
| Labor              | 4   | Install ignition distributors and set the timing.   |      | 115.00   | 460.00   |
| Parts              | 2   | 50-38-7 oil seals   |      | 13.00    | 26.00    |
| Parts              | 1   | Fuel hose 16" 5/16"   |      | 15.00    | 15.00    |
| Parts              | 1   | Fuel Pressure regulator diaphragm   |      | 55.00    | 55.00    |
| Gas, Oil & Gre...  |     | Aviation gas  |      | 55.00    | 55.00    |
| Sublet Repairs/... |     | Service, check, overhaul distributors   |      | 1,750.00 | 1,750.00 |
| Storage            | 12  | Storage. December 2017 to December 2018   |      | 125.00   | 1,500.00 |

|                         |             |
|-------------------------|-------------|
| <b>Total</b>            | \$6,391.00  |
| <b>Payments/Credits</b> | -\$6,391.00 |
| <b>Balance Due</b>      | \$0.00      |



**Restoration & Performance Motorcars**  
 462 Monkton Road  
 Vergennes, VT 05491

# Invoice

|           |           |
|-----------|-----------|
| Date      | Invoice # |
| 1/30/2019 | 14968     |

802-877-2645

**PAID**  
**02/06/2019**

Bill To

Customer Phone

Customer Alt. Phone

|                                |                |                   |             |        |
|--------------------------------|----------------|-------------------|-------------|--------|
| Yr/Make/Model                  | Serial Number: | Odometer Reading: | Project/Job | Terms  |
| 1975 Lambo Countach Perisco... | 1120064        | 20951             |             | Net 30 |

| Item               | Qty | Description   | List | Rate   | Amount |
|--------------------|-----|---|------|--------|--------|
| Labor              | 6   | RH fuel tank had an old leak, LH tank is leaking now. Had to cut body rivits and peel back lots of glue and things to access leaking fuel tanks   |      | 115.00 | 690.00 |
| Labor              | 5   | Strip outer coating on the tanks. Leave in hot water bath overnight to strip fiberglass coating and get to the bare aluminum to weld cracks   |      | 115.00 | 575.00 |
| Labor              | 7   | Cut out damaged parts of tank. Fabricated patch panels. Set up to weld. Steve welded tank. Set up rig to test for leaks. Only leaks found in sending unit and cap repaired. Prepped for paint.  |      | 115.00 | 805.00 |
| Labor              | 6   | Sprayed tank with etch primer. Set up infrared heat gun to get paint to stick. Applied 3M rubberized coatin. Lifted up in areas, had to scrape it away. Cleaned and applied again. Set up heat and let it dry. Set up timing by piston height because there were no marks on flywheel. Made new marks on crank pulley for ease of timing. |      | 115.00 | 690.00 |
| Labor              | 8   | Installed fuel sender. Installed tanks into car. Repaired wiring. Strapped in. Rivited body back. Painted over. Pinch welded rivots.  |      | 115.00 | 920.00 |
| Labor              | 4   | Routed tank vent line. Filled with 2 gallons of gas. Test and tune. Timing set. Needs to be driven and road tested in the spring time.  |      | 115.00 | 460.00 |
| Parts              | 2   | Rocker Schutz Coating   |      | 53.36  | 106.72 |
| Gas, Oil & Grea... |     | Aviaton Gas   |      | 30.00  | 30.00  |

|                         |             |
|-------------------------|-------------|
| <b>Total</b>            | \$4,276.72  |
| <b>Payments/Credits</b> | -\$4,276.72 |
| <b>Balance Due</b>      | \$0.00      |