

PATRICK OTTIS
 1220 TENTH STREET
 BERKELEY, CALIFORNIA 94716
 ARO NO 120777

INVOICE NO.

369210

SOLD	
ADDI	
CITY, STATE, ZIP	

SHIP TO:	FANTASY JUNCTION
ADDRESS:	1145 PARK AVENUE
CITY, STATE, ZIP	EMERYVILLE, CALIF, 94608

CUSTOMER'S ORDER:	SOLD BY:	TERMS:	F.O.B.	DATE:
500 MONDIAL SERIES 1	0430 MD	THANK YOU		25 NOVEMBER 70

QUANTITY	DESCRIPTION	PRICE	AMOUNT
26 OCT	1 LEFT CAR AND MAKE PRELIMINARY INSPECTION & OBSERVATIONS		1.0
27 OCT	2 BEGIN INVESTIGATION INTO MAKING MOTOR RUN AND BRAKES		
	3 FUNCTION). WE UNDERSTAND THAT THERE IS A POSSIBILITY OF		
	4 FUDS MIXING IN MOTOR - WATER IN OIL. TO VERIFY THIS, REMOVE		
	5 BOTH INSPECTION COVERS FROM MOTOR SUMP, LOOK FOR EVIDENCE		
	6 OF WATER OR EMULSIFIED OIL - NONE SEEN. FILL COOLING SYSTEM		
	7 WITH WATER AND NOTE SOME SORT OF OILY SUBSTANCE (NOT MOTOR		
	8 OIL) ON TOP OF WATER IN RADIATOR. PRESSURIZE COOLING SYSTEM		
	9 & INSERT FOR WATER IN SUMP - NONE SEEN. CLEAN, REINSTALL		
	10 SUMP INSPECTION COVERS. ADD 9 QTS MOTOR OIL TO DRY		

INVOICE
 71721 ©2004 REDIFORM®

ATRICK OUTS

INVOICE NO.

369211

SOL	
ADD	
CITY	

SHIP TO:
ADDRESS:
CITY, STATE, ZIP

CUSTOMER'S ORDER: 500 MONDIAL	SOLD BY: 0430HD	TERMS:	F.O.B.	DATE: 25 NOVEMBER 20
----------------------------------	--------------------	--------	--------	-------------------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	SUMP-TANK. TRUCKER CHARGE BATTERY. TEST STARTING MOTOR		
2	FUNCTION - OK. MOCK UP FUEL SUPPLY CANISTER ALONG SIDE		
3	OF CAR. PUMPS TO MOTOR. (CLOSE OFF FUEL LOG AS REQUIRED)		
4	ADDRESS FUEL LEAKS. CORRODED FUEL LOG COMES APART IN OUR		
5	HANDS. REMOVE FUEL LOG & DRAWING TO NORMAN RACING FOR		
6	SILVER SOLDER REPAIR.		6.0
29 OUT	7 RETRIEVE NEWLY REPAIRED FUEL RAIL FROM NORMAN RACING.		
8	INSERT WITH NEW SEAL RINGS, CONNECT FUEL & ATTEMPT TO START		
9	MOTOR. REMOVE CARBURETOR TOPS - REMOVE CLEAN MAIN		
10	& IDLE JETS, PLUGGED WITH VARNISHED FUEL. CLEAN AND		

INVOICE
71721 ©2004 REDIFORM®

STUCK STICKS

INVOICE NO.

369212

SOLD	
ADD	
CITY, STATE, ZIP	

SHIP TO:
ADDRESS:
CITY, STATE, ZIP

CUSTOMER'S ORDER: 500 MONDIAL	SOLD BY: 0430 MD	TERMS:	F.O.B.	DATE: 25 NOVEMBER 20
----------------------------------	---------------------	--------	--------	-------------------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
	1. REBRATE ACCELERATOR PUMP MECHANISM/CIRCUIT. REINSTALL.		
	2. ALL SETTING & CURNS. START AND WARM UP MOTOR. ADJUST		
	3. MIXTURES FOR NICEST RUNNING. ADJUST IDLE SPEED. ADD		
	4. THREE MORE QUARTS OF OIL. DRAIN ENGINE COOLANT & INSPECT		
	5. FOR OIL CONTAMINATION.		6.0
30 OUT	6. BEGIN DISASSEMBLY FOR INSPECTION OF BRAKES & REPAIR.		
	7. REMOVE RIM WHEELS, FOUR BRAKE DRUMS WITH HUBS. NOTE		
	8. BRAKE SHOES NOT INSTALLED CORRECTLY - THEY ARE NOT CENTERED		
	9. CORRECTLY AT WHEEL CYLINDERS. NOTE ALSO BRAKE MASTER		
	10. CYLINDER IS LEAKING. REMOVE BRAKE MASTER CYLINDER.		

INVOICE 71721 ©2004 REDIFORM®

ATTACK OTTS

INVOICE NO.

369213

SOLD
ADDI
CITY, STATE, ZIP

SHIP TO:
ADDRESS:
CITY, STATE, ZIP

CUSTOMER'S ORDER: 500 MONDIAL	SOLD BY: 0430 HD	TERMS:	F.O.B.:	DATE: 25 NOVEMBER 20
----------------------------------	---------------------	--------	---------	-------------------------

INVOICE
71721 ©2004 MEDIFORM®

QUANTITY	DESCRIPTION	PRICE	AMOUNT
	1 FOR DISASSEMBLY & REPAIR.		4.0
3100T	2 DISASSEMBLE BRAKE MASTER CYLINDERS WASH & INSPECT PARTS		
	3 BORE IS WORN & SEALS WORN OUT. REMOVE SELECTED FRONT		
	4 & REAR BRAKE WHEEL CYLINDERS, DISASSEMBLE & INSPECT. SLEEVES		
	5 ARE WORN & SEALS FOR BLEED SCREWS DISTORTED. PACK		
	6 CAREFULLY & SHIP BRAKE MASTER FOR SERVING. RECOMMEND		
	7 REPLACEMENT OF ALL WHEEL CYLINDERS		4.0
02 NOV.	8 CONTINUE INVESTIGATION OF MISALIGNMENT OF BRAKE SHOES		
	9 TO PUSH RODS IN WHEEL CYLINDERS. SHOES ARE INSTALLED		
	10 UPSIDE DOWN, LEFT TO RIGHT INCORRECTLY. REMOVE SHOES.		

PATRICK OTTIS

INVOICE NO.

369214

SOLD TO:
ADDRESS:
CITY, STATE, ZIP:

SHIP TO:
ADDRESS:
CITY, STATE, ZIP:

CUSTOMER'S ORDER: 500 MINDIAL	SOLD BY: 0430 MD	TERMS:	F.O.B.:	DATE: 25 NOVEMBER 20
----------------------------------	---------------------	--------	---------	-------------------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
	1 DISCARD, ALIGNMENT BUSHINGS IN SHOES NOT FULLY SEATED,		
	2 CAUSING SHOES TO MISALIGN.		3.0
03 NW.	3 ASSIST BRUCE WITH SHOWING & DISPLAYING CAR TO POTENTIAL		
	4 BUYER, LEFT CAR, SHARE WHAT WE SEE AND KNOW. SET		
	5 UP RUN MOTOR.		2.0
05 NW.	6 INSPECT CHASSIS / FRAME WITH GOOD LIGHT FOR EVIDENCE OF		
	7 CHASSIS NUMBERS TOP & BOTTOM. GILCO NUMBERS IDENTIFIED		
	8 AS: 6321B E4.		1.0
06 NW.	9 REMOVE BUSHINGS FROM REAR BRAKE SHOES, REINSTALL BUSHINGS		
	10 TO PROPER DEPTH. INSTALL FOUR NEW REAR WHEEL CYLINDERS		

INVOICE
71721 ©2004 REDIFORM®

ARTRICK OTTIS

INVOICE NO.

369215

SOLE [REDACTED]
 ADD [REDACTED]
 CITY, STATE, ZIP [REDACTED]

SHIP TO:
 ADDRESS:
 CITY, STATE, ZIP

CUSTOMER'S ORDER: 500 MONDIAL SOLD BY: 0430 MD TERMS: F.O.B. DATE: 25 NOV 2002

INVOICE
71721 ©2004 MEDIFORM®

QUANTITY	DESCRIPTION	PRICE	AMOUNT
	1 ASSEMBLES, INSTALL FRONT BRAKE SHORS PROPERLY. SHORS NOW		6.0
	2 ALIGN WITH WHEEL CYLINDERS PROPERLY.		
09 NW.	3 UNBOLT, REMOVE FRONT BRAKE BACKING PLATES AS ASSEMBLES.		
	4 REMOVE BRAKE SHORS AND WHEEL CYLINDERS. WAS 4 CLEAN		
	5 INSPECT ALL COMPONENTS, REMOVE BUSHINGS FROM SHORS		
	6 REALIGN AND PRESS INTO PLACE. REASSEMBLE SHORS ONTO FRONT		
	7 BACKING PLATES WITH NEW WHEEL CYLINDERS.		7.0
11 NW.	8 REINSTALL ASSEMBLED FRONT BRAKE BACKING PLATES, CONERT		3.0
	9 BRAKE HOSES WITH ALL NEW SEAL RINGS.		
12 NW.	10 PAINT STRIP TOP OF LEFT FRONT CHASSIS TUBE IN STARELL		

ATTRICK OTTIS

INVOICE NO.

369216

SOL
ADD
CITY, STATE, ZIP

SHIP TO:
ADDRESS:
CITY, STATE, ZIP

CUSTOMER'S ORDER: 500 MONDIAL	SOLD BY: 0430 MD	TERMS:	F.O.B.	DATE: 25 NOVEMBER 20
----------------------------------	---------------------	--------	--------	-------------------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	OF CHASSIS NUMBER STAMPING - NONE FOUND. REMOVE WORK		
2	TRUMPET TO ACCESS.		1.0
13 MIN.	3 INSTALL FRONT & REAR BRAKE DRUM / HWB ASSY S. TORQUE &		
4	COTTER PIN. ADJUST BRAKE SHOE. REMOVE CAR FROM		
5	LIFT		3.5
6	SHOP LABOR TO DATE 47.5 HRS @		
7			
8	8 NGK B6ES SPARK PLUGS @ 6 ⁰⁰		
9	12 QTS PTH 70.50 RACING OIL @ 18 ⁹⁵		
10	FUEL, OIL, BRAKE COPPER SEAL RING SELECTION		

INVOICE
71721 ©2004 REDIFORM®

TRICK OTTIS

INVOICE NO.

369217

SO
AD
CITY, STATE, ZIP

SHIP TO:
ADDRESS:
CITY, STATE, ZIP

CUSTOMER'S ORDER: 500 MONDIAL	SOLD BY: 0430 MD	TERMS:	F.O.B.:	DATE: 25 NOVEMBER 20
----------------------------------	---------------------	--------	---------	-------------------------

INVOICE
71721 ©2004 REDIFORM®

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	4 NEW FRONT AS ORIGINAL WHEEL CYLINDERS 1 1/8" c 650		
2	4 NEW REAR AS ORIGINAL WHEEL CYLINDERS 1" c 650		
3	3 LOCKHEED 1/4 BRAKE MASTER KIT c 50		
4	ORIGINAL BRAKE SHOE RETURN SPRING		
5			
6	PARTS TOTAL TO DATE		
7	TAX ON PARTS		
8			
9			
10			

PATRICK OTTIS

INVOICE NO.

369218

SC
AD
CITY, STATE, ZIP

SHIP TO:
ADDRESS:
CITY, STATE, ZIP

CUSTOMER'S ORDER: 500 HONDA	SOLD BY: 0930 MD	TERMS:	F.O.B.	DATE: 25 NOVEMBER 20
--------------------------------	---------------------	--------	--------	-------------------------

INVOICE 71721 ©2004 REDIFORM®

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1			
SUBTOT	2 SILVER SOLDIER REPAIR (PREVIOUSLY REPAIRED) CORRODED / BROKEN		
	3 FUEL LOG. STRENGTHEN WITH INTERNAL SCREW		
	4 NORMAN RACING		
SUBTOT	5 SLEAVE DUAL CIRCUIT BRAKE MASTER CYLINDER, BRK EQUIP WARE,		
	6 SUBTOT TOTAL TO DATE		
	7 FED-EXP SHIP W/INS STD. OVERNIGHT TO MINNESOTA BRK MASTER		
	8 FED-EXP SHIP W/INS OVERNIGHT FROM MINNESOTA BRK MASTER		
	9 91 OCTANE FUEL		
	10 JOB TOTAL TO DATE		