## Patrick Ottis 1220 Tenth Street Berkeley, CA 94710

December 31, 2015

## Re: 250 Scaglietti Berlinetta (TDF) Chassis 1031GT, 56471 Kms

02 Dec	Assemble fuel pump drive mechanism and fit to engine. Install distributer tower	4.0
	seals and mount drives to engine. Fit and trim cam cover gaskets, install cam	
	cover studs. Install chain covers. Chase and clean water drains, block and bungs.	
	Work on assembly of fuel log and carb fittings.	
03 Dec	Assemble fuel log and fit to carburators. Mock up carb assemblies to engine.	6.0
	Retime ignition distributors. Install new oil filter conversion kit. Machine end	
	plate to fit. Begin assembling spark plug wiring. Rig cooling system to pressure	
	test.	
04 Dec	Continue work on ignition wiring looms. Install newly received carburetor drip	4.5
	trays with drain manifold. Pressure test cooling system. Address minor leak.	
	Retest. Install cam covers – align cam cover studs to fit.	
08 Dec	Finish making spark plug wire looms. Install to engine. Figure out problem with	6.0
	lower sump not seating on upper sump. Remove oil pick up assembly. Look for	
	correct carburator linkage hardware from P. Ottis stock.	
09 Dec	Assemble and install carburetor rod linkages. Change threads as required.	4.5
	Assemble breathers. Mock up oil pick-up and check sump fit. Install new hose	
	with clamps. Install lower sump. Remove degree wheel. Install pilot bearing	
	and flywheel bolts – torque to spec. Install crankshaft nose gear bolt and torque.	
14 Dec	Glass bead, prep misc hardware for black oxide to include motor mount bolts, all	1.0
	rear suspension trailing arm bolts etc. Pack and ship for plating.	
	Shop labor to date 26.0 hours @ \$120.00	\$3,120.00
	Parts:	
	2 oil seals – Dist angle drives to cylinder heads 204010 @ 16.50	33.00
	4 as original ign. wire manifold aluminum spacers @ 10.00	40.00
	38 feet 7mm spark plug wire @ 1.50	57.00
	12 spark plug wire ends ST. 113 @ 1.50	18.00
	12 spark plug bolts SPP 15 @ 2.50	30.00
	12 spark plug wire manifold grommets @ .75	9.00
	O-ring 25mm	40.00
	Original 14mm wrench size 8mm x 1.0 nuts	20.00
	Oil filter conversion kit – Betz and Peters	250.00
	Oil filter element Puralator L20178B	19.95
	Pilot bearing 103877	55.00
	Pilot bearing snap ring	4.00
	2 brass bungs for water/oil temp sending units as original @ 150.00	300.00

Job total to date`	\$4,900.18
oxide plating 14 Dec	20100
FedEx ship rear suspension trail arm hardware – motor mount bolts for black	20.00
Sublet total to date	440.00
as original B. White	
Sublet: Fabricate machine 8mm x 1.0 nuts with 12mm hex for carburetor bases	260.00
Sublet: Fabricate one screen for oil fill cap (missing) Norman Racing	60.00
 Sublet: Fabricate 3 fuel filter screens for fuel loc. @ 40.00 Norman Racing	120.00
Tax on parts	106.22
Parts total to date	1213.95
 Original chain tensioner dome nut (missing)	200.00
22mm oil pick up hose 240299	75.00
 2 temp. sending units, 1 oil – 1 water 100453 @ 29.50	59.00