

May 20, 2019

Re: Ferrari 330 GT, Chassis# 6077, Blue, 82353 kilometers

JN 1281

SUPPLEMENTARY SUSPENSION ESTIMATE

Taxable parts:

2x Front Outer Bottom Suspension Pin (may not be	
required)	\$ 384.08
2x Front Outer Top Suspension Pin (may not be	
required)	\$ 448.82
8x Trunnion Bush	\$ 285.20
2x King Pin Bearing Housing	\$ 252.90
120x King Pin Needle Rollers	\$ 43.20
8x Front Suspension O Ring	\$ 35.60
2x Droop Stop Rubber	\$ 98.00
2x King Pin Lock Washer	\$ 24.90
Front Suspension Spring Rubber Set	\$ 127.00
2x Front Wheel Bearing Outer	\$ 240.00
2x Front Wheel Bearing Inner	\$ 398.00
2x Front Hub Felt Seal	\$ 52.90
Outer Trunnion Spacers	TBD
Consumables	\$ 19.00
	\$ 2,409.60

All parts are new, unless otherwise stated



Non-taxable items/sublet charges: To ream in bushes * * sublet item			TBD
Labor (charged at \$170/hour) To strip front suspension (both sides), replace suspension pins (if required), replace king pin and trunnion bushes. To repair bent spring seats, replace spring rubbers, replace wheel bearings and reassemble.	\$	8	5,950.00
T:	s ax \$		8,359.60 228.91
ESTIMATE TOTA	AL \$	5	8,588.51
This estimate is valid for 14 days after date of estimate.	_		
I hereby authorize the above work to be completed with the express mechanic's lien is acknowledged on the above items to strepairs thereto. Work not picked up within 7 days following charged storage at a daily rate of \$85. All items left over 30 discarded.	secure the notification in the secure of the	ne ati	amount of on will be
Print Name: Dat	:e:		
Sign:			
BAR Registration Name: GTO Engineering LA LLC			
BAR License Number: ARD00286121			