

ROY SASAKI PORSCHE SERVICE

6997

PHONE: 297-1416
785 NO. 13th ST.
SAN JOSE, CA. 95112

CASH	CHARGE	BUDGET

Quan. PART NO. DESCRIPTION PRICE

Gen CHANGE
IS OK - 14.5 VOLTS

[Handwritten signature]

TOTAL PARTS

SUBLET REPAIRS

TOTAL SUBLET REPAIRS

ESTIMATE AMOUNT - FOR PARTS AND LABOR

ESTIMATE TOTAL

NAME: _____ DATE: 1-27-83 A.M. P.M.

ADDRESS: _____ PHONE: _____ YES NO

PROMISED _____ A.M. P.M.

YEAR MAKE MODEL COLOR LICENSE SPEEDOMETER RETAIN PARTS FOR INSPECTION

96 Porsche 18178

MOTOR NUMBER SERIAL NUMBER WRITTEN BY DISCARD PARTS

LUBRI-CATE CHANGE OIL FLUSH TRANS. FLUSH DIFF. WASH POLISH

OPER.No.	INSTRUCTIONS	LABOR
	SPARK PLUGS	6 00
	FAN BELT	3 00
	TRANS OIL	12 00
	OIL FILTER	5.50
	4 SPARK PLUGS	
	ADJ VALVES & 2 GASKETS	20 00
	5 OIL ENGINE	7 50
	Fix R. Door pocket	5 00
	HOME switch for L. door	3 00
	INSTALL plugs & check ignition	10 00

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto.

AUTHORIZED BY: _____ F.S. _____

RECEIVED BY: *[Signature]*

TOTAL LABOR	35 00
TOTAL PARTS	37 00
SUBLET REPAIRS	3 00
ACCESSORIES	
GAS, OIL TRANS. FLD.	
TAX	2 90
TOTAL	74.40

Not Responsible For Loss or Damage to Cars or Articles Left in Cars in Case of Fire, Theft or Any Other Cause Beyond Our Control.


GALS. GAS @ _____

QTS. OIL @ _____

QTS. TRANS. FLD. @ _____

TOTAL _____

 CARLSEN MOTOR CARS, INC
 SERVICE DEPARTMENT
 1730 EMBARCADERO RD PALO ALTO, CA 94303-3397
 (415) 856-6300



REPAIR INVOICE

 SERVICE OPEN 7:30 AM - 5:30 PM MON - FRI
 CASHIER OPEN 8:00 AM - 6:00 PM MON - FRI
 BAR REG # 40022
 P O R S C H E * * * * A U D I * * * * P E U G E O T

CUSTOMER #	SERVICE ADVISOR	P.O. NUMBER	INVOICE DATE	INVOICE NUMBER
30589	CINDY CHARDT		08 MAY 1989	PBCR126904



VIN# 129020920 YEAR 69 MODEL 912 PROD DEL DLR# ST# CHASSIS#	RO-DT 05/03/89 MILES 52473 LIC. 460KTR HAT# BACK MOD#
---	---

***** CUSTOMER INVOICE *****

LABOR	-----	
(JOB# 1) 28 0.5	CUSTOMER STATES VEHICLE WONT START INTERMITTENLY NONE FOUND AT THIS TIME INSPECTED CHARGING SYSTEM CHECKS O.K	36.00
(JOB# 2) 28PR-1 0.5	CUSTOMER REQUESTS GENERAL VEHICLE INSPECTION CUSTOMER REQUEST INSPECTED ENGINE POWER BALANCE O.K SEE COMMENTS	36.00
(JOB# 3) 15 0.8	CUSTOMER STATES TRANSMISSION HARD TO SHIFT INTERMITTENLY WORN CLUTCH ARM CLEVIS REPLACE CLUTCH ARM CLEVIS	57.60
	TOTAL-LABOR	129.60
PARTS (J 3)	-----	
1	PR911-423-205-03 BOLT	11.79
	TOTAL-PARTS	11.79
MISC..	-----	
	SHOP SUPPLIES	3.88
	TOTAL-MISC..	3.88

CUSTOMER HEREBY ACKNOWLEDGES RECEIVING ORIGINAL ESTIMATE OF \$ 72.00 (+TAX)	TOTAL LABOR.. 129.60
MS PINAGLIA APPROVED REVISED ESTIMATE (+TAX)	TOTAL PARTS.. 11.79
OF \$ 150.00 ON 05/04/89 AT 17:20 BY PHONE TO CINDY	TOTAL SUBLET.. 0.00
APPROVED REVISED ESTIMATE (+TAX)	TOTAL G.O.G.. 0.00
OF \$ ON AT BY	TOTAL MISC... 3.88
	TOTAL TAX.... 1.10
TOTAL INVOICE \$	146.37

CUSTOMER SIGNATURE

===== C O M M E N T S =====
 VEHICLE IS IN VERY GOOD GENERAL CONDITION,
 BRAKE PADS ARE GOOD AT THIS TIME. WE FOUND SOME SLIGHT SEEPAGE
 AT THE REAR MAIN SEAL AND THE INTERMEDIATE PLATE.
 JUST A NOTE. A DIFFERENT DISTRIBUTOR IS IN THE VEHICLE OTHER THAN
 WHAT WAS ORIGINA. THIS PRESENT ONE IS GOOD BUT WILL NOT PASS A
 SMOG CERTIFICATION. THE DECEL VALVE HAS ALSO BEEN DISCONNECTED.
 THANK YOU!

* CODE N-NEW U-USED R-REBUILT



ROY SASAKI PORSCHE SERVICE

785 N. 13th St. - Phone: (408) 297-1410
 San Jose, CA 95112
 B.A.R. Reg. No. AD 0780

000723
INVOICE

DATE
 5-18-94

QTY.	* PART NO. OR DESCRIPTION	SALE AMT.
1	PISTON RING FRANKSHEET	190.95
1	PISTON RING 175-UPP'S	425.00
1	CRANK SHAFT	77.80
2	VALVE GUIDES	34.00
1	ROCKER ARM BUSHINGS	18.20
1	ROCKER ARM VALVES 2385	95.40
1	VALVE ED VALVES 490	191.60
2	VALVE SPRINGS 34500	43.60
2	SPRINGER PIN TUBES 92000	71.40
1	WASHER SOCKET CAP	111.70
1	LOWER SOCKET CAP	40.20
2	ROD NUTS	45.00
1	STD ROD BEARING SET	22.10
1	OLD ROD STD MAIN BEARING SET	208.80
1	MAIN BEARING SEAL (SEALING)	7.00
1	CLUTCH DISC	132.60
1	PLATE	115.50
1	THROW OUT BEARING	101.50
TOTAL PARTS		679.25

YEAR - MAKE - MODEL	N/A
LICENSE	4601KTR
SPEEDOMETER	14014
ID #	4571
BILL TO	13.46
ADDRESS	771 6688
MECH.	REPAIR ORDER - DESCRIPTION OF WORK
LABOR CHG.	

MECH.	REPAIR ORDER - DESCRIPTION OF WORK	LABOR CHG.
	RECONDITION CAMSHAFT (OWN)	95.00
	2 VALVE CYL HEADS	26.00
	4 P/R VALVE GUIDES	26.00
	8 SPRING SEALS	41.60
	2 FLY CAT + OIL RYL HEADS	65.00
	WASH 4 CON RODS	32.50
	RECONDITION 4 CONN RODS COMPLETE	78.00
	BALANCE	26.00
	CLEAN + REGRIND & LITEN	32.50
	CRANK ALIGNMENT FLYWHEEL	52.00
	BALANCE FLYWHEEL & CLUTCH	45.50
	BALANCE 4 PISTONS	26.00
	CHECK OUT NEW CRANK (BALANCE SIZE)	32.50
	CHECK OUT CAPS	26.00

ORIGINAL ESTIMATE \$	DATE	TIME	BY	BODY LABOR
REVISED ESTIMATE \$	DATE	TIME	BY	PARTS
REVISED ESTIMATE \$	DATE	TIME	BY	ADVANCE CHARGES
I acknowledge notice and oral approval of an increase in the original estimated price.				PAINT
I hereby authorize the repair work as per estimate to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Storage will be charged forty-eight hours after repairs are completed. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I acknowledge a receipt of an estimate.				PAINT LABOR
SIGNED X				SUBLET REPAIRS
DEFECTIVE PARTS REQUESTED BY CUSTOMER YES <input type="checkbox"/> NO <input type="checkbox"/>				CAR RENTAL
TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE.				SALES TAX
				TOTAL AMOUNT

CASH
 CHECK
 CHARGE
 CREDIT CARD

INTEREST WILL BE CHARGED AT A RATE OF 1 1/2% PER MONTH ON ACCOUNTS OVER 30 DAYS.

SEE IMPORTANT INFORMATION ON BACK

*CODE N-NEW U-USED R-REBUILT



ROY SASAKI PORSCHE SERVICE

786 N. 13th St. - Phone: (408) 297-1416
 San Jose, CA 95112
 B.A.R. Reg. No. AD 0780

000748
INVOICE

DATE
 6-20-90

QTY.	PART NO. OR DESCRIPTION	SALE AMT.
1	AIR HOSE 35MM RUBBER	14.00
1	OIL PAIL	288.00
2	CUPPER GASKETS (4)	6.00
2	OIL LINES	12.00
4	VALVE STEM SEAL	9.00
1	GEN. BRUSHES	9.00
1	SPARK PLUG WIRES	19.50
1	FRONT GASKET	2.00
1	ENGINE COMPART INSUL.	68.90
2	SMALL PIPE BUSHINGS	3.30
1	PULLEY SEAL & O-RING	7.00
1	MAIN SEAL	7.00
1	LOWER SWAMP SCREEN	66.65
10	6MM LOCKING WTS	1.50
3	SPARK PLUG WIRES HAND DOWN	3.75
1	35MM PAPER HOSE	15.00
1	BAND IRON 5 STRIPS	10.00
1	3' GAS HOSE	3.00
1	FRONT HOSE CLAMP	60.00
2	HOPE BUSHING (BALL JOINT)	5.80
TOTAL PARTS		776.15

YEAR - MAKE - MODEL
 LICENSE
 SPEEDOMETER
 ID # AGENT

BILL TO DEDUCTIBLE
 ADDRESS ALLOWANCE

MECH.	REPAIR ORDER - DESCRIPTION OF WORK	LABOR CHG.
	LABOR INSTALL ENGINE COMPART INSULATION	30.00
	BATTERY	60.00
	2 AXLE BOOTS LEFT SIDE ONLY	23.50
	LABOR INSTALL BOOTS L. SIDE	50.00
	ONE CAP GASKET	1.75

PAID

USE INITIAL HERE

TOTAL SUBLET REPAIRS

FOLLOWING REPAIRS RECOMMENDED

AIR HOSE 1"	5.50
-------------	------

ORIGINAL ESTIMATE \$	DATE	TIME	BY	BODY LABOR	80.00
REVISED ESTIMATE \$	DATE	TIME	BY	PARTS	645.05
REVISED ESTIMATE \$	DATE	TIME	BY	ADVANCE CHARGES	
I acknowledge notice and oral approval of an increase in the original estimated price.				PAINT	
I hereby authorize the repair work as per estimate to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Storage will be charged forty-eight hours after repairs are completed. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I acknowledge a receipt of an estimate.				PAINT LABOR	
SIGNED <input checked="" type="checkbox"/>				SUBLET REPAIRS	
DEFECTIVE PARTS REQUESTED BY CUSTOMER YES <input type="checkbox"/> NO <input type="checkbox"/>				CAR RENTAL	
TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE.				SALES TAX	46.10
				TOTAL AMOUNT	776.15

CASH CHECK CHARGE CREDIT CARD

INTEREST WILL BE CHARGED AT A RATE OF 1 1/2% PER MONTH ON ACCOUNTS OVER 30 DAYS.

SEE IMPORTANT INFORMATION ON BACK

*CODE N-NEW U-USED R-REBUILT



ROY SASAKI PORSCHE SERVICE

785 N. 13th St. - Phone: (408) 297 1416
 San Jose, CA 95112
 B.A.R. Reg. No. AD 0780

000770

INVOICE

DATE
 9-2-94

YEAR - MAKE - MODEL N
 LICENSE A
 SPEEDOMETER C
 ID # 14014
 AGENT

P.A

BILL TO _____ DEDUCTIBLE _____
 ADDRESS _____ ALLOWANCE _____

MECH. REPAIR ORDER - DESCRIPTION OF WORK LABOR CHG.

*RETURN
 FOR 500 MILE
 VALUE ADJUSTMENT
 AND CHECK UP.*

PAID ESTIMATE 6000.00
 5918.79
 CREDIT → 81.21
 (INVOICE 0748) ADDITIONAL 771.15
 CREDIT 81.21
 BALANCE → 689.94
 PAID #483

TOTAL PARTS _____
 OUTSIDE-SUBLET REPAIRS _____
 TOTAL SUBLET REPAIRS _____
 FOLLOWING REPAIRS RECOMMENDED
 MASTER CITE
 TRANS.

ORIGINAL ESTIMATE \$ _____ DATE _____ TIME _____ BY _____
 REVISED ESTIMATE \$ _____ DATE _____ TIME _____ BY _____
 REVISED ESTIMATE \$ _____ DATE _____ TIME _____ BY _____
 I acknowledge notice and oral approval of an increase in the original estimated price.
 I hereby authorize the repair work as per estimate to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Storage will be charged forty-eight hours after repairs are completed. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I acknowledge a receipt of an estimate.
 SIGNED _____
 DEFECTIVE PARTS REQUESTED BY CUSTOMER YES NO
 TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE.

BODY LABOR	
PARTS	
ADVANCE CHARGES	
PAINT	
PAINT LABOR	
SUBLET REPAIRS	
CAR RENTAL	
SALES TAX	
TOTAL AMOUNT	

CASH CHECK CHARGE CREDIT CARD

SEE IMPORTANT INFORMATION ON BACK

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

* CODE N-NEW U-USED R-REBUILT

CLAIM REP. GLENN HOPKINS 879-3712

ROY SASAKI RESTORATION

785 N. 13th Street • San Jose, CA 95112
(408) 297-1416
B.A.R. Reg. No. ADO 78048

1021

INVOICE

DATE 2-11-97

QTY	* PART NO. OR DESCRIPTION	SALES AMT.
	RIGHT REAR BUMPER	
	901 505 022 20 *	375.00
	CENTER PANEL (PURSUE)	
	901 505 023 20 *	247.50
	TAIL LIGHT ASSY. R.	
	901 631 404 01 *	350.00
	19+ MATCHED PAINT (FARM OUT)	
	MATERIAL	
	* 40.00	
	1 RAMP BUMPER GUARD	
	* 190.00	
	901 505 013 21	
TOTAL PARTS		
OUTSIDE SUBLET REPAIRS		
TOTAL SUBLET REPAIRS		
FOLLOWING REPAIRS RECOMMENDED		
Shop Hourly RATE IS		
8.80/hour		

TARGA

YEAR - MAKE - MODEL 88 POR 912

LICENSE 2LL 849

SPEEDOMETER 62747

ID # 14870750

BILL TO

ADDRESS 5-19-91
AHSWOR

TITLE

ANCE

MECH.	REPAIR ORDER - DESCRIPTION OF WORK	LABOR CHG.
	PULL FRAME (FARM OUT)	350.00
3.	METAL FINISH R. QUARTER PANEL	174.00
2.	OVER HILL CENTER PANEL + R.R BUMPER	116.00
1.	REFINISH CENTER PANEL	58.00
1.	" R.R. BUMPER	58.00
3.	" R QUARTER PANEL	174.00
	FREIGHT FROM OHIO (STANDARD)	25.00
	UPR + PACKAGING Standard	
2.	STRAIGHTEN REAR CROSS BAR	116.00

ORIGINAL ESTIMATE \$	DATE	TIME	BY	BODY LABOR	1046.00
ORIGINAL ESTIMATE \$	DATE	TIME	BY	PARTS	1273.50
ORIGINAL ESTIMATE \$	DATE	TIME	BY	ADVANCE CHARGES	
I acknowledge notice and oral approval of an increase in the original estimated price.				PAINT	
I hereby authorize the repair work as per estimate to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereon. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Storage will be charged forty-eight hours after repairs are completed. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I acknowledge a receipt of an estimate.				PAINT LABOR	
				SUBLET REPAIRS	
				CAR RENTAL	
				SALES TAX	93.65
SIGNED X				(OHIO) FREIGHT	25.00
DEFECTIVE PARTS REQUESTED BY CUSTOMER YES <input type="checkbox"/> NO <input type="checkbox"/>				TOTAL AMOUNT	2443.15

CASH CHECK CHARGE CREDIT CARD

INTEREST WILL BE CHARGED AT A RATE OF 1 1/2% PER MONTH ON ACCOUNTS OVER 30 DAYS

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

* CODE N-NEW U-USED R-REBUILT

ROY SASAKI RESTORATION

785 N. 13th Street • San Jose, CA 95112

(408) 297-1416

B.A.R. Reg. No. ADO 78048

1040

INVOICE

DATE 6-11-97

QTY	PART NO. OR DESCRIPTION	SALES AMT.
	<i>a must:</i>	
	<i>valve adjustment</i>	
	<i>wash oil change</i>	

YEAR - MAKE - MODEL
 1982 DODG 91L
 LICENSE
 460 KTR
 SPEEDOMETER
 41970
 ID #

BILL TO
 ADDRESS

MECH.	REPAIR ORDER - DESCRIPTION OF WORK	LABOR CHG.
	INSTALL GRAM SHIFT LOCKOUT	25.00
	R+R. LEFT DASH PANEL, GREASE LOCKER	40.00
	2 CARBS: REPAIR, CLEAN ADJUST	100.00
	AOS VALVES	25.00
	CARB BLOC	4.00
	2 VALVE COVER GASKETS (CURK)	7.00
	2 EX. GASKETS	2.00
	2 EX. CLAMPS 760	15.20
	R+R + FIT MUFFLER	50.00
	19" oil	2.00

TOTAL PARTS	
OUTSIDE SUBLET REPAIRS	
PLEASE INITIAL HERE <input type="checkbox"/>	TOTAL SUBLET REPAIRS
FOLLOWING REPAIRS RECOMMENDED	

ORIGINAL ESTIMATE \$	DATE	TIME	BY	BODY LABOR	240.00
ORIGINAL ESTIMATE \$	DATE	TIME	BY	PARTS	30.20
ORIGINAL ESTIMATE \$	DATE	TIME	BY	ADVANCE CHARGES	
I acknowledge notice and oral approval of an increase in the original estimated price.				PAINT	
<input checked="" type="checkbox"/>				PAINT LABOR	
I hereby authorize the repair work as per estimate to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereon. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Storage will be charged for 48 hours after repairs are completed. In the event legal action is necessary to enforce this contract. I understand that I am solely responsible for all costs including attorney's fees and court costs. I acknowledge a receipt of an estimate.				SUBLET REPAIRS	
				CAR RENTAL	
				SALES TAX	2.49
				TOTAL AMOUNT	272.69

SIGNED _____
 DEFECTIVE PARTS REQUESTED BY CUSTOMER YES NO

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE
 INTEREST WILL BE CHARGED AT A RATE OF 1 1/2% PER MONTH ON ACCOUNTS OVER 30 DAYS

CASH CHECK CHARGE CREDIT CARD

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

* CODE N-NEW U-USED R-REBUILT

ROY SASAKI RESTORATION

785 N. 13th Street • San Jose, CA 95112

(408) 297-1416

B.A.R. Reg. No. ADO 78048

1075

INVOICE

DATE 11-25-97

YEAR - MAKE - MODEL <u>69 Ford 912</u>	N	TOES	DRIVE
LICENSE	A		
SPEEDOMETER <u>45961</u>	C		
ID #	A		
BILL TO			
ADDRESS			

*PAID
5604*

MECH.	REPAIR ORDER - DESCRIPTION OF WORK	LABOR CHG.
	Busch REBUILT STARTER REPLACE	150. ⁰⁰
	REMOVE DOOR PANEL TO FREE UP FROZEN INSIDE DOOR HANDLE	25. ⁰⁰
	ADJ VALVES	25. ⁰⁰
	LABOR FOR STARTER	20. ⁰⁰
	TRANS DRAINED & REFILL	20. ⁰⁰

TOTAL PARTS	
OUTSIDE SUBLET REPAIRS	
PLEASE INITIAL HERE <input type="checkbox"/>	TOTAL SUBLET REPAIRS
FOLLOWING REPAIRS RECOMMENDED	

ORIGINAL ESTIMATE \$	DATE	TIME	BY	BODY LABOR
ORIGINAL ESTIMATE \$	DATE	TIME	BY	PARTS
ORIGINAL ESTIMATE \$	DATE	TIME	BY	ADVANCE CHARGES
I acknowledge notice and oral approval of an increase in the original estimated price.				PAIN
<input checked="" type="checkbox"/>				PAIN LABOR
I hereby authorize the repair work as per estimate to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Storage will be charged forty-eight hours after repairs are completed. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I acknowledge a receipt of an estimate.				SUBLET REPAIRS
SIGNED <input checked="" type="checkbox"/>				CAR RENTAL
DEFECTIVE PARTS REQUESTED BY CUSTOMER YES <input type="checkbox"/> NO <input type="checkbox"/>				SALES TAX <u>8.25</u>
TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE				TOTAL AMOUNT <u>198.25</u>

CASH CHECK CHARGE CREDIT CARD

INTEREST WILL BE CHARGED AT A RATE OF 1 1/2% PER MONTH ON ACCOUNTS OVER 30 DAYS

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

* CODE N-NEW U-USED R-REBUILT

ROY SASAKI RESTORATION

785 N. 13th Street • San Jose, CA 95112

(408) 297-1416

B.A.R. Reg. No. ADO 78048

1085

INVOICE

DATE

1-22-98

YEAR - MAKE - MODEL N

69 Buick Wildcat A

LICENSE

460 KTR C

SPEEDOMETER

76 746 A

ID #

BILL TO

ADDRESS

Handwritten: Paid \$54.50

MECH.	REPAIR ORDER - DESCRIPTION OF WORK	LABOR CHG.
	2 REAR AXLE BEARING	80.00
	4 " " " " GASKETS	4.00
4 hrs.	LABOR INSTALL BOTH REAR AXLE BRGS.	200.00

ORIGINAL ESTIMATE \$	DATE	TIME	BY	BODY LABOR	200.00
----------------------	------	------	----	------------	--------

ORIGINAL ESTIMATE \$	DATE	TIME	BY	PARTS	84.00
----------------------	------	------	----	-------	-------

ORIGINAL ESTIMATE \$	DATE	TIME	BY	ADVANCE CHARGES	
----------------------	------	------	----	-----------------	--

I acknowledge notice and oral approval of an increase in the original estimated price.

PAINT

I hereby authorize the repair work as per estimate to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereon. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Storage will be charged forty-eight hours after repairs are completed. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I acknowledge a receipt of an estimate.

PAINT LABOR

SUBLET REPAIRS

CAR RENTAL

SIGNED _____

DEFECTIVE PARTS REQUESTED BY CUSTOMER YES NO

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE

SALES TAX 6.93

TOTAL AMOUNT 290.93

INTEREST WILL BE CHARGED AT A RATE OF 1 1/2% PER MONTH ON ACCOUNTS OVER 30 DAYS

CASH CHECK CHARGE CREDIT CARD

PLEASE INITIAL HERE

TOTAL SUBLET REPAIRS

FOLLOWING REPAIRS RECOMMENDED



PARTS HEAVEN

23694 BERNHARDT STREET
HAYWARD, CA 94545

(510) 782-0354 • (FAX) (510) 782-0358 • (800) 767-7250
www.partsheaven.com

SOLD TO

RSJ3366

3:48 PM

Invoice No.

97447

ROY SASAKI RESTORATION
785 N 13TH ST.
SAN JOSE, CA. 95112

ORDER BY	DEPARTMENT	P.O. NUMBER	DATE ORDERED					
			04/16/01					
WORK ORDER NO.	MAL COPY	DISMANTLER	READY	CORE EXCHANGE	R/O NUMBER	TRUCK LINE	SALES PERSON	SHIPPING DATE
114329				OUTRIGHT			ROB	04/16/01

ITEM / DESCRIPTION	STOCK NO.	LOC.	AMOUNT
DISTRIBUTOR 1 PORSCHE 912/E ANY (Extra Sale) 68	#0002	#	72.00 T
			72.00

Doc # :87648

5334-7405-4601-9909 X11-01
UPS GROUND SERV.

DISCLAIMER
 ALL SALES SUBJECT TO FOLLOWING TERMS:
 NO CASH REFUNDS
 NO GUARANTEE ON LABOR
 NO PARTS EXCHANGED OR RETURNED WITHOUT THIS INVOICE. A 20% RESTOCKING FEE WILL BE CHARGED ON ALL NEW PARTS. NO RETURNS ON SPECIAL ORDERS. ALL PARTS COME WITH A 90 DAY, REPLACEMENT ONLY GUARANTEE. IF PROPERLY INSTALLED. ALL EXPRESS OR IMPLIED WARRANTIES OF MERCHANTABILITY OF FITNESS FOR USE ARE DISCLAIMED. PARTS HEAVEN INC. WILL NOT BE LIABLE FOR DAMAGES OF ANY LOSS CAUSED BY LABOR, REMOVAL, INSTALLATION, OR ANY CONSEQUENTIAL DAMAGES OR USE OF THIS MERCHANDISE. A \$15.00 SERVICE CHARGE WILL BE ASSESSED ON ALL RETURNED CHECKS.

SUB TOTAL	72.00
SALES TAX	5.76
SHIPPING CHARGES	5.00
TOTAL	82.76

ALL CLAIMS & RETURNED GOODS MUST BE ACCOMPANIED BY THIS BILL.

Amount paid: 82.76
Amount due: 0.00

AUTO BODY REPAIR ORDER

Specializing in Early Model Diesels
 785 N. 13th Street
 SAN JOSE, CA 95112
 (415) 261-9115

1156

QTY.	PART NO. & DESCRIPTION <small>All parts new unless otherwise specified</small>	AMOUNT
	WINDSHIELD	135.00
	WINDSHIELD SEAL	5.00
	REAR WINDOW SEAL	61.00
2	FRONT WINDOW SEAL	122.00
	TRUNK SEAL	29.00
1	FRONT BUMPER	68.00
2	REAR BUMPER	12.00
1	REAR BUMPER BR.	55.00
2	COIL SPRING	5.00
1	14000 DISC BRAKE	37.00
1	Gas Strut	2.25
	FRONT BUMPER TO BUMPER SEAL	23.00
4	WHEEL BOLTERS	2.00
2	REAR BUMPER TO BODY SEAL	27.00
2	TRUCK HUB BOLTS	21.00
4	BUMPER GUARD SEAL	2.15
2	REAR BUMPER DISC	83.00
1	WINDOW PINNIT	26.00
2	WHEEL LAMP SEAL	19.00
1	LAMP LAMP GUARD	10.50
2	WHEEL LAMP SEAL TO BODY	7.00
2	WHEEL LAMP SEAL TO BODY	7.00
	GAS PIPE SEAL	2.00
	GAS CAP CABLE	7.95
2	REAR BUMPER TO BODY SEAL	10.00
2	WHEEL LAMP SEAL TO BODY	7.00
1	REAR BUMPER TO BODY SEAL	10.00

NAME	DATE		
AL	12-26-91		
CI	ZIP		
PK	95124		
	EXT		
YEAR, MAKE, MODEL	COLOR	LICENSE NO.	MILEAGE
68 PONTIAC GIL		8	2
PAINT CODE	TRIM	BODY TYPE	PROD. DATE
		SEDAN	
VER.			
INS. CO.	PHONE NO.		
ADJUSTER	CLAIM NO.		

QTY.	PAINT & MATERIALS	AMOUNT
4	ALL BUMPER TAPE	105.00
2	ALL COIL SPRING	14.00
2	WHEEL LAMP SEAL	4.00
2	REAR BUMPER TO BODY SEAL	14.00
	TOTAL	23.00

DESCRIPTION OF WORK	HRS.	AMOUNT
<input type="checkbox"/> Repair As Per Estimate		
<input type="checkbox"/> Supplementary Repairs		
2 FRONT BUMPER TO BUMPER SEAL	2.00	23.00
4 WHEEL BOLTERS	2.00	2.00
2 REAR BUMPER TO BODY SEAL	2.00	27.00
2 TRUCK HUB BOLTS	2.00	21.00
4 BUMPER GUARD SEAL	2.15	2.15
2 REAR BUMPER DISC	83.00	83.00
1 WINDOW PINNIT	26.00	26.00
2 WHEEL LAMP SEAL	19.00	19.00
1 LAMP LAMP GUARD	10.50	10.50
2 WHEEL LAMP SEAL TO BODY	7.00	7.00
2 WHEEL LAMP SEAL TO BODY	7.00	7.00
1 GAS PIPE SEAL	2.00	2.00
1 GAS CAP CABLE	7.95	7.95
2 REAR BUMPER TO BODY SEAL	10.00	10.00
2 WHEEL LAMP SEAL TO BODY	7.00	7.00
1 REAR BUMPER TO BODY SEAL	10.00	10.00

Ins. Co. Pays \$	TOTAL LABOR
Customer Pays \$	TOTAL PARTS
Insurance Check Payable To	PAINT & MATERIALS
	SUBLET
	TOWING / STORAGE
	EPA / WASTE DISPOSAL
DEDUCTIBLE PAID BY	SUB-TOTAL
<input type="checkbox"/> Cash <input type="checkbox"/> Check <input type="checkbox"/> Credit Card	TOTAL
<input type="checkbox"/> MC <input type="checkbox"/> AMEX <input type="checkbox"/> VISA	
Other	
CC No.	

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate vehicle for purpose of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is understood that you will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control. It is also understood that full payment for repairs is due upon release or delivery of vehicle, including supplemental charges.

Signature _____ Date _____

Thank You

AUTO BODY REPAIR ORDER

ROY SASAKI RESTORATION
 725 N. 1st Street
 SAN JOSE, CA 95112
 (408) 297-1414 FAX (408) 297-1415

1159

QTY.	PART NO. & DESCRIPTION <small>All parts new unless otherwise specified</small>	AMOUNT
LABOR PERFORMED:		
1.	REMOVE PAINT INSIDE & OUT	
2.	DISASSEMBLE MASOR BODY SECTION (DOORS, HOODS, BUMPERS) WINDOWS ETC.	
3.	METAL WORK WELDING, METAL FINISH, RUST WORK	
4.	TREAT BARE METAL & PRIME	
5.	SAND PRIMER SURFACER	
6.	APPLY SEALER, PAINT, CLEAR COAT	
7.	COLOR SAND & POLISH	
8.	RE ASSEMBLE BUMPERS DOORS, HOODS, WINDOWS, ETC.	
9.	PREPARE FOR DELIVERY	
	TOTAL LABOR	1664.00

DATE: 12-31-06
 G 4124 ZIP
 YEAR, MAKE, MODEL: 69 PONTIAC 402
 COLOR: _____ LICENSE NO.: 81712
 PAINT CODE: _____ TRIM: _____ BODY TYPE: _____
 VIN: _____
 INS. CO.: _____ PHONE NO.: _____
 ADJUSTER: _____ CLAIM NO.: _____

DESCRIPTION OF WORK	HRS.	AMOUNT
<input type="checkbox"/> Repair As Per Estimate		
<input type="checkbox"/> Supplementary Repairs		
PAINTING MATERIAL		1.00
PAINT & MATERIALS		
GLASSIT PAINT 1 GAL		3.00
" CLEAR COAT 1 GAL		3.00
HARDNER 2 qts		1.50
PRIMER SURFACER (1 qt / 100) 1 GAL		2.00
" " ACTIVATOR 1 GAL		1.18
BARE METAL PRIMER 1 GAL		1.00
" " ACTIVATOR		5.70
SEALER 2 qts		5.20
" 2 quarts ACTIVATOR		6.10
2 GAL PAINT REMOVER		5.70
2 GAL LAC THINNER		4.00
LEAD & MISC		50.00

QTY.	PAINT & MATERIALS	AMOUNT
	TOTAL	

Ins. Co. Pays \$ _____

Customer Pays \$ _____

Insurance Check Payable To _____

DEDUCTIBLE PAID BY
 Cash Check Credit Card
 MC AMEX VISA

Other _____

CC No _____

TOTAL LABOR	
TOTAL PARTS	
PAINT & MATERIALS	157.00
SUBLET	
TOWING / STORAGE	
EPA / WASTE DISPOSAL	
SUB-TOTAL	
TAX	130.00
TOTAL	1706.00

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate vehicle for purpose of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is understood that you will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control. It is also understood that full payment for repairs is due upon release or delivery of vehicle, including supplemental charges.

Signature _____ Date _____

Thank You

AUTO BODY REPAIR ORDER

ROY SASAKI RESTORATION
 Specializing in Early Model Porsches
 785 N. 13th Street
 SAN JOSE, CA 95112
 (408) 297-1416 BAR #AD078048

1275

QTY.	PART NO. & DESCRIPTION <small>All parts new unless otherwise specified</small>	AMOUNT
1	Suspension Front panel SIC-501-955-01	179.00
1	Fuel tank/Battery Box SIC 50104420	76.50
1	Angular piece 90150131020	84.54
1	tow Hook 90150153020	105.34
2	GAS TANK BASKET 90150493220	62.80
1	Suspension mount 90150142721	14.39
1	Fuel tank - reproduction	510.00
1	Sleeve for filler neck 90120159120	36.68
1	Front Floor pan SIC-501-937-00	231.50
1	Rear Floor pan SIC-50193800	221.00
2	Hood shocks - trunk	59.98
	Front Right FENDER - used 500.00	
	Left FENDER - USED 500.00	
REFUND FOR WORK 10776.36 NOT PERFORMED CK# 7636 Robert Sasaki		

YEAR, MAKE, MODEL		COLOR	LICENSE NO.	MILEAGE
PAIN CODE	TRIM	BODY TYPE	PROD. DATE	
VIN		INS. CO.		
ADJUSTER		PHONE NO.		
CLAIM NO.				

DESCRIPTION OF WORK	HRS.	AMOUNT
<input type="checkbox"/> Repair As Per Estimate		
<input type="checkbox"/> Supplementary Repairs		
INSTALL RELAY		
PAINT AND CLEANERS		
rear deck lid repair	5	350.00
FLOOR PAN - PARTIAL	12	840.00
FRONT SUSPENSION / GAS TANK	11	720.00
PARTIAL RUST REPAIR		
BUMPER - PRIME	5.5	385.00
Longitudinal 3 door rust		
inspection (remove PAINT)	2	140.00

QTY.	PAINT & MATERIALS	AMOUNT
	Paint	
	PAYMENTS 8 checks (16000.00) \$1000 each	
	TOTAL	

Ins. Co. Pays \$	TOTAL LABOR	2485.00
Customer Pays \$	TOTAL PARTS	1591.43
Insurance Check Payable To	FENDERS PAINT & MATERIALS	1000.00
	PAYMENTS SUBLET	(16000.00)
	TOWING / STORAGE	
DEDUCTIBLE PAID BY	EPA / WASTE DISPOSAL	
<input type="checkbox"/> Cash <input type="checkbox"/> Check <input type="checkbox"/> Credit Card	SUB-TOTAL	(10923.57)
<input type="checkbox"/> MC <input type="checkbox"/> AMEX <input type="checkbox"/> VISA	TAX	147.24
Other _____	TOTAL	(10776.36)
CC No. _____		

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate vehicle for purpose of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is understood that you will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control. It is also understood that full payment for repairs is due upon release or delivery of vehicle, including supplemental charges.

Signature _____ Date _____

Thank You

Parts					
	Total		\$ 2,591.43		
Susp rep pan	sic- 501-955-01		\$ 199.00		parts total \$ 1,591.43
				Fuel tank/battery box support. Fits 1969-1973. Superseded to SIC- 501-117-02. 911-501-117-02-GRV also needs to be purchased to complete the supercession	
Tank Support	sic-501-049-20		\$ 76.50		tax \$ 147.21
Angle Bracket	901-501-310-20		\$ 74.54		used parts 1000
Tow hook	901-501-530-20		\$ 105.34		labor \$ 2,485
gas tank gasket	901-504-932-20		\$ 62.80		Total \$ 5,223.64
suspension mount	901-501-427-21		\$ 14.39		
Fuel Tank - reproductive	SIC-201-904-00		\$ 510.00		payments 16000
sleeve for filler neck	901-201-591-20		\$ 36.38		Total refund \$ 10,776.36
Floor pan					
Hood shocks			\$ 59.98		
fender right -used			\$ 500.00		
fender left -used			\$ 500.00		
floor pan front	SIC-501-937-00		\$ 231.50		
floor pan rear	SIC-501-938-00		\$ 221.00		
Labor	Hours			\$ 2,485	
	30.5				
Install relay - other car					
Paint air cleaners - other car					
repair deck lid	5	\$ 350.00			
Floorpan				\$ 840	
	2	\$ 140.00		Remove interior	
	6	\$ 420.00		Cut & Fit driver side	
	3	\$ 210.00		Repair tunnel	
	1	\$ 70.00		Cut passenger side	
Trunk				\$ 770	
	1	\$ 70.00		remove gas tank	
	8	\$ 560.00		cut & fit and weld suspension mount	
	2	\$ 140.00		repair front trunk	
Bumper				\$ 385	
	1.5	\$ 105.00		strip paint	
	4	\$ 280.00		metal prep and prime	
Misc					
	2	\$ 140.00		remove paint, rust inspection longitudal area	