

NO. 5679

* CODE: N - NEW U - USED R - REBUILT

QTY.	*	PART NO. OR DESCRIPTION	AMOUNT
1		TANK SCREEN	8.21
4		FUEL NOSE	2.04 8.16
1 qt		90WT.	4.25 4.25
3		ZINK (CARBON) FITTING 2 IN	7.50
1		CLUTCH CABLE LONG PIN	2.29
2		LL PAN BUTT	.30 .60
1		LT TIE ROD	51.04
1		RT TIE ROD (ADD)	51.04
2		STRAP, NUTS, COP NUTS	2.00
1		TALL SUCKET, BALL 4 CEN	7.95

EBERT'S VW. REPAIR
 2670 17th. Ave.
 Santa Cruz, Ca. 95065
 831-476-8214

VIN #
25E069313

DATE 3 / 7 / 14	
WRITTEN BY	LABOR CHARGE
LUBRICATION <input type="checkbox"/>	
CHANGE OIL <input type="checkbox"/>	
CHANGE OIL FILTER CART. <input type="checkbox"/>	
SERVICE AIR CLEANER <input type="checkbox"/>	
CHANGE TRANS. OIL <input type="checkbox"/>	
ADJUST TRANSMISSION <input type="checkbox"/>	
CHANGE DIFF. OIL <input type="checkbox"/>	
PACK FRONT WHEEL BRGS. <input type="checkbox"/>	
ROTATE TIRES <input type="checkbox"/>	
ADJUST BRAKES <input type="checkbox"/>	
RETAIN PARTS <input type="checkbox"/>	
DESTROY PARTS <input type="checkbox"/>	

NAME _____
 ADDRESS _____
 CITY _____
 BILL TO _____
 ADDRESS _____
 PHONE _____
 YES

DELIVERY YES NO

TIME RECEIVED AM _____ PM _____
 TIME PROMISED AM _____ PM _____

YEAR 66 MAKE VW MODEL U
 LICENSE SWDCOB
 SPEEDOMETER 90570
 MOTORING 12V.

ADDITIONAL PARTS FROM REVERSE SIDE OF SHOP COPY 8.10

TOTAL PARTS 151.14

ESTIMATE OF LABOR AT THIS ADDRESS

SUBLET REPAIRS:

TOTAL SUBLET REPAIRS

TOTAL ESTIMATE AMOUNT

INCLUDES PARTS, ACCESSORIES OUR LABOR AND SUBLET REPAIRS

ADDL. AUTH. AMT. TIME DATE BY

ADDL. AUTH. AMT.

ADDL. AUTH. AMT.

TOTAL ESTIMATE

OPER. NO.	REPAIR ORDER - LABOR INSTRUCTIONS	INTERNAL	LABOR CHARGE
1:30	DRAIN FUEL TANK, REP TANK SCREEN & NOSE TO PUMP		
1:55	CHANGE LUBE (BRAKE FLUID EMPTY) + TIE TROD, ADD		
2:40	TIE T-3 ROD (3 MISSING ZINK FITTINGS) + STRAP BOX		
1:30	PULL CLUTCH PIPES & LABS, FAST AP WITH NUTS & LABS		
1:00	REP 2 TIE RODS (1 OLD, 1 BEAT), TIGHTEN LIKE PINS		
1:50	ADD SHIFTS, RE-ATTACH SIDE OWN CLUTCH BRACKET		565
1:40	REMOVE OLD MINOR PUT (RT) & ADD NEW MINOR		
1:40	REPLACE RT TAIL LT SUCKET, REP BELT (CHECK)		
1:45	PULL BACK DOWN PANEL, OPEN DOWN LABS (REPAIR)		
1:55	REP BATTERY STRAP, PULL SEAT FOOT GUARD (SEE NOTE)		
	TOTAL FOR LABOR PERFORMED AT THIS ADDRESS		561

"All warranties on the products sold hereby are those made by the manufacturer. The seller (above named Dealer/Shop) hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability, or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products."

QTY.	GAS, OIL AND ATF	PRICE	BILLING INFO.	INTERNAL ACCT.	COST	ESTIMATE CHARGE
	GALS. GAS @		<input type="checkbox"/> CASH			SUBLET REPAIRS
	QTS. OIL @		<input type="checkbox"/> CHARGE			TOTAL PARTS 151.14
	QTS. ATF @		<input type="checkbox"/> INTERNAL			GAS, OIL, ATF
TOTAL - GAS, OIL AND ATF			OK'D BY			PAINT
			Replaced parts will be returned if you request them when the repairs are ordered. (You may inspect those parts which must be returned to the manufacturer).			ACCESSORIES
			Replaced Parts Requested by Customer (Please Check) <input type="checkbox"/> Yes <input type="checkbox"/> No			TIRES AND TUBES
			I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to vehicles placed with them for storage.			SALES TAX 12.47
						TOTAL AMOUNT 728.61

IS GAS TANK LEAKING? (SMELL?)
 RE-CHECK TROD OIL LEVEL, & SPARE TIRE.
 DO FT. ALIGNMENT & TIRE BALANCE
 GET NEW LITE SHAWL
 REP 2 AXLE BUTS (TUNE, LEAKING?)
 GET LOCK # 211829231C / 2311?
 (FIT A KEY TO OTHER DOWN LOCKS & IT
 MIGHT WORK IN BACK CAR LOCKS)

ADD BUMPER OVER RIDER, PIPES, & SALON DOWN (RT + LFT) (RE-O SEAT BELT REPAIR & MID SEAT)

WHITE - Office Copy
 YELLOW - Customer's Invoice
 PINK - Estimate
 TAG - Shop Copy

NC 5680

EBERT'S VW. REPAIR
 2670 17th. Ave.
 Santa Cruz, Ca. 95065
 831-476-8214

VIN #
 256069313

DATE 3 / 7 / 14

WRITTEN BY _____ LABOR CHARGE

LUBRICATION

CHANGE OIL

CHANGE OIL FILTER CART.

SERVICE AIR CLEANER

CHANGE TRANS. OIL

ADJUST TRANSMISSION

CHANGE DIFF. OIL

PACK FRONT WHEEL BRGS.

ROTATE TIRES

ADJUST BRAKES

RETAIN PARTS

DESTROY PARTS

DELIVERY TIME RECEIVED

YES AM

NO PM

TIME PROMISED

YEAR 66 MAKE VW MODEL II

LICENSE SNOCOR

SPEEDOMETER 90520

MOTOR NO. 2V.

QTY	DESCRIPTION	UNIT PRICE	TOTAL
4	WHEEL	15.91	62.84
2	BRONZE NUTS	19.95	39.90
2	BLEEDER SCREWS	5.00	10.00
2	BALL SEALS	5.39	10.78
1	CAUTION		2.26
2	WHEEL TUBS	.99	1.98
2	AXLE PINS	.40	.80
1	SPIDER - CAP		.50
1	BRONZE FEND	2.55	3.83

NAME _____

ADDRESS _____

CITY _____

BILL TO _____

ADDRESS _____

PHONE _____

YES

ADDITIONAL PARTS FROM REVERSE SIDE OF SHOP COPY

TOTAL PARTS 174.33

ESTIMATE OF LABOR AT THIS ADDRESS

SUBLET REPAIRS:

TOTAL SUBLET REPAIRS

TOTAL ESTIMATE AMOUNT
 INCLUDES PARTS, ACCESSORIES
 OUR LABOR AND SUBLET REPAIRS

ADDL. AUTH. AMT.	TIME	DATE	BY

TOTAL ESTIMATE

OPER. NO.	REPAIR ORDER - LABOR INSTRUCTIONS	INTERNAL	LABOR CHARGE
4:45	REPLACE FRONT BRAKES (TIRES & STICKLE, L&R WHEEL CYL - 2 ROD SPRINGS) USE 4 SHOCKS, 4 WC, 2 NUTS, PACK FT. BRONZE BLEED & ADJUST		
1:50	INSPECT REAR BRAKES (LOOK GWO) SAND SHOCK/DISK ADJ. & ADJ. C-ROCKETS (TO TIGHT)		3.75
5:31			
TOTAL FOR LABOR PERFORMED AT THIS ADDRESS			3.75

"Any warranties on the products sold hereby are those made by the manufacturer. The seller (above named Dealership) hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products."

QTY.	GAS, OIL AND ATF	PRICE	BILLING INFO.	INTERNAL		ESTIMATE CHARGE
				ACCT.	COST	
	GALS. GAS @		<input type="checkbox"/> CASH			SUBLET REPAIRS
	QTS. OIL @		<input type="checkbox"/> CHARGE			TOTAL PARTS 174.33
	QTS. ATF @		<input type="checkbox"/> INTERNAL			GAS, OIL, ATF
TOTAL - GAS, OIL AND ATF			OK'D BY			PAINT

Replaced parts will be returned if you request them when the repairs are ordered. (You may inspect those parts which must be returned to the manufacturer).
 Replaced Parts Requested By Customer (Please Check) Yes No

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss of age, sale or damage to vehicle when repaired with them for storage.

SALES TAX 14.38

TOTAL AMOUNT 523.91

WHITE - Office Copy
 YELLOW - Customer's Invoice
 PINK - Estimate
 TAG - Shop Copy

ALL BRAKE DAMS OVER-SIZED 2-3 TIMES LOCAL LIMIT OF .060 (.120-.200)

EST. FOR R400 MASTERY CYL UP CAROL (#250?) EST. ONLY

CHK. CLOCK (12V) CH. APPROV?

PAID OLD ALARM PART

ADD 12V. FUSE SHUT OFF?

* CODE: N - NEW U - USED R - REBUILT

EBERT'S VW REPAIR

005928

NO 5709

COST	QTY.	* PART NO. OR DESCRIPTION	AMOUNT
	4	1/4" U-Bolts	1.77
			5.00

EBERT'S VW. REPAIR
 2670 17th. Ave.
 Santa Cruz, Ca. 95065
 831-476-8214

Pl. F.M.
 930-741

DATE 5/22/79

WRITTEN BY

LABOR CHARGE

LUBRICATION

CHANGE OIL

CHANGE OIL FILTER CART.

SERVICE AIR CLEANER

CHANGE TRANS. OIL

ADJUST TRANSMISSION

CHANGE DIFF. OIL

PACK FRONT WHEEL BRGS.

ROTATE TIRES

ADJUST BRAKES

RETAIN PARTS

DESTROY PARTS

NAME

AD

CIT

BIL

AD

YE

DELIVERY

TIME RECEIVED

AM

PM

YES

NO

TIME PROMISED

AM

PM

YEAR 64 MAKE VW MODEL J

LICENSE SMO CAB

SPEEDOMETER 90537

MOTOR NO.

ADDITIONAL PARTS FROM REVERSE SIDE OF SHOP COPY

TOTAL PARTS

ESTIMATE OF LABOR AT THIS ADDRESS

SUBLET REPAIRS:

TOTAL SUBLET REPAIRS

TOTAL ESTIMATE AMOUNT INCLUDES PARTS, ACCESSORIES OUR LABOR AND SUBLET REPAIRS

ADDL. AUTH. AMT. TIME DATE BY

ADDL. AUTH. AMT.

ADDL. AUTH. AMT.

TOTAL ESTIMATE

OPER. NO.

REPAIR ORDER - LABOR INSTRUCTIONS

INTERNAL

LABOR CHARGE

Drop FT. WOPROL & CIL FOR MAINTEN - CYC LTRIL (-MUNE, OK)

LTRIL II FROM STAINAL Box (9000)

590L II old, add so 30 parts of BRACK

RSP. - TINY LOWE CLAMP ON MID 590

DRIT WITH 1/4" BRKT & ADD H3 OIL

TOTAL FOR LABOR PERFORMED AT THIS ADDRESS 60.00

"Any warrantee on the products sold hereby are those made by the manufacturer. The seller (above named Dealership) hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products."

SEE LOT 2 TOU FOR MORE WORK TO DO!

DO NOT REQUEST AS THE REPAIR AMOUNT WITHOUT MY AUTHORIZATION

QTY.	GAS, OIL AND ATF	PRICE	BILLING INFO.	INTERNAL ACCT.	COST	ESTIMATE CHARGE
	GALS. GAS @		<input type="checkbox"/> CASH			SUBLET REPAIRS
	QTS. OIL @		<input type="checkbox"/> CHARGE			TOTAL PARTS 5.00
	QTS. ATF @		<input type="checkbox"/> INTERNAL			GAS, OIL, ATF
TOTAL - GAS, OIL AND ATF			OK'D BY			PAINT
						ACCESSORIES
						TIRES AND TUBES
						SALES TAX 41
						TOTAL AMOUNT 65.41

Replaced parts will be returned if you request them when the repairs are ordered. (You may inspect those parts which must be returned to the manufacturer).

Replaced Parts Requested By Customer (Please Check) Yes No

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage, sale, (placed with them for storage, sale, (

AUTHORIZED

WHITE - Office Copy
 YELLOW - Customer's Invoice
 PINK - Estimate
 TAG - Shop Copy

EDERT'S VW REPAIR

2670 17th Ave.
SANTA CRUZ, CA 95065
(831) 476-8214
B.A.R. 152336

005928

Date 7/19/16
Time Received
7/23
A.M.
P.M.
A.M.
P.M.

QUAN.	PART NO. DESCRIPTION	ESTIMATED AMOUNT	ACTUAL AMOUNT
4	ROTOR BRAKE SHOE		31.44
2	" " WHEEL CYL	18.91	33.82
1 1/2	BRAKE FLUID	2.52	3.98
1	" LTR OIL (3M)		9.99
2 or	AXLE PIN + 2 S-CUR	88	1.76
2	WAVE W. PAN	06	12
1	8A- ROLT, W. 2W. (BAMPS)		3.9
9/8 oz	90WT. TRAN. OIL	4.85	4.24
			85.52

Name _____
Address _____
City _____
Phone _____
Phone when ready Yes No
Cust. Order No. _____
Estimator/Writer _____
Retain Parts Yes No
Daily Storage \$ _____ Diagnostic Charge \$ _____
Rate: Flat Hrly. Both Cash Check Credit Card Charge

Unless otherwise provided by law, the seller (above named dealership) hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

REPAIR ORDER • LABOR INSTRUCTIONS		Est. Time Hrs. 10's	Estimated Amount	Actual Amount
Serv. Tech.	(CUT, SOLD RE. LT. BRAKE STUCK ON)			
	PAN Rotor DRUMS (MAJOR LEAK LT. SIDE)			
	(WHEEL CYL LEAKING)			
	AIR TO TIRE = 32 PSI			
	REP Rotor BRAKE (WHEEL CYL, 4 SHOE)			3.24
	BLEED + ADJ			
	(NOTE: 2-CAROLS NOT REPLACED, WORKING!)			
	INSTR PT. BROSSES (LOOK NEW + GOOD)			
	MINOR ADJ			
	ADDED TRAN. OIL (90WT) WAS LOW			
	REP BRAKE LITE SWITCH (NOT COMING ON)			

REPAIR ORDER

SPECIAL REPAIRS

ALL 4 DRUMS ARE OVER SIZE +
NEED REPLACING, AXLE PIN + OIL
SHOULD REPLACE

4.30

BROUGHT FORWARD

TOTAL PARTS

PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW, AND SIGN:
I UNDERSTAND THAT UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE, IF MY FINAL BILL WILL EXCEED \$50.

- I REQUEST A WRITTEN ESTIMATE.
- I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED \$_____. THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.
- I DO NOT REQUEST A WRITTEN ESTIMATE.

SIGNED X _____ DATE _____

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.
I HAVE READ AND UNDERSTAND THE ABOVE TERMS.

X

AUTHORIZED BY _____

GAL. GASOLINE	REPAIRS ON THIS TAG	
QTS. OIL	"DO NOT" COME WITH ANY WARRANTY!!	
LBS. GREASE	@	
TOTAL GAS - OIL - GREASE		

Estimated Cost of Repair Work	
Total Labor	324
Total Parts	85.52
Environmental Charges	
Special Repairs	
Gas, Oil, Grease	
Tires, Tubes	
Total	
Tax	7.06
Less Deposit	
TOTAL AMOUNT	416.58

EDERT'S VW REPAIR