



# Invoice

**PETERSON MOTORSPORTS, LLC**  
 22255 ARNOLD DRIVE SONOMA, CA 95476  
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	3/17/2014
Invoice #	201271
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	1	Water housing.	68.87	68.87T
Parts	1	Leaf spring	431.98	431.98T
Parts	2	Bolts.	4.31	8.62T
Parts	2	Set Wheel studs	19.22	38.44T
Parts	6	Set of 4 Lug nuts with washers	21.56	129.36T
Parts	1	Sway bar link	22.94	22.94T
Parts	1	Oil pan	553.10	553.10T
				1,253.31
Labor	1	Crack check parts	264.48	264.48
Labor	3	Finish installing brake caliper on left front rear. Install right rear trailing arm, hub assembly, rotor, caliper, half shaft, shock and mount. Install driveshaft and tighten front bolts.	95.00	285.00
Labor	1.5	Install new water neck. Measure for and fabricate new hose for neck. Move temperature sending unit to opposite side of manifold to accommodate new water neck. Adel clamp and zip tie sending unit in place.	95.00	142.50
Labor	4.5	Install rear spring in car. Cut and grind bolts to length for center strut rod carrier. Install support for rear control arms. Install strut rods and carrier.	95.00	427.50
Labor	4	Install rear driveshaft U-bolts. Measure for, mark, cut and grind down tips of rear spring for wheel clearance.	95.00	380.00
Labor	12	Measure track, toe and camber. Put car on caster plates. Remove tower support. Adjust camber and caster. Jack up rear of car and loosen camber rod nuts. Sand inner right rear fender edge to keep from rubbing. Install correct shims. Re-adjust rear camber. Set up box string around car for alignment. Remove right upper control arm, set front bushing, rotate bushing for more adjustment and tig weld. Reinstall control arm and adjust camber and caster on right hand side. Align rear wheels. Set rear toe.	95.00	1,140.00

Pay online at: <https://ipn.intuit.com/zip/zipform>

<b>Due Upon Receipt</b>	<b>Subtotal</b>
	Sales Tax (8.25%)
	<b>Total</b>
	Payments/Credits
	<b>Balance Due</b>





Pd

# Invoice

**PETERSON MOTORSPORTS, LLC**  
 22255 ARNOLD DRIVE SONOMA, CA 95476  
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	2/15/2014
Invoice #	201292
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	1	Spherical bearing	45.52	45.52T
Parts	1	Adapter, -6 to 7/8 dbl Holley	9.27	9.27T
Parts	5	Aluminum hose end, -6 straight	18.52	92.60T
Parts	1	Hose end, -6 90deg, forged	35.03	35.03T
Parts	1	Tee, -6, steel	14.86	14.86T
Parts	2	Rod end, 1.4 x 1/4 male RH, 3-piece	19.51	39.02T
				236.30
Labor	7	Beadblast and paint caliper mounts. Machine bearing holder for trailing arms. Machine 4 spacers for spherical bearing. Grease and install last U-joint in driveshaft. Assemble left front spindle. Beadblast and install aluminum plugs in manifold. Install carburetor.	95.00	665.00
Labor	5	Measure and shim calipers and straighten. Install front spindle assembly, hub and brakes on left front of car. Connect steering and wire tie bolts. Remove old front sway bar and install new one. Install carburetor return spring and bracket. Install distributor hold down and stud. Press in and weld bearing holders in rear control arms.	95.00	475.00
Labor	5	Press bearings into holders. Measure for, machine, cut and tack weld keepers for bearings. Clean and beadblast rear control arms and paint. Measure for, cut, bend, drill and tap rod. Assemble throttle linkage. Trim and file tabs on air cleaner base for proper linkage fit. Beadblast, clean and install carburetor fuel fittings. Mock set up fuel rail.	95.00	475.00
Labor	5	Beadblast anodizing from all fittings needed for fuel rail. Clean all fittings. Measure for, fabricate and put heat shrink tubing on fuel lines for rail. Install on motor. Set motor to top dead center. Install distributor. Mock lay out wiring for distributor system. Fabricate new ground wire for oil pressure light switch. Wire up distributor and zip tie wires for clearance. Tape off wires not used.	95.00	475.00

Pay online at: <https://ipn.intuit.com/zip/2101881>

<b>Due Upon Receipt</b>	<b>Subtotal</b>
	Sales Tax (8.25%)
	<b>Total</b>
	Payments/Credits
	<b>Balance Due</b>



# Invoice

PETERSON MOTORSPORTS, LLC  
 22255 ARNOLD DRIVE SONOMA, CA 95476  
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	2/15/2014
Invoice #	201292
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Labor	8	Pack all rear hub bearings with grease. Install with spacers and seals. Install rear caliper mounting brackets and press axles into hubs. Press bolts into rear control arms and install onto the hubs. Measure for, mark and drill small holes in floor pan to access frame for control arms. Remove some rivets that hold rear brake line and fire system tube down and drill 4 holes in frame. Cut out and re-rivet lines back in place. Reinstall rear cover.	95.00	760.00
Labor	3.25	Test fit, measure, trim and grind rear control arm bolts for proper fit. Install left rear control arm Install shock and strut rod. Install left half shaft and tighten. Drill out left and right rotor lug hoes to 1/2 in. Paint rear strut rod. Labor subtotal.	95.00	308.75
				3,158.75

Pay online at: <https://ipn.intuit.com/62h8t8th>

<b>Due Upon Receipt</b>	<b>Subtotal</b>	\$3,395.05
	<b>Sales Tax (8.25%)</b>	\$19.49
	<b>Total</b>	<b>\$3,414.54</b>
	<b>Payments/Credits</b>	\$0.00
	<b>Balance Due</b>	<b>\$3,414.54</b>

2/12/14



# Invoice

**PETERSON MOTORSPORTS, LLC**  
 22255 ARNOLD DRIVE SONOMA, CA 95476  
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	1/31/2014
Invoice #	201290
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	4	Wheel bearing set	22.80	91.20T
Parts	2	Taper cone	13.85	27.70T
Parts	2	Taper cup	8.32	16.64T
Parts	1	Hi-performance distributor.	397.64	397.64T
Parts	1	Throttle return spring kit.	10.80	10.80T
Parts	1	1/2" male pipe plug internal hex.	4.10	4.10T
Parts	1	3/8" male pipe plug internal hex.	3.90	3.90T
Parts	1	Distributor hold down.	13.18	13.18T
Parts	1	U-joint.	25.64	25.64T
		Parts subtotal.		590.80
Labor	3.5	Grease and press U-joints into shafts. Beadblast, clean, polish and paint yoke. Clean threads on yoke.	95.00	332.50
Labor	6.75	Begin to assemble front hubs. Assemble and grease steering arm. Install left front spindle, spring, shock, brake mount, air duct and steering arm. Cotter pin and wire tie in place. Press races into front hubs. Pack bearings with grease and install seals. Install right hub. Cut down bolts for right caliper and install. Torque bolts. Install left front spring and shock.	95.00	641.25
Labor	1	Disassemble distributor and machine parts.	95.00	95.00
Labor	1	Disassemble spindles and trailing arms. Clean parts in preparation for crack checking.	95.00	95.00
		Labor subtotal		1,163.75
Reimbursables	1	Shipping of distributor.	17.64	17.64

Pay online at: <https://ipn.intuit.com/g9mp2b6n>

<b>Due Upon Receipt</b>	<b>Subtotal</b>	\$1,772.19
	Sales Tax (8.25%)	\$48.74
	<b>Total</b>	<b>\$1,820.93</b>
	Payments/Credits	50.00
	<b>Balance Due</b>	<b>\$1,820.93</b>



1/28/14

# Invoice

**PETERSON MOTORSPORTS, LLC**  
 22255 ARNOLD DRIVE SONOMA, CA 95476  
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	12/31/2013
Invoice #	201278
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	4	Left inner rear axle shaft U-joint.	25.64	102.56T
Parts	1	Rear axle U-joint.	24.02	24.02T
Parts	1	U-joint.	22.40	22.40T
Parts	2	Inner front wheel bearing.	14.16	28.32T
Parts	2	Outer front wheel bearing.	11.73	23.46T
Parts	2	Front wheel seal.	20.91	41.82T
Parts	2	Outer rear wheel bearing.	16.19	32.38T
Parts	2	Inner rear wheel bearing cone.	18.21	36.42T
Parts	2	Inner rear wheel bearing cup.	8.76	17.52T
Parts	2	Inner rear wheel seal.	20.91	41.82T
Parts	2	Outer rear wheel seal.	26.31	52.62T
Parts	1	Air cleaner base.	83.70	83.70T
Parts	1	Air cleaner element.	6.62	6.62T
Parts	1	Air cleaner lid.	39.15	39.15T
		Parts subtotal.		552.81
Labor	3.5	Remove and disassemble rear camber mount. Locate new mount and square outer and inner washers for spacers. Beadblast mount and spacer washers. Tack weld spacer washers onto camber mount. Enlarge mounting holes in mount. Enlarge camber holes.	95.00	332.50
Reimbursables	1	Shipping of air cleaner base, lid and element.	13.86	13.86
		Reimbursables subtotal.		346.36

Pay online at: <https://ipn.intuit.com/53xbjsfn>

<b>Due Upon Receipt</b>	<b>Subtotal</b>	\$899.17
	Sales Tax (8.25%)	\$45.61
	<b>Total</b>	<b>\$944.78</b>
	Payments/Credits	\$0.00
	<b>Balance Due</b>	<b>\$944.78</b>



1/28/14

# Invoice

PETERSON MOTORSPORTS, LLC  
22255 ARNOLD DRIVE SONOMA, CA 95476  
PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	1/15/2014
Invoice #	201280
Project	
1963 Corvette #5	

Item Code	Quantity	Description	Rate	Amount
Parts	1	Custom made heavy duty rear axle	2,400.00	2,400.00T
Parts	2	5/8 x 4.5 bolts.	4.17	8.34T
Parts	2	5/8 x 5 bolts.	5.66	11.32T
Parts	2	Reluctor wheel	48.74	97.48T
		Parts subtotal.		2,517.14
Reimbursables	1	Shipping on reluctor wheel	12.05	12.05

Pay online at: <https://ipn.intuit.com/rjnp2wpb>

<b>Due Upon Receipt</b>	<b>Subtotal</b>	\$2,529.19
	Sales Tax (8.25%)	\$207.66
	<b>Total</b>	<b>\$2,736.85</b>
	Payments/Credits	\$0.00
	<b>Balance Due</b>	<b>\$2,736.85</b>

Albany Annex

Henk Boverhuis  
2490 Hilgard Avenue  
Berkeley, CA 94709

1/3/14

# Invoice

Date	Invoice #
12/31/2013	287

Bill To
Scuderia Veloce Sud Jeff Abramson 181 South Avenue Alamo, CA 94507

P.O. No.	Terms	Project
#5 Corvette MGN	Due on receipt	

Description	Qty	Rate	Amount
Performance mufflers	2	65.00	130.00
Turn mufflers to slip into side pipes		174.00	174.00
Weld reduction pipes to mufflers and weld assemblies in side pipes.		120.00	120.00
Shipping side pipes to coat.		33.60	33.60
Transport vehicle in enclosed trailer to Randy Peterson	70	1.35	94.50
Richmond - San Rafael Bridge		20.00	20.00

**Total** \$572.10

**Payments/Credits** \$0.00

**Balance Due** \$572.10



# Invoice

PETERSON MOTORSPORTS, LLC  
 22255 ARNOLD DRIVE SONOMA, CA 95476  
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	12/15/2013
Invoice #	201273
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Labor	5	Retrieve all part numbers and dimensions from bearings, races, seals and U-joints needed for car and order. Remove rear brakes. Remove old rear sway bar mounts, spring bolts and lower shock mounts. Remove rear swing arms. Bag, box, and label all hardware. Wash all parts removed from car. Remove and wash transmission yoke and steering balljoint spacers. Drill and press out studs and bushing on right trailing arm.	95.00	475.00
Labor	5	Drill and press out studs and bushing on left trailing arm. Cut and grind off old brackets on trailing arms. Measure arm and check how bent it was. Hammer left side arm to straighten. Beadblast and clean left trailing arm. Hammer down unwelded edges on seam and weld all up. Touch up welds with grinder. Beadblast and clean right trailing arm and weld up a few seams. Grind welds.	95.00	475.00
Labor	3.5	Remove parts from parts washer. Beadblast washed parts.	130.00	455.00
Labor	0.5	Deliver suspension parts to be magnafluxed.	95.00	47.50
		Labor subtotal.		3,376.25
Reimbursables	1	Shipping for springs	25.17	25.17

Pay online at: <https://ipn.intuit.com/4mn37f4f>

Due Upon Receipt	<b>Subtotal</b>	\$6,981.61	4,581.61
	Sales Tax (8.25%)	<del>\$295.37</del>	90.89
	<b>Total</b>	<del>\$7,276.98</del>	4,672.50
	Payments/Credits	\$0.00	
	<b>Balance Due</b>	<del>\$7,276.98</del>	



# Invoice

PETERSON MOTORSPORTS, LLC  
 22255 ARNOLD DRIVE SONOMA, CA 95476  
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	12/15/2013
Invoice #	201273
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	1	Custom made heavy duty rear axle assembly	<del>2,400.00</del>	<del>2,400.00T</del>
Parts	1	Holley racing carburetor	975.00	975.00T
Parts	2	5"x9.5 1250 Springs	56.67	113.34T
Parts	1	SBC Reluctor wheel	24.37	24.37T
Parts	2	MSD Pickup	33.74	67.48T
				3,580.19
Labor	5.5	Disconnect sway bar. Measure front and rear toe and front and rear camber. Inspect underside of car and record findings. Put car on scales and record information. Check caster. Remove left, rear spring. Remove wheel, ducting, ball joint and shock. Test spring rate and reassemble.	95.00	522.50
Labor	4.75	Drain coolant. Remove air cleaner assembly. Remove hoses, lines, linkage and springs from fuel injection system. Unbolt and remove injection unit from manifold. Remove cables, lines and wires from distributor. Remove radiator hose and temperature sending unit. Remove water pump fitting. Remove intake manifold and scrape off old gaskets. Grind and beadblast new intake to remove new manufacture markings. Clean new intake and install on motor. Remove fitting from pressure sending unit (no longer used). Remove restrictor plate from old manifold and install on new one.	95.00	451.25
Labor	5	Put car on stands and remove wheels. Remove front brakes, rotors, hubs, spindles, steering arms and ducting. Disassemble hubs and steering linkage. From right rear remove brake, axle, half shaft, shock and other hardware.	95.00	475.00
Labor	5	From left rear, remove half shaft, brake, axle and housing, rear spring and struts. Remove front springs. Press apart rear bearing housing from axles. Press out bearings, seals and races. Remove driveshaft. Press out all U-joints in driveshaft and half shafts.	95.00	475.00

Due Upon Receipt	<b>Subtotal</b>
	Sales Tax (8.25%)
	<b>Total</b>
	Payments/Credits
	<b>Balance Due</b>



11/18/13

# Invoice

PETERSON MOTORSPORTS, LLC  
22255 ARNOLD DRIVE SONOMA, CA 95476  
PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	11/15/2013
Invoice #	201261
Project	

Item Code	Quantity	Description	Rate	Amount
Parts	1	Intake manifold.	197.09	197.09T
Parts	1	Intake manifold gaskets.	25.64	25.64T
Parts	1	Intake manifold bolt kit.	19.58	19.58T
		Parts subtotal.		242.31

Pay online at: <https://ipn.intuit.com/7955x4st>

<b>Due Upon Receipt</b>	<b>Subtotal</b>	\$242.31
	Sales Tax (8.25%)	\$19.99
	<b>Total</b>	<b>\$262.30</b>
	Payments/Credits	\$0.00
	<b>Balance Due</b>	<b>\$262.30</b>

Albany Annex

Henk Boverhuis  
2490 Hilgard Avenue  
Berkeley, CA 94709

# Invoice

Date	Invoice #
11/30/2013	286

Bill To
Scuderia Veloce Sud Jeff Abramson 181 South Avenue Alamo, CA 94507

12/3/13

P.O. No.	Terms	Project
#5 Corvette	Due on receipt	

Description	Qty	Rate	Amount
Fabricate permanent mount for larger oil cooler.	3.5	90.00	315.00
Materials	1	45.00	45.00
25 row oil cooler	1	265.00	265.00
Hooker Competition Sidetubes.	1	295.20	295.20
Brad Penn 20w50 Racing oil.	12	5.95	71.40
Shipping		13.90	13.90
Oil filter.	1	6.95	6.95
Change oil and filter. Safety wire drain plug.	1	90.00	90.00
Concentric exhaust reducers	2	41.90	83.80
Shipping		14.25	14.25
Oil Analysts Inc.		91.00	91.00
4" x 2 1/2" concentric exhaust reducer	2	50.45	100.90

**Total** \$1,392.40

**Payments/Credits** \$0.00

**Balance Due** \$1,392.40

Albany Annex

Henk Boverhuis  
2490 Hilgard Avenue  
Berkeley, CA 94709

# Invoice

Date	Invoice #
11/1/2013	281

Bill To
Scuderia Veloce Sud Jeff Abramson 181 South Avenue Alamo, CA 94507

Description	P.O. No.	Terms	Project
	Qty	Rate	Amount
Remove F.I. unit from motor. Remove high pressure pump from F.I. unit and ship to rebuilders.	0	90.00	0.00
Rebuild gear pump, replace worn carbon bearings. Replace seal, new gasket, recolor, resurface and set to factory clearance. Replace drive pin.		228.00	228.00
Shipping back and forth.		43.80	43.80
Re-install high pressure pump in F.I. unit. Re-install F.I. unit on motor. Install new drive cable and run motor.	0	90.00	0.00
<b>Total</b>			\$271.80
<b>Payments/Credits</b>			\$0.00
<b>Balance Due</b>			\$271.80

Albany Annex

Henk Boverhuis  
 2490 Hilgard Avenue  
 Berkeley, CA 94709

# Invoice

Date	Invoice #
10/3/2013	278

Bill To
Scuderia Veloce Sud Jeff Abramson 181 South Avenue Alamo, CA 94507

10/4/13

P.O. No.	Terms	Project
#5 Corvette	Due on receipt	

Description	Qty	Rate	Amount
Remove alternator and source better unit. Modify alternator bracket to accept new unit. Make new electrical lead from alternator to master cut-off switch.	3	90.00	270.00
Nippondenso alternator with regulator built in	1	274.10	274.10
Remove distributor and check for "ignition shudder". Distributor has excessive play at drive gear. Ordered shims and correct clearance.	2.5	90.00	225.00
Drive shims	1	10.45	10.45
Remove fuel injection unit from motor to begin dis-assembly and inspection.	3	90.00	270.00
Inspection reveals "axle and linkage" broken. Spill valve missing "thumb tack". High speed pump shaft has excessive play causing irregular wear on gears.	2	90.00	180.00
Remove dash panel to install voltmeter. Current amp meter has been epoxyed to dash and can not be removed without damaging dash. Remove black disc and installed volt meter on left side of steering column.	4	90.00	360.00
Volt meter	1	49.55	49.55
Spare alternator	1	274.10	274.10
Removed right side pipe to install baffles. 4" Side pipes have baffles. Ordered parts needed for F.I. rebuild.	1	90.00	90.00
Mount fuse block. Run ground from battery to block. Removed "master" toggle switch and trace wires. Remove "ignition" toggle switch and trace wires. Remove "fan" switch and trace wires.	5	90.00	450.00
Fuse block	1	48.90	48.90
Continue testing, replacing and wiring switches to fuse block. Mount second fuel pump and discover 5 micron filter on suction side of pump. Ordered two 100 micron filters and fittings. Wire in double throw double pole switch for fuel pumps.	7	90.00	630.00

<b>Total</b>
<b>Payments/Credits</b>
<b>Balance Due</b>

Albany Annex

Henk Boverhuis  
 2490 Hilgard Avenue  
 Berkeley, CA 94709

# Invoice

Date	Invoice #
10/3/2013	278

<b>Bill To</b>
Scuderia Veloce Sud Jeff Abramson 181 South Avenue Alamo, CA 94507

Description	Qty	Rate	Amount	P.O. No.	Terms	Project
				#5 Corvette	Due on receipt	
Removed shift linkage, driveshaft, transmission, bell housing and clutch assembly. Removed flywheel and check ring gear to be the same. Inspect three disc unit, ordered two float plates.	4	90.00	360.00			
Removed rear spring and disconnect axle shafts. Removed 4.10 differential. Install fuel lines from cell to pumps with 100 micron filters.	5	90.00	450.00			
100 micron fuel filters	2	90.00	180.00			
6AN fittings	8	11.50	92.00			
S.S. 6AN hose	5	4.80	24.00			
Y-block	1	30.00	30.00			
6AN - 3/8NPT adapters	4	3.55	14.20			
Install flex plate/ring gear to crank. Assemble QuarterMaster clutch with new float plates and hardware to flex plate. Pick up 4.33 diff from Peterson.	2	90.00	180.00			
Float plates	2	97.00	194.00			
Hardware kit	1	53.80	53.80			
Shipping	1	40.60	40.60			
RE-install bell housing, transmission and driveshaft. Install shift lever and console.	6	90.00	540.00			
Install 4.33 diff. Re-attach axle shafts and lower control links. Re-install rear spring.	4	90.00	360.00			
Re-assemble distributor with the correct shaft, weights and springs. Set clearances. Install in motor. Begin re-assemble F.I. unit. Install fresh hardware for spring and lower link assembly.	4.5	90.00	405.00			
Continue re-assembly of F.I. unit. Vacuum check test found pipe leaking. Borrowed pipe from spare unit. Complete assembly and mount on motor. Adjust clutch. Replace #1 ignition wire. Build three fuel hoses.	7	90.00	630.00			
Wire set	1	46.75	46.75			
				<b>Total</b>		
				<b>Payments/Credits</b>		
				<b>Balance Due</b>		

Albany Annex

Henk Boverhuis  
2490 Hilgard Avenue  
Berkeley, CA 94709

# Invoice

Date	Invoice #
10/3/2013	278

<b>Bill To</b>
Scuderia Veloce Sud Jeff Abramson 181 South Avenue Alamo, CA 94507

P.O. No.	Terms	Project
#5 Corvette	Due on receipt	

Description	Qty	Rate	Amount
Install remaining fuel hoses. Check for leaks. Start motor. Check for leaks. Set ignition timing. Check and service for track.	3	90.00	270.00
Supplies including battery ground cable, switches, wire, connectors and hardware.	1	204.20	204.20

<b>Total</b>		\$7,206.65
<b>Payments/Credits</b>		\$0.00
<b>Balance Due</b>		\$7,206.65



# Invoice

PETERSON MOTORSPORTS, LLC  
 22255 ARNOLD DRIVE SONOMA, CA 95476  
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	9/30/2013
Invoice #	201242
Project	

Item Code	Quantity	Description	Rate	Amount
Parts	1	Rebuilt Corvette rear end prepared for racing  <i>4:33 Gears</i>	2,500.00	2,500.00T
Pay online at: <a href="https://ipn.intuit.com/8bdsqtm6">https://ipn.intuit.com/8bdsqtm6</a>				

<b>Due Upon Receipt</b>	<b>Subtotal</b>	\$2,500.00
	Sales Tax (8.25%)	\$206.25
	<b>Total</b>	<b>\$2,706.25</b>
	Payments/Credits	\$0.00
	<b>Balance Due</b>	<b>\$2,706.25</b>

## TRANSPORT SPECIALTIES

2290 Ivy St #140  
Chico, Ca 95928

Jeff Abramson  
'64 Corvette #5

R/O 408

July 14, 2013

### Repairs & upgrades Final, week ending 7/13

<u>Work descrip.</u>	<u>5.5 hrs</u>	<u>Labor</u>
Pick up engine at engine shop, trim out for installation. Installed in car, installed headers, fit and installed side pipes. Realigned alternator mounting for belt alignment. Fit new starter, replaced battery cable end at starter. Primed oil and fuel systems and checked for leaks. Ran engine and adjusted as needed. Re-torqued engine after cool down.		16.0 hrs
Unpacked and unwrapped headers and side pipes and inspected.		.50 hr
Installed driveline, adjusted trans and engine mounts for better alignment. Filled trans.		.75 hr
Found failing fuel pump switch, replaced switch and more wiring in dash. Changed some circuit connections for better utilization of power.		2.0 hrs
Replaced LH lower ball joint.		.50 hr
Test drive and discovered FI unit overflowing fuel. Disassembled metering unit and modified float alignment to eliminate contacting side of bowl. Final test drive.		2.0 hrs
Fit new enclosure over fuel cell and secured.		2.50 hrs
Checked and adjusted alignment. Set toe and centered steering wheel.		3.25 hrs
Quick cleaned car and fueled. Customer fuel.		N/C
	<u>Total labor</u>	<u>27.50 hrs</u>

### Sublet labor:

Custom fab alum enclosure for fuel cell.	150.00
Headers and side pipes thermal coating, includes shipping cost. (at cost)	850.22

**Parts: (R/O 408)**

8) qts AMSOIL break in oil	@7.15/qt	57.20
1-1/2 qts AMSOIL 75/90 Severe Gear oil	@ 13.95/qt	20.93
1) 1444 Felpro exhaust set		16.95
1 ft x -12 heat sleeve		11.25
1) Toggle switch		12.75
1) Ball joint-lower		49.95
5) 3005 ¼ turn studs	@ 3.25/ea	16.25
6) 3011 spring receptacle for studs	@ 1.25/ea	7.50
1) Distributor rotor		7.97
1) Mcleod clutch kit-10.4 x 10 spline		295.55
1) Pressure plate bolt kit-ARP		13.95
1) MSD wire set – prefit		52.95
1) Deluxe wire loom set		13.79
1) 7485 V-belt		14.62
1) 7328 V-belt		13.75
1) Rear view mirror, used		10.50
2 ft x ¾" heater hose		4.00
4) Gal distilled water	@1.25 / gal	5.00
Misc hardware, heat shrink, wire ties.		15.00
Misc shop supplies		22.00

Thank you for your business

**AMERICAN PRIDE MOTORWORKS**

Vintage Hot Rods, Inc.

631 Country Drive  
 Chico, CA 95928  
 530-343-9228  
 BAR AB243729

*pd Balance 7/6/13*

# Invoice

Date	Invoice #
6/10/2013	1248

<b>Bill To</b>
Vintage Vettes

<b>Ship To</b>

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
			6/10/2013			Vintage Vettes #3

Quantity	Item Code	Description	Price Each	Amount
1	Labor	Mag and micro polish crank	72.00	72.00
1	Labor	Hot tank , mag , and media blast block-good	160.00	160.00
1	Labor	Line bore with 3 new center caps	675.00	675.00
1	Labor	Parallel decks on block-set at zero deck	110.00	110.00
1	Labor	Power hone with torque plate	170.00	170.00
1	Labor	Press fit cam bearings	40.00	40.00
1	Labor	Torque and check conrods-good	40.00	40.00
1	Labor	clean pistons and all other engine parts	80.00	80.00
1	Labor	HP enduro valve job	160.00	160.00
1	Labor	Surface cyl heads	120.00	120.00
1	Labor	Competition porting-clean up and repair what was started	1,275.00	1,275.00
1	Labor	Fill heat risers with aluminum	90.00	90.00
1	Labor	Install heli coil motor mount right side	10.00	10.00
1	Labor	R&R pilot bushing	10.00	10.00
1	Labor	oil pan repair	45.00	45.00
1	Labor	Machine valve covers and set up breathers	85.00	85.00
1	Labor	Assemble complete race V8	1,475.00	1,475.00
1	Labor	Dyno test and tune w / Roch FI	600.00	600.00
1	Labor	Balance flywheel	45.00	45.00
1	Parts	Crane 968821 blueprinted camshaft	263.63	263.63T
1	Parts	Crane 99250 solid lifters	114.40	114.40T
1	Parts	Cloyes 9-3100 true roller timing set	112.55	112.55T
1	Parts	ARP 234-4301 head studs	218.58	218.58T
1	Parts	Manley 42355 Guide plates	48.40	48.40T
1	Parts	RK1508 rocker arms	201.60	201.60T
1	Parts	ARP234-7202 pro rocker studs	127.89	127.89T
1	Parts	Manley 13194-16 valve locks	49.40	49.40T
1	Parts	Manley lash caps	39.36	39.36T
1	Parts	Manley 22429-16 valve springs	236.15	236.15T
1	Parts	Manley 23661-16	236.15	236.15T
1	Parts	Positive valve seals	32.00	32.00T

**Total**

Vintage Hot Rods, Inc.

631 Country Drive  
 Chico, CA 95928  
 530-343-9228  
 BAR AB243729

# Invoice

Date	Invoice #
6/10/2013	1248

<b>Bill To</b>
Vintage Vettes

<b>Ship To</b>

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
			6/10/2013			Vintage Vetts #3

Quantity	Item Code	Description	Price Each	Amount
1	Parts	Engine Pro 581-8150 pushrods (20)	163.66	163.66T
1	Parts	CH-8 cam bearings	33.30	33.30T
1	Parts	663HN rod bearings	81.94	81.94T
1	Parts	909H main bearings	93.29	93.29T
1	Parts	R9902 .040 Speed Pro rings	124.44	124.44T
1	Parts	1003 Fel Pro head gaskets (2)	93.29	93.29T
1	Parts	1803 Fel Pro pan gasket	17.17	17.17T
1	Parts	2912 Fel Pro rear main seal	34.19	34.19T
1	Parts	1644 Fel pro valve cover gaskets	49.88	49.88T
1	Parts	1205 Fel Pro int manifold gaskets	19.87	19.87T
1	Parts	TCS5124-1 Fel Pro timing cover gasket set	10.82	10.82T
1	Parts	Steel dist gear	39.90	39.90T
1	Parts	Milodon 11165 main caps	291.04	291.04T
1	Parts	ARP134-5403 Main stud kit	98.63	98.63T
1	Parts	Spark plugs Autolite racing AR72	46.08	46.08T
1	Parts	Fuel for dyno (10 gal )	149.00	149.00
1	Parts	Oil filter	8.87	8.87T
1	Parts	Pilot bushing	26.92	26.92T
1	Shipping	Shipping on all parts	91.75	91.75
1	Disposal	Hazardous Waste	15.00	15.00
		Sales Tax	7.50%	218.51

**Total** \$8,649.66

*\$ 4649.66*  
*Balance*

*Barker*

# Transport Specialties

2290 Ivy St #140  
Chico, Ca 95928  
530 342 0422

# Invoice

Date	Invoice #
6/29/2013	94

Bill To
Jeff Abramson 1964 Corvette

P.O. No.	Terms	Project
	Due on receipt	

Quantity	Description	Rate	Amount
6.75	Labor- R/O #- 406	80.00	540.00
	Parts - R/O #- 406	456.05	456.05T
1	Advance payment	1,500.00	1,500.00
	Sales Tax	7.50%	34.20
Thank you for your business!		<b>Total</b>	<b>\$2,530.25</b>

**TRANSPORT SPECIALTIES**

2290 Ivy St #140  
Chico, Ca 95928

Jeff Abramson  
'64 Corvette #5

R/O 406

June 29, 2013

Repairs & updates  
Bi-weekly, ending 6/29

<u>Work descrip.</u>	<u>Labor</u>
Removed incorrect Dzus fasteners in rear firewall panel and panel over fuel cell and replaced with proper ones.	.75 hr
Set shock bump settings and installed shocks on car.	1.00 hr
Nut and bolt rear of car, installed rear wheels.	.50 hr
Loaded car, took to carwash and degreased engine compartment and front suspension.	1.50 hr
Centered front steering linkage and steering wheel for alignment.	.25 hr
Replaced front brake pads (customer), check rotor dragging on cooling duct. Fixed.	.75 hr
R&R oil cooler lines, remove anodizing from fittings.	2.00 hr
	<hr/>
Total labor	6.75 hrs

**Parts: (R/O 406)**

2) Koni Classic front shocks	@ 105.60	211.20
2) Koni Classic rear shocks	@ 105.60	211.20
2) 3005 ¼ turn studs	@ 3.25/ea	6.50
4) 3011 spring receptacle for studs	@ 1.25/ea	5.00
4) 2 <sup>nd</sup> design disc pad retainer cotter pins	@ 1.75/ea	7.00
3) Brakleen	@ 3.25/ea	9.75
Misc shop supplies		5.40

Thank you for your business

AMERICAN PRIDE MOTORWORKS

# Transport Specialties

2290 Ivy St #140  
 Chico, Ca 95928  
 530 342 0422

# Invoice

6/16/13

Date	Invoice #
6/15/2013	88

Bill To
Jeff Abramson 1964 Corvette

P.O. No.	Terms	Project
	Due on receipt	

Quantity	Description	Rate	Amount
25	Labor- R/O #-403	80.00	2,000.00
	Sublet labor-Trans refresh, oil cooler flush-(cost)	815.17	815.17
	Parts - R/O #-403	1,049.77	1,049.77T
1	Steering box core charge	80.00	80.00
	Freight charges-Incoming/outgoing	49.63	49.63
14	Hazmat disposal	0.50	7.00
	Advance payment- 6/12/2013	-2,500.00	-2,500.00
	Sales Tax	7.50%	78.73

Thank you for your business!	<b>Total</b>	<b>\$1,580.30</b>
------------------------------	--------------	-------------------

# TRANSPORT SPECIALTIES

2290 Ivy St #140  
Chico, Ca 95928

Jeff Abramson  
'64 Corvette #5

R/O 403

June 15, 2013

## Repairs & updates 5.5 hrs

<u>Work descrip.</u>	<u>Labor</u>
Reorganized gauges in dash, changed to all mechanical. Moved fuel pressure source downstream from regulator. Eliminated excess -6 fuel lines. Cleaned up some of sloppy wiring in area and eliminated some at same time. Removed anodizing from fittings.	6.25 hrs
Repaired fuel leak at FI distribution meter. Only temporary, will need perm fix in future. Also, cleaned FI unit complete for better appearance.	1.50 hrs
Resealed distributor, repaired advance mechanism, cleaned unit and lubed.	1.75 hrs
R&R oil cooler for flush.	1.0 hr
R&R throttle pedal and repaired torn out fiberglass at attachment points. Installed throttle stop in firewall.	3.5 hrs
Removed M/cyl and brake booster unit, replaced with manual brake M/cyl. Installed rear brake bias control valve on tunnel and plumbed into rear system. Replaced brake line from M/cyl to front brakes "tee" on frame.	6.25 hrs
Replaced steering box, installed new bearings and retainers in column. Replaced clutch release rod boot on firewall.	2.50 hrs
Removed and checked 4 shocks and found 2 bad ones.	.50 hr
Installed, adjusted and lubed shifter.	.50 hr
Fit new K&N air filter in housing.	.50 hr
Misc parts research	.75 hr
Total labor	25.0 hrs

### Sublet labor:

Transmission refresh. (cost)	770.17
Engine oil cooler flush.	45.00

**Parts: (R/O 403)**

2) Corvette script valve covers	@ 66.70/ea	133.40
1) 30"x3/16" steel brake lines		9.90
2) 40"x3/16" steel brake line	@ 6.25/ea	2.50
1) -3 x 90 bulkhead w/ nut		8.26
2) -3 tubing nuts w/ sleeves	@ 5.15/ea	10.30
1) Brake proportioning valve		48.23
1) -3m x 1/8" PT m adaptor		4.58
1) -3 st hose end		6.84
1) -3 x 45 hose end		12.59
1) -4 x 1/8" 90 fitting		6.84
2.5 ft x -3 steel braid TPFE hose	@ 3.63/ft	9.08
1.5 bottles Motul 600 fluid (1 for spare)	@ 20.95/ea	31.42
2) 70194 Felpro gaskets	@ 1.45/ea	2.90
3) Brakleen	@ 3.95/ea	11.85
1) Master cylinder-manual		69.99
1) Master cylinder-Power (returned)		(49.95)
1) Brake pedal pushrod		5.99
1) K&N cone air filter		70.09
1) PS-3001 K&N oil filter		7.19
1) Pair Moroso motor mounts, HD		34.44
1) Solid trans mount		29.80
1) set 3/8" x1" w/ 3/8 hex head header bolts		28.70
2) FI unit drive input flange gaskets	@ 3.95/ea	7.90
1) Column upper bearing		21.99
1) Column lower bearing		28.99
1) Lower bearing spring		4.99
1) Lower bearing retainer clamp		11.99
1) Column clamp-lower		11.99
1) Steering box, rebuilt		199.99
1) Core charge ( will credit upon acceptance)		80.00
1) Clutch rod boot-firewall		11.99
1) Lightweight GM flywheel 158T		220.00
Misc hardware, heat shrink, ties		15.00
Misc shop supplies		20.00

**Freight:**

Incoming- Valve covers	16.35
Outgoing- Water pump to rebuild	9.89
Core return	23.39

**Hazmat:**

14 qts waste oil

Thank you for your business

**AMERICAN PRIDE MOTORWORKS**

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

**Roger Kraus Tires, Inc.**  
 2896 Grove Way  
 Castro Valley, CA 94546  
 (510) 582-5031  
 BAR # 102319

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

Invoice # 73538

**Jeffrey Abramson**  
 181 South Ave  
 Alamo, CA 94507

**2013 GOODYEAR HOO VINTAGE**

Inv Date: 4/10/2013 @ 11:11am

VIN:  
 Engine:  
 Trans:  
 ODO In: 0 Out: 0  
 Color:  
 License #

Service Writer: Brandon Kraus  
 Status: Posted  
 Driver: Abramson, Jeffrey  
 Mfg. Date:  
 Unit #

(925) 314-3823 Home (925) 855-1926 Home

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
<b>Customer states that: Requests for Service &amp; Vehicle Problems -</b>						
Labor Service - CREDIT CARD ON FILE BK						0.00
New	GYR1724	Gyr 600-15 D1724 R655		4.00	307.00	1,228.00
Used	STDRT	Race Tire Disposal Track		4.00	5.00	20.00
New	HOO50015SHAV	Hoosier 500-15 Shaved		4.00	242.00	968.00
Labor Service - Usage tax tires ca only BK						21.00
Labor Service - Mount & bal vin. W/ sale TL						264.00
New	HOO215813FEHO	Hoosier 21.5/8.0-13 FE HIST OLD	12.00	2.00	245.00	490.00
New	HOO221013FEHO	Hoosier 22.0/10.0-13 FE HIST OLD	12.00	2.00	266.00	532.00
Labor Service - Dismount only TL						32.00

**Notes**  
 DONE AT WINE COUNTRY RACE 5/13 NO MOUNT AND BALANCE CHARGES ON THE 4 HOOSIER 500-15 PER BK  
 CAR # 5 AND 9  
 BILLED 5/20/2013 RK

444226808889  
 ROGER KRAUS TIRES  
 2896 GROVE WAY  
 CASTRO VALLEY, CA,  
 94546 510-582-5031

Posted 5/20/13 1:19PM  
 Master Card

Invoice Summary

Parts 3,238.00  
 Labor 317.00

ERMINAL I.D.: 26808884  
 restocking charge. Returned Goods  
 All returns must be made in 60 days.

MASTERCARD  
 XXXXXXXXXXXXXXX3932 \*  
 SALE  
 BATCH: 000003 INU: 24  
 DATE: MAY 20, 13 TIME: 13:18:40  
 AUTH NO: 96348P  
 US: 181 94507  
 TOTAL \$3822.14

*Thank You!*  
 I AGREE TO PAY ABOVE TOTAL AMOUNT  
 ACCORDING TO CARD ISSUER AGREEMENT  
 (MERCHANT AGREEMENT IF CREDIT VOUCHER)

Sub Total 3,555.00  
 Sales Tax (SP) 267.14

Discard old parts

Original Estimate: 3,809.44

**Total 3,822.14**

\*\*\*CUSTOMER COPY\*\*\*

# Transport Specialties

2290 Ivy St #140  
Chico, Ca 95928  
530 342 0422

# Invoice

Date	Invoice #
6/8/2013	87

Bill To
Jeff Abramson 1964 Corvette

6/8/13

P.O. No.	Terms	Project

Quantity	Description	Rate	Amount
	Advance payment, parts for '64 Corvette	2,500.00	2,500.00
	Sales Tax	7.50%	0.00

Thanks for your support!

**Total**

**\$2,500.00**



1-800-230-3030  
www.SummitRacing.com



1-800-575-1932  
www.GenuineHotrod.com



1-800-709-1079  
www.PowerSportsPlace.com

Calling Customer Service?  
Please reference your  
invoice number.

INVOICE NUMBER      DATE

7495860      06/05/13

CUSTOMER NUMBER      PAGE

14437496      1

- 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250
- 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787
- 20 King Mill Road • McDonough, GA 30253 • 770-288-3200

INVOICE

S  
O  
L  
D  
T  
O

TRANSPORT SPECIALTIES  
C/O AIC-AMERICOAT  
4039 LEOS LN

CARMICHAEL      CA 95608-1707  
(925) 855-1864

S  
H  
I  
P  
T  
O

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	HOK-2224HKR	HDR CHEV SIDEMOUNT		519.95	519.95
		OVERSIZE SHIP CHRG		9.50	9.50
1	HOK-50735HKR	SIDE PIPE KIT		245.95	245.95
	**** CATALOG *****CATALOG *****				

Your purchase of a set of Hooker Headers entitles you to a FREE Hooker Headers metal sign, \$40 value! Go to [www.summitracing.com/go/hly](http://www.summitracing.com/go/hly) for complete rebate details and redemption information. Valid on purchases made between 4/1/13 and 7/1/13. Valid in the Continental United States only. Must be redeemed by 9/1/13. Allow 4-6 for processing.

*It's  
Jeff Raab*

**NOTE:** If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.

Thank You!

\*Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

*397 0010*



1-800-230-3030  
www.SummitRacing.com



1-800-575-1932  
www.GenuineHotrod.com



1-800-709-1079  
www.PowerSportsPlace.com

Calling Customer Service?  
Please reference your  
invoice number.

INVOICE NUMBER	DATE
7653700	06/03/13

CUSTOMER NUMBER	PAGE
14434279	1

- 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250
- 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787
- 20 King Mill Road • McDonough, GA 30253 • 770-288-3200

1-330-630-3030

INVOICE

S  
O  
L  
D  
  
T  
O

DAN WASSAM  
TRANSPORT SPECIALTIES  
2290 IVY ST STE 140  
  
CHICO CA 95928  
  
(925) 855-1864

S  
H  
I  
P  
  
T  
O

#5  
PAID BY JEFF

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	SWW-82323	GA PRESS OIL MECH DLX	S/S	Shipped from Nevada	
1	SWW-82410-72	GA TMP OIL MECH DLX	S/S	Shipped from Nevada	
1	SWW-82319	GA PRESS FUEL MECH D		51.87	51.87
<p>IMPORTANT NOTICE</p> <p>-----</p> <p>To continue providing you with the best service, we are now shipping out of our Ohio, Nevada and Georgia facilities. Depending on your location, shipments may arrive at different times.</p>					

**NOTE:** If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.

Thank You!

\*Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate



1-800-230-3030  
www.SummitRacing.com

1-800-575-1932  
www.GenuineHotrod.com

1-800-709-1079  
www.PowerSportsPlace.com

Calling Customer Service?  
Please reference your  
invoice number.

INVOICE NUMBER	DATE
7653700	06/03/13
CUSTOMER NUMBER	PAGE
14434279	1

- 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250
- 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787
- 20 King Mill Road • McDonough, GA 30253 • 770-288-3200

1-330-630-3030

INVOICE

S  
O  
L  
D  
T  
O

DAN WASSAM  
TRANSPORT SPECIALTIES  
2290 IVY ST STE 140  
CHICO CA 95928  
(925)855-1864

S  
H  
I  
P  
T  
O

*HS Paid By JEFF*

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	SWW-82323	GA PRESS OIL MECH DLX		40.42	40.42
1	SWW-82410-72	GA TMP OIL MECH DLX		63.94	63.94
1	SWW-82319	GA PRESS FUEL MECH D	S/S	Shipped from Ohio	
**** CATALOG ***** CATALOG *****					
IMPORTANT NOTICE ----- To continue providing you with the best service, we are now shipping out of our Ohio, Nevada and Georgia facilities. Depending on your location, shipments may arrive at different times.					
** DECLARED PART VALUE THIS SHIPMENT **				104.36	U.S.D.

**NOTE:** If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.

Thank You!

\*Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

Some parts are not legal for sale or use in California on any pollution controlled motor vehicles.

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:  
GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

S16550603

Vintage Hot Rods, Inc.

631 Country Drive  
 Chico, CA 95928  
 530-343-9228  
 BAR AB243729

# Estimate

Date	Estimate #
6/4/2013	98

Name / Address
Vintage Vettes

*Pl 4,000 Deposit  
 6/7/13*

			Project
Description	Qty	Rate	Total
Cam bearings	1	64.59	64.59T
Rod bearings	1	81.94	81.94T
Main bearings	1	93.29	93.29T
Rings	1	177.80	177.80T
all gaskets	1	227.55	227.55T
Steel dist gear		39.90	39.90T
Billit main caps	1	* 450.00	450.00T
ARP main studs	1	* 166.00	166.00T
Fuel for dyno	1	80.00	80.00T
	1	40.00	40.00T
Hazardous Waste	1	15.00	15.00
		<b>Subtotal</b>	\$8,349.53
		<b>Sales Tax (7.5%)</b>	\$241.88
		<b>Total</b>	\$8,591.41

Vintage Hot Rods, Inc.

631 Country Drive  
 Chico, CA 95928  
 530-343-9228  
 BAR AB243729

# Estimate

Date	Estimate #
6/4/2013	98

Name / Address
Vintage Vettes

Project

Description	Qty	Rate	Total
Mag and micro polish crank	1	72.00	72.00
Hot tank , media blast and mag block	1	160.00	160.00
Line bore block with new main caps	1	* 625.00	625.00
Power hone with torque plate	1	170.00	170.00
Press fit cam bearings	1	40.00	40.00
Torque and check conrods	1	40.00	40.00
Clean pistons and all engine parts	1	80.00	80.00
HP enduro valve job	1	160.00	160.00
Surface cyl. heads	1	120.00	120.00
Competition porting -finish and repair what was started	1	* 1,275.00	1,275.00
Fill heat risers	1	90.00	90.00
Oil pan repair-estimate	1	127.50	127.50
Set up valve cover breathers-estimate	1	75.00	75.00
Assemble complete race V8	1	1,475.00	1,475.00
Dyno test and tune w/ Roch FI	1	600.00	600.00
Crane 968821 Blueprinted camshaft	1	263.63	263.63T
Crane 99250 solid lifters	1	114.40	114.40T
Cloyes 9-3100 true roller timing set	1	112.55	112.55T
ARP 234-4301 head studs	1	218.58	218.58T
Manley guide plates	1	48.40	48.40T
RK1508 rocker arms	1	201.60	201.60T
ARP pro rocker studs	1	127.89	127.89T
Manley valve locks	1	49.40	49.40T
Manley lash caps	1	39.36	39.36T
Manley valve springs	1	216.00	216.00T
Manley ti retainers	1	236.15	236.15T
Valve seals	1	32.00	32.00T
Pushrods	1	144.00	144.00T
		<b>Subtotal</b>	
		<b>Sales Tax (7.5%)</b>	
		<b>Total</b>	

# Transport Specialties

2290 Ivy St #140  
Chico, Ca 95928  
530 342 0422

6/6/13

# Invoice

Date	Invoice #
5/31/2013	86

Bill To
Jeff Abramson 1964 Corvette

P.O. No.	Terms	Project

Quantity	Description	Rate	Amount
6.5	Labor- Remove engine and transmission for upgrades. Look over car for parts needed and work required. Delivered engine to rebuilder.	80.00	520.00
	Transport-Pick up car in Alamo, RT	320.00	320.00
	Sales Tax	7.50%	0.00
Thank you for your business!		<b>Total</b>	<b>\$840.00</b>



1-800-230-3030  
www.SummitRacing.com



1-800-575-1932  
www.GenuineHotrod.com



1-800-708-1079  
www.PowerSportsPlace.com

Calling Customer Service?  
Please reference your  
invoice number.

# INVOICE

- 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250
- 980 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787
- 20 King Mill Road • McDonough, GA 30253 • 770-288-3200

SUMMIT RACING EQUIPMENT  
JEFFREY ABRAMSON  
181 SOUTH AVE

ALAMO CA 94507  
(925) 855-1864

S H I P T O

## EXCHANGE/RETURN FORM

INVOICE NUMBER DATE  
6539529-3 05/29/13

CUSTOMER NUMBER PAGE  
10114271 1



JEFFREY ABRAMSON  
181 SOUTH AVE

ALAMO CA 94507  
(925) 855-1864 PH  
WEB NV  
MICHELE

Phone: ( )

### Reason Codes

- M. No longer need the part
- D. The part is defective or missing a piece
- Q. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other, please explain

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.	Qty.	Part Number	Reason Code
1	PWM-9540 **** CATALOG *****	STARTER ***** CATALOG *****	CATALOG	218.95 *****	218.95 *****	1	PWM-9540	
** DECLARED PART VALUE THIS SHIPMENT ** 218.95 U.S.D.								

\*\* DECLARED VALUE 218.95

Jeffrey Abramson  
181 South Ave  
Alamo, CA 94507



725 00 94507 02 1352 0 1 6539529 8

NO POSTAGE  
NECESSARY IF  
MAILED IN THE  
UNITED STATES

**NOTE:** If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.  
\*Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

Thank You!

Credit Card Charge 218.95

Some parts are not legal for sale or use in California on any pollution controlled motor vehicles.

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR. GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

S16550528

# PARCEL SELECT RTN SVC

NEWSTATICS, INC.  
PRODUCT NO. 27000

SMART LABEL RTNS  
PARCEL RTN SVC  
56901

USPS PARCEL RETURN SVC



9202 3901 0071 2037 9370 81

# V248

## TRANSPORT SPECIALTIES

P.O. Box 7148  
Chico, Ca 95927

Jeff Abramson  
'64 Corvette #5

R/O 401

May 9, 2013

### Repairs & updates

0.0 hrs

<u>Work descrip.</u>	<u>Labor</u>
Inspect car(some disassembly required), record repairs needed. Research parts and order as needed.	3.75 hrs
Installed hour meter.	1.0 hr
Change all fluids-trans, diff, engine. Drill & tap diff for drain plug.	1.75 hrs
Repair RH tail light wiring.	.25 hr
Clean, inspect, repack, install front wheel bearings and seals.	2.00 hrs
Replaced RH outer t/rod end.	.50 hr
Removed old fuel cell, fitted new ATL fuel cell. Re-fitted support cradle. Replaced 2 old fuel pumps with one (1) new pump, replaced fuel filter, re-plumbed new cell as needed.	16.0 hrs
Installed new fire suppression system, added nozzle to fuel cell area.	8.75hrs
Secured trim around fuel filler. Required different fasteners and attachment.	.50 hr
Re-routed and shortened main feed to MSD box.	.50 hr
Attempted flush and bleed of brakes. Found leaking and bypassing M/cyl.	
Replaced M/cyl and bled brakes.	2.50 hrs
Bored wheel stud holes in new wheels for shank style wheel nuts.	1.25 hr
Replaced damaged steering coupler bolts. Required removal of steering shaft and slight modification to coupler for proper fit of bolts.	1.25 hr
Start, run, adjust timing, adjust fuel pressure, check for leaks.	.50 hr
Check out noisy starter, removed, found starter hitting engine block causing mis-alignment. Relieved interference and reinstalled starter. Needs new starter, will replace at later date.	1.25 hr
Changed shoulder belt securement on cage diagonal.	.75 hr
Nut and bolt chassis and engine.	1.5 hr
Check and adjust alignment as needed.	3.0 hrs
	<hr/>
Total labor	47.00 hrs

**Parts: (R/O 401)**

3)qts AMSOIL 75/90 Severe Gear lube	@ 14.95/qt	44.85
1) Limited slip additive		8.25
2) Front wheel seals	@ 11.25/ea	22.50
1) RH outer tie rod end		37.87
2) M/cyl brake line adaptors	@ 7.95/ea	15.90
7 ft X 1" flat bar	@ .90/ft	6.30
Stroud 10# FE-36 fire suppression system		751.79
ATL 15 gal "Saver Cell" fuel cell kit		901.67
1) Rectangular hour meter		37.25
1) Holley fuel pump		134.04
2) Fram fuel filters	@ 7.95	15.90
1)Master cylinder		49.95
3)bottles Motul 600	@ 20.95/ea	62.85
1) KN 3001 oil filter		12.95
4) .060" rear toe shims	@1.75/ea	7.00
Misc hardware		15.00
Misc shop supplies		37.60

**Freight:**

Inbound- 3-day fuel cell	143.00
Hazmat freight charge- fire system	27.50

**Hazmat:**

12 qts waste oil

Thank you for your business

**AMERICAN PRIDE MOTORWORKS**