

**ADVANCED AUTO SERVICES**

1115 Landini Lane  
 Concord, CA 94520  
 Shop Phone: (925) 680-8448  
 Fax: (925) 680-0757

Invoice

18523

Estimate Ref #21,938  
 Date Printed: 05/31/2022  
 Printed Time: 3:13 pm  
 AG240596  
 CAL000305195

Hat/Ref:

ALL MAKES &amp; MODELS - ALL SERVICED WITH THE SAME GREATEST CARE!

Time Promised:

1973 CHEVROLET BLAZER V8 5.7L 350CID CARB GAS N V

VIN: CKY183F105693

License: 3EYH954

Mileage In: 55,510

Date Written: 05/19/2022

Unit #:

Mileage Out: 55,510

Written By:

DOM:

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
<b>Job #1</b>	<b>CHECK ENGINE VIBRATION</b>				
Labor STD	Work Requested - CHECK ENGINE VIBRATION CARBURTOR NEED REPAIR				0.00
<b>Job #2</b>	<b>REMOVE AND CLEANING CARBURATOR</b>				
Labor STD	Work Requested - REMOVE AND CLEANING CARBURATOR TOP REPAIR CHOCK ( STUCK )				255.00
Part C-CLEANER	HEAVY DUTY CARBON CLEANER		1.00	29.95	29.95
<b>Job #3</b>	<b>MACK ENGINE OIL LEVEL ( OIL DIPSTICK MARKER)</b>				
Labor STD	Work Requested - MACK ENGINE OIL LEVEL ( OIL DIPSTICK MARKER)				45.00
Part OIL 5W/30	MULTIGRADE MOTOR OIL - PER QUART		5.00	2.95	14.75

Payment Date	Type	Method	Amount
5/31/2022	Credit	Visa	349.06
Payment Totals:			\$349.06

Parts: \$44.70  
 Labor: \$300.00  
 Sublet: \$0.00  
 Misc: \$0.00

Hazmat: \$0.00  
 Supplies: \$0.00

Tax Total: \$4.36

Invoice Total: **\$349.06**

Less Paid: 349.06

Balance Due: **\$0.00**

All pickups after 3 days from notification would be subjected to \$85 per day.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Authorized By \_\_\_\_\_

Date \_\_\_\_\_

Time \_\_\_\_\_



805.922.9684  
www.supermufflersm.com  
Lic. # AB214920

## Sales Receipt

Date	Sale No.
4/16/2021	46292

**Super Muffler Inc.**  
**926 W. Main St.**  
**Santa Maria, CA. 93458**

Sold To
<div style="background-color: white; width: 100%; height: 100%;"></div>

Payment Method	Check No.	Mileage
Visa		

VIN	Qty	Rate	Amount
	2	135.00	135.00T
		44.99	89.98T
		75.00	75.00T
		30.00	30.00T
		150.00	150.00

**Description**  
Super 44 Flowmaster  
2 1/2 " Custom Bent Aluminized Tubing  
X-6301 Xelerator 3" Mandrell Bent Pipe 45 deg.  
Gaskets, Bolts, Nuts, Hangers Etc.  
LABOR Note: all labor guaranteed for 90 days ,  
unless otherwise stated .

<b>Subtotal</b>	\$479.98
<b>Sales Tax (8.75%)</b>	\$28.87
<b>Total</b>	<b>\$508.85</b>

# Power Performance

3661 Sacramento Drive, Unit #6  
San Luis Obispo, CA 93401

4205

NAME

ADDRESS

CITY

MAKE OF UNIT

YEAR

ENGINE OR SERIAL NO.

MODEL

DATE

CUSTOMER  
ORDER NO.

TERMS: ☐ CASH  
☐ CHARGE

PHONE NO.

PHONE WHEN READY

QTY.	PART NUMBER	SIZE	PART	List Each	Net Each	AMOUNT	2	SERVICE	List	Net
SET	CB663	10	Rod Bearings					Valve Job		
SET	MS904P	10	Main Bearings					Multi Valves Job		
	CHP84		Camshaft Bear.					Comp. Valve Job		
SET	2M139	30	Rings					Valve Adjustment		
8	1479H	30	Pistons					Install Valve Guides X16		
			Pin Bushings					Install Valve Seats		
	08-1100R		T. Chain					Prep. Intake Manifold		
			T. Gears					Cylinder Head Surfacing ( )		
1	PB1046-H		T. Cover Seal					Surface Block		
1	260-1000		Rear Main Seal					Rebore Block ( 30 )		
			F.S. Gasket Set					Hone Cylinders		
			H.S. Gasket Set					Install Sleeves		
			O.S. Pan Set					Install Cam Bearings		
8	01195		Valves — Intake					Fit Pins R.R. Pistons		
8	01192		Valves — Exhaust					Recondition Rods X8		
32	VALVE LOCKS (60)		Valve Seats					Align Rods		
16	140-1467		Valve Guides					Align, Bore Main Bearings		
16	981-742		Valve Springs					Grind Crankshaft ( MAIN ) ( ROD )		
16	1412-16		Rockers					Surface Flywheel		
	5551		VSI Shims					Press Work		
	MP1000		Freeze Plugs					Labor on Assembling Engine OIL		
	12-239-3		Camshaft Comp					Clean Motor and Parts		
16	HA317		Lifters					Balance Engine Assembly		
	1155 HV		Oil Pump					Magna Flux		
1	1555		Shaft					Polish Crankshaft		
16	192-1331		Paint: Push Rods					R & R Soft Plugs		
			New Cylinder Heads					Repair Head and Block		
SET	220-14001		Valve Cvr Seals					Cut Guide for Seals		
								Glass Beading		
SET	6003		APP BOLT ROD					Cut Stem Height X16		
5	1116X 1116		OIL BREAK TH					Pressure Test Cylinder Head X2		
	51061		OIL FILTER					Vacuum Test Valves		
			MISC. PARTS					MISC. SERVICE		

## SPECIAL INSTRUCTIONS

ROA 1500.00 FEB 10  
BAL 2250.62

TOTAL PARTS

\$ 1150.00

Authorized  
By X

Received  
By X

TOTAL SERVICE

TOTAL PARTS

TAX

TOTAL  
AMOUNT

2500.00  
1150.00  
100.62  
\$ 3750.62

ALL CLAIMS AND RETURNED GOODS MUST BE ACCOMPANIED BY THIS BILL  
CONDITIONAL SALES CONTRACT

Title to the above merchandise shall remain wholly in Power Performance until fully paid. Upon default in payment the entire balance shall become due and bear interest at the highest legal rate. The buyer agrees to pay all costs of collection including attorney fees of not less than Twenty-five percent (25%), and hereby waives all rights under all statutes of limitation. Time is of the essence of this agreement.

POWER PERFORMANCE

Thank You

ADDITIONAL REPAIR AUTHORIZATION  
EST. COST OF ADDITIONAL REPAIRS

\$

PHONE O.K. YES ☐ NO ☐ TIME

SIGNED

ESTIMATED COST OF REPAIRS BELOW

\$

DO YOU WANT OLD PARTS YES ☐ NO ☐

SIGNED

MERCHANDISE UNCLAIMED 60 DAYS  
AFTER COMPLETION SHALL BE SOLD.

Driveline

# CENTRAL COAST SPRING & ALIGNMENT

708 E. OAK ST.  
SANTA MARIA, CA 93454  
(805) 347-7335  
FAX 347-1086  
BAR # AH179810

CUSTOMER

PHONE #

ADDRESS

WORK ORDER N° 13249

DATE TAKEN

4/13/2021

DATE DUE

P.O. #

FRONT ☐

THICK

WIDTH

NO LVS

LENGTH

SE

LE

FREE  
ARCH

BUSHINGS

SE

LE

YR.

MAKE

MODEL

LIC.

MILEAGE

- ☐ Retain Parts  
☐ Destroy Parts  
**ESTIMATE**

REAR ☐

NOTES

PRICE

MATERIALS USED

QUA

SIZE OR NO

PART

EXTENDED PRICE

BUSH

BUSH

U-BOLTS

C-BOLT

REBND  
CUP

STEEL

WORK DONE

LABOR

shock 1310CV Driveline

1.5

Made 1350 Driv per customer specs

1.5

56.60

1

3104-32CV yoke

56.60

127.24

1

3-4-62H-1 yoke

127.24

10.17

1

3-70-288 yoke

10.17

25.42

1

N3-25-57 yoke

25.42

112.00

1

N024-2-40-27 yoke

112.00

55.54

1

N240-1521 slip

55.54

61.55

1

N3-3-10014 yoke

61.55

15.14

2

2-0055 yoke

30.28

LATE CHARGES OF MAXIMUM ALLOWED CHARGED AFTER 30 DAYS.

Any warranties on the products sold hereby are those made by the manufacturer. The seller, above named dealership, hereby expressly disclaims all warranties, either expressed or implied including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorized any other person to assume for it any liability in connection with the sale of said products. All spring, wheel, and u-bolts must be re-torqued at 600 miles of use.

Received by

PARTS

487.30

3.0

LABOR

330.00

FREIGHT

15.00

SALES TAX

43.96

TOTAL

876.26



• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250  
 • 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787  
 • 20 King Mill Road • McDonough, GA 30253 • 770-288-3200  
 • 2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700

Calling Customer Service?  
 Please have your  
 invoice number ready.

INVOICE NUMBER DATE  
 2357385 04/03/21  
 CUSTOMER NUMBER PAGE

INVOICE

9997477 1

# EXCHANGE/RETURN FORM

INVOICE NUMBER DATE

2357385-7 04/03/21



**NOTE:** Please read the *How to Return an Order* instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ( )

## Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- Q. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other; please explain

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	TAY-42700	SPARK PLUG WIRE DIVIDER	S/S	Shipped from Texas	
1	TAY-79232	SPARK PLUG WIRE SET		107.99	107.99 T
<b>WARNING:</b> Proposition 65 Compliance Statement California Safe Drinking Water & Toxic Enforcement Act of 1986 Some products purchased from our catalog or website contain chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm. Purchaser may receive full refund, including shipping costs, for return of unopened package within 30 days.					
** DECLARED PART VALUE THIS SHIPMENT **				107.99 U.S.D.	
** TOTAL INVOICE CA SALES TAX **					7.84

**NOTE:** If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.  
 \*Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

Thank  
 You!

Credit Card Charge 130.82

Some parts are not legal for sale or use in California on any pollution controlled motor vehicles.

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:  
 GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

S16550403 CCU U0000884

Qty.	Part Number	Exchange	Refund	Qty.	Reason Code	Explanation
1	TAY-79232					
<b>** DECLARED VALUE **</b> 107.99						

## PRIORITY MAIL RETURNS® SERVICE

James Klunke  
 920 Calle Roble  
 Nipomo, CA 93444  
 Order: 2357385

NO POSTAGE  
 NECESSARY IF  
 MAILED IN THE  
 UNITED STATES

Summit Racing Equipment  
 Attn: Returns Dept.  
 2200 East Interstate 20  
 Arlington, Tx. 76018-9804

USPS TRACKING NUMBER



9201 9902 3186 9080 4950 43

**LMC TRUCK**

15450 W. 108TH STREET, LENEXA KS 66219  
800-562-8782 ORDERS-CATALOG REQUESTS-STATUS  
913-541-0684 WORLDWIDE ORDERS  
913-599-0323 FAX ORDERS

www.LMCTRUCK.com

**LMC  
TRUCK**

ORDER #

**W4560142**

DATE

03/22/21

PAGE 1

ORDER #	DATE	CATALOG	VEHICLE	PAYMENT	METHOD OF PYMENT OR CREDIT CARD		
W4560142	03/20/21	CSB76	CT K5 73	VISA	**** * 8085		
LOCATION	QTY	PART	DESCRIPTION		O/S	PRICE	AMOUNT
B08 01 00	1	36-4071	HOSE-WASHER/VACUUM			4.95	4.95
D05 01 03	2	30-1423	WASHER NOZZLE	2 REQ		6.95	13.90

**W4560142**

3

Regular - B2

Run# 07: 99 of 197

**LONG  
MOTOR  
CORPORATION**

BACKORD - BACKORDERED, WILL SHIP WHEN AVAILABLE.  
TOS - TEMPORARILY OUT OF STOCK, CANCELLED, REORDER IN 3-4 WEEKS.  
TBA - TO BE ANNOUNCED (AVAILABILITY), PART HAS BEEN CANCELLED  
FROM ORDER, CHECK AVAILABILITY AT A FUTURE DATE.  
NLA - NO LONGER AVAILABLE, STOCK DEPLETED OR NO MANUFACTURER.

NOTES:

**STD**

PARTS 18.85

SHIPPING  
CORES 6.00  
C.O.D.STATE TAX 1.36  
SHIPMENT TOTAL 26.21

PAYMENT CREDIT



**WARNING:**  
Cancer and Reproductive Harm  
www.P65Warnings.ca.gov

THIS SHIPMENT COMPLETES THE ORDER



FAMILY OF AUTOMOTIVE PARTS COMPANIES

CUSTOMER SERVICE  
1-800-327-4868

Customer No.	Shipping No.	Order No.	
71295536-000	50194475-00001	WO-50194475	
Bin No.	Batch No.	Order Date	Page
016	0002726131	3/16/21	1
Sls#	P.O. Number	Order Type	Print Date/Time
XXX		RTL	3/16/21 12:12:09
Ship Via		Terms	
GROUND BW		MASTER CARD	

Location	Part No.	Shpd	UM	Description	B/O	Unit Price	Sale Price	Amount
FlF82-12-03	846667	1	EA	Grille Emblem 73-74	TW	0	59.99	59.99
FlF88-99-01	378780	1	EA	TRK Catalog (most recent)	USA	0	.00	.00
**** Parts with 'ALT' are shipping from an alternate location. ****								
**** Parts with 'B/O' are out of stock and will ship at a later date. ****								
B/O	866540	0	EA	Door Bumper 60-91	TW	1		
B/O	847100	0	EA	78-87 SUBREN TAILGATE CABLE	TW	2		

Cust. #: 71295536-000  
Order #: 50194475-00001**ECKLER'S**7980 Grissom Parkway  
Titusville, FL 32780  
ATTN: RETURNS DEPT.INSPECTS CONTENTS OF  
SHIPMENT FOR DAMAGES AND  
SHORTAGES WITHIN 5 DAYS

PICK

PACK

Sale Amount	59.99
Shpg & Hndg	18.49
Sales Tax	5.69
COD Charges	.00
Total	84.17
Prepayment	84.17
Balance Due	.00

Comments:

**RTL**



**1 Chevy Duty Drive**  
**Kansas City, MO 64150**  
**Phone (816) 741-8029**  
**Fax (816) 741-5255**

Page	Date	Order No.
1	03/16/21	2086075B



**S  
O  
L  
D  
T  
O**

Customer No.	Sales I.D.	Reference #	Media Code	Terms		
1299277	WWW/REM		/OTHER	XXXXXXXXX8085 VISA		
Credit Card Number	Type	Phone Number	Total Wt.	Zone	Packages	Ship Via
	A		1.2 Lbs	1	1	BST

Message:

\*\*\*Test fit all parts before painting or modifying!\*\*\*

\*\*\*Painted or modified parts are non-returnable!\*\*\*

Quantity	B/O	Shpd	Item #	Description	Unit Price	Disc	Extension
1	0	1	59-337	Grill Emblem - Chevrolet - Bowtie 73-74	59.9500		59.95
MERCHANDISE INVOICE TOTAL \$							59.95
STATE SALES TAX \$							3.75
COUNTY SALES TAX \$							0.60
INVOICE TOTAL \$							64.30
CR. CARD: VI, APPR:02835C \$							-64.30



**Checkout - Complete - Thanks for Your Order!**

- To pay with PayPal, choose "Pay with my PayPal account" at the next step.
- In the unlikely event that you run into problems completing your PayPal transaction please send us an email ([tech@dennysdriveshaft.com](mailto:tech@dennysdriveshaft.com)) or call us (800-955-1872) and we will send you a PayPal Invoice to complete your order.

Order Receipt				
<b>Denny's Driveshafts</b> 1189 Military Road Kenmore, NY 14217 (800) 955-1872 Phone - <i>Orders Only</i> (716) 875-6640 Phone - <i>Customer Service,</i> <i>Tech Line questions</i> <a href="http://www.DennysDriveshaft.com">www.DennysDriveshaft.com</a> <a href="mailto:Sales@DennysDriveshaft.com">Sales@DennysDriveshaft.com</a>		Date: 03/10/2021  Order #: 117580		
Bill To:		Ship To:		
<div></div>				
Payment Method:				
Credit Card Visa - James Kiunke - XXXXXXXXXXXXX8085 Exp: 11/2025				
Shipping Method:				
Free Ground Shipping on Parts Orders Over \$99 @ \$0.00				
Qty	Name	Price	Each	Subtotal
1	<a href="#">820054 FORGED STEEL PINION YOKE 1350 series 2.800 inches tall with hardware fits 12 Bolt Chevy Car and Truck rear ends</a> Part #: 820054	\$115.95	\$115.95	\$115.95
1	<a href="#">TIMKEN 8460N Pinion Seal fits Chevy 12 Bolt CAR &amp; TRUCK rear ends</a> Part #: 8460N	\$10.95	\$10.95	\$10.95
Subtotal:				\$126.90
Shipping (Free Ground Shipping on Parts Orders Over \$99) :				\$0.00
Grand Total:				\$126.90



**1 Chevy Duty Drive**  
**Kansas City, MO 64150**  
**Phone (816) 741-8029**  
**Fax (816) 741-5255**

Page	Date	Order No.
1	03/09/21	2086075A



**SOLD TO**

Customer No.	Sales I.D.	Reference #	Media Code	Terms			
1299277	WWW/REM		/OTHER	XXXXXXXXX8085 VISA			
Credit Card Number	Type	Phone Number	Total Wt.	Zone	Packages	Ship Via	
	A		2.1 Lbs	1	1	BST	

Message:

\*\*\*Test fit all parts before painting or modifying!\*\*\*  
 \*\*\*Painted or modified parts are non-returnable!\*\*\*

Quantity	B/O	Shpd	Item #	Description	Unit Price	Disc	Extension
2	0	2	18-016	Inside Window Handle - with Black Knob 67-76 Truck, 67-81 Camaro, 68-74 Nova, 68-72 Chevelle	4.9500	--	9.90
2	0	2	18-046	Inside Handle Escutcheon 72-77 Truck, 67-69 Camaro, 68-74 Nova, 68-72 Chevelle	1.9500	--	3.90
2	0	2	18-057	Inside Handle Retainer Clip 67-98 Truck, 67-81 Camaro, 68-74 Nova, 68-72 Chevelle	0.2500	--	0.50
1	0	1	18-321	Door Bumper 60-91	0.9900	--	0.99
2	0	2	53-611	Door Jamb Switch Bullet Type 67-84 Truck, 67-73 Camaro, 68-74 Nova, 68-72 Chevelle	6.9500	--	13.90
1	0	1	38-021	Hood Bumper Set 73-74	7.9500	--	7.95
1	0	1	32-351	Steering Column To Dash Cover 73-77	21.9500	--	21.95
2	0	2	51-538	Side Marker Lamp-F-REP-DLX 73-80	8.9500	--	17.90
1	0	0	59-337	Grill Emblem - Chevrolet - Bowtie 73-74	59.9500	--	0.00
2	0	2	98-686	Key Chain - Chevrolet Bowtie Emblem 73-81	11.9500	--	23.90

MERCHANDISE INVOICE TOTAL \$ 100.89  
 SHIPPING & HANDLING \$ 14.95  
 STATE SALES TAX \$ 6.31  
 COUNTY SALES TAX \$ 1.01  
 INVOICE TOTAL \$ 123.16  
 CR. CARD. VI, APPR.02195C \$ -123.16



**FLATRATE** shipping **1-800-741-1678**  
TOLL FREE USA NUMBER

1

CUSTOMER INFORMATION

2

CHECKOUT

3

CONFIRMATION

Thank you for your order.

Your web confirmation number is 87438669.

[Click Here to Print this Page](#)

Qty	Description	Total
1	(1973-74) Hood Bumper Set 73-74 Item: 38-021 Price: \$7.95	\$7.95
2	(1967-81) Inside Window Handle - with Black Knob 67-76 Truck, 67-81 Camaro, 68-74 Nova, 68-72 Chevelle Item: 18-016 Price: \$4.95	\$9.90
2	(1972-77) Inside Handle Escutcheon 72-77 Truck, 67-69 Camaro, 68-74 Nova, 68-72 Chevelle Item: 18-046 Price: \$1.95	\$3.90
2	(1967-98) Inside Handle Retainer Clip 67-98 Truck, 67-81 Camaro, 68-74 Nova, 68-72 Chevelle Item: 18-057 Price: \$0.25	\$0.50
2	(1973-80) Side Marker Lamp Assy-Front-Repro-Deluxe 73-80 Item: 51-538 Price: \$8.95	\$17.90
2	(1973-87) Key Chain - Chevrolet Bowtie Emblem 73-81 Item: 98-686 Price: \$11.95	\$23.90
1	(1973-77) Steering Column To Dash Cover 73-77 Item: 32-351 Price: \$21.95	\$21.95
2	(1967-84) Door Jamb Switch Bullet Type 67-84 Truck, 67-73 Camaro, 68-74 Nova, 68-72 Chevelle Item: 53-611 Price: \$6.95	\$13.90
1	(1960-91) Door Bumper 60-91 Item: 18-321 Price: \$0.99	\$0.99
1	(1973-74) Grill Emblem - Chevrolet - Bowtie 73-74 Item: 59-337 Price: \$59.95	\$59.95

Subtotal: \$160.84  
(National, State and Local taxes) Tax: \$11.66  
(USA GROUND RES) Shipping: \$14.95

**TOTAL: \$187.45**

# Packing Slip



**InlineTube 04-2020**

15066 Technology Drive  
Shelby Township, MI 48315

Order #	Date
S12133	03/04/2021



Ship To:

Bill To:

Carton Count	Date Scheduled	FOB Point	Shipping Terms	Carrier	Order Num
1	03/04/2021	Origin	Prepaid & Billed	FedEx Only	329963

## Carton Info

Carton #	Weight	Tracking #
----------	--------	------------

1

Total Weight:

Carton Count: 1

Line #	Part #	Description	Qty Ordered	Qty Shipped	Qty Remaining
1	CTT7301	1973-80 Chevrolet GMC Truck Blazer jimmy 2WD T350 5/16" Trans Cooler Lines 2pc, OE Steel	1.00 ea	1.00 ea	0.00 ea
3	PROP65	California Proposition 65 Warning, WARNING: This product can expose you to certain chemicals, which are known to the State of California to cause cancer or birth defects or other reproductive harm. for more information go to <a href="http://www.p65Warnings.ca.gov">www.p65Warnings.ca.gov</a>	1.00 ea	1.00 ea	0.00 ea



1 Chevy Duty Drive  
 Kansas City, MO 64150  
 Phone (816) 741-8029  
 Fax (816) 741-5255

Page	Date	Order No.
1	03/04/21	2084333A



Customer No.	Sales I.D.	Reference #	Media Code	Terms			
1299277	WWW/REM		/OTHER	XXXXXXXXX8085 VISA			
Credit Card Number	Type	Phone Number		Total Wt.	Zone	# Packages	Ship Via
		A		3.1 Lbs	1	1	BST

Message:

\*\*\*Test fit all parts before painting or modifying!\*\*\*  
 \*\*\*Painted or modified parts are non-returnable!\*\*\*

Quantity	B/O	Shpd	Item #	Description	Unit Price	Disc	Extension
1	0	1	TRK-5	73-87 Truck Catalog Vol 21	0.0000	-	0.00
1	0	1	22-017	Glove Box-Without A/C 73-91	32.9500	-	32.95
MERCHANDISE INVOICE TOTAL \$							32.95
SHIPPING & HANDLING \$							9.95
STATE SALES TAX \$							2.06
COUNTY SALES TAX \$							0.33
INVOICE TOTAL \$							45.29
CR. CARD: VI, APPR.08348C \$							45.29





• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250  
 • 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787  
 • 20 King Mill Road • McDonough, GA 30253 • 770-288-3200  
 • 2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700

Calling Customer Service?  
 Please have your  
 invoice number ready.

# INVOICE

INVOICE NUMBER	DATE
2778130	02/24/21
CUSTOMER NUMBER	PAGE
9997477	1

## EXCHANGE/RETURN FORM

INVOICE NUMBER	DATE
2778130-2	02/24/21

**NOTE:** Please read the *How to Return an Order* instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ( )

### Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- Q. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other; please explain

27

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	BSP-95129	VALVECOVERS SBC PLAIN		91.99	91.99 T
1	CLP-IN38RS	MANIFOLD VACUUM FITTING		7.99	7.99 T
1	SUM-221100	FITTING 1/2 NPT TO 3/4 H		12.99	12.99 T
1	SUM-221122	FITTING 1/2 NPT TO 3/4 H		26.99	26.99 T
<b>WARNING:</b> Proposition 65 Compliance Statement California Safe Drinking Water & Toxic Enforcement Act of 1986 Some products purchased from our catalog or website contain chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm. Purchaser may receive full refund, including shipping costs, for return of unopened package within 30 days.					
** DECLARED PART VALUE THIS SHIPMENT **			139.96 U.S.D.		
** TOTAL INVOICE CA SALES TAX **				10.16	

Qty.	Part Number	Exchange	Refund	Qty.	Reason Code	Explanation
1	BSP-95129					
1	CLP-1N38RS					
1	SUM-221100					
1	SUM-221122					
** DECLARED VALUE		139.96				

**NOTE:** If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.  
 \*Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

Thank  
 You!

Credit Card Charge 150.11

Some parts are not legal for sale or use in California on any pollution controlled motor vehicles.

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:  
 GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

S16550224 CCU U0001015

## PRIORITY MAIL RETURNS® SERVICE

James Klunke  
 920 Calle Roble  
 Nipomo, CA 93444

Ord: 2778130

Summit Racing Equipment  
 Attn: Returns Dept.  
 2200 East Interstate 20  
 Arlington, Tx. 76018-9804

NO POSTAGE  
 NECESSARY IF  
 MAILED IN THE  
 UNITED STATES

## USPS TRACKING NUMBER



9201 9902 3186 9076 2928 85

**LMC TRUCK**

15450 W. 108TH STREET, LENEXA KS 66219  
800-562-8782 ORDERS-CATALOG REQUESTS-STATUS  
913-541-0684 WORLDWIDE ORDERS  
913-599-0323 FAX ORDERS

www.LMCTRUCK.com

**LMC  
TRUCK**

ORDER #

**W4510341**

DATE

**02/22/21**

PAGE 1

ORDER #	DATE	CATALOG	VEHICLE	PAYMENT	METHOD OF PYMENT OR CREDIT CARD
W4510341	02/21/21	CSB76	CT K5 73	VISA	**** * 8085

LOCATION	QTY	PART	DESCRIPTION	O/S	PRICE	AMOUNT
A11 04 00	1	36-4401	LICENSE LAMP ASSY W/STD BUMPER		12.95	12.95
D11 01 00	1	30-3706	REAR LICENSE PANEL-CHROME		49.95	49.95
D11 03 00	1	38-2400	DOOR SILL PLATE SET-FRONT		29.95	29.95

**W4510341**

3

Regular - A2

Run# 05: 107 of 120

**LONG  
MOTOR  
CORPORATION**

NOTES:

BACKORD - BACKORDERED, WILL SHIP WHEN AVAILABLE.  
TOS - TEMPORARILY OUT OF STOCK, CANCELLED, REORDER IN 3-4 WEEKS.  
TBA - TO BE ANNOUNCED (AVAILABILITY), PART HAS BEEN CANCELLED  
FROM ORDER, CHECK AVAILABILITY AT A FUTURE DATE.  
NLA - NO LONGER AVAILABLE, STOCK DEPLETED OR NO MANUFACTURER.

**STD**

PARTS 92.85

SHIPPING 15.75  
CORES  
C.O.D.STATE TAX 6.73  
SHIPMENT TOTAL 115.33

THIS SHIPMENT COMPLETES THE ORDER

PAYMENT CREDIT



**WARNING:**  
Cancer and Reproductive Harm  
www.P65Warnings.ca.gov



• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250  
 • 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787  
 • 20 King Mill Road • McDonough, GA 30253 • 770-288-3200  
 • 2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700


Calling Customer Service?  
 Please have your  
 invoice number ready.

# INVOICE

INVOICE NUMBER	DATE
1881429	02/15/21
CUSTOMER NUMBER	PAGE
22787603	1

## EXCHANGE/RETURN FORM

INVOICE NUMBER	DATE
1881429-5	02/15/21



**NOTE:** Please read the *How to Return an Order* instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ( )

### Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- Q. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other; please explain

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	SUM-890014	DUAL FAN RELAY		64.99	64.99 T
<b>WARNING:</b> Proposition 65 Compliance Statement California Safe Drinking Water & Toxic Enforcement Act of 1986 Some products purchased from our catalog or website contain chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm. Purchaser may receive full refund, including shipping costs, for return of unopened package within 30 days.					
** DECLARED PART VALUE THIS SHIPMENT **			64.99 U.S.D.		
** TOTAL INVOICE CA SALES TAX **					4.71

Qty.	Part Number	Exchange	Refund	Qty.	Reason Code	Explanation
1	SUM-890014					
<b>** DECLARED VALUE 64.99</b>						

**NOTE:** If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.  
 \*Explanation of status column codes: B/D = backorder C/S = cancel ship S/S = shipped separate

**Thank You!** Delivery Prepaid PREPAID

Credit Card Charge 69.70

Some parts are not legal for sale or use in California on any pollution controlled motor vehicles.

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:  
 GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

YOUR SALES REP IS EVAN.  
 P92840211 U0000471

James Kiunke  
 920 Calle Roble  
 Nipomo, CA 93444  
 Odr: 1881429

Summit Racing Equipment  
 Attn: Returns Dept.  
 2200 East Interstate 20  
 Arlington, Tx. 76018-9804

NO POSTAGE  
 NECESSARY IF  
 MAILED IN THE  
 UNITED STATES

## USPS TRACKING NUMBER



9201 9902 3186 9075 5369 11

**LMC TRUCK**

15450 W. 108TH STREET, LENEXA KS 66219  
800-562-8782 ORDERS-CATALOG REQUESTS-STATUS  
913-541-0684 WORLDWIDE ORDERS  
913-599-0323 FAX ORDERS

www.LMCTRUCK.com

**LMC  
TRUCK®**

ORDER #

**7525594**

DATE

02/14/21

PAGE 1

ORDER #	DATE	CATALOG	VEHICLE	PAYMENT	METHOD OF PYMENT OR CREDIT CARD
7525594	02/14/21	CSB76	CT K5 73	CR	*** XXXX XXXX

LOCATION	QTY	PART	DESCRIPTION	O/S	PRICE	AMOUNT
B01 03 00	1	36-4288	TAIL LIGHT-LH W/TRIM		19.95	19.95
B01 05 01	1	36-4289	TAIL LIGHT-RH W/TRIM		19.95	19.95
C10 01 00	2	38-2239-BL	RETRACTABLE LAP SEAT BELT		59.95	119.90
E06 05 01	1	38-2833	BUCKET SEAT BACK SET 1 REQ		69.95	69.95
E06 15 01	2	38-2249-BL	LAP SEAT BELT-BLACK		24.95	49.90
E11 09 02	1	38-6925	CENTER CONSOLE-REPLACEMENT		99.95	99.95

**7525594**

8

Plus - B1

Run# 03: 83 of 96

**LONG  
MOTOR  
CORPORATION**

BACKORD - BACKORDERED, WILL SHIP WHEN AVAILABLE.  
TOS - TEMPORARILY OUT OF STOCK, CANCELLED, REORDER IN 3-4 WEEKS.  
TBA - TO BE ANNOUNCED (AVAILABILITY), PART HAS BEEN CANCELLED  
FROM ORDER, CHECK AVAILABILITY AT A FUTURE DATE.  
NLA - NO LONGER AVAILABLE, STOCK DEPLETED OR NO MANUFACTURER.

PARTS 379.60

**STD**SHIPPING  
CORES  
C.O.D.NOTES: SPLIT ORDER SEE  
W4499578STATE TAX 27.52  
SHIPMENT TOTAL 407.12

WARNING:  
Cancer and Reproductive Harm  
www.P65Warnings.ca.gov

THIS SHIPMENT COMPLETES THE ORDER

PAYMENT CREDIT 407.12

**Split Order**

**LMC TRUCK**

15450 W. 108TH STREET, LENEXA KS 66219  
800-562-8782 ORDERS-CATALOG REQUESTS-STATUS  
913-541-0684 WORLDWIDE ORDERS  
913-599-0323 FAX ORDERS

www.LMCTRUCK.com

**LMC  
TRUCK**

ORDER #

**W4499578**

DATE

02/14/21

PAGE 1

ORDER #	DATE	CATALOG	VEHICLE	PAYMENT	METHOD OF PYMENT OR CREDIT CARD
W4499578	02/13/21	CC A3	CT C10 87	VISA	**** * 8085

LOCATION	QTY	PART	DESCRIPTION	O/S	PRICE	AMOUNT
O/S 3P-253A	1	38-9883	REAR BUMPER-CHROME-PREMIUM	2	199.95	199.95

3G-051B

**W4499578**

1  
O/S - O  
Run# 64: 108 of 113

**LONG  
MOTOR  
CORPORATION**

NOTES:

7525594

BACKORD - BACKORDERED, WILL SHIP WHEN AVAILABLE.  
TOS - TEMPORARILY OUT OF STOCK, CANCELLED, REORDER IN 3-4 WEEKS.  
TBA - TO BE ANNOUNCED (AVAILABILITY), PART HAS BEEN CANCELLED  
FROM ORDER, CHECK AVAILABILITY AT A FUTURE DATE.  
NLA - NO LONGER AVAILABLE, STOCK DEPLETED OR NO MANUFACTURER.

**STD**

PARTS	199.95
	20.00
SHIPPING	40.75
CORES	
C.O.D.	

STATE TAX	14.50
SHIPMENT TOTAL	275.20

PAYMENT CREDIT	275.20
----------------	--------

THIS SHIPMENT COMPLETES THE ORDER



**WARNING:**  
Cancer and Reproductive Harm  
www.P65Warnings.ca.gov



• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250  
 • 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787  
 • 20 King Mill Road • McDonough, GA 30253 • 770-288-3200  
 • 2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700

Calling Customer Service?  
 Please have your  
 invoice number ready.

# INVOICE

INVOICE NUMBER DATE

1671849 02/11/21

CUSTOMER NUMBER PAGE

9997477 1

## EXCHANGE/RETURN FORM

INVOICE NUMBER DATE

1671849-2 02/11/21



**NOTE:** Please read the *How to Return an Order* instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ( )

### Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- Q. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other; please explain

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	WRN-20990	HUB FORD CHEVY DODGE JE		147.99	147.99 T
1	SUM-381536-KIT	FAN/SHROUD COMBO 2X13		303.95	303.95
1	SUM-381536	ALUM DUAL FAN SHROUD 2X1	S/S	149.99	149.99 T
2	SUM-G4903S	FAN 13IN ELEC S-BLADE	S/S	Shipped from Texas	
2	SUM-G4992	SS FAN MOUNTING HARDWARE		Kit Item	T
1	EDL-8036	BRCKT THRTTL CHEV		39.95	39.95 T
** DECLARED PART VALUE THIS SHIPMENT **				345.91 U.S.D.	
** TOTAL INVOICE CA SALES TAX **					25.09

Qty.	Part Number	Exchange	Refund	Qty.	Reason Code	Explanation
1	WRN-20990					
1	SUM-381536-KIT					
1	SUM-381536				S	
2	SUM-G4992					
1	EDL-8036					
** DECLARED VALUE				345.91		

**WARNING:** Proposition 65 Compliance Statement  
 California Safe Drinking Water & Toxic Enforcement Act of 1986  
 Some products purchased from our catalog or website contain chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm. Purchaser may receive full refund, including shipping costs, for return of unopened package within 30 days.

**NOTE:** If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.

\*Explanation of status column codes: B/D = backorder C/S = cancel ship S/S = shipped separate

Thank  
 You!

Credit Card Charge 527.55

Some parts are not legal for sale or use in California on any pollution controlled motor vehicles.

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:  
 GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

B66000211 CCU U0003566

## PRIORITY MAIL RETURNS® SERVICE

James Klunke  
 920 Calle Roble  
 Nipomo, CA 93444

Edr: 1671849

Summit Racing Equipment  
 Attn: Returns Dept.  
 2200 East Interstate 20  
 Arlington, Tx. 76018-9804

NO POSTAGE  
 NECESSARY IF  
 MAILED IN THE  
 UNITED STATES

## USPS TRACKING NUMBER



9201 9902 3186 9075 2410 82

# SPECIALTY GEAR AND TRANSMISSION

8910 EL CAMINO REAL  
ATASCADERO, CA 93422-5336  
Ph: (805) 462-9324 • Fax: (805) 462-9524  
WWW.specialtygear.net

Invoice #188

Service Writer: Service Writer

Date: 02/10/21 03:57 PM

1973 Chevy Truck Blazer 4X4

V8-350 4-bbl

Mileage: In 0 | Out 0

ITEM	DESCRIPTION	QUANTITY	PRICE	TOTAL
Transmission Overhaul				2000.00
Flat Fee	Convert transfer case from NP203 to NP205			2000.00
Note	Custom Note: 1500.00 to 2000.00			

Authorizer	Date	Authorization Method	Shop Representative	Add. Amount	Total
James Klunke	2/10/21 (03:56pm)	In Person	Service Writer	(Original Estimate)	\$2000.00

## Payments:

Date	Method	Reference #	Amount Paid
2/10/21 (03:59PM)	Cash		\$500.00
Total Payments			\$500.00

Parts:	\$0.00
Labor:	\$0.00
Flat Fees:	\$2000.00
Shop Supplies:	\$0.00
HazMat:	\$0.00
Subtotal:	\$2000.00
Total Tax:	\$0.00

Invoice Total:	\$2000.00
Payments	-\$500.00
Balance:	\$1500.00



# All Automatic Transmission Rebuild

70 Prado Rd.

San Luis Obispo, CA 93401

## Repair Order

B.A.R. ARD00253730

805-543-2660

EPA NO.  
CAL000385061

Date	Invoice #
2/9/2021	30694

Customer Name
Estimate: _____ Revised Estimate: _____ Phone Approval: _____ Date: _____ Time: _____

P.O. Number	ALCRA 103
-------------	-----------

Vehicle	1973 Chevy Blazer
License	
Vin	
Engine	350
Transmission	TH350
Mileage	56,XXX

Quantity	Description	Rate	Amount
1	Master Rebuild Kit	275.00	275.00T
1	GM 350 Remanufactured Torque Converter	199.95	199.95T
1	Pump Complete	100.00	100.00T
1	Direct Drum	45.00	45.00T
6	Rebuild Transmission as Necessary	125.00	750.00
(MERCON/DEXRON BLEND)			
Ø SYNTHETIC			
9 QTS			

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. I understand that All Automatic Trans. is not an insurer of said vehicle and will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Credit Card Transactions will incur a 2.79% fee.

Authorized By \_\_\_\_\_

Subtotal	\$1,369.95
Sales Tax (7.75%)	\$48.05
Total	\$1,418.00



• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250  
 • 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787  
 • 20 King Mill Road • McDonough, GA 30253 • 770-288-3200  
 • 2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700

Calling Customer Service?  
 Please have your  
 invoice number ready.

# INVOICE

INVOICE NUMBER	DATE
9727733	01/29/21
CUSTOMER NUMBER	PAGE
9997477	1

## EXCHANGE/RETURN FORM

INVOICE NUMBER	DATE
9727733-3	01/29/21



**NOTE:** Please read the *How to Return an Order* instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ( )

### Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- Q. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other; please explain

QTY	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	ENS-3-1106G	TRANSMISSION MOUNT	\$/S	Shipped from Ohio	
1	EDL-9265	SQ BORE HEAT INSULATOR		23.95	23.95 T
1	OER-3989349	1969-92 ALUMINUM VALVE C		6.99	6.99 T
1	SUM-G3418	BREATHER CAP PUSH PVC CH	\$/S	Shipped from Texas	
1	RNB-42323	PCV VALVE GROMMET		3.99	3.99 T
1	ADO-CV774C	PCV VALVE		12.99	12.99 T

Warranty	Part Number	Exchange	Refund	Qty.	Reason Code	Explanation
IAN	NV					
	EDL-9265					
	OER-3989349					
	RNB-42323					
	ADO-CV774C					

**WARNING:** Proposition 65 Compliance Statement  
 California Safe Drinking Water & Toxic Enforcement Act of 1986  
 Some products purchased from our catalog or website contain chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm. Purchaser may receive full refund, including shipping costs, for return of the defective package within 30 days. and complete the attached Exchange/Return Form.

**NOTE:** No costs for return of the defective package within 30 days. and complete the attached Exchange/Return Form.  
 \*Explanation of status: \*\* TOTAL INVOICE CA SALES TAX

47.92 U.S.D.  
 3.47

Credit Card Charge 132.93

\*\* DECLARED VALUE 47.92

Some parts are not legal for sale or use in California on any pollution controlled motor vehicles.



• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250  
 • 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787  
 • 20 King Mill Road • McDonough, GA 30253 • 770-288-3200  
 • 2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700


Calling Customer Service?  
 Please have your  
 invoice number ready.

# INVOICE

INVOICE NUMBER	DATE
9045943	01/28/21
CUSTOMER NUMBER	PAGE
9997477	1

## EXCHANGE/RETURN FORM

INVOICE NUMBER	DATE
9045943-6	01/28/21



**NOTE:** Please read the *How to Return an Order* instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ( )

### Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- Q. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other; please explain

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.	Qty.	Part Number	Exchange	Refund	Qty.	Reason Code	Explanation
1	AAZ-20-6000	PWR STRNG		38.99	38.99 T	1	AAZ-20-6000					
	Note: One or more items on this order contain a core charge. Note: For instructions about how to return the core for credit, Note: please use one of these options: Search "Core Charge" in Note: Frequently Asked Questions at SummitRacing.com for refund Note: info or send an e-mail to CustomerService@SummitRacing.com. Note: You may also call Customer Service at 1-800-517-1035. Note: Cores must be returned within 90 days of purchase, and Note: customers are responsible for return shipping.											
		CORE CHARGES		25.00	25.00 T							
1	FEL-35062	GASKET		1.99	1.99 T	1	FEL-35062					
1	FEL-70194	BASE GASKET		1.99	1.99 T	1	FEL-70194					
1	SUM-G9200N	EXHAUST MANIFOLD NATURAL		168.99	168.99 T	1	SUM-G9200N					
1	ADO-252-592	ENGINE WATER PUMP		53.99	53.99 T	1	ADO-252-592					
1	SUM-810344	ALT GM AS CAST 140A V PU		119.99	119.99 T	1	SUM-810344					
1	RSD-TPC7301	FUEL LINE		18.00	18.00 T	1	RSD-TPC7301					
1	DFP-MF0001	MECHANICAL FUEL PUMP		19.99	19.99 T	1	DFP-MF0001					
1	FRM-FV178	PCV VALVE		3.99	3.99 T	1	FRM-FV178					
1	EDL-2701	MANIFOLD		149.95	149.95 T	1	EDL-2701					
1	PRS-1001	HEATER HOSE FITTING	S/S	Shipped from Texas								
1	SUM-G1484N	ALUM 6PC PLUG KIT 3/8"		11.99	11.99 T	1	SUM-G1484N					
1	MIL-85400	SBC INTAKE BOLTS		10.95	10.95 T	1	MIL-85400					
1	SUM-110503	INTAKE MANIFOLD GASKET		14.99	14.99 T	1	SUM-110503					

**NOTE:** If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.

\*Explanation of status column codes: B/D = backorder C/S = cancel ship S/S = shipped separate

Thank  
 You!



• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250  
 • 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787  
 • 20 King Mill Road • McDonough, GA 30253 • 770-288-3200  
 • 2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700

# INVOICE

Calling Customer Service?  
 Please have your  
 invoice number ready.

INVOICE NUMBER	DATE
9045943	01/28/21
CUSTOMER NUMBER	PAGE
9997477	2

## EXCHANGE/RETURN FORM

INVOICE NUMBER	DATE
9045943-6	01/28/21

**NOTE:** Please read the *How to Return an Order* instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ( )

### Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- O. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other; please explain

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	NAL-10108470	Thermostat housing		5.09	5.09 T
1	ICB-551411	ALTERNATOR BRACKET ADJUS		30.99	30.99 T
2	PIO-602292	ENGINE MOUNT		10.99	21.98 T
1	DEM-1901	625 CFM STREET DEMON CAR		337.95	337.95 T
1	SUM-G5211	HEI POWER PIGTAIL		5.99	5.99 T
1	SUM-850001-1	DIST CHEVY HEI RED CAP		99.99	99.99 T
1	SUM-868836R	RED SPARK PLUG WIRE SET	S/S Shipped from Ohio		
1	SUM-384029	81-90 GM TRUCK ALUM RADI	S/S Shipped from Texas		
1	SUM-G30010B	14" A/C BLACK FLAT PE		24.99	24.99 T

Core charge present. Please use the FAQ's or 'Ask a Question' tools on our Customer Service page at [www.summitracing.com](http://www.summitracing.com) to find out more.

**WARNING:** Proposition 65 Compliance Statement  
 California Safe Drinking Water & Toxic Enforcement Act of 1986  
 Some products purchased from our catalog or website contain chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm. Purchaser may receive full refund, including shipping costs, for return of unopened package within 30 days.

\*\* DECLARED PART VALUE THIS SHIPMENT \*\* 1142.78 U.S.D.  
 \*\* TOTAL INVOICE CA SALES TAX \*\* 84.65

Qty.	Part Number	Exchange	Refund	Qty.	Reason Code	Explanation
1	NAL-10108470					
1	ICB-551411					
2	PIO-602292					
1	DEM-1901					
1	SUM-G5211					
1	SUM-850001-1					
1	SUM-G30010B					

\*\* DECLARED VALUE 1142.78

**NOTE:** If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.  
 \*Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

Thank  
 You!

Credit Card Charge 1622.42

Some parts are not legal for sale or use in California on any pollution controlled motor vehicles.

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:  
 GO TO [WWW.SUMMITRACING.COM](http://WWW.SUMMITRACING.COM) AND CLICK THE ORDER STATUS LINK.

S16550127 CCU U0010967

## PRIORITY MAIL RETURNS® SERVICE

James Klunke  
 920 Calle Roble  
 Nipomo, CA 93444  
 Odr: 9045943

Summit Racing Equipment  
 Attn: Returns Dept.  
 2200 East Interstate 20  
 Arlington, Tx. 76018-9804

NO POSTAGE  
 NECESSARY IF  
 MAILED IN THE  
 UNITED STATES

USPS TRACKING NUMBER



9201 9902 3186 9074 0274 58

DATE 8-13-2019

INVOICE # \_\_\_\_\_

805-481-8468  
velocitytint.com1351 W Grand Ave  
Grover Beach, CA 93433

## CUSTOMER INFORMATION

Name \_\_\_\_\_  
Email \_\_\_\_\_  
Address \_\_\_\_\_  
City \_\_\_\_\_  
Phone \_\_\_\_\_

## VEHICLE INFORMATION

Year 1973  
Make Chery  
Model Blazer  
VIN# \_\_\_\_\_  
Film Type 3M FT  
3M CS

## JOB DESCRIPTION

HOME ☐ AUTO ☐ OFFICE ☐

## AMOUNT

+2 35%  
Back 1/2 20%\$325

APPROVED BY CUSTOMER

SHOP REPRESENTATIVE

Paid In Full \_\_\_\_\_ Deposit Amount \_\_\_\_\_ NET \_\_\_\_\_ Days

## Warranty

1-Year \_\_\_\_\_  
3-Year \_\_\_\_\_  
10-Year \_\_\_\_\_  
Lifetime \_\_\_\_\_  
Premium Lifetime X

Warranty Details On Reverse Side



Fastenal  
P.O Box 978  
WINONA, MN 55987-0978

# Invoice

Cust. No. BACA0033

Cust. P.O.

Job No.

Sold To

The store serving you is  
2220 A Street Unit102

SANTA MARIA, CA 93455

Phone #: (805)925-7425

Fax #: (805)349-0161


Date 7/23/19  
Reference No. CABAR100588  
Page 1  
DUE DATE: 08/15/2019

This Order and Document are subject to the "Terms of Purchase" posted on [www.fastenal.com](http://www.fastenal.com).

Line No.	Quantity Ordered	Quantity Shipped	Quantity Backorder	Description	Control No.	Part No.	Price / Hundred	Amount
1	1	1		0 1/4INDPLUG1/4NPT FEM	240179474	430017	167.0000	1.67 N
2	1	1		0 1/4INDPLUG1/4NPTMALE	240164596	430020	198.0000	1.98 N
3	25	25		0 5/16-18X5/8S/S BHSCS	240132510	1173778	38.9600	9.74 N

Visa Account # XXXXXXXXXXXXX7413 Exp XX/XX

Cardmember acknowledges receipt of goods or services in the amount of the total shown hereon and agrees to perform the obligations set forth by the cardmember's agreement with the issuer.

  
X

Card Member Signature

Received By

Tax Exemption

No Exemption

Comments

Contact: JAMES KIUNKE Phone: 45646

CA

Subtotal	13.39
Shipping & Handling	0.00
State Tax	0.80
County Tax	0.24
City Tax	0.13
<b>TOTAL USD</b>	<b>14.56</b>

If you re-package or re-sell this product, you are required to maintain integrity of Country of Origin to the consumer of this product.

Reasonable collection and attorneys fees will be assessed to all accounts placed for collection  
No materials accepted for return without our permission.

X indicates part is a hazardous material

\* indicates part was sold at a promotional or special discount price

This is your invoice.

All discrepancies must be reported within 10 days.

\*0\*

Thank You !

**Denny's Driveshafts**

1189 Military Road  
Kenmore, NY 14217  
(800) 955-1872 **Phone - Orders Only**  
(716) 875-6640 **Phone - Customer Service,**  
**Tech Line & Pricing questions**  
[www.DennysDriveshaft.com](http://www.DennysDriveshaft.com)  
[Sales@DennysDriveshaft.com](mailto:Sales@DennysDriveshaft.com)

**Order #:** 99567  
**Status:** Paid  
**Date:** 07/20/2019 23:26:47  
**Updated:** 07/20/2019 23:28:57

**Salesperson:**

**Bill To:**

Name  
Address  
City  
State/Province  
ZIP/Postal Cod  
Country  
Phone  
E-Mail

**Ship To:****Payment Method:**

Credit Card  
Visa - James Kiunke - XXXXXXXXXXXX5605 Exp: 11/2019

**Shipping Method:**

Free Ground Shipping on Parts Orders Over \$99 @ \$0.00

Qty	Part Number	Name	Price	Each	Subtotal
2	5-760X	<u>Dana Spicer 5-760X Front Axle Universal Joint for CHEVY and GMC 1973 and ne</u>	\$18.50	\$18.50	\$37.00
2	SET 37	<u>TIMKEN Bearings SET 37 Front INNER WHEEL BEARING Fits 1957 to 1977 Chevy GM</u>	\$13.95	\$13.95	\$27.90
2	SET 45	<u>TIMKEN Bearings SET 45 Front OUTER WHEEL BEARING Fits 1957 to 1977 Chevy GM</u>	\$13.55	\$13.55	\$27.10
2	706527X	<u>Dana Spicer 706527X Spindle Bearing and Seal Set fits 1973 and newer Chevy</u>	\$9.95	\$9.95	\$19.90
2	471271	<u>Timken 471271 Front Wheel Seal 1973 to 1987 Chevy GMC K10, K15 4X4 1/2 Ton</u>	\$5.25	\$5.25	\$10.50
2	36352	<u>SPICER 36352 Dana 44 TUBE Seal fits 1972 to 1977 K5, K10 and K20</u>	\$3.60	\$3.60	\$7.20
2	36364	<u>Dana Spicer 36364 Seal Retainer for Outer Axle Shaft fits 1973 and newer Ch</u>	\$3.50	\$3.50	\$7.00
2	31624	<u>Snap Ring for Outer Axle Shafts DANA 44</u>	\$0.80	\$0.80	\$1.60

**PAID**

Subtotal: \$138.20  
Shipping (Free Ground Shipping on Parts Orders Over \$99) : \$0.00  
Sales Tax: \$0.00  
Grand Total: \$138.20