

Reg Beer Coachbuilder Corp
 12944 Albion Vaughan Rd. Bolton Ont. L7E 4C6
 Telephone\ Fax; (905) 857-3210. Email cmcmog@idirect.ca
 GST # 12178 9812 RT

18 June 2007

Repair Estimate;

1963 Jaguar MK2 Lic. AHHA 137 Mi. 7695 VIN # 222752

Re & Re head light, driving light, park & turn ind light	3.0 Hrs	
Re & Re front bumper assembly & re-align	4.5 Hrs	
Re & Re coolant tank	.75 Hrs	
Re & Re grille	3.0 Hrs	
Repair left front fender	20.0 Hrs	
Prep & paint fender	17.0 Hrs	
Flat & polish paintwork	7.0 Hrs	
Re-undercoat front fender	2.0 Hrs	
Paint formulation & tint matching	<u>3.0 Hrs</u>	
	60.25 Hrs	
60.25 Hrs. @ 70.00		\$4217.50
Materials	\$350.00	
1- front lamp assembly	<u>\$159.60</u>	
	\$509.60	\$509.60
<u>Sublet;</u>		
Re-chrome bumper guard		<u>\$200.00</u>
		4927.10
	GST	\$295.62
	PST	<u>\$394.17</u>
	Total	\$5616.89

GARAGE REPAIR ORDER

KEN BROWNE (SERVICE)
960 BATHURST ST. TOR.
M5R 3G5
416-588-1998

ENGINE
OVERHAUL

039650

MATERIALS			
QTY.	PART NO.	DESCRIPTION	PRICE
Motor Mount	42.17	Gasket Set	256 81
Starter Motor	426.80	Filter Head Gasket	168 92
Clutch Slave Kit	62.71	Hardware	26 00
Brake Fluid	26.00	Bat. Switch	18 95
Piston Rings	195.95	12 Lt. 20-50	59 40
Main Brgs	224.95	Clutch Fluid	10 00
Rod Brgs	234.92	Flex Hose	62 19
Thrust Brgs	56.21	Oil Pump	118 22
Front Seal	38.24	2 Seals	10 00
Rear Seal	109.16	A/c Oil	2 00
Housing Gasket	6.18	Terminal	1 50
Oil Filter	28.95	Hardware	22 20
Pressure Valve	61.92	4 O Rings	20 00
Chain Cover ^{used}	262.00	Alum. Polish	6 00
Top Chain	98.72	Steering Fluid	6 85
Bottom Chain	82.46	Trans Oil	6 00
Tensioner	76.90	Therm Housing	118 24
Fan Shroud	268.90	Thermostat	38 90
Freon R12A	135.00	Ant. Freeze	36 00
Stab Bush	18.20	Gasoline	25 00
Starter Cable	21.98	TOTAL PARTS	
QTY.	PART NO.	ACCESSORIES	PRICE
Terminal Block	13.80	Copper Hardware	40 80
2 Sock Mounts	72.48	6 O/D Del Washers	34 92
6 Valve Seals	40.22	2 Banjo Bolts	85 92
13 Support Packs	85.92	16 Brass Nuts	52 48
6 Ex. Springs	59.41	2 Head Nuts	27 32
Machining	152.80	2 Spring Sclles	12 28
2 Carb Kits	186.32	TOTAL ACCESSORIES	1373 20

DATE 25 Sept 08		
MAKE Jaguar	MODEL 3.8 Mk III	TAX REG. NO.
SERIAL NO.	MOTOR NO.	PROMISED AM. PM.
ODOMETER 08071	LICENCE NO.	TERMS
WRITTEN BY	PHONE WHEN READY <input type="checkbox"/> QUI/YES <input type="checkbox"/> NON/NO	

OPERATION NO.	INSTRUCTIONS
2 Ex Champs 7.90 2 O Rings 9.27 4 Drive Shafts 12.80 6 Hose Clamps 21.00	Decarb + Reset Cyl. Head. Rebuild Bottom End - New Brgs, Seals, Piston Rings etc. - Mains O/D, Rods O/D, Bores O/D
Clutch Disk 217.02 Pushrod 2.50 Clutch Brg 47.61	Replace Clutch Disk. Rekit Slave Cyl. Bleed all Brakes + Replace Fluids. Fit New Fan Shroud. Replace Therm Housing and Chain Covers. Cleanup + Repair Front Suspension while off Car. Fit New Steering Wheel. Reset toe in. Rebuild Cables
3 Clips 1.58 Clutch Hard 14.68 6 Carb Cleaner 89.70 Paint Under. 36.42 Tach Drive 18.02	Fit New Bat Switch. Tune Motor. Road test
6 Plugs 62.70 Total 541.20	Labour 8 1/2 hrs @ 89 ⁰⁰ - 7342.50

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.

Paid on Account \$10,000⁰⁰

AUTHORIZED BY

LABOUR	AMOUNT
LUBRICATION <input type="checkbox"/>	
CHANGE OIL <input type="checkbox"/>	
CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REPLACE OIL FILTER <input type="checkbox"/>	
CLEAN AIR FILTER <input type="checkbox"/>	
REPACK FRONT WHEELS <input type="checkbox"/>	
ADJUST BRAKES <input type="checkbox"/>	
ROTATE TIRES <input type="checkbox"/>	
WASH <input type="checkbox"/> POLISH <input type="checkbox"/>	
TUNE MOTOR <input type="checkbox"/>	

TOTAL LABOUR	7342 50
TOTAL PARTS	3087 27
TOTAL ACCESSORIES	1373 20
TOTAL SUB CONTRACT	12344 17
TOTAL GAS-OIL-GREASE	
GST	617 21
PST	987 53
TOTAL	13948 91

GAS, OIL, & GREASE	
QTY.	PRICE
LITERS GAS	
LITERS OIL	
GREASE	
TOTAL	

FORM 4811E

Total 3087.27

GARAGE REPAIR ORDER

KEN BROWNE (SERVICE)
 960 BATHURST ST. TOR.
 M5R 3G5
 416-588-1988

240475

MATERIALS			
QTY.	PART NO.	DESCRIPTION	PRICE
		Fuel Float	38.97
		Seal	5.00
		Oil Delivery Pipe	171.84
6		Washers	16.56
6		Plugs	87.90
		Exhaust Clamp	6.70
		Welding Supplies	15.00
		Hardware	2.50
		T.O. (Rover St.)	3.00
Total			347.47

		DATE	
MAKE	MODEL	YEAR	TAX REG. NO.
Jaguar	3.8 MK II		
SERIAL NO.	MOTOR NO.	PROMISED	A.M. P.M.
ODOMETER	LICENCE NO.	TERMS	PHONE WHEN READY
08135			<input type="checkbox"/> OUI/YES <input type="checkbox"/> NON/NO
WRITTEN BY	RES. PHONE	BUS. PHONE	

LABOUR	AMOUNT
LUBRICATION <input type="checkbox"/>	
CHANGE OIL <input type="checkbox"/>	
CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REPLACE OIL FILTER <input type="checkbox"/>	
CLEAN AIR FILTER <input type="checkbox"/>	
REPACK FRONT WHEELS <input type="checkbox"/>	
ADJUST BRAKES <input type="checkbox"/>	
ROTATE TIRES <input type="checkbox"/>	
WASH <input type="checkbox"/> POLISH <input type="checkbox"/>	
TUNE MOTOR <input type="checkbox"/>	

OPERATION NO.	INSTRUCTIONS
6 3/4 hr. @ 89 ⁰⁰	600.75
Car towed in to shop. Running Poorly. Replace Spark Plugs - (Fouled) Check Wiring & Distributor - OK. Check Carb Fuel Bowls. - Replace One Fuel Float. Reset Carbs. Blow out Air Filter. Torque Cyl. Head. Check Exhaust. Main Mufflers are Rusted & Leaking - Weld Mufflers as temporary Repair. Order New Mufflers/system. Remove Bonnet, Tach Drive, Power Steering Reservoir to gain access to Oil Delivery Pipe. Fit New Aircraft Style Pipe. Retit all. No Oil Change Yet.	
Note - Order S.S. Main Mufflers. 877.27	
TOTAL PARTS	

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.		TOTAL LABOUR	600.75
		TOTAL PARTS	347.47
		TOTAL ACCESSORIES	948.22
		TOTAL SUBCONTRACT	
		TOTAL GAS-OIL-GREASE	
		GST	47.41
		PST	75.86
		TOTAL	1071.49

QTY.	PART NO.	ACCESSORIES	PRICE
TOTAL ACCESSORIES			

GAS, OIL, & GREASE	
QTY.	PRICE
LITERS GAS	
LITERS OIL	
GREASE	
TOTAL	

GARAGE REPAIR ORDER

KEN BROWNE (SERVICE)
980 BATHURST ST. TOR.
M5R 3G5
416-588-1988

STAINLESS
SPECIAL EXHAUST

240488

QTY.	PART NO.	DESCRIPTION	PRICE
		Fuel Filter	21.95
		Fuel Hose	10.00
		Brass Fitting	6.90
4		Clamps	10.80
		Stainless Exhaust Kit	195.60
4		Exh. Mounts	1493.84
		Hardware	14.82
		Fuse	1.65
		R12A Freon	135.00
		A/C Oil	2.00
Total			1892.56

			DATE 4 May 09	
MAKE	MODEL	YEAR	TAX REG. NO.	
Jaguar MKII 3.8				
SERIAL NO.	MOTOR NO.		PROMISED	A.M. P.M.
ODOMETER	LICENCE NO.	TERMS	PHONE WHEN READY	
08341	AHHA 137		<input type="checkbox"/> OUI/YES <input type="checkbox"/> NON/NO	
WRITTEN BY	RES. PHONE	BUS. PHONE		

LABOUR	AMOUNT
LUBRICATION <input type="checkbox"/>	
CHANGE OIL <input type="checkbox"/>	
CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REPLACE OIL FILTER <input type="checkbox"/>	
CLEAN AIR FILTER <input type="checkbox"/>	
REPACK FRONT WHEELS <input type="checkbox"/>	
ADJUST BRAKES <input type="checkbox"/>	
ROTATE TIRES <input type="checkbox"/>	
WASH <input type="checkbox"/> POLISH <input type="checkbox"/>	
TUNE MOTOR <input type="checkbox"/>	

		LABOUR 7 3/4 hrs @ 89 ⁰⁰	645.25
TOTAL PARTS			

OPERATION NO. **INSTRUCTIONS**

Replace Main Mufflers and tail pipe. Fit 4 New Mounts. Fit In line Fuel Filter in series with Fuel Bowl. Check Ign. Coil-ok. Reset Carbs, Mixture & Idle & Check Ign. timing. Check Operation of A/C. System low. Evacuate & check for leaks. None Found. Charge with R12A. Check Overdrive lamp. - Wire Rubbing on Column. Repair Wiring. Road test. Alter Mirror Arm.
Order Speedo Cable.

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.		TOTAL LABOUR	645.25
I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.		TOTAL PARTS	1892.56
		TOTAL ACCESSORIES	2537.81
GAS, OIL, & GREASE		TOTAL SUBCONTRACT	
		TOTAL GAS-OIL-GREASE	
		GST	126.89
		PST	203.02
		TOTAL	2867.72

		Note - Labour Reduced by <u>1 hr</u>	
TOTAL ACCESSORIES			

GARAGE REPAIR ORDER

KEN BROWNE (SERVICE)
980 BATHURST ST. TOR.
M5R 3G5
416-588-1996

~~CLUTCH~~
OUTER HOUL.

030149

QTY.	PART NO.	DESCRIPTION	PRICE
		Clutch Master Cyl.	328.42
		Brake Fluid	8.00
		Hardware	4.20
		Total	330.62

Labour 4 1/4 hr. @ 94⁰⁰ 399.50

			DATE 19 Oct 09	
MAKE Jaguar	MODEL Mk II	YEAR 3.8	TAX REG. NO.	
SERIAL NO.	MOTOR NO.	PROMISED		A.M. P.M.
ODOMETER 08618	LICENCE NO.	TERMS	PHONE WHEN READY <input type="checkbox"/> QUI/YES <input type="checkbox"/> NON/NO	
WRITTEN BY	RES. PHONE	BUS. PHONE		

LABOUR	AMOUNT
LUBRICATION <input type="checkbox"/>	
CHANGE OIL <input type="checkbox"/>	
CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REPLACE OIL FILTER <input type="checkbox"/>	
CLEAN AIR FILTER <input type="checkbox"/>	
REPACK FRONT WHEELS <input type="checkbox"/>	
ADJUST BRAKES <input type="checkbox"/>	
ROTATE TIRES <input type="checkbox"/>	
WASH <input type="checkbox"/> POLISH <input type="checkbox"/>	
TUNE MOTOR <input type="checkbox"/>	

OPERATION NO.	INSTRUCTIONS	
	Transmission will not go in to Gear - Check Hydraulics. Remove Brake Master cyl, Power St. Reservoir, Brake Fluid Reservoir etc. Replace Clutch Master cyl. & Bleed system. Adjust Clutch. Road test.	

QTY.	PART NO.	ACCESSORIES	PRICE
		TOTAL PARTS	
		TOTAL ACCESSORIES	

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.			TOTAL LABOUR	399.50
			TOTAL PARTS	330.62
			TOTAL ACCESSORIES	730.12
			TOTAL SUBCONTRACT	
			TOTAL GAS-OIL-GREASE	
			GST	36.51
			PST	58.41
		TOTAL	TOTAL	825.04

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.

GAS, OIL, & GREASE	
QTY.	PRICE
LITERS GAS	
LITERS OIL	
GREASE	
TOTAL	

GARAGE REPAIR ORDER

KEN BROWNE (SERVICE)
980 BATHURST ST. TOR
M5R 3G5
416-588-1998

24k
Repairs

240437

MATERIALS			
QTY.	PART NO.	DESCRIPTION	PRICE
7		Lt. 20-50	56.16
		Oil Filter	28.95
		Fuel Solvent	2.65
		Brake Fluid	2.00
		Air Filter	23.79
		Cam Cover Gasket total	32.76
		Shop Supplies	3.00
		Flasher Unit	38.90
		Total	188.21

			DATE 15 April 10	
MAKE Jaguar	MODEL MKII 3.8	YEAR 64	TAX REG. NO.	
SERIAL NO. 223752	MOTOR NO.	PROMISED	A.M. P.M.	
ODOMETER 08854	LICE			
WRITTEN BY				

LABOUR	AMOUNT
LUBRICATION <input type="checkbox"/>	
CHANGE OIL <input type="checkbox"/>	
CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REPLACE OIL FILTER <input type="checkbox"/>	
CLEAN AIR FILTER <input type="checkbox"/>	
REPACK FRONT WHEELS <input type="checkbox"/>	
ADJUST BRAKES <input type="checkbox"/>	
ROTATE TIRES <input type="checkbox"/>	
WASH <input type="checkbox"/> POLISH <input type="checkbox"/>	
TUNE MOTOR <input type="checkbox"/>	

Labour 6 1/2 hr @ 94.00 611.00

OPERATION NO.	INSTRUCTIONS
	Change Oil & Filter. Lubricate & check all Levels. Check Hoses & Belts. - Major Oil leak down LM Side of Motor. - Exhaust Cam Cover is Cracked. Remove Cover and Repair with J.B. Weld. Refit & test - Ok. Replace Air Filter. - Reset throttle Linkages - Check plugs - Ok. Check Dush pots & Reset Mixture & Idle. Pressure for Cooling System. Remove fan signal Switch and clean Points & tighten Rivets. Replace Flasher Unit. (Original Lucas Fitted) Road test.

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.

TOTAL LABOUR	611.00
TOTAL PARTS	188.21
TOTAL ACCESSORIES	799.21

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.

GAS, OIL, & GREASE			
QTY.	PRICE	TOTAL SUBCONTRACT	
LITERS GAS		TOTAL GAS-OIL-GREASE	
LITERS OIL			
GREASE		GST	39.96
		PST	63.94
		TOTAL	903.11

QTY.	PART NO.	ACCESSORIES	PRICE
		TOTAL PARTS	
		TOTAL ACCESSORIES	

GARAGE REPAIR ORDER

KEN BROWN (SERVICE)
 960 BATHURST ST. TOR.
 M5R 3G5
 416-588-1890

003830

QTY.	PART NO.	DESCRIPTION	PRICE
9/2		Lt. 10-40	59.85
		Oil Filter	24.95
		Fuel Solvent	2.65
		Carb Cleaner	14.95
		Speedo Cable	87.61
5 3/4		Anti freeze	36.51
Total			226.52
Also For E type Wrench			125.80
Pouch			25.54
Total			151.34

			DATE 12 Oct 10	
MAKE Jaguar	MODEL Mk # 3.4	YEAR	TAX REG. NO.	
SERIAL NO.	MOTOR NO.	PROMISED	A.M. P.M.	
ODOMETER 09172	LICE			
WRITTEN BY				

LABOUR	AMOUNT
LUBRICATION <input type="checkbox"/>	
CHANGE OIL <input type="checkbox"/>	
CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REPLACE OIL FILTER <input type="checkbox"/>	
CLEAN AIR FILTER <input type="checkbox"/>	
REPACK FRONT WHEELS <input type="checkbox"/>	
ADJUST BRAKES <input type="checkbox"/>	
ROTATE TIRES <input type="checkbox"/>	
WASH <input type="checkbox"/> POLISH <input type="checkbox"/>	
TUNE MOTOR <input type="checkbox"/>	

OPERATION NO.	INSTRUCTIONS
	Change Oil + Filter. Lubricate + check all Levels. Drain + Replace Anti freeze. Check Hoses + Belts. Pressure test. Blow out Air Filter. Clean spark Plugs. Clean Carb + Wash jets + Reset mixtures. Lub + Reset throttle Linkages. Torque Cyl Head. Check Charging. Remove Speedo Head and Fit New Speedo Cable. Check tyre pressures, Horn Wipers etc. Road test. Put Wheel Wrench for E type in trunk.

TOTAL PARTS		TOTAL LABOUR	540.50
TOTAL ACCESSORIES		TOTAL PARTS	151.34
TOTAL ACCESSORIES		TOTAL ACCESSORIES	226.52
TOTAL ACCESSORIES		Total	918.36
TOTAL ACCESSORIES		HST GST	119.39
TOTAL ACCESSORIES		PST	
TOTAL ACCESSORIES		TOTAL	1037.75

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.

GAS, OIL, & GREASE	
QTY.	PRICE
LITERS GAS	
LITERS OIL	
GREASE	
TOTAL	

TOTAL SUBCONTRACT		918.36
TOTAL GAS-OIL-GREASE		
HST GST		119.39
PST		
TOTAL		1037.75

GARAGE REPAIR ORDER

KEN DROWN (SERVICE)
980 BATHURST ST. TOR
M5R 3G5
416-588-1998

003845

MATERIALS	QTY.	PART NO.	DESCRIPTION	PRICE
	4		Carb Kits	543.88
	2		Air Filters	97.20
			Fuel Hose	12.50
	4		Clamps	14.00
			Fuel Filter	24.11
	2		Fuel Solvent	5.30
			Total	696.99
			7 1/4	681.50
			Labour @ 94.00	775.50

			DATE 16 Dec. 10
MAKE Jaguar	MODEL E V12	YEAR	TAX REG. NO.
SERIAL NO.	MOTOR NO.	PROMISED	A.M. P.M.
ODOMETER 96641	LIC		
WRITTEN BY			

LABOUR	AMOUNT
LUBRICATION <input type="checkbox"/>	
CHANGE OIL <input type="checkbox"/>	
CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REPLACE OIL FILTER <input type="checkbox"/>	
CLEAN AIR FILTER <input type="checkbox"/>	
REPACK FRONT WHEELS <input type="checkbox"/>	
ADJUST BRAKES <input type="checkbox"/>	
ROTATE TIRES <input type="checkbox"/>	
WASH <input type="checkbox"/> POLISH <input type="checkbox"/>	
TUNE MOTOR <input type="checkbox"/>	

OPERATION NO.	INSTRUCTIONS
	<p>Car towed into shop. Carbs are Flooding Badly. Remove all Four Carbs & Rekit. Refit all & Adjust. Replace Fuel Hoses as Necessary. Plugs Recently Replaced but Remove & Clean. Replace Air filters. Road test at Operate time. Fit inline Fuel Filter.</p> <p>Also - Reoperate Inst. Lamps on Dash - Fault is in Contact in Side Lamp Switch - Remove switch & Clean Contacts - OK.</p>

QTY.	PART NO.	ACCESSORIES	PRICE
		TOTAL PARTS	
		TOTAL ACCESSORIES	

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.		TOTAL LABOUR	681.50
I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.		TOTAL PARTS	696.99
		TOTAL ACCESSORIES	1378.49
GAS, OIL, & GREASE		TOTAL SUBCONTRACT	
		TOTAL GAS-OIL-GREASE	
		HST GST	179.20
		PST	
AUTHORIZED BY		TOTAL	1557.69

GARAGE REPAIR ORDER

KEN BROWN (SERVICE)
980 BATHURST ST. TOR.
MSR 365
416-599-1990

061498

MATERIALS

QTY.	PART NO.	DESCRIPTION	PRICE
9 1/2	LT.20-50		60 33
		Oil Filter	
		Brake Fluid	32 00
		Front Brake Pads	97 95
		Carb Cleaner	3 00
		Brake Cleaner	14 95
Total			208 23
Labour 4 1/2 hr. @ 94.00			423 00

DATE 27 May 11		
MAKE Jaguar	MODEL MLFF 3.8	YEAR 64
SERIAL NO. 223752	MOTOR NO.	PROMISED
ODOMETER 09478	LICENCE NO. AHHA137	TERMS
WRITTEN BY	RES. PHONE	PHONE WHEN READY <input type="checkbox"/> QUI/YES <input type="checkbox"/> NON/NO
		BUS. PHONE

LABOUR	AMOUNT
LUBRICATION <input type="checkbox"/>	
CHANGE OIL <input type="checkbox"/>	
CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REPLACE OIL FILTER <input type="checkbox"/>	
CLEAN AIR FILTER <input type="checkbox"/>	
REPACK FRONT WHEELS <input type="checkbox"/>	
ADJUST BRAKES <input type="checkbox"/>	
ROTATE TIRES <input type="checkbox"/>	
WASH <input type="checkbox"/> POLISH <input type="checkbox"/>	
TUNE MOTOR <input type="checkbox"/>	

OPERATION NO.	INSTRUCTIONS
	Change Oil - No filter change - Lubricate & check levels. Check hoses & Belts. Safety Check Steering & Brakes. Replace Front Brake pads. Flush Brake Fluid and Fill Fresh Fluid. Check Plugs - ok. Service Distributor. Topup Dash pots & Reset Mixture & Idle. Blow out Air Filter. Check Lights, Wipers etc & Topup Washer Fluid. Bleed Clutch Slave Cyl.

TOTAL PARTS	
QTY.	PART NO.
ACCESSORIES	PRICE
TOTAL ACCESSORIES	

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.

GAS, OIL, & GREASE		TOTAL LABOUR	TOTAL PARTS	TOTAL ACCESSORIES
QTY.	PRICE	TOTAL SUBCONTRACT	TOTAL GAS-OIL-GREASE	TOTAL
LITERS GAS				
LITERS OIL			HST	82.06
GREASE			GST	
			PST	
TOTAL			TOTAL	713.29

BON DE RÉPARATION DE GARAGE
GARAGE REPAIR ORDER

KEN BROWN (SERVICE)
960 BATHURST ST. TOR.
M5R 3G5
416-588-1988

072076

MATÉRIEL/MATERIALS			
QTE QTY.	N° DE PIÈCE PART NO.	DESCRIPTION	PRIX PRICE
9 1/2		Lt. 10-40	6603
6 1/2		Lt. A/F	4219
6		Plugs.	8940
		Fuel Solvent	265
		Total	20027

			DATE	25 Sept 12
MARQUE MAKE	MODÈLE MODEL	ANNÉE YEAR	N° DE TAXE TAX REG. NO.	
Saguar	Mk II 3.0	64		
N° DE SÉRIÉ SERIAL NO.	N° DE MOTEUR MOTOR NO.	PROMIS LE PROMISED	A.M. P.M.	
ODOMÈTRE ODOMETER	N° 1 LIC			
PRÉPARÉ PAR WRITTEN BY				

Labour 3 1/2 hr. @ 94.00 32900

MAIN-D'ŒUVRE LABOUR	MONTANT AMOUNT
LUBRIFICATION LUBRICATION <input type="checkbox"/>	
CHANG. D'HUILE CHANGE OIL <input type="checkbox"/>	
CHANG. DE LUBRIF. / CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REPLACER FILTRE À HUILE REPLACE OIL FILTER <input type="checkbox"/>	
NETT. FILTRE À AIR CLEAN AIR FILTER <input type="checkbox"/>	
GRAISSAGE DES ROUES AVANT REPACK FRONT WHEELS <input type="checkbox"/>	
RÉGLAGE DES FREINS ADJUST BRAKES <input type="checkbox"/>	
PERMUTATION DES PNEUS ROTATE TIRES <input type="checkbox"/>	
LAVAGE WASH <input type="checkbox"/> CIRAGE POLISH <input type="checkbox"/>	
MISE AU POINT DU MOTEUR TUNE MOTOR <input type="checkbox"/>	

OPÉRATION N° / NO. **INSTRUCTIONS**

Change Oil - Not Filter - Lubricate including Door hinges. Check all Levels - Change A/F. Fit New Spark plugs + check Compressions - good - Adjust Mixtures + Idle! Blow out Air Filter. Check Hoses + Belts. Safety check Brakes + Steering. Replace Short Vacuum Hose Under Fender. Increase tyre Pressures to 30 PSI. Refit Heater Flap Cable at R.H. Side of Console. Tighten screws on trunk trim. Check Belt for changing - ok. Road test. Adjust Clutch.

Nous ne pourrions être tenus responsables des pertes ou des dommages causés aux véhicules ou aux articles laissés dans le véhicule en cas d'incendie, de vol ou de toute autre cause indépendante de notre volonté.

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.

TOTAL DES PIÈCES TOTAL PARTS		TOTAL DE LA MAIN-D'ŒUVRE TOTAL LABOUR	32900
TOTAL DES ACCESSOIRES TOTAL ACCESSORIES		TOTAL DES PIÈCES TOTAL PARTS	20027
		TOTAL DES ACCESSOIRES TOTAL ACCESSORIES	52927
Par la présente, j'autorise les réparations ci-dessus indiquées ainsi que l'achat du matériel nécessaire. De plus, je vous donne la permission ainsi qu'à un de vos employés de conduire le véhicule décrit dans la présente dans les rues, sur les autoroutes ou ailleurs, dans le but d'en faire l'essai ou l'inspection. Par la présente, un privilège de construction exprès est accordé en ce qui a trait au véhicule décrit ci-dessus afin de garantir le coût des réparations.		ESSENCE, HUILE ET GRAISSE GAS, OIL, & GREASE	
I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.		QTE QTY.	PRIX PRICE
		LITRES D'ESSENCE LITERS GAS	
		LITRES D'HUILE LITERS OIL	
		GRAISSE GREASE	
		TOTAL	HST 6881
TOTAL DES ACCESSOIRES TOTAL ACCESSORIES		TOTAL	59808
AUTORISÉ PAR / AUTHORIZED BY			

BON DE RÉPARATION DE GARAGE
GARAGE REPAIR ORDER

KEN BROWN (SERVICE)
980 BATHURST ST. TOR.
M5R 3G5
416-590-1988

035108

MATÉRIEL/MATERIALS			
QTE QTY.	N° DE PIÈCE PART NO.	DESCRIPTION	PRIX PRICE
		Cam Cover Gasket set	42 84
		Brake Master kit	68 90
		Brake Fluid	18 00
		Hardware	2 00
		Paint + Supplies	4 28
1	Lt 20-50		6 95
	AIF		1 00
		Fuel Solvent	2 65
		Total	146 62

DATE: 23 May 13

MARQUE MAKE	MODÈLE MOD.	ANNÉE YEAR	N° DE TAXE TAX REG. NO.
Jaguar	Mk. II	64	
N° DE SÉRIE SERIAL NO.	N° DE MOTEUR MOTOR NO.	PROMIS LE PROMISED	A.M. P.M.
ODOMÈTRE ODOMETER	N° D'IMMATRICULATION LICENCE NO.	CONDITIONS TERMS	TÉL. UNE FOIS PRÊT PHONE WHEN READY
			<input type="checkbox"/> OUI/YES <input type="checkbox"/> NON/NO
PRÉPARÉ PAR WRITTEN BY	TÉL. DOM. RES. PHONE	TÉL. BUR. BUS. PHONE	

MAIN D'ŒUVRE LABOUR	MONTANT AMOUNT
LUBRIFICATION LUBRICATION <input type="checkbox"/>	
CHANG. D'HUILE CHANGE OIL <input type="checkbox"/>	
CHANG. DE LUBRIF. / CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REPLACER FILTRE À HUILE REPLACE OIL FILTER <input type="checkbox"/>	
NETT. FILTRE À AIR CLEAN AIR FILTER <input type="checkbox"/>	
GRAISSAGE DES ROUES AVANT REPACK FRONT WHEELS <input type="checkbox"/>	
RÉGLAGE DES FREINS ADJUST BRAKES <input type="checkbox"/>	
PERMUTATION DES PNEUS ROTATE TIRES <input type="checkbox"/>	
LAVAGE WASH <input type="checkbox"/> CIRAGE POLISH <input type="checkbox"/>	
MISE AU POINT DU MOTEUR TUNE MOTOR <input type="checkbox"/>	

QTE QTY.	N° DE PIÈCE PART NO.	DESCRIPTION	PRIX PRICE
		Labour 4 ³ / ₄ hr @ 94 ⁰⁰	446 50

OPÉRATION N° / NO. **INSTRUCTIONS**

Lubricate - Oil + Filter OK - Check Hoses & Belts
 Safety Check Steering - Brake Master Cyl leaking.
 All Wheel Cyls OK. - Servo May have leakage into
 Canister but OK. - Re + Re Master Cyl. Re kit
 for short term Repair - Order New cyl. - Bleed
 Brakes - Clean out Reservoirs Replace Exhaust side
 Cam Cover Gasket - Leaking oil on to Exhaust.
 Cleanup Motor. Adjust Cabs only. Road test.

TOTAL DES PIÈCES TOTAL PARTS			
QTE QTY.	N° DE PIÈCE PART NO.	ACCESSOIRES / ACCESSORIES	PRIX PRICE
		TOTAL DES ACCESSOIRES TOTAL ACCESSORIES	

Nous ne pouvons être tenus responsables des pertes ou des dommages causés aux véhicules ou aux articles laissés dans le véhicule en cas d'incendie, de vol ou de toute autre cause indépendante de notre volonté.		Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.		TOTAL DE LA MAIN D'ŒUVRE TOTAL LABOUR	446 50
Par la présente, j'autorise les réparations ci-dessus indiquées ainsi que l'achat du matériel nécessaire. De plus, je vous donne la permission ainsi qu'à un de vos employés de conduire le véhicule décrit dans la présente dans les rues, sur les autoroutes ou ailleurs, dans le but d'en faire l'essai ou l'inspection. Par la présente, un privilège de construction exprès est accordé en ce qui a trait au véhicule décrit ci-dessus afin de garantir le coût des réparations.		I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.		TOTAL DES PIÈCES TOTAL PARTS	146 62
		ESSENCE, HUILE ET GRAISSE GAS, OIL & GREASE		TOTAL DES ACCESSOIRES TOTAL ACCESSORIES	593 12
QTE QTY.		PRIX PRICE		TOTAL SOUS-TRAIT. TOTAL SUBCONTRACT	
	LITRES D'ESSENCE LITERS GAS			TOTAL ESSENCE-HUILE-GRAISSE TOTAL GAS-OIL-GREASE	
	LITRES D'HUILE LITERS OIL				77 11
	GRAISSE GREASE			TPS/GST TVH/HST	
				TVP/PST	
	TOTAL			TOTAL	670 23

4811B

BON DE RÉPARATION DE GARAGE
GARAGE REPAIR ORDER

KEN BROWNE SERVICE
960 BATHURST ST. TOR
M5R 3G5
416-588-7996

006917

MATÉRIEL/MATERIALS			
QTÉ QTY.	N° DE PIÈCE PART NO.	DESCRIPTION	PRIX PRICE
1	LT. 20-50		7 89
		Carb Cleaner	14 95
		Fuel Solvent	2 65
		Brake Fluid	4 50
		Bulk	4 35
		Alternator Rebuild	526 80
		Motor Mount	48 74
		Welding Supplies	15 00
		P.S. Fluid (Sealing)	23 80
		Relay	32 95
		Wiring	6 80
		Neg Earth Badge	28 90
		Hardware	10 14
		Total	727 47
		Labour 10 1/4 hr. @ 105 ⁰⁰	1076 25
		Modify Alt. Adjusting Bracket, Repair Main Mounting Bracket.	
QTÉ QTY.	N° DE PIÈCE PART NO.	ACCESSOIRES / ACCESSORIES	PRIX PRICE
		TOTAL DES PIÈCES TOTAL PARTS	
		TOTAL DES ACCESSOIRES TOTAL ACCESSORIES	

DATE: 6 Aug 80

MARQUE MAKE: Jaguar

MODELE MOD.: Mk. II

ANNÉE YEAR: 64

N° DE TAXE TAX REG. NO.:

N° DE SÉRIE SERIAL NO.:

N° DE MOTEUR MOTOR NO.:

PROMIS LE PROMISED: A.M. P.M.

ODOMETRE ODOMETER: 11106

N° D'IMMATRICULATION LICENCE NO.:

CONDITIONS TERMS:

TÉL. UNE FOIS PRÊT PHONE WHEN READY: OUI/YES NON/NO

PRÉPARÉ PAR WRITTEN BY:

TÉL. DOM. RES. PHONE:

TÉL. BUR. BUS. PHONE:

OPÉRATION N° / NO. **INSTRUCTIONS**

Top up Motor Oil Only - Ok. Clean Carb dash pots - Clean Spark plugs - Blow out Air Filter. Check Dist. + timing. Set this times

Check Hoses + Belts - Safety check Brakes + Steering - Bleed Wheel Cyls + top up Reservoir. Check Clutch Fluid + Push wood Free play.

Check tyre Pressures - lights Coolant etc. Replace One Bulb Road side.

- Alternator Not Charging - Test with Wiring to Alt. Fault is in Alt. - Remove Alt pump, P.S. Pump. Mounting Brackets

LH Motor Mount + Brackets - Remove Alt. Rebuild + Refit. Fit Field Isolation Relay to Circuit. Fit Neg Ground Badge. Replace LH Motor Mount.

Nous ne sommes étre tenus responsables des pertes ni des dommages causés au véhicule ou à ses articles à moins dans le véhicule en cas d'incendie, de vol ou de toute autre cause indépendante de notre volonté.

No Responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.

MAIN-D'ŒUVRE LABOUR	MONTANT AMOUNT
LUBRIFICATION LUBRICATION <input type="checkbox"/>	
CHANG. D'HUILE CHANGE OIL <input type="checkbox"/>	
CHANG. DE LUBRI. / CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REPLACER FILTRE À HUILE REPLACE OIL FILTER <input type="checkbox"/>	
NETT. FILTRE À AIR CLEAN AIR FILTER <input type="checkbox"/>	
GRAISSAGE DES ROUES AVANT REPACK FRONT WHEELS <input type="checkbox"/>	
RÉGLAGE DES FREINS ADJUST BRAKES <input type="checkbox"/>	
PERMUTATION DES PNEUS ROTATE TIRES <input type="checkbox"/>	
LAVAGE WASH <input type="checkbox"/> CIRAGE POLISH <input type="checkbox"/>	
MISE AU POINT DU MOTEUR TUNE MOTOR <input type="checkbox"/>	

ESSENCE, HUILE ET GRAISSE GAS, OIL, & GREASE		TOTAL DE LA MAIN-D'ŒUVRE TOTAL LABOUR
QTÉ QTY.	PRIX PRICE	
LITRES D'ESSENCE LITERS GAS		1076 25
LITRES D'HUILE LITERS OIL		727 47
GRAISSE GREASE		1803 72
		TOTAL SOUS-TRAIT TOTAL SUBCONTRACT
		TOTAL ESSENCE-HUILE-GRAISSE TOTAL GAS-OIL-GREASE
		HST 234 48
		TVP/PST
		TOTAL 2038 20

4811B

AUTORISÉ PAR / AUTHORIZED BY

BON DE RÉPARATION DE GARAGE
GARAGE REPAIR ORDER

KEN BROWNE SERVICE
960 BATHURST ST. TOR
M5R 3G5
416-588-1996

006902

MATÉRIEL/MATERIALS			
QTE QTY.	N° DE PIÈCE PART NO.	DESCRIPTION	PRIX PRICE
9/2		Lt. 20-50	66 03
		Oil Filter	28 95
2		Needle Valves	77 30
2		Gaskets	4 20
1		Used Pad	
		Brake Cleaner	14 95
		Brake Fluid	7 00
		Fuel Solvent	2 65
Total			201 08

Non chargée

NOM NAME		DATE	
ADRESSE/ ADDRESS			
MARQUE MAKE	MODÈLE MODEL	ANNÉE YEAR	N° DE TAXE TAX REG. NO.
Jaguar	Mk II	38 '62	
N° DE SÉRIE SERIAL NO.	N° DE MOTEUR MOTOR NO.	PROMIS LE PROMISED	A.M. P.M.
		<input type="checkbox"/> OUI/YES <input type="checkbox"/> NON/NO	
ODOMETRE ODOMETER	N° D'IMMATRICULATION LICENCE NO.	CONDITIONS TERMS	TÉL. UNE FOIS PRÊT PHONE WHEN READY
			<input type="checkbox"/> OUI/YES <input type="checkbox"/> NON/NO
PRÉPARÉ PAR WRITTEN BY	TÉL. DOM. RES. PHONE	TÉL. BUR. BUS. PHONE	

MAIN-D'ŒUVRE LABOUR	MONTANT AMOUNT
LUBRIFICATION LUBRICATION <input type="checkbox"/>	
CHANG. D'HUILE CHANGE OIL <input type="checkbox"/>	
CHANG. DE LUBRIF. / CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REMPLEUR FILTRE À HUILE REPLACE OIL FILTER <input type="checkbox"/>	
NETT. FILTRE À AIR CLEAN AIR FILTER <input type="checkbox"/>	
GRAISSAGE DES ROUES AVANT REPAK FRONT WHEELS <input type="checkbox"/>	
RÉGLAGE DES FREINS ADJUST BRAKES <input type="checkbox"/>	
PERMUTATION DES PNEUS ROTATE TIRES <input type="checkbox"/>	
LAVAGE WASH <input type="checkbox"/> CIRAGE POLISH <input type="checkbox"/>	
MISE AU POINT DU MOTEUR TUNE MOTOR <input type="checkbox"/>	

OPÉRATION N° / NO.	INSTRUCTIONS
Labour 4 3/4 hr @ 105.00	498 75

Change Oil & Filter - Lubricate - check all levels. Check A/F to 30°F. Replace Both Carb Needles & Seats. (Sometimes flooding) Blowout Air Filter - Reset Carb Mixtures Adjust Handbrake Switch. Check all Brakes - RH Rear wheel cyl was tight & pad worn - Free off Cyl and fit one used pad - Bleed all Brakes - Refit tyres Front to Rear. Check Lights Horn etc. Road test

QTE QTY.	N° DE PIÈCE PART NO.	ACCESSOIRES / ACCESSORIES	PRIX PRICE
TOTAL DES PIÈCES TOTAL PARTS			
TOTAL DES ACCESSOIRES TOTAL ACCESSORIES			

Nous ne pouvons être tenus responsables des pertes ou des dommages causés aux véhicules ou aux articles laissés dans le véhicule en cas d'incendie, de vol ou de toute autre cause indépendante de notre volonté.		Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.	
Par la présente, j'autorise les réparations ci-dessus indiquées ainsi que l'achat du matériel nécessaire. De plus, je vous donne la permission ainsi qu'à un de vos employés de conduire le véhicule décrit dans la présente dans les rues, sur les autoroutes ou ailleurs, dans le but d'en faire l'essai ou l'inspection. Par la présente, un privilège de construction exprès est accordé en ce qui a trait au véhicule décrit ci-dessus afin de garantir le coût des réparations.		I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.	
AUTORISÉ PAR / AUTHORIZED BY		TOTAL	

ESSENCE, HUILE ET GRAISSE GAS, OIL, & GREASE		TOTAL DE LA MAIN-D'ŒUVRE TOTAL LABOUR	
QTE QTY.	PRIX PRICE	498 75	
LITRES D'ESSENCE LITERS GAS		TOTAL DES PIÈCES TOTAL PARTS	201 08
LITRES D'HUILE LITERS OIL		TOTAL DES ACCESSOIRES TOTAL ACCESSORIES	700 83
GRAISSE GREASE		TOTAL SOUS-TRAIT TOTAL SUBCONTRACT	
		TOTAL ESSENCE-HUILE-GRAISSE TOTAL GAS-OIL-GREASE	
		HST	91 11
		TPS/GST TVH/HST	
		TVP/PST	
		TOTAL	791 94

4811B

BON DE RÉPARATION DE GARAGE
GARAGE REPAIR ORDER

KEN BROWNE SERVICE
960 BATHURST ST TOR
M5R 3G5
416-588-7996

085727

MATÉRIEL/MATERIALS			
QTE QTY.	N° DE PIÈCE PART NO.	DESCRIPTION	PRIX PRICE
6		Plugs	89.40
9 1/2		Lt. 20-50	70.78
		Oil Filter	24.95
		Carb Cleaner	7.00
		Total	192.13
		Labour 5 1/2 hr @ 105 ⁰⁰	577.50

NK N°		DATE 26 May 16	
AC AC			
MARQUE MAKE Jaguar	MODÈLE MODEL MKII	ANNÉE YEAR	N° DE TAXE TAX REG. NO.
N° DE SÉRIE SERIAL NO.	N° DE MOTEUR MOTOR NO.	PROMIS LE PROMISED	A.M. P.M.
ODOMETRE ODOMETER	N° D'IMMATRICULATION LICENCE NO.	CONDITIONS TERMS	TÉL UNE FOIS PRÊT PHONE WHEN READY ES <input type="checkbox"/> NON/NO
PRÉPARÉ PAR WRITTEN BY			

MAIN D'ŒUVRE LABOUR	MONTANT AMOUNT
LUBRIFICATION LUBRICATION <input type="checkbox"/>	
CHANG. D'HUILE CHANGE OIL <input type="checkbox"/>	
CHANG. DE LUBRIF. / CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REPLACER FILTRE À HUILE REPLACE OIL FILTER <input type="checkbox"/>	
NETT. FILTRE À AIR CLEAN AIR FILTER <input type="checkbox"/>	
GRAISSAGE DES ROUES AVANT REPACK FRONT WHEELS <input type="checkbox"/>	
RÉGLAGE DES FREINS ADJUST BRAKES <input type="checkbox"/>	
PERMUTATION DES PNEUS ROTATE TIRES <input type="checkbox"/>	
LAVAGE WASH <input type="checkbox"/> CIRAGE POLISH <input type="checkbox"/>	
MISE AU POINT DU MOTEUR TUNE MOTOR <input type="checkbox"/>	

OPÉRATION N° / NO.	INSTRUCTIONS
*Also FIT Viz Replace Side Lamp Switch	Chack over Car. Running Poorly. Replace Plugs. Compressions Good - Clean Dashpots + Resct Carbs + Resct choke - Service Dist. Change Oil + Filter. Lubricate. Check Pads + Rotors. Pressure test Cooling System. Belts Ok. Check Lights etc. Check Charging + Battery - OK. Road test.
Switch 61.28 Labour 1 hr 52.25 Total 114.53 HST 14.89 Total 129.42	

QTE QTY.	N° DE PIÈCE PART NO.	ACCESSOIRES / ACCESSORIES	PRIX PRICE
		TOTAL DES PIÈCES TOTAL PARTS	192.13
		TOTAL DES ACCESSOIRES TOTAL ACCESSORIES	

Nous ne pourrons être tenus responsables des pertes ou des dommages causés aux véhicules ou aux articles laissés dans le véhicule en cas d'incendie, de vol ou de toute autre cause indépendante de notre volonté.		Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.		TOTAL DE LA MAIN-D'ŒUVRE TOTAL LABOUR	577.50
Par la présente, j'autorise les réparations ci-dessus indiquées ainsi que l'achat du matériel nécessaire. De plus, je vous donne la permission ainsi qu'à un de vos employés de conduire le véhicule décrit dans la présente dans les rues, sur les autoroutes ou ailleurs, dans le but d'en faire l'essai ou l'inspection. Par la présente, un privilège de construction exprès est accordé en ce qui a trait au véhicule décrit ci-dessus afin de garantir le coût des réparations.		ESSENCE, HUILE ET GRAISSE GAS, OIL, & GREASE		TOTAL DES PIÈCES TOTAL PARTS	192.13
I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.		QTE QTY.	PRIX PRICE	TOTAL DES ACCESSOIRES TOTAL ACCESSORIES	769.63
		LITRES D'ESSENCE LITERS GAS		TOTAL SOUS-TRAIT. TOTAL SUBCONTRACT	
		LITRES D'HUILE LITERS OIL		TOTAL ESSENCE-HUILE-GRAISSE TOTAL GAS-OIL-GREASE	
		GRAISSE GREASE		HST	100.05
				*Also TPS/GST TVH/HST	129.42
				Total V/P/PST	999.10
		TOTAL		TOTAL	869.60

4811B

BON DE RÉPARATION DE GARAGE
GARAGE REPAIR ORDER

108303

MATÉRIEL/MATERIALS		
QTÉ QTY.	N° DE PIÈCE PART NO.	DESCRIPTION
		Switch
		Wiring Supplies etc.
		Total

Labour 2 1/2 hr. @ 105⁰⁰ 262.50

NO NA		DATE 7 July 16	
ADJ ADI			
MARQUE MAR Jaguar	MODÈLE MOU MK II	ANNÉE YEAR	N° DE TAXE TAX REG. NO.
N° DE SÉRIE SERIAL NO.	N° DE MOTEUR MOTOR NO.	PROMIS LE PROMISED	A.M. P.M.
ODOMÈTRE ODOMETER	N° D'IMMATRICULATION LICENCE NO.	CONDITIONS TERMS	TÉL. UNE FOIS PRÊT PHONE WHEN READY <input type="checkbox"/> OUI/YES <input type="checkbox"/> NON/NO
PRÉPARÉ PAR WRITTEN BY	TÉL. DOM. RES. PHONE	TÉL. BUR. BUS. PHONE	

MAIN-D'ŒUVRE LABOUR	MONTANT AMOUNT
LUBRIFICATION LUBRICATION <input type="checkbox"/>	
CHANG. D'HUILE CHANGE OIL <input type="checkbox"/>	
CHANG. DE LUBRIF. / CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REPLACER FILTRE À HUILE REPLACE OIL FILTER <input type="checkbox"/>	
NETT. FILTRE À AIR CLEAN AIR FILTER <input type="checkbox"/>	
GRAISSAGE DES ROUES AVANT REPACK FRONT WHEELS <input type="checkbox"/>	
RÉGLAGE DES FREINS ADJUST BRAKES <input type="checkbox"/>	
PERMUTATION DES PNEUS ROTATE TIRES <input type="checkbox"/>	
LAVAGE WASH <input type="checkbox"/> CIRAGE POLISH <input type="checkbox"/>	
MISE AU POINT DU MOTEUR TUNE MOTOR <input type="checkbox"/>	

OPÉRATION N° / NO. **INSTRUCTIONS**

Car will Not crank - Check Starter/Solenoid/ Button Connections & Clean. Check Starter Draw-OK But Very Good. - Fit Switch under Bonnet to crank motor Directly

Note - Danger - Do Not use unless car is Out of Gear!

TOTAL DES PIÈCES TOTAL PARTS

QTÉ QTY.	N° DE PIÈCE PART NO.	ACCESSOIRES / ACCESSORIES	PRIX PRICE
		TOTAL DES ACCESSOIRES TOTAL ACCESSORIES	

Nous ne pouvons être tenus responsables des pertes ou des dommages causés aux véhicules ou aux articles laissés dans le véhicule en cas d'incendie, de vol ou de toute autre cause indépendante de notre volonté.

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.

TOTAL DE LA MAIN-D'ŒUVRE TOTAL LABOUR 262.50

TOTAL DES PIÈCES TOTAL PARTS 22.10

TOTAL DES ACCESSOIRES TOTAL ACCESSORIES 284.60

Par la présente, j'autorise les réparations ci-dessus indiquées ainsi que l'achat du matériel nécessaire. De plus, je vous donne la permission ainsi qu'à un de vos employés de conduire le véhicule décrit dans la présente dans les rues, sur les autoroutes ou ailleurs, dans le but d'en faire l'essai ou l'inspection. Par la présente, un privilège de construction exprès est accordé en ce qui a trait au véhicule décrit ci-dessus afin de garantir le coût des réparations.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.

ESSENCE, HUILE ET GRAISSE GAS, OIL, & GREASE	
QTÉ QTY.	PRIX PRICE
LITRES D'ESSENCE LITERS GAS	
LITRES D'HUILE LITERS OIL	
GRAISSE GREASE	
TOTAL	

TOTAL SOUS-TRAIT TOTAL SUBCONTRACT

TOTAL ESSENCE-HUILE-GRAISSE TOTAL GAS-OIL-GREASE

HST 37.01

TPS/GST TVH/HST

TVP/PST

TOTAL 321.61

AUTORISÉ PAR / AUTHORIZED BY

BON DE RÉPARATION DE GARAGE
GARAGE REPAIR ORDER

KEN BROWNE SERVICE
960 BATHURST ST. TOR.
M5R 3G5
416-588-7996

108309

MATÉRIEL/MATERIALS			
QTÉ QTY.	N° DE PIÈCE PART NO.	DESCRIPTION	PRIX PRICE
		Fuel Pump Warranty	
		Gasket	4 20
		Oil Filter	24 95
		1 Lt. 20-50	7 45
		Total	36 60
		Labour 2hr. @ 105 ⁰⁰	210 60
		TOTAL DES PIÈCES TOTAL PARTS	
QTÉ QTY.	N° DE PIÈCE PART NO.	ACCESSOIRES / ACCESSORIES	PRIX PRICE
		TOTAL DES ACCESSOIRES TOTAL ACCESSORIES	

NO. NAI		DATE	
ADR ADC		26 July 16	
MARQUE MAKE	MODÈLE MODEL	ANNÉE YEAR	N° DE TAXE TAX REG. NO.
Jaguar	Mk II		
N° DE SÉRIE SERIAL NO.	N° DE MOTEUR MOTOR NO.	PROMIS LE PROMISED	A.M. P.M.
ODOMÈTRE ODOMETER	N° D'IMMATRICULATION LICENCE NO.	CONDITIONS TERMS	TÉL. UNE FOIS PRÊT PHONE WHEN READY
			<input type="checkbox"/> OUI/YES <input type="checkbox"/> NON/NO
PRÉPARÉ PAR WRITTEN BY	TÉL. DOM. RES. PHONE	TÉL. BUR. BUS. PHONE	

MAIN D'ŒUVRE LABOUR	MONTANT AMOUNT
LUBRIFICATION LUBRICATION <input type="checkbox"/>	
CHANG. D'HUILE CHANGE OIL <input type="checkbox"/>	
CHANG. DE LUBRIF. / CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REPLACER FILTRE À HUILE REPLACE OIL FILTER <input type="checkbox"/>	
NETT. FILTRE À AIR CLEAN AIR FILTER <input type="checkbox"/>	
GRAISSAGE DES ROUES AVANT REPACK FRONT WHEELS <input type="checkbox"/>	
RÉGLAGE DES FREINS ADJUST BRAKES <input type="checkbox"/>	
PERMUTATION DES PNEUS ROTATE TIRES <input type="checkbox"/>	
LAVAGE WASH <input type="checkbox"/> CIRAGE POLISH <input type="checkbox"/>	
MISE AU POINT DU MOTEUR TUNE MOTOR <input type="checkbox"/>	

OPÉRATION N° / NO.	INSTRUCTIONS
	2 Fuel Pumps Fitted to car. One pump has Failed. Failed Pump is Little more than one year old. Still ok for warranty. Oil leak from Oil Filter housing. Replace Gasket. Fit New Oil Filter while off car. Road test.

Nous ne pouvons être tenus responsables des pertes ou des dommages causés aux véhicules ou aux articles laissés dans le véhicule en cas d'incendie, de vol ou de toute autre cause indépendante de notre volonté.		Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.		TOTAL DE LA MAIN D'ŒUVRE TOTAL LABOUR	210 00
Par la présente, j'autorise les réparations ci-dessus indiquées ainsi que l'achat du matériel nécessaire. De plus, je vous donne la permission ainsi qu'à un de vos employés de conduire le véhicule décrit dans la présente dans les rues, sur les autoroutes ou ailleurs, dans le but d'en faire l'essai ou l'inspection. Par la présente, un privilège de construction exprès est accordé en ce qui a trait au véhicule décrit ci-dessus afin de garantir le coût des réparations.		ESSENCE, HUILE ET GRAISSE GAS, OIL, & GREASE		TOTAL DES PIÈCES TOTAL PARTS	36 60
I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.		QTÉ QTY.	PRIX PRICE	TOTAL DES ACCESSOIRES TOTAL ACCESSORIES	246 60
		LITRES D'ESSENCE LITERS GAS		TOTAL SOUS-TRAIT TOTAL SUBCONTRACT	
		LITRES D'HUILE LITERS OIL		TOTAL ESSENCE-HUILE-GRAISSE TOTAL GAS-OIL-GREASE	HST 32 06
		GRAISSE GREASE		TPS/GST TVH/HST	
				TVP/PST	
		TOTAL		TOTAL	278 66

Reg Beer Coachbuilder Corp & CMC Enterprises (1990) Inc.

12944 Albion Vaughan Rd. Bolton Ont. L7E 4C6
Telephone\ Fax; (905) 857-3210. Email cmcmog@idirect.ca
GST # 12178 9812 RT

24 Nov. 2016

INVOICE;
Re: Jaguar MK II;

Lic. # AHHA 137

Mi. 12138

Replace oil pressure sender unit. Remove sun visor, research availability. Replace 3 exhaust mounts.

Labour;

3 Hrs. @ 100.00 300.00

Parts;

3- exhaust mounts	36.00	
1- oil sender	118.00	
materials	<u>10.00</u>	
	164.00	<u>164.00</u>

HST

60.32

Deductable

400.00

\$924.32

Paid By Cheque.

233.

Nov 26 16.

The Quality is Remembered Long After The Price is Forgotten
(Sir Henry Royce)

BON DE RÉPARATION DE GARAGE
GARAGE REPAIR ORDER

KEN BROWNE SERVICE
960 BATHURST ST. TORONTO
M5R 3G6
416-588-1996

108402

MATÉRIEL/MATERIALS			
QTÉ QTY.	N° DE PIÈCE PART NO.	DESCRIPTION	PRIX PRICE
		Visor Hardware	30 00
		Battery	235 80
		Lucas Label	19 95
		Total	285 75

Labour 2 3/4 hr @ 105⁰⁰ 288 75

NC N°	DATE	25 April 20	
AD AD			
MARQUE MAKE	MODÈLE MODEL	ANNÉE YEAR	N° DE TAXE TAX REG. NO.
Jaguar	Mk II		
N° DE SÉRIE SERIAL NO.	N° DE MOTEUR MOTOR NO.	PROMIS LE PROMISED	A.M. P.M.
ODOMÈTRE ODOMETER	N° D'IMMATRICULATION LICENCE NO.	CONDITIONS TERMS	TÉL. UNE FOIS PRÊT PHONE WHEN READY
			<input type="checkbox"/> OUI/YES <input type="checkbox"/> NON/NO
PRÉPARÉ PAR WRITTEN BY	TÉL. DOM. RES. PHONE	TÉL. BUR. BUS. PHONE	

MAIN-D'ŒUVRE LABOUR	MONTANT AMOUNT
LUBRIFICATION LUBRICATION <input type="checkbox"/>	
CHANG. D'HUILE CHANGE OIL <input type="checkbox"/>	
CHANG. DE LUBRIF. / CHANGE LUB. TRANS. <input type="checkbox"/> DIFF. <input type="checkbox"/>	
REPLACER FILTRE À HUILE REPLACE OIL FILTER <input type="checkbox"/>	
NETT. FILTRE À AIR CLEAN AIR FILTER <input type="checkbox"/>	
GRAISSAGE DES ROUES AVANT REPACK FRONT WHEELS <input type="checkbox"/>	
RÉGLAGE DES FREINS ADJUST BRAKES <input type="checkbox"/>	
PERMUTATION DES PNEUS ROTATE TIRES <input type="checkbox"/>	
LAVAGE WASH <input type="checkbox"/> CIRAGE POLISH <input type="checkbox"/>	
MISE AU POINT DU MOTEUR TUNE MOTOR <input type="checkbox"/>	

OPÉRATION N° / NO.	INSTRUCTIONS
	Car just out of winter storage - Check Battery & charging - Battery is faulty. Fit New Battery (Lucas Label In test state) Fit Driver's Sun Visor. Check all levels. Road test. Clean spark plugs. Do minor clean up under Bonnet. Tighten Cam cover Nuts. Check Dush pots - Road test.

TOTAL DES PIÈCES TOTAL PARTS			
QTÉ QTY.	N° DE PIÈCE PART NO.	ACCESSOIRES / ACCESSORIES	PRIX PRICE
		TOTAL DES ACCESSOIRES TOTAL ACCESSORIES	

Nous ne pourrons être tenus responsables des pertes ou des dommages causés aux véhicules ou aux articles laissés dans le véhicule en cas d'incendie, de vol ou de toute autre cause indépendante de notre volonté.		Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.		TOTAL DE LA MAIN-D'ŒUVRE TOTAL LABOUR	288 75
Par la présente, j'autorise les réparations ci-dessus indiquées ainsi que l'achat du matériel nécessaire. De plus, je vous donne la permission ainsi qu'à un de vos employés de conduire le véhicule décrit dans la présente dans les rues, sur les autoroutes ou ailleurs, dans le but d'en faire l'essai ou l'inspection. Par la présente, un privilège de construction exprès est accordé en ce qui a trait au véhicule décrit ci-dessus afin de garantir le coût des réparations.		I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.		TOTAL DES PIÈCES TOTAL PARTS	285 75
		ESSENCE, HUILE ET GRAISSE GAS, OIL, & GREASE		TOTAL DES ACCESSOIRES TOTAL ACCESSORIES	574 50
QTÉ QTY.		PRIX PRICE		TOTAL SOUS-TRAIT. TOTAL SUBCONTRACT	
	LITRES D'ESSENCE LITERS GAS			TOTAL ESSENCE-HUILE-GRAISSE TOTAL GAS-OIL-GREASE	
	LITRES D'HUILE LITERS OIL			HIST	74 69
	GRAISSE GREASE			TPS/GST TVH/HST	
				TVP/PST	
	TOTAL			TOTAL	649 19



British Car Repair, Inc.
(415) 457-1707
ocwbc@gmail.com
142 Mill Street, San Rafael, CA, USA, 94901
Business/GST#: AB 220451

Invoice # 50543

Against Estimate#: 10513
Created: Nov 29, 2021
Invoiced: Mar 8, 2022
Service advisor: Olivia Wright

Vehicle: 1963 JAGUAR MK II
VIN: 222752
Mileage: 13129 mi
License Plate: 8XZH363

SERVICE				Authorized
Name	Description	Price	QTY/HRS	Amount
1 Labor	CHANGE ENGINE OIL AND FILTER. CHECK/TOP-UP FLUID LEVELS. INSPECT LIGHTS, BRAKE PADS, WHEEL BEARINGS, FAN BELT TENSION, TIRE PRESSURE AND SPARE. ROTATE TIRES WHERE NECESSARY. LUBRICATE CHASSIS AND GREASE FITTINGS. DRAIN AND REFILL TRANSMISSION. ROAD TEST VEHICLE.	\$125.00	2	\$250.00
2 OIL 20\50	ENGINE OIL 20\50	\$10.00	11	\$110.00
3 GFE 101	OIL FIL EARLY JAG CANISTER	\$20.00	1	\$20.00
				Service subtotal: \$380.00

SAFETY INSPECTION				Authorized
Name	Description	Price	QTY/HRS	Amount
1 Labor	PERFORM THOROUGH SAFETY INSPECTION. CUSTOMER REPORTS AND REQUESTS: THROTTLE PEDAL HAS LIMITED TRAVEL - ADJUST LINKAGE. BRAKE PEDAL SHUTTERS WHEN DEPRESSED - CUSTOMER HAS SUPPLIED NEW FRONT AND REAR BRAKE HOSES, MASTER CYLINDER, PADS AND ROTORS TO BE INSTALLED. DIFFERENTIAL HAS SMALL OIL LEAK - CUSTOMER SUPPLIED NEW GASKET. SUSPENSION IS BOUNCY - SPAX SHOCKS ? ALL FRONT SUSPENSION BUSHINGS LOOK OLD - CUSTOMER SUPPLIED NEW BUSHING KITS. HOT AIR COMES UP INTO CABIN FROM SHIFTER BOOT AND FIREWALL ON DRIVERS SIDE - CUSTOMER SUPPLIED A GROMMET KIT. FUEL SMELL PRESENT, SUSPECT IT COMING FROM THE GASCOLATOR. LEFT REAR INTERIOR LIGHT OUT - REPLACE BULB. DASH LIGHTS DO NOT ILLUMINATE. STEERING HAS ONE SPOT THAT BINDS SLIGHTLY AND IT IS ACCENTUATED WHEN BRAKING.	\$150.00	2	\$300.00
				Service subtotal: \$300.00



British Car Repair, Inc.
 (415) 457-1707
 ocwbcr@gmail.com
 142 Mill Street, San Rafael, CA, USA, 94901
 Business/GST#: AB 220451

Invoice # 50543

Against Estimate#: 10513
 Created: Nov 29, 2021
 Invoiced: Mar 8, 2022
 Service advisor: Olivia Wright

REAR BRAKES, AXLE & SHOCK ABSORBERS				Authorized
Name	Description	Price	QTY/HRS	Amount
1 Labor	FIT CUSTOMER SUPPLIED REAR SHOCK ABSORBERS. REPLACE REAR BRAKE PADS AND ROTORS WITH CUSTOMER SUPPLIED PARTS. OBTAIN REPLACEMENT USED LEFT SIDE AXLE SHAFT. CLEAN THREADS AND POLISH SPLINES ON AXLE SHAFT. REASSEMBLE. BLEED BRAKE HYDRAULIC SYSTEM. ROAD TEST VEHICLE TO SEAT PADS.	\$150.00	13	\$1,950.00
2 57905	GEAR OIL	\$70.00	0.5	\$35.00
3 HAZARDOUS WASTE		\$5.00	1	\$5.00
4 USED AXLE	USED AXLE LEFT SIDE	\$300.00	1	\$300.00
5 FREIGHT	FREIGHT	\$20.00	1	\$20.00
6 B\F	BRAKE FLUID	\$3.25	2	\$6.50
Service subtotal:				\$2,316.50

HEATER AND A/C				Authorized
Name	Description	Price	QTY/HRS	Amount
1 Labor	INSPECT HEATER AND AIR CONDITIONING. HEATER WORKS. A/C: WIRE TO COMPRESSOR IS DISCONNECTED. FREON LEVEL SEEMS TO BE OK. COMPRESSOR NOT NOISY WHEN ENGAGED. AIR FROM VENTS IS COOL - NOT COLD. A/C FAN SWITCH IS QUESTIONABLE. A/C BLOWER FAN TESTS GOOD. NOTE: SOMETIMES ENGINE WILL NOT SHUT OFF WHEN A/C IS ON. ELECTRIC RADIATOR FAN WORKS.	\$150.00	1	\$150.00
Service subtotal:				\$150.00

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

We warrant our labor service and new parts for 12 months or 6000 miles, whichever occurs first. If our repair or replacement part fails within warranty duration, you must return your vehicle to us and we will repair or replace those items free of charge. There is no other warranty written or implied. Warranties for sublet repairs are done under the terms of the sublet company.

Signature:

Part	\$471.50
Labor	\$2,650.00
Amount	\$3,121.50
Fees (Hazmat / EPA)	\$25.00
Subtotal	\$3,146.50
Tax	\$43.61
Grand total	\$3,190.11
Paid to date	\$3,190.11
Remaining balance	\$0.00



British Car Repair, Inc.
 (415) 457-1707
 ocwbc@gmail.com
 142 Mill Street, San Rafael, CA, USA, 94901
 Business/GST#: AB 220451

Invoice # 50597

Against Estimate#: 10729
 Created: Apr 4, 2022
 Invoiced: Apr 7, 2022
 Service advisor: Olivia Wright

Vehicle: 1963 JAGUAR MK II
 VIN: 222752
 Mileage: 13130 mi
 License Plate: 8XZH363

Customer notes

LEFT FRONT BRAKE CALIPER OUTER PISTON NEEDS TO BE REPLACED.
 STEERING IS TIGHT.
 SPEEDOMETER NEEDLE IS BOUNCING - REPLACE SPEEDOMETER CABLE.

FRONT SUSPENSION & BRAKES

Authorized

Name	Description	Price	QTY/HRS	Amount
1 Labor	DISASSEMBLE FRONT BRAKES - REMOVE CALIPERS, PADS, ROTORS. DISASSEMBLE FRONT SUSPENSION TO GAIN ACCESS TO AND REPLACE UPPER AND LOWER CONTROL ARM BUSHINGS - WITH CUSTOMER SUPPLIED PARTS. REPLACE FRONT SHOCK ABSORBERS WITH CUSTOMER SUPPLIED PARTS. REPLACE SWAY BAR BUSHINGS AND LINKS WITH CUSTOMER SUPPLIED PARTS. REPLACE UPPER AND LOWER BALL JOINTS. REPLACE FRONT BRAKE ROTORS AND PADS WITH CUSTOMER SUPPLIED PARTS. SAFETY WIRE BRAKE CALIPER BOLTS. REASSEMBLE. BLEED BRAKE HYDRAULIC SYSTEM. ROAD TEST VEHICLE TO SEAT PADS.	\$175.00	25	\$4,375.00
2 JLM 11860	BALL JOINT LOWER - JAG XJ & E-TYPE	\$75.00	2	\$150.00
3 BVF	BRAKE FLUID	\$3.25	4	\$13.00
4 BRAKE CLEANER		\$5.00	0.5	\$2.50
5 HAZARDOUS WASTE		\$4.60	1	\$4.60

Service subtotal: \$4,545.10

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

We warranty our labor service and new parts for 12 months or 6000 miles, whichever occurs first. If our repair or replacement part fails within warranty duration, you must return your vehicle to us and we will repair or replace those items free of charge. There is no other warranty written or implied. Warranties for sublet repairs are done under the terms of the sublet company.

Signature: _____

Part	\$165.50
Labor	\$4,375.00
Amount	\$4,540.50
Fees (Hazmat / EPA)	\$4.60
Subtotal	\$4,545.10
Tax	\$14.90
Grand total	\$4,560.00
Paid to date	\$4,560.00
Remaining balance	\$0.00



British Car Repair, Inc.
 (415) 457-1707
 ocwbc@gmail.com
 142 Mill Street, San Rafael, CA, USA, 94901
 Business/GST#: AB 220451

Invoice # 50621

Against Estimate#: 10757
 Created: Apr 14, 2022
 Invoiced: Apr 20, 2022
 Service advisor: Olivia Wright

Vehicle: 1963 JAGUAR MK II
 VIN: 222752
 Mileage: 13130 mi
 License Plate: 8XZH363

Customer notes

REPLACE FUEL TANK SENDING UNIT - EMPTY IS AT 1/8" OF A TANK.
 REPLACE CLUTCH SLAVE CYLINDER AND CLUTCH MASTER CYLINDER CAP.
 ALL TIRES NEED TO BE REPLACED - VERY OLD.

FRONT BRAKES

Authorized

Name	Description	Price	QTY/HRS	Amount
1 Labor	DISASSEMBLE RIGHT FRONT BRAKE CALIPER - NEW ONE DID NOT FIT, LARGER THAN STOCK CALIPER. MACHINE ALL FOUR CALIPERS ON ONE SIDE TO GAIN CLEARANCE FROM ROTOR HUB. INSTALL NEW CALIPERS ON BOTH FRONT WHEELS. FREE OFF FROZEN NUT ON BRAKE HYDRAULIC LINE. PRESSURE BLEED BRAKE HYDRAULIC SYSTEM. ROAD TEST VEHICLE.	\$175.00	6	\$1,050.00
2 8777G	FRONT CALIPER PISTON ASSEMBLY, GIRLING - JAG MKII, MKX, XK150, E-TYPE S1 & S1.5	\$195.00	4	\$780.00
3 BRAKE CLEANER		\$5.00	0.3	\$1.50
4 B\F	BRAKE FLUID	\$3.25	2	\$6.50
5 FREIGHT	FREIGHT	\$26.01	1	\$26.01
6 GASOLINE		\$1.00	25	\$25.00
Service subtotal:				\$1,889.01

ALIGNMENT

Authorized

Name	Description	Price	QTY/HRS	Amount
1 Labor	ALIGN STEERING - SET TOE. NOTE: CAMBER AND CASTER ARE OFF A BIT BUT VEHICLE TRACKS STRAIGHT.	\$150.00	1	\$150.00
Service subtotal:				\$150.00

POWER STEERING FAN BELT

Authorized

Name	Description	Price	QTY/HRS	Amount
1 Labor	REPLACE POWER STEERING FAN BELT.	\$175.00	1	\$175.00
2 FAN BELT		\$23.00	1	\$23.00
Service subtotal:				\$198.00



British Car Repair, Inc.
 (415) 457-1707
 ocwbc@gmail.com
 142 Mill Street, San Rafael, CA, USA, 94901
 Business/GST#: AB 220451

Invoice # 50621
 Against Estimate#: 10757
 Created: Apr 14, 2022
 Invoiced: Apr 20, 2022
 Service advisor: Olivia Wright

SPEEDOMETER INNER CABLE				Authorized	
Name	Description	Price	QTY/HRS	Amount	
1 Labor	REPLACE INNER SPEEDOMETER CABLE WITH CUSTOMER SUPPLIED PART. OUTER CABLE COULD NOT BE REPLACED DUE TO AIR CONDITIONING. BATTERY REQUIRED REMOVAL DUE TO MISROUTING OF ORIGINAL CABLE.	\$175.00	2	\$350.00	
				Service subtotal: \$350.00	

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

We warranty our labor service and new parts for 12 months or 6000 miles, whichever occurs first. If our repair or replacement part fails within warranty duration, you must return your vehicle to us and we will repair or replace those items free of charge. There is no other warranty written or implied. Warranties for sublet repairs are done under the terms of the sublet company.

Signature: _____

Part	\$836.00
Labor	\$1,725.00
Amount	\$2,561.00
Fees (Hazmat / EPA)	\$26.01
Subtotal	\$2,587.01
Tax	\$72.99
Grand total	\$2,660.00
Paid to date	\$2,660.00
Remaining balance	\$0.00



British Car Repair, Inc.
 (415) 457-1707
 ocwbcrr@gmail.com
 142 Mill Street, San Rafael, CA, USA, 94901
 Business/GST#: AB 220451

Invoice # 50661

Against Estimate#: 10799
 Created: May 3, 2022
 Invoiced: May 10, 2022
 Service advisor: Olivia Wright

1963 JAGUAR MK II
 VIN: 222752
 Mileage: 13213 mi
 License Plate: 8XZH363

Customer notes

CLUTCH SLAVE CYLINDER LEAKING.

TIRES

					Authorized
Name	Description	Price	QTY/HRS	Amount	
1 Labor	MOUNT AND BALANCE FIVE NEW TIRES WITH INNER TUBES. ROAD TEST VEHICLE.				\$450.00
2 VREDESTEIN SPRINT CLASSIC SL 185VR15	185VR15 VREDESTEIN SPRINT CLASSIC SL	\$220.00	5		\$1,100.00
3 INR TBE	INNER TUBE	\$38.00	5		\$190.00
4 TIRE DISPOSAL FEE		\$7.00	5		\$35.00
5 CA TIRE TAX FEE		\$1.75	5		\$8.75
6 FREIGHT		\$155.15	1		\$155.15
Service subtotal: \$1,938.90					

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

We warranty our labor service and new parts for 12 months or 6000 miles, whichever occurs first. If our repair or replacement part fails within warranty duration, you must return your vehicle to us and we will repair or replace those items free of charge. There is no other warranty written or implied. Warranties for sublet repairs are done under the terms of the sublet company.

Signature: _____

Part	\$190.00
Labor	\$450.00
Tire	\$1,100.00
Amount	\$1,740.00
Fees (Hazmat / EPA)	\$198.90
Subtotal	\$1,938.90
Tax	\$116.10
Grand total	\$2,055.00
Paid to date	\$2,055.00
Remaining balance	\$0.00



British Car Repair, Inc.
 (415) 457-1707
 ocwbc@gmail.com
 142 Mill Street, San Rafael, CA, USA, 94901
 Business/GST#: AB 220451

Invoice # 50694

Against Estimate#: 10823
 Created: May 12, 2022
 Invoiced: May 24, 2022
 Service advisor: Olivia Wright

1963 JAGUAR MK II
 VIN: 222752
 Mileage: 13213 mi
 License Plate: 8XZH363

FUEL TANK SENDING UNIT					Authorized
Name	Description	Price	QTY/HRS	Amount	
1 Labor	DIAGNOSE DEFECTIVE FUEL TANK SENDING UNIT. REPLACE SENDING UNIT. TEST OPERATION - GOOD.				\$175.00
2 C937	FUEL TANK SENDING UNIT GASKET - JAG MKII	\$1.25	1	\$1.25	
3 C2296/9*	COPPER WASHER	\$0.75	6	\$4.50	
4 C15476	FUEL TANK SENDING UNIT - JAG MKII	\$75.00	1	\$75.00	
5 FREIGHT	FREIGHT	\$11.98	1	\$11.98	
					Service subtotal: \$267.73

CLUTCH SLAVE CYLINDER					Authorized
Name	Description	Price	QTY/HRS	Amount	
1 Labor	REPLACE CLUTCH SLAVE CLYINDER. BLEED CLUTCH HYDRAULIC SYSTEM ROAD TEST VEHICLE.				\$262.50
2 C21470	CLUTCH SLAVE CYL JAG	\$175.00	1	\$175.00	
3 B\F	BRAKE FLUID	\$4.00	4	\$16.00	
4 HAZARDOUS WASTE	HAZ	\$2.00	1	\$2.00	
5 GASOLINE	GAS	\$40.00	1	\$40.00	
6 FREIGHT	FREIGHT	\$12.31	1	\$12.31	
					Service subtotal: \$507.81

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

We warranty our labor service and new parts for 12 months or 6000 miles, whichever occurs first. If our repair or replacement part fails within warranty duration, you must return your vehicle to us and we will repair or replace those items free of charge. There is no other warranty written or implied. Warranties for sublet repairs are done under the terms of the sublet company.

Signature:

Part	\$311.75
Labor	\$437.50
Amount	\$749.25
Fees (Hazmat / EPA)	\$26.29
Subtotal	\$775.54
Tax	\$24.46
Grand total	\$800.00
Paid to date	\$800.00
Remaining balance	\$0.00



British Car Repair, Inc.
 (415) 457-1707
 ocwbc@gmail.com
 142 Mill Street, San Rafael, CA, USA, 94901
 Company Business/GST number: AB 220451

Invoice # 51711

Against Estimate#: 12044
 Created: Jan 4, 2024
 Invoiced: Jan 15, 2024
 Service advisor: Olivia Wright

1963 JAGUAR MK II
 VIN: 222752
 Mileage in: 14221 mi
 Mileage out: 14230 mi
 License Plate: 8XZH363

Customer notes

MAGNETIC TRANSMISSION DRAIN PLUG HAD METAL SHAVINGS ON IT.

SERVICE

Item	Name	Description	Price	QTY/HRS	Authorized Amount
1	Labor	CHANGE ENGINE OIL AND FILTER. CHECK/TOP-UP UNDER HOOD AND DRIVELINE FLUID LEVELS. INSPECT INTERIOR AND EXTERIOR LIGHTS, BRAKE PADS AND ROTORS, WHEEL BEARINGS AND FAN BELT TENSIONS. CHECK/SET TIRE PRESSURES INCLUDING SPARE. LUBRICATE CHASSIS AND GREASE FITTINGS. DRAIN AND REFILL TRANSMISSION OIL - MAGNETIC DRAIN PLUG HAD DIRTY, METAL SHAVINGS ON IT. SEE PICTURE ATTACHED. DRAIN AND REFILL DIFFERENTIAL OIL. DRAIN AND REFILL ANTIFREEZE FROM RADIATOR. REPLACE IGNITION POINTS AND CONDENSER. GAP POINTS. CLEAN DEBRIS FROM REAR CARBURETOR FLOAT BOWL WHICH WAS CAUSING A FUEL LEAK. REPLACE GEAR SELECTOR RUBBER BOOT/SEAL WITH PART SUPPLIED BY OWNER. ADJUST IDLE SPEED. ROAD TEST VEHICLE.			\$1,600.00
2	OIL 20/50	ENGINE OIL 20/50	\$13.00	8.5	\$110.50
3	HAZARDOUS WASTE - OIL		\$0.85	12	\$10.20
4	152-210	IGNITION POINTS/CONTACT SET	\$10.00	1	\$10.00
5	OIL 75/90		\$8.00	1.5	\$12.00
6	ANTIFREEZE		\$45.00	1	\$45.00
7	HAZARDOUS WASTE - ANTIFREEZE		\$3.00	1	\$3.00
8	75-115	NON-DETERGENT 30 OIL	\$10.00	2	\$20.00

Approved by Olivia Wright (Phone) on Jan 11, 2024 5:33 pm

Service subtotal: \$1,810.70

Date and time	Receipt No	Payment method	Amount	Service Amount	
Jan 15, 2024 11:02 am	11903	Card - Visa xxxx-xxxx-5882	\$1,828.97	Part	\$197.50
				Labor	\$1,600.00
				Total Service level fee	
				Hazardous Waste - Oil	\$10.20
				Hazardous Waste - Antifreeze	\$3.00
				Subtotal	\$1,810.70
				Taxes	
				Sales Tax (9.25%)	\$18.27
				Grand total	\$1,828.97
				Paid to date	\$1,828.97
				Remaining balance	\$0.00

By signing this document, you agree to the Terms and Conditions mentioned below.

Signature:

Disclaimer:

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did. If the vehicle is not picked up after two days of completing repairs, a storage fee of \$75 per day will commence.

British Car Repair, Inc. charges a 3% credit card surcharge for merchant transaction costs. If you pay by debit card, cash or check, there is no additional fee. If you pay by credit card, there will be an additional fee of 3%.

We warranty our labor service and new parts for 12 months or 6000 miles, whichever occurs first. If our repair or replacement part fails within warranty duration, you must return your vehicle to us and we will repair or replace those items free of charge. There is no other warranty written or implied. Warranties for sublet repairs are done under the terms of the sublet company.



VINNY'S AUTO BODY

vinnys_auto_body@yahoo.com
29659 Arnold Dr, Suite K12, Sonoma, CA 95476
Phone: (707) 849-2797

Workfile ID: f80d6948
PartsShare: 7QTDyN
BAR: ARD00296191

Preliminary Estimate

Customer:

Job Number:

Written By: Vincent Thorsson

Insured:
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:

Inspection Location:
VINNY'S AUTO BODY
29659 Arnold Dr, Suite K12
Sonoma, CA 95476
Repair Facility
(707) 849-2797 Business

Insurance Company:

VEHICLE

GENERIC CAR red

VIN:
License:
State:

Interior Color:
Exterior Color: red
Production Date:

Mileage In:
Mileage Out:
Condition:

Vehicle Out:
Job #:

Preliminary Estimate

Customer:

GENERIC CAR ri

Job Number:

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	Rpr fiber glass cracks				6.0	
2	#	Rpr body filler				8.0	
3	#	Refn primer and block					5.0
4	#	Refn seal and spray red					5.0
5	#	Refn add for 2 tone on nose					3.0
6	#	Subl Hazardous waste removal		1	5.00 T		
7	#	Repl Cover Car		1	5.00 T	0.3	
8	#	Rpr Color sand and buff					2.0
SUBTOTALS					10.00	14.3	15.0

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			0.00
Body Labor	14.3 hrs @	\$ 125.00 /hr	1,787.50
Paint Labor	15.0 hrs @	\$ 125.00 /hr	1,875.00
Paint Supplies	15.0 hrs @	\$ 55.00 /hr	825.00
Body Supplies	14.3 hrs @	\$ 20.00 /hr	286.00
Miscellaneous			10.00
Subtotal			4,783.50
Sales Tax	\$ 1,121.00 @	9.0000 %	100.89
Grand Total			4,884.39

Repair Auth