

# SUPERFORMANCE

2316 Cotner Ave  
Los Angeles, CA. 90064  
Phone - 310-445-2314 Fax - -

## Customer and Vehicle Report

Print Date: 08/07/2025

Vehicle: 2002 BMW - Z8, 5L,V8 (303CI) VIN(3), 4XYU237

Average Daily Mileage: 6

Invoice: 051565, Posted On: 05/17/2022, SW: LEVITT, DEVON

Odometer in: 84,531 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
	- CHECK TAIL LIGHTS; CUSTOMER REPORTS THAT RIGHT REAR BRAKE LIGHT IS INOPERATIVE Rear left taillamp inoperative. Recommend removing and replacing rear left taillamp. (See below)			DEVON sLEVITT		0.00	0.00		180.00
1.00	OIL SERVICE OIL SERVICE, TOP UP AL FLUIDS, CHECK TIRE PRESSURES AND RESET SERVICE LIGHT			JOHN xHIGA	1.00	180.00	180.00		180.00
	- OIL FILTER	11 42 7 510 717		Technician t/Please Sele	1.00	21.65	21.65	21.65	
	- HAZARDOUS WASTE	HW	Miscellaneous	Technician t/Please Sele	1.00	5.00	5.00	5.00	
	- SYNTHETIC OIL 5W40	2332	Maintenance	Technician t/Please Sele	7.00	10.95	76.65	10.95	
0.94	EMISSION CONTROL CHECK			TOM sMORGAN	0.94	160.00	160.00		180.00
1.00	BRAKE FLUID FLUSH			JOHN xHIGA	1.00	180.00	180.00		180.00
	- BRAKE FLUID	BF	Brake System	Technician t/Please Sele	2.00	8.95	17.90	8.95	
2.00	REPLACE L/REAR TAIL LIGHT Removed and replaced left rear tail light assembly.			BRUNO CAVALLINI	2.00	360.00	360.00		180.00
	- TAIL LIGHT ASSEMBLY	63 21 4 859 157		Technician t/Please Sele	1.00	3,420.80	3,420.80	4,993.94	
<b>Totals for Invoice:</b>		<b>Parts</b>	<b>Labor</b>	<b>Discount</b>	<b>Subtotal</b>	<b>Haz Mat</b>	<b>Supplies</b>	<b>Tax</b>	<b>Total</b>
		3,542.00	880.00	0.00	4,422.00	0.00	0.00	336.49	4,758.49

Invoice: 050250, Posted On: 11/05/2021, SW: LEVITT, DEVON

Odometer in: 83,318 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
	- CAR TOWED IN- CAR DIED WHILE DRIVING LAST WEEK- UNABLE TO KEEP BATTERY CHARGED WITH TRICKLE CHARGER			BRUNO CAVALLINI		0.00	0.00		180.00

# Customer and Vehicle Report

Print Date: 08/07/2025

Vehicle: 2002 BMW - Z8, 5L,V8 (303CI) VIN(3), 4XYU237

Average Daily Mileage: 6

Invoice: 050250, Posted On: 11/05/2021, SW: LEVITT, DEVON

Odometer in: 83,318 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
	Jump started car; attempted to force charge battery. Battery is not charging. Checked alternator and alternator is charging to spec and no battery drains are present. Recommend replacing battery (see below)								
-	INTERSTATE BATTERY	IMTP 49/H8	Charging/Starting System		1.00	224.95	224.95	224.95	
1.00	REPLACE BATTERY; Removed and replaced battery			BRUNO CAVALLINI	1.00	180.00	180.00		180.00
<b>Notes - 42 Month Old Battery Pro-rated price 50\$ off to \$224.95</b>									
<b>Totals for Invoice:</b>		<b>Parts</b>	<b>Labor</b>	<b>Discount</b>	<b>Subtotal</b>	<b>Haz Mat</b>	<b>Supplies</b>	<b>Tax</b>	<b>Total</b>
		224.95	180.00	0.00	404.95	0.00	0.00	21.37	426.32

Invoice: 049451, Posted On: 07/16/2021, SW: LEVITT, JOHNNY

Odometer in: 82,742 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
-	CUSTOMER HEARD LOUD METALLIC NPOISE FROM ENGINE AREA- NO WARNING LIGHTS WERE ON- HE ADDED ONE QUART OIL AND HAS NOT HEARD NOISE SINCE checked oil level ok- no leak found- drove car- no problem found								
				BRUNO CAVALLINI		0.00	0.00		180.00
<b>Totals for Invoice:</b>		<b>Parts</b>	<b>Labor</b>	<b>Discount</b>	<b>Subtotal</b>	<b>Haz Mat</b>	<b>Supplies</b>	<b>Tax</b>	<b>Total</b>
		0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

Invoice: 047289, Posted On: 08/12/2020, SW: LEVITT, DEVON

Odometer in: 81,335 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
-	MIRROR REPAIR	4567567			1.00	410.00	410.00	410.00	
0.50	r&r interior mirror for repair			JOHN xHIGA	0.50	85.00	85.00		170.00
<b>Totals for Invoice:</b>		<b>Parts</b>	<b>Labor</b>	<b>Discount</b>	<b>Subtotal</b>	<b>Haz Mat</b>	<b>Supplies</b>	<b>Tax</b>	<b>Total</b>
		410.00	85.00	0.00	495.00	0.00	0.00	38.95	533.95

Invoice: 047235, Posted On: 07/15/2020, SW: LEVITT, JOHNNY

Odometer in: 81,302 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
------	-------------	----------	----------	------------	-----	------	------	-------	------



# Customer and Vehicle Report

Print Date: 08/07/2025

Vehicle: 2002 BMW - Z8, 5L,V8 (303CI) VIN(3), 4XYU237

Average Daily Mileage: 6

Invoice: 047235, Posted On: 07/15/2020, SW: LEVITT, JOHNNY

Odometer in: 81,302 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
1.00	OIL SERVICE			RICH yPAPENGUTH	1.00	170.00	170.00		170.00
	OIL SERVICE, TOP UP AL FLUIDS, CHECK TIRE PRESSURES AND RESET SERVICE LIGHT								
-	OIL FILTER	11 42 7 510 717		Technician t/Please Sele	1.00	21.65	21.65	21.65	
-	HAZARDOUS WASTE	HW	Miscellaneous	Technician t/Please Sele	1.00	5.00	5.00	5.00	
-	SYNTHETIC OIL 5W40	2332	Maintenance	Technician t/Please Sele	7.00	9.95	69.65	9.95	
0.94	EMISSION CONTROL CHECK			JOHNNY sLEVITT	0.94	160.00	160.00		170.00
1.00	BRAKE FLUID FLUSH			RICH yPAPENGUTH	1.00	170.00	170.00		170.00
-	BRAKE FLUID	BF	Brake System	Technician t/Please Sele	2.00	8.95	17.90	8.95	
1.00	REPLACE AIR AND CABIN FILTERS			RICH yPAPENGUTH	1.00	170.00	170.00		170.00
-	Air Filter	13 72 1 736 675		Technician t/Please Sele	2.00	47.47	94.94	16.12	
-	Cabin Air Filter Set - Activated Charcoal	64 31 2 339 891		Technician t/Please Sele	1.00	114.85	114.85	66.00	
-	Manual Transmission Fluid - MTF-LT-2 - SAE 75W-80 (1 Liter)	83 22 2 339 219		Technician t/Please Sele	2.00	40.16	80.32	21.90	
0.50	SERVICE MANUAL TRANSMISSION			RICH yPAPENGUTH	0.50	85.00	85.00		170.00
1.00	COOLING SYSTEM FLUSH			RICH yPAPENGUTH	1.00	170.00	170.00		170.00
-	COOLANT	COOL	Cooling/Belts/Hoses	Technician t/Please Sele	2.00	35.00	70.00	35.00	
Totals for Invoice:		Parts	Labor	Discount	Subtotal	Haz Mat	Supplies	Tax	Total
		474.31	925.00	0.00	1,399.31	0.00	0.00	45.06	1,444.37

Invoice: 042696, Posted On: 07/12/2018, SW: PREISER, JUSTIN

Odometer in: 79,789 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
1.00	CUSTOMER STATES THAT THE FUEL DOOR WILL NOT OPEN - CHECK AND ADVISE			CHARLES BALL	1.00	140.00	140.00		140.00
-	LOCK ACTUATOR	67 11 8 360 193			1.00	105.08	105.08	105.08	
-	CABLE HOLDER	7211 8 177 700			1.00	1.04	1.04	1.04	
Totals for Invoice:		Parts	Labor	Discount	Subtotal	Haz Mat	Supplies	Tax	Total
		106.12	140.00	0.00	246.12	0.00	0.00	10.08	256.20

# Customer and Vehicle Report

Print Date: 08/07/2025

Vehicle: 2002 BMW - Z8, 5L,V8 (303CI) VIN(3), 4XYU237

Average Daily Mileage: 6

Invoice: 042452, Posted On: 05/30/2018, SW: PREISER, JUSTIN

Odometer in: 79,566 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
-	CUSTOMER REQUEST OIL SERVICE AND TUNE UP - NEEDS SMOG TEST SPARK PLUGS ARE OKAY AT THIS TIME - SCANNED VEHICLE FOR TROUBLE CODES - FOUND CODES FOR CYLINER MISFIRE - RECOMMEND REPLACE IGNITION COILS AND RECHECK AFTER REPAIRS TO VERIFY PROPER OPERATION.			JAMES CRAM		0.00	0.00		140.00
-	CUSTOMER STATES THAT THE CONVERTIBLE TOP WINDOW ZIPPER IS BROKEN - CHECK AND ADVISE TOOK VEHICLE FOR ESTIMATES FOR TOP REPAIRS - BOTH PLACES SAID THE TOP NEEDS TO BE REPLACED DUE TO DIFFICULTY IN REPAIRING IT.			JAMES CRAM		0.00	0.00		140.00
-	CUSTOMER STATES THAT THERE IS A PROBLEM WITH THE DRIVER SEAT REMOVED DRIVERS SEAT - FOUND SEAT BASE BROKEN - NEED TO SEND SEAT BASE OUT FOR REPAIRS			JAMES CRAM		0.00	0.00		140.00
-	Direct Ignition Coil w/o Plug Connector	1 227 030 081			8.00	107.39	859.12	107.39	
3.00	REPLACE IGNITION COILS AND IGNITION COIL CONNECTORS			JAMES CRAM	3.00	420.00	420.00		140.00
-	IGNITION COIL CONNECTOR	12 13 1 730 412			8.00	25.49	203.92	25.49	
-	HAZARDOUS WASTE	HW	Miscellaneous		1.00	5.00	5.00	5.00	
0.25	OIL SERVICE OIL SERVICE, TOP UP AL FLUIDS, CHECK TIRE PRESSURES AND RESET SERVICE LIGHT			JAMES CRAM	0.25	35.00	35.00		140.00
-	OIL FILTER KIT	11427953129	Maintenance		1.00	17.25	17.25	17.25	
-	SYNTHETIC OIL 5W40	2332	Maintenance		7.00	9.95	69.65	9.95	
2.00	REMOVE DRIVERS SEAT TO INSPECT THE CAUSE OF THE SEAT MOVING WHEN IT SHOULD NOT MOVE AT ALL FOUND BROKEN SEAT BASE SUPPORT BAR WELDS AND ALSO BROKEN BUSHING - SENT SEAT BASE OUT FOR REPAIR			JAMES CRAM	2.00	280.00	280.00		140.00
-	DRIVERS SEAT BASE/POWER SEAT ADJUSTER REPAIR					700.00	700.00		
0.50	DRIVE VEHICLE THRU OBD2 DRIVE CYCLE - SET UP FOR SMOG TEST			JAMES CRAM	0.50	70.00	70.00		140.00

# Customer and Vehicle Report

Print Date: 08/07/2025

Vehicle: 2002 BMW - Z8, 5L,V8 (303CI) VIN(3), 4XYU237

Average Daily Mileage: 6

Invoice: 042452, Posted On: 05/30/2018, SW: PREISER, JUSTIN

Odometer in: 79,566 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
	- TAKE VEHICLE TO SMOG FOR CUSTOMER					75.00	75.00		
	- INTERSTATE BATTERY	IMTP 49/H8	Charging/Starting System		1.00	274.95	274.95	274.95	
0.50	REPLACE BATTERY			JAMES CRAM	0.50	70.00	70.00		140.00
<b>Totals for Invoice:</b>		<b>Parts</b>	<b>Labor</b>	<b>Discount</b>	<b>Subtotal</b>	<b>Haz Mat</b>	<b>Supplies</b>	<b>Tax</b>	<b>Total</b>
		1,429.89	1,650.00	0.00	3,079.89	0.00	0.00	135.84	3,215.73
<b>Totals for Owner:</b>		<b>Parts</b>	<b>Labor</b>	<b>Discount</b>	<b>Subtotal</b>	<b>Haz Mat</b>	<b>Supplies</b>	<b>Tax</b>	<b>Total</b>
		6,187.27	3,860.00	0.00	10,047.27	0.00	0.00	587.79	10,635.06