



1960 Kellison J4X ☆ 🔒 🌐

File Edit View Insert Format Data Tools Add-ons Help

🖨️ 📶 100% ▾ View only

1	Engine block		
	A	B	C
1	Engine block	3849852	1964-1968 283 V8
2	Cam	12-672-4	Comp Cam
3	Carburetor		Holley 4150 Double Pumper
4	Differential	3.73 ratio. 41 ring 11 pinion	GM 7.625 w/ TrueTrac Limited Slip
5	Intake	SP2P	Edelbrock
6	Heads	3884520	Power Pack Heads 1.72/1.50 valves
7			
8			
9			
10			
11			

INVOICE

August 22, 2015

TO:

FROM: Dave Schaible
1329 Jobs Peak Drive
Gardnerville, NV 89460

#1
paid check #
7396

~~~~~  
Labor: 63hrs @ \$50.00 3150.00  
Remove engine and trans. Remove inner panels to  
Remove body

Total \$3150.00

Thanks,

Dave

Please send check to:

Dave Schaible  
1329 Jobs Peak Drive  
Gardnerville, NV 89460

# INVOICE

January 14, 2017

TO:

FROM: Dave Schaible  
1329 Jobs Peak Drive  
Gardnerville, NV 89460

~~~~~  
Labor: Install engine trans and rear end. Fit rear
brakes, shocks and fuel cell mounts. Install pedals
and some brake lines.

63 hrs @ \$50 ----- 3650.00

Parts:

Bellhousing scatter shield, -----	553.34*
Driveshaft-----	495.90*
Throttle bell crank-----	41.99
Throttle pedal-----	191.25
Steering wheel adapter-----	50.98
Hand brake clevis kit-----	2.97
Emer. brake cable kit-----	34.97
Hand brake, 11" chrome-----	55.97
Sales tax-----	3.71
Brake line clips-----	2.99
(3) Brake line mounting tabs @ 5.99---	17.97
(6) Brake line fittings @ 8.99-----	53.94
(5) banjo fittings @ 22.57-----	112.85
(6) Brake lines @ 29.95-----	179.70
3/4" master cylinder-----	72.25
Sales tax-----	31.22

Brake line clips-----	2.99
(2) Steering shaft rod end @ 9.99-----	19.98
Mounting tabs-----	5.99
Steering shaft bearing-----	19.99
(2) steering u-joints @ 87.97-----	175.94
Steering vibration reducer-----	126.95
SS Steering shaft support-----	76.84
Quick release steering hub-----	69.97
Throttle cable-----	57.97
Sales tax-----	39.55
Rollover vent valve-----	17.11*
Fuel Pressure regulator-----	179.97
Fuel filter-----	35.97
Electric fuel pump-----	205.97
Sales tax-----	29.96
(2) starter bolts @ 2.97-----	5.94
Starter-----	151.97
Sales tax-----	12.20
Panhard bar-----	99.97
Sales tax-----	7.10
16 gallon fuel cell-----	125.97
Foam kit-----	102.97
Engine mid-plate-----	90.32
Bellhousing dowel pins-----	17.97
Motor mount pads-----	27.97
Sales tax-----	20.39
External battery charge terminals-----	39.52*
(6) Flare nuts @ 3.99-----	23.94
(3) line clamps @ 6.99-----	20.97
Steering shaft stop-----	12.99
Inverted flare fitting-----	4.99
Adapter tee-----	11.99
NPT adapter tee-----	7.99
Stop light switch-----	17.99
SS steering shaft-----	57.32

Parts total -----3810.51

Total-----\$7,460.51

*Tax included

Thanks,

Dave

Please send check to:

Dave Schaible
1329 Jobs Peak Drive
Gardnerville, NV 89460

INVOICE

March 19, 2017

*Paid check #8317
19 March 2017*

TO:

FROM: Dave Schaible
1329 Jobs Peak Drive
Gardnerville, NV 89460

~~~~~  
Labor:

Brake and clutch lines. Fuel lines and battery cable. Firewall and floors.

39 hrs@ \$50.00-----\$1950

Parts:

|                                                         |        |
|---------------------------------------------------------|--------|
| (4) Cans spray paint-----                               | 36.37  |
| Battery cables, ends and shrink tube-----               | 164.49 |
| Hose ends, fittings and solder-----                     | 44.72  |
| Battery-----                                            | 179.96 |
| Fuel line and brake fittings-----                       | 72.64  |
| Aluminum for floor and tunnel-----                      | 534.88 |
| Fuel filler neck, steering bearing, fuel cell foam----- | 210.72 |
| Fuel Hose clamps-----                                   | 8.27   |
| Brake lines and fittings-----                           | 50.58  |
| Fuel line fittings-----                                 | 23.42  |
| Clutch line fitting-----                                | 23.00  |
| Fuel sender-----                                        | 75.91  |
| Steering U-joints, fuel pump and fuel hose-----         | 499.15 |
| Steel material-----                                     | 13.91  |
| Rear shocks-----                                        | 125.01 |

Front shock and spray paint----- 170.91

Rear brake calipers, pads and brake lines----- 334.16

Total parts-----2568.10

Total-----4518.10

Thanks,

Dave Schaible  
1329 Jobs Peak Drive  
Gardnerville, NV 89460

# INVOICE

**December 16, 2017**

TO:

FROM: Dave Schaible  
1329 Jobs Peak Drive  
Gardnerville, NV 89460

~~~~~  
Labor: 192.5 hrs. @ \$50.00 ----- 9,625.00
Parts:
Misc. hardware and steel for body and
Seat mounting-----141.77
Seat belt mounting bungs-----47.96
Seat belt mounting eye bolts----- 47.64
(2) Safecraft seat belt sets-----798.73

Total-----\$10,661.10

Date corrected on invoice PAID

Thank you,

Dave

Please send check to:

Dave Schaible
1329 Jobs Peak Drive
Gardnerville, NV 89460

INVOICE

January 12, 2018

TO:

FROM: Dave Schaible
1329 Jobs Peak Drive
Gardnerville, NV 89460

~~~~~

|                                     |            |
|-------------------------------------|------------|
| Labor: 173 hrs. @ \$50.00 -----     | 8,650.00   |
| Parts:                              |            |
| Radiator -----                      | 532.88     |
| Water neck -----                    | 20.56      |
| Fuse panel -----                    | 60.87      |
| Upper radiator manifold -----       | 50.00      |
| Mufflers-----                       | 150.00     |
| Radiator installation bushings----- | 24.92      |
| Ignition coil and bracket-----      | 58.44      |
| Master kill switch-----             | 95.79      |
| Toggle switch for headlights-----   | 10.25      |
| Copper wire lugs-----               | 16.48      |
| Radiator cap, exhaust gaskets,      |            |
| Fuel filler hose-----               | 128.64     |
| Battery cable-----                  | 11.94      |
| Heat shrink tubing-----             | 25.47      |
| Total-----                          | \$9,836.24 |

Thank you,

Please send check to:  
Dave Schaible  
1329 Jobs Peak Drive  
Gardnerville, NV 89460

# INVOICE

February 3, 2018

TO:

FROM: Dave Schaible  
1329 Jobs Peak Drive  
Gardnerville, NV 89460

PAID  
check # 9289

2/5/18

~~~~~  
Labor: 66 hrs. @ 50.00-----3,300.00

Parts:

Oil press. Gauge, air cleaner, flasher----- 53.55

Refund: battery shut-off switch ----- (75.00)

Misc. supplies and construction steel----- 59.52

Total----- \$3,338.07

Thank you,

Dave

Please send check to:

Dave Schaible
1329 Jobs Peak Drive
Gardnerville, NV 89460

BRANNON CANVAS UPHOLSTERY & AWNINGS

945 W. Fremont St.
Stockton, CA 95203

(209) 465-2480

Fax: (209) 465-4069

brannoncanvas@sbcglobal.net

CUSTOMER NAME

INITIALS

INVOICE

10093

DATE:

3-10-19

WRITTEN BY:

LB

HARBOR

CF#

TYPE OF BOAT

BERTH NO.

HOME

WORK

FAX NUMBER

EMAIL

ESTIMATED COMPLETION DATE

CELL

QUAN.

DESCRIPTION

PRICE/UNIT

AMOUNT

Kelison Interior

Headliner DASH

door panels CARPET

4200⁰⁰

Red vinyl DIAMONDS

ESTIMATE

PARTS

FABRICATION

INSTALLATION

LABOR

TOTAL

SUBTOTAL

4200

FABRICATION

INSTALLATION

LABOR

SHIPPING

SALES TAX

168⁰⁰

TOTAL

4368⁰⁰

CUSTOMER

%

INSURANCE

%

DEPOSIT

1000⁰⁰

BALANCE

3368⁰⁰

TERMS

Deposits required on all jobs. Balance due and payable upon completion of work.

The above prices, specifications and conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified. Payment will be made as outlined above or I agree to pay maximum interest rate on past due amount, as well as attorney's fees if collection shall be made by legal proceedings. Failure to pay this account within the agreed terms could result in the assessment of a FINANCE CHARGE. The FINANCE CHARGE is at a "periodic rate" of 1 1/2 % per month or an ANNUAL PERCENTAGE RATE OF 18%.

Applicable sales tax will be added to all fabricated items.

CUSTOMERS AUTHORIZATION:

X

RECEIVED BY

X

CHECK NO.

9878

DEPOSIT DATE

3 19 19

BILLED

A/R

CAVALLINO COACHWORKS, INC.

2124 W Fremont St, Stockton, CA 95203

Phone: (209) 944-9840

FAX: (209) 944-9832

Workfile ID: ad763e02

Federal ID: 680465996

Federal EPA: TXR000081205

State EPA: CAL000220411

BAR: AB215090

Preliminary Estimate**RO Number: 35740**

Written By: Greg Campigli Ext #215

Insured:
Type of Loss:
Point of Impact: 16 Non-Collision

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:**Inspection Location:**

CAVALLINO COACHWORKS, INC.
2124 W Fremont St
Stockton, CA 95203-1915
Repair Facility
(209) 944-9840 Business

Insurance Company:**VEHICLE**

1960 CHEV PRIMER

VIN: 093W
License: 093W
State: CA

Interior Color:
Exterior Color: PRIMER
Production Date:

Mileage In: 30,000
Mileage Out:
Condition:

Vehicle Out:
Job #:

Kellison
paint
Order #2

Get live updates at www.carwise.com/e/3AMKQN

Preliminary Estimate

RO Number: 35740

1960 CHEV PRIMER

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	VEHICLE IS A 1960 KELLISON NO DATE BASEIN SYSYTEM		1			
2	#	Rpr COMPLETE BODY WORK				22.0	
3	#	Refn REFINISH COMPLETE VEHICLE					20.0
4	#	ADD FOR CLEAR COAT		1			2.5
SUBTOTALS					0.00	22.0	22.5

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			0.00
Body Labor	22.0 hrs @	\$ 76.00 /hr	1,672.00
Paint Labor	22.5 hrs @	\$ 76.00 /hr	1,710.00
Paint	22.5 hrs @	\$ 38.00 /hr	855.00
Subtotal			4,237.00
Sales Tax	\$ 855.00 @	9.0000 %	76.95
Grand Total			4,313.95
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			4,313.95

MCSPARREN AUTO GLASS
2634 NORTH WILSON WAY
STOCKTON, CA 95205

Copy 1

PH:(209) 466-4901 FAX:(209)466-0316

Federal Tax ID: 68-0194706

P/O#:
Taken By: KENDRA
Installer: AC/JM

Cust State Tax ID:
Cust Fed Tax ID:
Ship Via:

Invoice: I38830
Date: 10/31/2019
Time: 10:55 AM

SalesRep:

Adv. Code:

Bill To: CASH SALES

Sold To: CASH SALES

Vehicle Information

Make: KELLISON
Odometer:

Model Style:
VIN:

Year: 1961
License:

Qty	Part Number	Description	List	Disc%	Sell	Total
1	MISC	BACK GLASS 1/8 CLEAR TEMPERED	\$120.00	0	\$120.00	\$120.00
1	100F	LABOR TO INSTALL BACK GLASS	\$100.00	0	\$100.00	\$100.00
1	HAH000004	Adhesive-(1.0,Urethane,Dam,Primer)	\$20.00	0	\$20.00	\$20.00
1	100F	LABOR TO INSTALL WINDSHIELD	\$100.00	0	\$100.00	\$100.00
1	HAH000004	Adhesive-(1.0,Urethane,Dam,Primer)	\$20.00	0	\$20.00	\$20.00
1	MISC	WINDSHIELD AND BACK GLASS MOULDING	\$40.00	0	\$40.00	\$40.00
1	75F	LABOR TO INSTALL LEFT QUARTER GLASS	\$75.00	0	\$75.00	\$75.00
1	75F	LABOR TO INSTALL RIGHT QUARTER GLASS	\$75.00	0	\$75.00	\$75.00
1	MISC	BOLTS AND L BRACKETS	\$35.00	0	\$35.00	\$35.00
1	MISC	Q/G LOUVERS	\$550.00	0	\$550.00	\$550.00

PLEASE READ BACK OF INVOICE FOR INSTRUCTIONS & WARRANTY INFO. THANK YOU FOR YOUR BUSINESS.

PAY

On Account:

Sub Total: \$1,135.00

Tax: \$60.84

Total: \$1,195.84

Customer's Signature: _____

Balance: \$1,195.84

Larry Cearley / Chucks Garage

1127 W. Freemont
Stockton, CA 95219

Invoice

Date	Invoice #
1/29/2020	300

Bill To

P.O. No.

Terms

Project

Quantity	Description	Rate	Amount
40	fabricate grill, lower intake panel, left and right door pockets, mounting panels for inner door handles. Install inner door handles, door trim panels, tail lights, head lights, fuel filler door, left and right door latches, left and right door strikers. Repair headlight and tail light wiring, adjust doors, glassbead wheels. Polish wheels Elite Custom Metals	90.00	3,600.00
	Repair damaged wheel, mount and balance wheels tires 75.00 repair/50.00 dismount and mount Stockton Wheel	350.00	350.00
		75.00	75.00
	Interior door handles, opening mech left & right, door opening bezels, door balls including shipping Top Flight Automotive	138.88	138.88
		Total	\$4,163.88



Sales Order

WFO CONCEPTS

WFO Concepts
10076 Streeter Road STE 7
Auburn, CA 95602
Phone: 530-268-9494
Fax: 530-268-9498

Order #	Date
S67238	08/21/2020

Bill To:

Ship To:

Notes: GM 7.5 rear axle.
Axle was ran with no oil and gears/ bearings were damaged
3.73 ratio Reuse posi NO WARRANTY ON USED PARTS
Change oil in 500 miles

Sales Rep	Payment Terms	Carrier	Ship Service	Date Scheduled	PO#
Alan	Due on Receipt	Install		08/21/2020	

Item #	Type	Number	Description	Unit Price	Qty Ordered	Total Price
1	Sale	GM 7.5-373	7.5" GM 3.73 R&P OEM	\$235.99	1 ea	\$ 235.99
2	Sale	NON STOCK	Nonstock inventory part	\$0.00	1 ea	\$ 0.00
3	Sale	IK GM7.5	7.5" GM '81 & Up Master Install Kit	\$135.99	1 ea	\$ 135.99
4	Sale	LABOR	LABOR	\$130.00	3.25 hr	\$ 422.50
5	Sale	Brake Clean	Brake Clean, for cleaning parts	\$4.00	1 ea	\$ 4.00
6	Sale	AK 5707	1563 Axle Bearing & Seal Kit	\$19.99	2 ea	\$ 39.98

Date	Payment	Amount
08/31/2020	VISA	\$ 869.66

Thank you for your purchase!

All shortages within a shipment must be reported to WFO within seven (7) days of receiving the shipment. If necessary, you may return your product within 60 days. All returns are subject to a 15% restock fee.

BAR# 261168 EPA # CAL000349315

August 31, 2020 2:32:16 PM PDT

Subtotal:	\$838.46
Sales Tax:	\$31.20
Total:	\$869.66
Paid:	\$869.66
Balance Due:	\$0.00



• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250
 • 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787
 • 20 King Mill Road • McDonough, GA 30253 • 770-288-3200
 • 2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700


INVOICE

Calling Customer Service?
 Please have your
 invoice number ready.

INVOICE NUMBER	DATE
8760461	08/27/20
CUSTOMER NUMBER	PAGE
4448489	1

EXCHANGE/RETURN FORM

INVOICE NUMBER	DATE
8760461-3	08/27/20



NOTE: Please read the *How to Return an Order* instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ()

Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- Q. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other; please explain

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	ATI-917781	*DAMPER- 6.37 - ST - CHE		289.00	289.00 T
WARNING: Proposition 65 Compliance Statement California Safe Drinking Water & Toxic Enforcement Act of 1986 Some products purchased from our catalog or website contain chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm. Purchaser may receive full refund, including shipping costs, for return of unopened package within 30 days.					
** DECLARED PART VALUE THIS SHIPMENT **				289.00 U.S.D.	
** TOTAL INVOICE CA SALES TAX **					24.20

Qty.	Part Number	Exchange	Refund	Qty.	Reason Code	Explanation
1	ATI-917781					
** DECLARED VALUE		289.00				

NOTE: If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.

*Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

Thank
 You!

Credit Card Charge 313.20

Some parts are not legal for sale or use in California on any pollution controlled motor vehicles.

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:
 GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

S16550827

U0002420

PRIORITY MAIL RETURNS® SERVICE

Summit Racing Equipment
 Attn: Returns Dept.
 1103 East Glendale Ave.
 Sparks, Nv. 89431-9809

NO POSTAGE
 NECESSARY IF
 MAILED IN THE
 UNITED STATES

USPS TRACKING NUMBER



9201 9902 3186 7261 0697 86

From:
Subject: Kellison Update and Billing
Date: September 5, 2020 at 3:00 PM
To:

Hey

So it been about a month with the Kellison, which has gone from Fucking Kellison to What the Fuck Kellison. Putting aside all the easy swipes at previous mechanics, I must say we have made some fine progress. Here are the highlights:

- Rear end has gone from tragic no-oil failure to completely rebuilt, repainted, and ready to reinstall.
- Shifter now has enough room for a human leg to occupy the right side of the driver's seat. (Still sourcing a longer shift arm and larger shift boot)
- Engine is no longer a mystery. We now know roughly what the build is including the cam and crank. The intake and valve covers have been cleaned and refinished and look terrific.
- My observation that the carburetor is a complete mess has been confirmed by Ace Fuel Systems (my go to carb guys with 40 years of experience.) They said the carb was made from three different carbs and was unfixable. As a favor they have pulled a vintage double pumper from the attic and are rebuilding it for us right now. Should be done in two weeks.
- After much digging around I found a company who will ceramic coat the header and pipes in white. The pipes are ready to leave. We have to talk about the headers.
- Templates have been made for the air gap firewall. They should be fabbed next week.

Obviously, a whole lot more was done, but those are the best bits. Like I said when we first talked, every part we remove is always cleaned, repainted, or restored. So be confident wherever we have been, it will look awesome. We are now on the ass kicking end of the work and every move from here on should be a solid move forward.

The total so far is \$5462.50 in labor and \$1677.89 in parts. The grand total is \$7140.39. You are welcome to just write a check and mail it, or you can get fancy and do a wire transfer or PayPal. Your call.

Here is a link to the work page so you can check out specifically what we are doing.

https://docs.google.com/spreadsheets/d/1cyH8UJ7lusY_7ZoZnGXQleKO8jKv84A5Y5TZ75ZV9iM/edit?usp=sharing

I am having trouble uploading photos due to our absolutely shitty internet. I will let you know when I have solved that problem. I like clients to see what we are doing.

This week I will start sending you before and after shots of some of the areas. That always makes folks feel good.

Well there you go! Let's talk when you get this.

Cheers,

1960 Kellison J4X					
VIN					
Date	Item	Hours	Vendor	Cost	
9/4/20	1st Parts Billing			\$1,677.89	
9/4/20	3 cans of Trim Black. 1 can of Chassis Primer.		Stock	\$56.00	
9/1/20	Fasteners		A to Z	\$7.07	
8/31/20	Mail Carburetor to Ace Fuel Systems for rebuild (Delivered 9/1/20)		USPS	\$21.10	
8/31/20	Oil Pan Gasket		Riebes NAPA	\$13.53	
8/31/20	Rivets		Ace Hardware	\$2.59	
8/31/20	Thermostat housing, ARP Intake bolt kit, Coil Bracket		Summit Racing	\$48.73	
8/28/20	Manifold gasket, Valve cover gaskets, Carb gasket, Thermostat housing gasket, Timing cover gasket, Engine assembly lube.		Riebes NAPA	\$72.69	
8/28/20	Aluminum for Firewall		S&K Steel	\$70.51	
8/27/20	ATI Crankshaft Damper		Summit Racing	\$289.00	
8/27/20	Tilton Brake Master Cylinder 7/8", ARP Balancer Bolt, Crank Pulley		Speedway Motors	\$115.26	
8/25/20	Fuel Pump Gasket		Riebes NAPA	\$2.13	
8/25/20	Fasteners		Ace Hardware	\$9.93	
8/21/20	Rear Differential Rebuild: GM 3.73 Ring and Pinion, Bearings, Axle Bearing and Seals		WFO Concepts	\$869.66	
8/11/20	Spark Plugs (8), Carb cleaner, Brake cleaner		Riebes NAPA	\$25.56	
8/4/20	Vehicle Pickup Fuel		Costco	\$74.13	
9/4/20	1st Labor Billing	57.5	x \$95 hour	\$5,462.50	
9/4/20	Clean rear end, prep for paint, prime. Install valve covers and distributor. Take headers to Pacific Flyer for assessment.	3.5			
9/3/20	Prep exhaust manifolds for ceramic coating. Grind sloppy welds that will be visible from engine bay. Fix flanges.	2.0			
9/1/20	Install oil pan. Finish motor mount paint. Set valve lash. Install intake manifold. Install water pump and motor mount.	5.5			
8/31/20	Fabricate egr block off plate. Finish prepping intake manifold. Clean, media blast, and hand finish valve covers.	4.0			
8/28/20	Install cam and timing gears. Install timing cover and new crank seal. Installed push rods and rocker arms. Remove front motor mount and oil pan. Clean and paint front motor mount plate. Clean mating surfaces on oil pan and block.	6.0			
8/27/20	Removed all electrical from firewall and labeled. Finish driver and passenger firewall airgap templates. Drilled holes for hood scoop. Made sealant gasket for hood scoop. Shop for better hood pin plates.	4.0			
8/25/20	Design, mock and fabricate shifter extension. Clean mating surfaces of intake and exhaust. Media blasted and hand finished intake manifold.	5.0			
8/24/20	Clean gasket surfaces. Clean galley. Drain engine oil. Remove fuel pump block off. Clean surfaces. Remove motor mounts. Remove shifter assembly.	3.5			
8/21/20	Remove crank pulley and damper. Remove rocker, lifters, and pushrods. Remove timing cover. Remove timing set. Remove cam. Drop off rear end for rebuild at WFO.	2.0			
8/20/20	Remove hood and hood scoop. Prep hood for underside paint. Remove all hood pin hardware. Paint hood underside. Remove wipers. Remove pedal set. Remove master cylinders. Remove steering linkage. Begin templates for firewall airgap panels.	4.0			
8/19/20	Removed choke, throttle cable, vac advance, and fuel lines. Removed carb. Removed distributor and spark wires. Removed coil. Removed coil. Removed intake. Unbolt engine bay shield and all attached wiring. Remove alternator. Remove passenger and driver exhaust manifolds. Remove water pump and pulley. Remove valve covers. Remove all hardware from intake and prep for blasting.	4.5			
8/17/20	Rearend removal: remove swaybar, remove driveshaft, remove brakes, remove brake lines, remove axles, remove leaf spring u-bolts, remove shocks, remove trackbar bolts, remove rear axle.	3.0			
8/12/20	Wrote up inspection notes and emailed to Jay				
8/11/20	More Inspection. Prep for test drive: Choke work, Cooling check, Rear brake drag work, Attempt to tune carb, Change spark plugs. Differential open and inspect after noise observed.	5.0			
8/6/20	Initial Insoection. chassis measurement. and photoaraphv (Holv Fuckervl)	5.5			

Ace Automotive and Fuel Systems

BAR #: ARD 156525

CAL 000039848

975 Richard Avenue

Santa Clara, CA 95050

Phone: 408-727-2838

Page 2

Order Date 09/01/20 03:55 pm

Paid: 09/18/20 03:02 pm

Invoice No.

66655

Payments to Ace Automotive and Fuel Systems

Cost Summary

Status: Paid Work Order

Labor 343.00

Parts 58.00

Non Taxable 100.00

Haz Waste 3.00

Total \$504.00

Payments 504.00

Bal Due 0.00

Payments: \$504.00

1 09/18/20 504.00 Visa /T8 5gvwOEq8nuKvV

Thank you for choosing Ace Automotive and Fuel Systems

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control. 1 Year warranty on parts and labor unless used part is specified.

(Signature) _____



• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250
• 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787
• 20 King Mill Road • McDonough, GA 30253 • 770-288-3200
• 2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700

Calling Customer Service?
Please have your
invoice number ready.

INVOICE NUMBER DATE
8135092 09/08/20

CUSTOMER NUMBER PAGE
4448489 1

INVOICE

S
O
L
D
T
O

S
H
I
P
T
O

Qty	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	SME-8510400NL	GM 10BOLT 7.5 DIFF COVER		149.99	149.99 T
1	OTT-6805	VALVE COVER BREATHER		45.00	45.00 T
1	SUM-380180	OIL CAP		1.99	1.99 T
1	AAF-ALL40306	BLOCK-OFF PLATE FUEL PUM		16.99	16.99 T
1	ARP-100-1201	HEADER BOLT KIT SBC 12PT		15.99	15.99 T
1	LOK-SK-6883	SHIFT KNOB		37.95	37.95 T
1	FOLLOWING ITEM WILL SHIP FROM MANUFACTURER:				
	RFL-2025	EXHAUST GASKET			
WARNING: Proposition 65 Compliance Statement California Safe Drinking Water & Toxic Enforcement Act of 1986 Some products purchased from our catalog or website contain chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm. Purchaser may receive full refund, including shipping costs, for return of unopened package within 30 days.					
** DECLARED PART VALUE THIS SHIPMENT **				267.91 U.S.D.	
** TOTAL INVOICE CA SALES TAX **					22.42

NOTE: If you wish to return an item, see instructions on the back of this form
and complete the attached Exchange/Return Form.

*Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

Thank
You!

Credit Card Charge 330.05

Some parts are not legal for sale or use in California on any
pollution controlled motor vehicles.
INVOICE INCLUDES ITEMS SHIPPING FROM MANUFACTURER.

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:
GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

S16550908

U0002551



POLYMER DYNAMICS, INC.
11211 Neeshaw • Houston, TX 77065
281.894.6382 • 281.894.2211 • 1.888.765.9396
polydyn.com • ar@polydyntx7.com



Page 1

<< I N V O I C E >>

Sold To

Phone
Email

Inv Date	Salesman	PO No	Date	Ship Via	Terms	Inv No
10/02/20	CFB/DB	JOHN	09/15/20	UPSGRDRES	CHARGE	00158335

Item	Description	Order	Ship	Uom	Price	Total
X/C	EXHAUST PIPE W/MUFFLER 36" COAT W/POLYDYN STORM WHITE	2	2	EA	150.00	300.00

PAID
CHECK NO. V67265
AMOUNT \$20.41
DATE 10-2-20

SO# 00053772

WE APPRECIATE YOUR BUSINESS

Non-Taxable	Taxable	Sales Tax	Freight	Handling	Invoice Total
.00	300.00	32.04	85.87	2.50	420.41



• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250
 • 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787
 • 20 King Mill Road • McDonough, GA 30253 • 770-288-3200
 • 2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700

S
O
L
D
T
O

INVOICE

S
H
I
P
T
O

Calling Customer Service?
Please have your
invoice number ready.

INVOICE NUMBER	DATE
1040414	10/09/20
CUSTOMER NUMBER	PAGE
4448489	1

EXCHANGE/RETURN FORM

INVOICE NUMBER	DATE
1040414-5	10/09/20

NOTE: Please read the *How to Return an Order* instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ()

Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- Q. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other; please explain

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	VPE-11205	3/8 NPT TO 3/8 BARB STRA		7.79	7.79
1	HDA-3653	FAN CONTROL		17.99	17.99
1	CEL-65128	FUEL HOSE		25.99	25.99
1	NXO-00-52033-2	DEUTSCH DT CONNECTOR KIT		7.99	7.99
1	AEI-13130	REGULATOR FITTING KIT	S/S	Shipped from Ohio	
219.38 T 235.83					
WARNING: Proposition 65 Compliance Statement California Safe Drinking Water & Toxic Enforcement Act of 1986 Some products purchased from our catalog or website contain chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm. Purchaser may receive full refund, including shipping costs, for return of unopened package within 30 days.					
** DECLARED PART VALUE THIS SHIPMENT **			59.76 U.S.D.		
** TOTAL INVOICE CA SALES TAX **			5.00		

219.36
+ 235.83

Qty.	Part Number	Exchange	Refund	Qty.	Reason Code	Explanation
1	VPE-11205					
1	HDA-3653					
1	CEL-65128					
1	NXO-00-52033-2					
** DECLARED VALUE		59.76				

NOTE: If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.

*Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

Thank
You!

Credit Card Charge 302.52

Some parts are not legal for sale or use in California on any pollution controlled motor vehicles.

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:
GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

S16551009

U0002338

PRIORITY MAIL RETURNS® SERVICE

Summit Racing Equipment
Attn: Returns Dept.
2200 East Interstate 20
Arlington, Tx. 76018-9804

NO POSTAGE
NECESSARY IF
MAILED IN THE
UNITED STATES

USPS TRACKING NUMBER



9201 9902 3186 9065 0044 51

083807

☐ ESTIMATE (VALID FOR 30 DAYS)

DATE 12/23/2020	<input checked="" type="checkbox"/> SERVICE <input type="checkbox"/> INSTALL	<input type="checkbox"/> WILL CALL <input type="checkbox"/> DELIVER	PHONE
NAME			MAKE
ADDRESS			MODEL
			SERIAL
ITEM TO BE SERVICED		NATURE OF SERVICE REQUEST	

QTY	PART #	DESCRIPTION OF PARTS OR MATERIALS	PRICE	AMOUNT
2		Bucket Seat - Leather Side	150	300
2		Panel Straps	75	150
		17 inch		
		Sierra - Carmine		450
		ESS-5198		
		Side leather Black		
		Black Snaps on Seat.		
LABOR PERFORMED			TOTAL MATERIALS	
Paco's Custom Upholstery			TAX	
100 Church Street			TOTAL LABOR	
Roseville CA				
(916) 749 3650			TOTAL AMOUNT	

DATE PAID 2nd week Jan-2021	DEPOSIT	RECEIVED BY
ESTIMATES ARE FOR LABOR ONLY, MATERIAL ADDITIONAL. WE WILL NOT BE RESPONSIBLE FOR LOSS OR DAMAGE CAUSED BY FIRE, THEFT, TESTING, OR ANY OTHER CAUSES-BEYOND OUR CONTROL.		
AUTHORIZED BY:		Repair Order DUPLICATE

order 5084

TERMS - NET CASH
NO GOODS HELD OVER 30 DAYS

09-11



7101 Vorden Parkway
South Bend, IN 46628-8422
Phone: (574) 287-2345
800: (800) 428-8355
Customer Service: Ext. 4360
Fax: (574) 236-7707

INVOICE

INVOICE NUMBER	INVOICE DATE	PAGE
FL58228	12/28/20	1
PURCHASE ORDER NUMBER		
RP1178512981		

12/28/20
15:12:10

BILL TO:

SHIP TO:

SHIP METHOD: OnTrac
CAP

Plan 000069390 Team TIRES Wave 006 Prcl 372932483

ORDER DATE	SALES REP./NAME/PHONE EXT	TERMS		MAKE, MODEL AND YEAR		WHSE
12/28/20	ECOMMERCE ORDERS	Visa		XXXX, KELL J4,60		NV
PART NUMBER	QUANTITY ORDERED	QUANTITY SHIPPED	GROUP	DESCRIPTION	UNIT PRICE	EXTENSION
065TR5H735 1021917 Road Hazard ID:	2	2	90	205/65R15 HK KINERGY ST 1021917 94T Two Year Road Hazard Included* 550001605006 550001605007	78.98	157.96
REGCARDR REGISTRATIONR	1	1		Tire DOT Number registration has been filed electronically FIND WARRANTY DETAILS @ WWW.TIRERACK.COM/HK0119	N/C	
27TR5H735 1022045 Road Hazard ID:	2	2	89	225/70R15 HK KINERGY ST 1022045 100T Two Year Road Hazard Included* 550001605008 550001605009	88.98	177.96
REGCARDR REGISTRATIONR	1	1		Tire DOT Number registration has been filed electronically FIND WARRANTY DETAILS @ WWW.TIRERACK.COM/HK0119 *Customer advised mixing tire types/sizes, or new and partially worn tires may cause unpredictable handling or loss of control in some driving situations *Always install new/deeper tread tires on the rear axle to help prevent oversteer in inclement weather conditions CUSTOMER FITMENT: CUSTOMER ASSUMES RESPONSIBILITY FOR USE ON VEHICLE.	N/C	
***** CONTINUED ON NEXT PAGE *****						

ALL PAST DUE ACCOUNTS ARE SUBJECT TO A FINANCE CHARGE OF 1 1/2% PER MONTH, WHICH IS AN ANNUAL PERCENTAGE RATE OF 18%.



7101 Vorden Parkway
South Bend, IN 46628-8422
Phone: (574) 287-2345
800: (800) 428-8355
Customer Service: Ext. 4360
Fax: (574) 236-7707

INVOICE

INVOICE NUMBER	INVOICE DATE	PAGE
FL58228	12/28/20	2
PURCHASE ORDER NUMBER		
RP1178512981		

12/28/20
15:12:10

BILL TO:

SHIP TO:

SHIP METHOD: OnTrac
CAP

Plan 000069390 Team TIRES Wave 006 Prcl 372932483

ORDR DATE		SALES REP. NAME/PHONE EXT		TERMS		MAKE, MODEL AND YEAR		WHSE	
12/28/20		ECOMMERCE ORDERS		Visa		XXXX, KELL J4,60		NV	
PART NUMBER		QUANTITY ORDERED	QUANTITY SHIPPED	GROUP	DESCRIPTION		UNIT PRICE	EXTENSION	
*****7265					California Tire Fee			7.00	
					Subtotal			342.92	
					Sales Tax-California			25.19	
					Visa Payment		-368.11		
					Total Payment			-368.11	
		* To make a claim visit www.tirerack.com/roadhazard .							
		* To obtain roadside assistance please call 877-920-0503.							
</									

ALL PAST DUE ACCOUNTS ARE SUBJECT TO A FINANCE CHARGE OF 1 1/2% PER MONTH, WHICH IS AN ANNUAL PERCENTAGE RATE OF 18%.

Hankook

driving emotion

Standard touring all season

KINERGY ST

205/65R15 94T

S1021917



* XL : Extra Load * RW : Reinforced

H735

205/65R15 94T

Hankook driving emotion

1021917

-0000100647-200830



UTQG Grade
TREADWEAR 680
TRACTION A
TEMPERATURE A

REMEMBER! The grade designations above are relative to standard reference conditions. Actual performance may vary due to differences in driving habits, road conditions, vehicle load, and other factors. For more information, please refer to the vehicle's owner's manual.

UTQG Grade
TREADWEAR 680
TRACTION A
TEMPERATURE A

REMEMBER! The grade designations above are relative to standard reference conditions. Actual performance may vary due to differences in driving habits, road conditions, vehicle load, and other factors. For more information, please refer to the vehicle's owner's manual.

UTQG Grade
TREADWEAR 680
TRACTION A
TEMPERATURE A

REMEMBER! The grade designations above are relative to standard reference conditions. Actual performance may vary due to differences in driving habits, road conditions, vehicle load, and other factors. For more information, please refer to the vehicle's owner's manual.

28-8355
ber. We accept
ew.
at no shipping

cannot have
g tires.
or dismount
for the return
Credit less all
rnable.
yment received
ss.
shipment has
partment at
will be scheduled.
the original pack-
material must be
depends upon these
the warranty
y to assist in
pplicable
r implied,
cular

YOU ARE RETURNING

TIRE

h Parkway • S

Hankook

driving emotion

Standard touring all season

KINERGY ST

225/70R15 100T

S1022045



* XL : Extra Load * RW : Reinforced

H735

225/70R15 100T

Hankook driving emotion

1027591

KC-0000100664-200912



UTQG Grade
TREADWEAR 680
TRACTION A
TEMPERATURE A

REMEMBER! The grade designations above are relative to standard reference conditions. Actual performance may vary due to differences in driving habits, road conditions, vehicle load, and other factors. For more information, please refer to the vehicle's owner's manual.

UTQG Grade
TREADWEAR 680
TRACTION A
TEMPERATURE A

REMEMBER! The grade designations above are relative to standard reference conditions. Actual performance may vary due to differences in driving habits, road conditions, vehicle load, and other factors. For more information, please refer to the vehicle's owner's manual.

UTQG Grade
TREADWEAR 680
TRACTION A
TEMPERATURE A

REMEMBER! The grade designations above are relative to standard reference conditions. Actual performance may vary due to differences in driving habits, road conditions, vehicle load, and other factors. For more information, please refer to the vehicle's owner's manual.

tire.
wheels.
foam
ty.
from
rice
n package.
ing material
of the
m cardboard
n package.



• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250
 • 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787
 • 20 King Mill Road • McDonough, GA 30253 • 770-288-3200
 • 2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700

Calling Customer Service?
 Please have your
 invoice number ready.

INVOICE

INVOICE NUMBER	DATE
1702396	12/29/20
CUSTOMER NUMBER	PAGE
4448489	1

EXCHANGE/RETURN FORM

INVOICE NUMBER	DATE
1702396-2	12/29/20

NOTE: Please read the *How to Return an Order* instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ()

Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- O. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other; please explain

S
O
L
D
T
O

S
H
I
P
T
O

Qty.	Part Number	Part Description	Status	Unit Price	Extended Amt.
1	ZSC-HSZ220CL	RZ-44/RZ-42/RZ40 REAR SP		30.56	30.56 T
3	GDR-73177	LUGS 7/16" STD MAG 4PK		10.99	32.97 T
3	GDR-73137	LUGS 12MMX1.50 STD MAG 4		10.99	32.97 T
FOLLOWING ITEMS WILL SHIP FROM MANUFACTURER:					
2	NXS-TM00090100	TIRE ATV			
2	NXS-TM00091100	TIRE ATV			
WARNING: Proposition 65 Compliance Statement California Safe Drinking Water & Toxic Enforcement Act of 1986 Some products purchased from our catalog or website contain chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm. Purchaser may receive full refund, including shipping costs, for return of unopened package within 30 days.					
** DECLARED PART VALUE THIS SHIPMENT **				96.50 U.S.D.	
** TOTAL INVOICE CA SALES TAX **					7.25

Qty.	Part Number	Exchange	Refund	Qty.	Reason Code	Explanation
1	ZSC-HSZ220CL			1		
3	GDR-73177			3		
3	GDR-73137			3		
** DECLARED VALUE		96.50				

NOTE: If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.

*Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

Thank
You!

Credit Card Charge 628.42

Some parts are not legal for sale or use in California on any pollution controlled motor vehicles.
 INVOICE INCLUDES ITEMS SHIPPING FROM MANUFACTURER.

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:
 GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

S16551228 CCU U0006382

PRIORITY MAIL RETURNS® SERVICE

Summit Racing Equipment
 Attn: Returns Dept.
 2200 East Interstate 20
 Arlington, Tx. 76018-9804

NO POSTAGE
 NECESSARY IF
 MAILED IN THE
 UNITED STATES

USPS TRACKING NUMBER



9201 9902 3186 9071 4016 57

662555 /

☐ ESTIMATE (VALID FOR 30 DAYS)

DATE 01/19/2021	<input checked="" type="checkbox"/> SERVICE <input checked="" type="checkbox"/> INSTALL	<input type="checkbox"/> WILL CALL <input type="checkbox"/> DELIVER	PHONE
NAME			MAKE
ADDRESS			MODEL
			SERIAL
ITEM TO BE SERVICED		NATURE OF SERVICE REQUEST	

QTY	PART #	DESCRIPTION OF PARTS OR MATERIALS	PRICE	AMOUNT
2		Bucket Seat	300	
		Side insert		
2		Panel Straps	100	
		Sierra - Carmine		
		ESS-5198		
		Paid cash	\$400	
LABOR PERFORMED			TOTAL MATERIALS	
Paco's Custom Upholstery 120 Church Street #3 Roseville CA 95678 (916) 749-3650			TAX	
			TOTAL LABOR	
			TOTAL AMOUNT	

DATE WANTED	DEPOSIT	PAID CASH	RECEIVED BY
ESTIMATES ARE FOR LABOR ONLY, MATERIAL ADDITIONAL. WE WILL NOT BE RESPONSIBLE FOR LOSS OR DAMAGE CAUSED BY FIRE, THEFT, TESTING, OR ANY OTHER CAUSES BEYOND OUR CONTROL.			
AUTHORIZED BY:			Repair Order DUPLICATE

adams 5084

TERMS - NET CASH
NO GOODS HELD OVER 30 DAYS

00-11

From:
Subject: Kellison Mid-Winter Report
Date: January 12, 2021 at 12:27 PM
To:

Last we heard our hero had it seats removed and taken to Sacramento for some retrimming. Rumor has it that they will be finished by the end of this week.

The lack of seats, a couple of holidays, and an attempted coup has limited the work in the past few weeks, but we are close!

New year Kellison accomplishments:

New tires are mounted and balanced.

Engine and steering badging has been delivered and we are working on hand painting them.

The wipers fit and work! Just need to source a new wiper arm as one of them is missing a spring.

Wheel badging stickers are in the mail.

Shift boot is in the mail.

Side vent grills are done and look the business.

Roundels are on.

Side view mirror is on.

Now have a matching set of lug nuts front and rear.

Started templating new quarter light windows.

Ordered some trim options for the roof edge.

I've looked at headlight options and tested a few. LED ones are rubbish. No focus or penetration. Recommendation is good old H4s. Hella is the standard, but do look a bit modern. Empi makes one a bit more sealed beam looking. We can swap out the regular 55/60 bulbs for 80/100 and really melt some eyeballs.

There you go! So close! Kellison should be back with you soon. Really need to get the seats back in and put some miles on it.

To get us up to date we are looking at \$1235 for labor and \$798.11 for parts, for a total of \$2033.11.

Cheers,

~~paid~~ DD1 checks
11280
1/11/21

From:
Subject: Re: Kellison: A Love Story
Date: February 14, 2021 at 4:26 PM
To:



On Feb 14, 2021, at 10:08 AM,

I Heart Kellison, I Hate Kellison. Not quite Harry Met Sally or Sleepless in Seattle. More like 10 Things I Hate About You.

It wasn't easy, but we've rewritten a horror story into more of a romcom, and we are almost finished with the ~~damn~~ beautiful thing.

Here is where we are at with some of the final items:

- We figured out what the wiper arms are from: late sixties MGB. Seems like every supplier is out of stock on the nice stainless replacements. Still searching for a pair. Good news is the system now works!
- The final quarter lights are out and ready. We figured a way to attach them so there will no stupid bolts and brackets visible. In the insurance photos you'll see they are still covered in protective white plastic. We have to finalize the window surround trim before we can make a final fitment. They are going to look super cool, and they are lexan, so no cracking when crawling in and out of the beast.
- Ah, the damn window surrounds inside and the finish around the doors. I ordered some more options. Should have photos by the end of next week of the best ones.
- Made a second run on the wheel badging. I put them on the car and will see how they hold up to temperature changes.
- Alignment: the car had over an inch of toe in and the rest was even crazier. No surprise there. We maxed out all the adjustments and got it civilized, but not perfect. Problem is that the previously wacked geometry kept the tires inside the wheel wells. Now the driver side sticks out at the top. We measured the hell out of the car and came to the conclusion that the body is not straight on the chassis AND the chassis is not straight to start with. Go figure. #lasersdontlie. What we need is adjustable upper control arms. With them I can get some negative camber and tuck those wheels in a bit without losing caster. Not sure if they exist, but the search is on. On the positive side, we found out that we got the rear axle in straight within a 1/16". Not too shabby.
- There are a few other little things that will be taken care of when we put some miles on the beast. It does already drive so much better.

So we are close. We are 10cm dilated and it's time for momma to push this baby out. I am going to shoot for a return to you in the first week of March.

Hopefully this should be our second to last bill for the beast. 32 hours labor at \$95: \$3040. Parts at \$1008.17. Total is \$4048.17. You can check the Google spreadsheet for details.

Give a call when you have time and we can talk through some of the items. Happy Valentine's Day to all!

Cheers,

PAID
2/14/21
DDI check # 11292



• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250
 • 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787
 • 20 King Mill Road • McDonough, GA 30253 • 770-288-3200
 • 2200 F Interstate 20 • Arlington, TX 76018 • 817-375-2700

S
O
L
D
T
O

Calling Customer Service?
Please have your
invoice number ready.

INVOICE

S
H
I
P
T
O

INVOICE NUMBER	DATE
1839299	02/17/21
CUSTOMER NUMBER	PAGE
4448489	1

EXCHANGE/RETURN FORM

INVOICE NUMBER	DATE
1839299-0	02/17/21

NOTE: Please read the *How to Return an Order* instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ()

Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- Q. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other: please explain

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	ARP-203-4205	HEAD STUD KIT		154.99	154.99 T
2	SPS-94800	MUSTANG II ADJUSTABLE UC		219.99	439.98 T
WARNING: Proposition 65 Compliance Statement California Safe Drinking Water & Toxic Enforcement Act of 1986 Some products purchased from our catalog or website contain chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm. Purchaser may receive full refund, including shipping costs, for return of unopened package within 30 days.					
** DECLARED PART VALUE THIS SHIPMENT **				594.97 U.S.D.	
** TOTAL INVOICE CA SALES TAX **					44.62

Qty.	Part Number	Exchange	Refund	Qty.	Reason Code	Explanation
1	ARP-203-4205					
2	SPS-94800					
** DECLARED VALUE 594.97						

NOTE: If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.

*Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

Thank
You!

Credit Card Charge 639.59

Some parts are not legal for sale or use in California on any pollution controlled motor vehicles.

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:
GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

S16550217 CCU U0004462

PRIORITY MAIL RETURNS® SERVICE

NO POSTAGE
NECESSARY IF
MAILED IN THE
UNITED STATES

Summit Racing Equipment
Attn: Returns Dept.
2200 East Interstate 20
Arlington, Tx. 76018-9804

USPS TRACKING NUMBER



9201 9902 3186 9075 6883 99

INVOICE



11947 STREETER RD. AUBURN, CA. 95602
(530)268-8912

Invoice # 617840

Date: 6/30/2021

Terms:

Bill to:

<u>Quantity</u>	<u>Discription</u>	<u>Amount</u>
6.5 Hrs	Fit side window trim on of Kellison automobile.	\$422.00

Amount Due

\$422.00



• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250
 • 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787
 • 20 King Mill Road • McDonough, GA 30253 • 770-288-3200
 • 2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700

Calling Customer Service?
 Please have your
 invoice number ready.

INVOICE

INVOICE NUMBER	DATE
690962	07/22/21
CUSTOMER NUMBER	PAGE
4448489	1

EXCHANGE/RETURN FORM

INVOICE NUMBER	DATE
690962-4	07/22/21

NOTE: Please read the *How to Return an Order* instructions on the back of this form.
 Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ()

Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- Q. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other; please explain

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	LOK-ED-5002	ENGINE DIPSTICK DRIVER S		75.95	75.95 T
1	MIL-16401	THERMOSTAT		27.95	27.95 T
1	MOR-63500	SHORT WATER PUMP SBC ALU		164.99	164.99 T
WARNING: Proposition 65 Compliance Statement California Safe Drinking Water & Toxic Enforcement Act of 1986 Some products purchased from our catalog or website contain chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm. Purchaser may receive full refund, including shipping costs, for return of unopened package within 30 days.					
** DECLARED PART VALUE THIS SHIPMENT **				268.89 U.S.D.	
** TOTAL INVOICE CA SALES TAX **					20.18

** DECLARED VALUE 268.89

PRIORITY MAIL RETURNS® SERVICE

NOTE: If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.
 *Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

Thank
 You!

Credit Card Charge 289.06

Some parts are not legal for sale or use in California on any pollution controlled motor vehicles.

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:
 GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

S16550722 CCU U0002017

Summit Racing Equipment
 Attn: Returns Dept.
 2200 East Interstate 20
 Arlington, Tx. 76018-9804

NO POSTAGE
 NECESSARY IF
 MAILED IN THE
 UNITED STATES

USPS TRACKING NUMBER



9201 9902 3186 9092 1171 55



• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250
 • 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787
 • 20 King Mill Road • McDonough, GA 30253 • 770-288-3200
 • 2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700

S
O
L
D
T
O

INVOICE

S
H
I
P
T
O

Calling Customer Service?
 Please have your
 invoice number ready.

INVOICE NUMBER DATE
 3725808 09/08/21
 CUSTOMER NUMBER PAGE
 4448489 1

EXCHANGE/RETURN FORM

INVOICE NUMBER DATE
 3725808-1 09/08/21



NOTE: Please read the *How to Return an Order* instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ()

Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- Q. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other, please explain

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	GRI-1-55182-X	RADIATOR	S/S	292.68	292.68 T
			** DECLARED PART VALUE THIS SHIPMENT **	292.68 U.S.D.	
			** TOTAL INVOICE CA SALES TAX **		24.51

WARNING: Proposition 65 Compliance Statement
 California Safe Drinking Water & Toxic Enforcement Act of 1986
 Some products purchased from our catalog or website contain chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm. Purchaser may receive full refund, including shipping costs, for return of unopened package within 30 days.

NOTE: If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.
 *Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

Thank
 You!

Credit Card Charge 317.19

Some parts are not legal for sale or use in California on any pollution controlled motor vehicles.

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:
 GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

S16550908 U0002451

PLEASE NOTE:

Items on this order do not qualify for return on a prepaid label. If you have questions about returning one of these items, please visit our Help Center at <https://help.summitracing.com>.

If you wish to make a return, please ship the product via UPS, Fedex or Postal to:

SUMMIT RACING EQUIPMENT
 ATTN: RETURNS DEPT.
 2200 East Interstate 20
 Arlington, TX 76018-9804

From: **Driven Garage** messenger@messaging.squareup.com
Subject: You paid an invoice! (#2115a)
Date: March 24, 2022 at 10:27 PM
To:



Driven Garage

Invoice Paid

\$1,778.93

Parts + 50% expected labor

Invoice #2115a

March 24, 2022

Customer

Kellison road tune & rally prep

Message

We appreciate your business.

Invoice summary

Parts

\$707.93

50% expected labor	\$1,071.00
--------------------	------------

Subtotal	\$1,778.93
----------	------------

Total Paid	\$1,778.93
-------------------	-------------------

Visa 7205

03/24/22, 10:27 PM

Send estimates or invoices for your business?

Process \$1,000 in sales free when you sign up for Square.

[Get Started](#)

Driven Garage

© 2022 Block, Inc.

[Square Privacy Policy](#) | [Security](#)






• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250
• 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787
• 20 King Mill Road • McDonough, GA 30253 • 770-288-3200
• 2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700

Calling Customer Service?
Please have your
invoice number ready.

INVOICE

INVOICE NUMBER	DATE
1164873	07/12/22
CUSTOMER NUMBER	PAGE
4448489	1

EXCHANGE/RETURN FORM

INVOICE NUMBER	DATE
1164873-7	07/12/22
	

NOTE: Please read the *How to Return an Order* instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ()

Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- Q. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other; please explain

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.	Qty.	Part Number	Exchange	Refund	Qty.	Reason Code	Explanation
1	CHP-CP106LT	OIL PAN		355.50	355.50 T	1	CHP-CP106LT					
1	CHP-JR131	ENGINE OIL DIPSTICK		25.43	25.43 T	1	CHP-JR131					
WARNING: Proposition 65 Compliance Statement California Safe Drinking Water & Toxic Enforcement Act of 1986 Some products purchased from our catalog or website contain chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm. Purchaser may receive full refund, including shipping costs, for return of unopened package within 30 days.												
** DECLARED PART VALUE THIS SHIPMENT **				380.93 U.S.D.		** DECLARED VALUE 380.93						
** TOTAL INVOICE CA SALES TAX **					28.58							

NOTE: If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.

*Explanation of status column codes: B/D = backorder C/S = cancel ship S/S = shipped separate

Thank
You!

Credit Card Charge 409.50

Some parts are not legal for sale or use in California on any pollution controlled motor vehicles.

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:
GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

S16550712 CCU U0002857

How to Return or Exchange a Product

To ensure the best service, returns and exchanges must be initiated online. Please disregard references to a printed label on this invoice.

Go to SummitRacing.com>Returns or visit the online Help Center at SummitRacing.com to start your return.

If you are unable to access the online returns process, please text RETURN to 330-302-1289 to receive a link to start your return.