

BILL TO:			

DATE	INVOICE #	
8/16/2021	64792	
BILLING PERIOD		
8/1 to 8/15/2021		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Lubricant, Cos	Cosworth Coolant	0.5	22.65	11.33T
Parts/Materials	New Racing Harness (Old one out of date)	1	469.87	469.87T
Labor - Bryce	8/9 remove radiator, install new radiator, fill with water and cosworth, remove seat, begin installing belts, run car, check water level, charge battery, clean car, remove wheels and have new tires put on both sets of wheels, reinstall wheels, finish installing belts, reinstall seat, prep camera and transponder for race day, etc.	8	103.00	824.00T
Shop Supplies	Shop Supplies Sales Tax 9.9%	1	9.90%	0.00T 129.21
				127.21
Please remit paym	nent to J & L Fabricating PO Box 70 Puyallup, Wa	. 98371	Total:	\$1,434.41



BILL TO:			

DATE	INVOICE #	
8/2/2021	64757	
BILLING PERIOD		
7/15 to 7/31/21		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Alum Sheet, 50	Alum Sheet, 5052 - H32.063" (per sq ft)	5	5.28646	26.43T
Alum Tube, 60	6061 Aluminum Tube 1.25 x .065 Wall	1	4.06	4.06T
Labor - Bryce	7/27 put on lift, remove wheels, begin nut and	2.5	103.00	257.50T
	bolt, weigh fire bottle, install battery, check			
	exhaust, check oil, prime oil system, etc.			
Labor - Bryce	7/28 remove radiator and drain cooling system,	9	103.00	927.00T
	finish nut and bolt, remove seat and order belts,			
	remove old belts, reinstall seat, clean car, bleed			
	brakes, check on tires, reinstall wheels, reinstall			
	radiator and fill cooling system, run car, etc.			
Labor - Bryce	7/30 gather spares	1	103.00	103.00T
Shop Supplies	Shop Supplies	1	38.63	38.63T
Machine - Evan	8/3/21	0.5	118.00	59.00T
	-Machined radiator mounting studs.			
Labor - Evan	8/3/21	7.5	103.00	772.50T
	-Trimmed radiator core to size, cleaned and			
	prepped for welding. Fabricated radiator end			
	tanks, and outlets. Welded tanks and outlets to			
	core, pressure tested. Fabricated header plates.			
	Welded header plates and mounting studs to			
	radiator.			
	Sales Tax 9.9%		9.90%	216.62
Please remit paym	l ent to J & L Fabricating PO Box 70 Puyallup, Wa.	98371		
	<u> </u>		Total:	\$2,404.74



yallup, WA 983/1 3.845.0617	W 1 2021
BILL TO:	0712812

DATE	INVOICE #	
7/1/2021	64663	
BILLING PERIOD		
6/15 to 6/30/21		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quan	tity	Rate	Amount
Parts/Materials	Tear down, access repairs, repairs declined pack and ship to Jay Ivey. Included in the package, head gasket, rod bearings, main bearings	l,	1	1,562.50	1,562.50
	Michael, This was for the 26R when it blew the head gasket and I sent it to Reilly for repairs and their bid came in at \$20K and we decided to send it to Jay Ivey. This was Reilly's labor f the tear down, parts that they sent with the engine to Ivey. Louie	9			
Please remit payr	nent to J & L Fabricating PO Box 70 Puyallu	p, Wa. 98371		Total:	\$1,562.50



0021
02/23/2

DATE	INVOICE #	
2/1/2021	64239	
BILLING PERIOD		
1/16 to 1/31/21		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	Custom Tach Cables	2	87.64	175.28
Freight-In	Freight in for Tachometer	1	38.92	38.92
Parts/Materials	Test Tachometer, repair as needed	1	763.00	763.00
Labor - Brian M	1/18/21 Install tachometer. Remove airbox cover, fire up engine, test tach and re-fog engine. Reinstall airbox cover.	0.5	103.00	51.50
Shop Supplies	Shop Supplies		4.64	4.64
Please remit paym	ent to J & L Fabricating PO Box 70 Puyallup, Wa	. 98371	Total:	\$1,033.34



.845.0617	2021
BILL TO:	01/2012
	-

DATE	INVOICE #	
12/20/2020	64149	
BILLING PERIOD		
11/16 to 12/20/20		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	T/C Engine, Etc. for the Malone 26R	1	8,755.72	8,755.72
Bolt, AN5-13A	Bolt, AN5-13A 5/16-24 x 1	6	1.74	10.44
Washer, Lockw	Lockwasher 5/16"	6	0.15	0.90
Bolt, AN5-11A	Bolt, AN5-11A 5/16-24 x 11/16	4	1.56	6.24
Washer, AN Th	5/16" AN Thin washer	14	0.056	0.78
Nut, Jet 5/16 - 24	5/16" - 24 Jet Nut	4	0.756	3.02
Washer, AN Th	1/4" AN Thick Washer	12	0.09	1.08
Bung, O2 Sens	O2 Sensor, Plug	1	15.68	15.68
Nut, Jet 3/8 - 24	3/8" x 24 Jet Nut	2	1.71	3.42
Washer, AN Th	3/8" Thick AN Washer	2	0.12	0.24
Lubricant, Joe	Lubricant, Joe Gibbs XP6	6.5	13.286	86.36
Chassis Dyno	Chassis Dyno (Initial setup, warmup, and 1 hour of Dyno time)	1	265.00	265.00
Labor - Brian M	12/8/20 Move engine crate to main shop. Uncrate engine and remove plastic. Clean and inspect clutch.	1	103.00	103.00
Labor - Brian M	12/9/20 Finish cleaning and inspecting engine change parts. Clean starter mount bolt holes and install mount bolts with blue Loctite. Put car on lift. Install clutch, driveshaft, gearbox and engine. Check crank end float.	8	103.00	824.00
Labor - Juan	12/09/20 clean the car inside out, under the car and the wheels	3.5	70.00	245.00
Labor - Bryce	12/9 assist Brian m with installing engine and transmission, install engine mounts, bleed clutch, install shifter, etc.	4	103.00	412.00
We appreciate you	r business! Happy Holidays!		Total:	



yallup, WA 98371 3.845.0617	AP A 0021
BILL TO:	0112012

DATE	INVOICE #	
12/20/2020	64149	
BILLING PERIOD		
11/16 to 12/20/20		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Brian M	12/10/20 Install fuel lines, oil lines, catch can lines, starter, air box, tach cable, throttle cable, exhaust system, swirl pot and radiator. Safety wire engine mounts, oil drain plug, carb hats and airbox. Fill oil and coolant to proper levels. Remove spark plugs and crank engine for oil pressure. Crack open oil line out of engine to filter to aid in getting pressure. Move car outside and run engine. Recheck oil and coolant levels. Tachometer does not work. Check dimensions of cable ends, engine drive and tach drive. Contact local vendor about making new cable using original cable sheath and nuts. Safety wire oil filler cap.	8	103.00	824.00
Labor - Bryce	12/10 assist Brian m with oil pressure, routing of lines, install of chassis brace, checking timing, tach cable issues, etc.	2	103.00	206.00
Labor - Brian M	12/16/20 Remove current tach cable sheath and install new part with updated cable. Install and level tachometer. Remove spark plugs and install TDC gauge. Turn engine over and find TDC for making timing marks.	1.5	103.00	154.50
Labor - Brian M	12/17/20 Assist Eddie with timing marks. Reinstall spark plugs and wires. Clean oil cooler. Warm up engine, check timing and for leaks. Post Dyno- Remove tachometer and bench test. Contact Vendor, box up tach and ship out. Pump out fuel and fill to 2 gallons for storage. Remove battery. Safety wire carb hats.	2	103.00	206.00
We appreciate you	lr business! Happy Holidays!		Total:	



yallup, WA 98371 3.845.0617	0021
BILL TO:	01 2012

DATE	INVOICE #		
12/20/2020	64149		
BILLING PERIOD			
11/16 to 12/20/20			

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Labor - Brian M	12/17/20 Strap car to Dyno, connect sensors, place fans and set up computer. Run Dyno computer and inspect car during pulls. Remove car from Dyno when finished with pulls.	1.75	103.00	180.25
Labor - Brian M	12/18/20 Remove engine airbox, run engine and fogging oil into each cylinder. Reinstall airbox and safety wire airbox bolt. Remove battery and place on charging cart. Install hood, wipe down body and cover.	0.75	103.00	77.25
Shop Supplies	Shop Supplies	1	98.55	98.55
Labor - Bryce	12/17 assist Brian m with strapping car on Dyno	0.5	103.00	51.50
We appreciate you	ur business! Happy Holidays!		Total:	\$12,530.93



yallup, WA 98371 3.845.0617	2020
BILL TO:	1211612

DATE	INVOICE #		
11/15/2020	64105		
BILLING PERIOD			
10/16 to 11/15/20			

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quan	tity	Rate	Amount
	For: Lotus, 26R				
Freight - Out	Engine From Phil Reilly to Ivey Engines		1	243.64	243.64T
	Sales Tax 9.9%			9.90%	24.12
Please remit pay	ment to J & L Fabricating PO Box 70 Puyai	llup, Wa. 98371		Total:	\$267.76



vallup, WA 98371 3.845.0617	2020
BILL TO:	1012312

DATE	INVOICE #		
9/30/2020	64025		
BILLING PERIOD			

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Freight-In	FREIGHT INBOUND - Diff	1	29.302	29.30T
	Housing/Seal/Output seal etc.			
Parts/Materials	Rear diff housing, Alum WT 7.8# p/n 026R	1	826.00	826.00T
	0004			
Parts/Materials	Seal, Diff Pinion p/n 036R 6017	1	43.40	43.40T
Parts/Materials	Diff output seal p/n 036 6007	2	10.50	21.00T
Parts/Materials	Diff gasket inv 3/19 p/n 026R 0014	1	10.50	10.50T
Parts/Materials	Gasket set, Trans p/n 026F 0810	1	42.00	42.00T
Parts/Materials	Input SH seal, Quaife GR kit M28x42x7 p/n R026F 7052	1	13.70	13.70T
Parts/Materials	Seal, tail shaft p/n 026F 7292	1	15.40	15.40T
Parts/Materials	Seal p/n NAT2443	1	12.02	12.02T
Parts/Materials	Seal p/n 2503N	1	10.68	10.68T
Parts/Materials	Too Credit Parts Return - Gasket Set invoiced on 9-15-2020 # 64025	-1	42.00	-42.00T
Freight - Out	FREIGHT OUTBOUND - XPO Logistics - Lotus 26R Engine	1	230.49	230.49T
Labor - Dennis	09-08 Start repair of rear end and inspection and gasket replacement of transmission	1	103.00	103.00T
Labor - Bryce	9/8 remove shifter and gearbox, drain gearbox and clean parts, give gearbox to Louie for repair, remove driveshaft, disconnect half shafts, remove broken rear end and install short gear, reassemble rear suspension, etc.	8	103.00	824.00T
Labor - Louie	09-09 Dismantle and inspect rear end and transmission; list parts to order	3	103.00	309.00T
Labor - Louie	09-10 Clean parts in preparation for reassemble	1	103.00	103.00T
			Total:	



	2020
BILL TO:	1012312
	•

DATE	INVOICE #		
9/30/2020	64025		
BILLING PERIOD			

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Labor - Louie	09-15 Inspect new rear end main case, install axle seals, drill for safety wire, install new pinion flange seal, install dropout, install axles with bearings; start reassemble of transmission	7.5	103.00	772.50T
Labor - Louie	09-16 Size and order transmission seals, Install seals in transmission extension and input housing		103.00	103.00T
Labor - Louie	09-18 Assemble transmission; make extension gasket, straighten shift rod	6	103.00	618.00T
Shop Supplies	Shop Supplies Sales Tax 9.9%	1	94.25 9.90%	94.25T 409.78
	•	•	Total:	\$4,549.02



	12020
BILL TO:	081241

DATE	INVOICE #		
7/31/2020	63910		
BILLING PERIOD			

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Parts/Materials	Tach cable	2	137.29	274.58T
	Sales Tax 9.9%		9.90%	27.18
	1	I		000 = -
			Total:	\$301.76



	2020
BILL TO:	081071

DATE	INVOICE #		
7/15/2020	63888		
BILLING PERIOD			

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	Tach cable spade adaptor p/n 472N 7120	2	24.25	48.50T
Labor - Bryce	7/1 follow up on parts orders, install new tach cable, re route wiring under dash, run car and test tach operation, etc.	2	103.00	206.00T
Labor - Dennis	07-09 Remove battery from car before taking to storage	0.25	103.00	25.75T
Shop Supplies	Shop Supplies	1	231.75	231.75T
	Sales Tax 9.9%		9.90%	50.69
	1		Total:	\$562.69



yallup, WA 98371 3.845.0617	0020
BILL TO:	0712712

DATE	INVOICE #		
6/30/2020	63856		
BILLING PERIOD			

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Alum Sheet, 50	Alum Sheet, 5052 - H32.063" (per sq ft)	5	5.28	26.40T
Radiator core	Radiator core	1	172.55	172.55T
Lubricant, Cos	Cosworth Coolant	1	16.58	16.58T
Chassis Dyno	Chassis Dyno (Initial setup, warmup, and 1 hour of dyno time)	1	265.00	265.00T
Labor - Bryce	6/22 put on lift, change rear gear, drain anti-freeze, add water, add fuel, top off all fluids, put on dyno, change jets, drain water and remove radiator for repair, etc.	6	103.00	618.00T
Labor - Evan	6/23/20 -Epoxied radiator core, pressure tested, repair unsuccessful. Cut down new radiator core to size, fabricated end tanks, outlets, and header plates. Welded all together and pressure tested. Installed radiator in car, filled with coolant, ran engine and checked coolant level.	8	103.00	824.00T
Labor - Bryce	6/25 remove tach cable, replace old transponder mount, add fuel, order new tach cables, look over car, gather spares, etc.	2	103.00	206.00T
Labor - Bryce	6/26 remove headlight cover and prep paint chip areas	0.5	103.00	51.50T
Shop Supplies	Shop Supplies		57.17	57.17T
	Sales Tax 9.9%		9.90%	221.48
			Total:	\$2,458.68



yallup, WA 98371 3.845.0617	0020
BILL TO:	05122120

DATE	INVOICE #	
4/30/2020	63714	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Tie, Self-Locki	Tie, Self-Locking 11.1 x .14	6	0.17	1.02T
Tie, Self-Locki	Tie Self Locking 14.19 TY28M	6	0.21	1.26T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	4	13.28	53.12T
Wire, Electrica	14 ga Wire Orange (Per Ft)	10	0.06	0.60T
Wire, Electrica	14 ga Wire Black (Per Ft)	10	9.39	93.90T
Heat Shrink Tu	Heat Shrink Tubing 5/16" (per ft)	6	2.42	14.52T
Heat Shrink Tu	3/8" Heat Shrink Tubing (Per Ft)	2	2.26	4.52T
Heat Shrink Tu	1/4" Heat Shrink Tubing (Per FT)	1	8.60	8.60T
Ignition, MSD	Wiring harness for MSD box 6425 6AL w/ rev limiter	1	40.00	40.00T
Electrical Ter	Electrical, 12-10 #10 ring terminal	2	0.42	0.84T
Electrical Ter	16-14 ga Butt connector non-insulated	4	0.37	1.48T
Electrical Ter	Electrical Term, KTN24 Connector Kwikon	2	0.60	1.20T
<i>Screw, #8 x 1/2</i>	Screw, #8 x 1/2 Sheet Metal	6	0.15	0.90T
	Michael, This is from a parts sheet that was not put on previous invoices for the 26R.			
	Sales Tax 9.9%		9.90%	21.97
			Total:	\$243.93



	2020
BILL TO:	041131

DATE INVOICE		
3/15/2020	63593	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Parts/Materials	MS21250-06008 Bolt	10	8.05	80.50T
Parts/Materials	MS20002C6 washer	10	0.17	1.70T
Freight-In	UPS SHIPPING - Bolts	1	14.35	14.35T
Labor	02/29/20	3.5	103.00	360.50T
	clean the car inside out, under the car and the			
	wheels, move to storage			
Shop Supplies	Shop Supplies	1	6.30	6.30T
	Sales Tax 9.9%		9.90%	45.87
			Total:	\$509.22



2020
11912

DATE	INVOICE #	
2/29/2020	63564	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	Long drive pegs p/n TTR-WH-001/002	12	14.86	178.32T
Freight-In	Drive Pins	1	44.80	44.80T
Outside Service	Balance two half shafts.	2	98.56	197.12T
Washer, AN Th	3/8" Thick AN Washer	4	0.12	0.48T
BOLT, AN5-7A	BOLT, AN5-7A	4	1.47	5.88T
Washer, AN Th	5/16" AN Thin	8	0.12	0.96T
<i>Nut, Jet 5/16 - 24</i>	5/16" - 24 Jet Nut	8	0.86	6.88T
Nut, Hex 1/2-2	1/2"-20 grade 8 hex nut	2	0.24	0.48T
Washer, AN Th	3/8" Thin AN Washer	4	0.37	1.48T
Lubricant, Cos	Cosworth Coolant	1	16.58	16.58T
Labor - Charles	2/27 began assembling rear suspension had to press apart axles to install bolt that holds hub to axle	5	103.00	515.00T
Labor - Charles	2/28 finished installing rear assembly axles, control arms, brakes, struts, serviced tranny, flushed system, start engine and run up to temp, car on ground and wheels on, safety wired wheels	9	103.00	927.00T
Shop Supplies	Shop Supplies	1	43.26	43.26T
	Sales Tax 9.9%		9.90%	191.89
			Total:	\$2,130.13



yallup, WA 98371 3.845.0617	2020
BILL TO:	0310512

DATE	INVOICE #	
2/15/2020	63527	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	SHIPPING - Nilos Seals	1	32.59	32.59T
Parts/Materials	Nilos seal p/n LM11949 11910 AV	2	25.92	51.84T
Parts/Materials	Nilos seal p/n L44649 44610AV	2	20.74	41.48T
Labor - Bryce	2/7 put car on different stands, install DIFF and new mounts, install DIFF brace, install driveshaft, install rear uprights and shocks, assemble rear axles, disassemble/reassemble rear axles and send out for balance, install forward portion of exhaust, go through old hardware and begin replacing, follow up on parts orders, etc.	8	103.00	824.00T
Shop Supplies	Shop Supplies	1	24.72	24.72T
			Total:	\$1,071.12



yallup, WA 98371 3.845.0617	0020
BILL TO:	0212112

DATE	INVOICE #	
1/31/2020	63492	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Parts/Materials	Return Parts - Drive pegs, 26 R wheels R026G 0011 - Previously Billed Malone Invoice 63337 11/15/2019	-8	15.37	-122.96T
Freight - Out	UPS Shipping - Drive Flanges	1	14.29	14.29T
Outside Service	Electroless Nickel Plate Drive Flanges	2	69.70	139.40T
Labor - Bryce	1/17 install front rotors and calipers, remove upper control arms and modify/ repair, reinstall, nut and bolt front suspension, etc.	8	103.00	824.00T
Shop Supplies	Shop Supplies	1	24.72	24.72T
			Total:	\$966.52



yallup, WA 983/1 3.845.0617	2020
BILL TO:	0212112

DATE	INVOICE #	
1/15/2020	63460	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Bolt, AN5-21A	Bolt, AN5-21A 5/16-24 x 1-11/16	4	2.37	9.48T
Nut, Jet M10-1	10mm-1.25 jet nut	12	2.82	33.84T
Nut, Jet 5/16 - 24	5/16" - 24 Jet Nut	4	1.86	7.44T
Bolt, AN6-7A	Bolt, AN6-7A 3/8-24 x 5/16	8	2.10	16.80T
Nut, Jet 3/8 - 24	3/8" x 24 Jet Nut	2	1.71	3.42T
Washer, Lockw	Lockwasher 3/8"	2	0.42	0.84T
Nut, Nyloc AN	Nyloc AN 5/16-24	2	1.50	3.00T
Rivet, Aluminu	1/8" Pop Rivet	4	0.27	1.08T
Washer, Backu	1/8" aluminum backup washer	4	0.09	0.36T
Washer, AN Th	3/8" Thick AN Washer	8	0.12	0.96T
Labor - Bryce	1/14 prep and build rear uprights, install races into front hubs, install fuel tank and fuel plumbing, install tail lights and wiring, etc.	8	103.00	824.00T
Labor - Bryce	1/15 pack front wheels bearings, blast and paint cross bar, install front rotors to hubs, etc.	8	103.00	824.00T
Shop Supplies	Shop Supplies	1	49.44	49.44T
	Sales Tax 9.9%		9.90%	175.69
			Total:	\$1,950.35



yallup, WA 98371 3.845.0617	2020
BILL TO:	0112112

DATE	INVOICE #	
12/31/2019	63408	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Parts/Materials	Drivetrain splined -yoke TTR-FD-015 and garloc Seals including shipping	2	560.11	1,120.22T
Time-sert, 5/16	Time-sert, 5/16-18 Long	1	2.98	2.98T
Lubricant, Gea	Mobile One 75w 90 Gear Oil	1	14.17	14.17T
Nut, Jam 5/8-1	Nut, Jam 5/8-18 RH	1	4.38	4.38T
Labor - Dennis	12-06 Repair stud threads in rear end case, install dropout	2	103.00	206.00T
Labor - Dennis	12-09 Install axles and bearings in 4.9 rear end	0.5	103.00	51.50T
Shop Supplies	Shop Supplies	1	7.73	7.73T
1 11	Sales Tax 9.9%		9.90%	139.29
	1	.	Total:	\$1,546.27



	2019
BILL TO:	12/2012
	-

DATE	INVOICE #		
11/30/2019	63379		
BILLING PERIOD			

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	DIFF housing bearings AXS 6206 2RSC3	2	7.18	14.36T
Magnaflux - Br	11/27 Magnaflux drive axle parts. 1 cracked yoke. Clean parts.	2	150.00	300.00T
Shop Supplies	Shop Supplies	1	10.55	10.55T
	Sales Tax 9.9%		9.90%	32.17
			Total:	\$357.08



845.0617	2019
BILL TO:	1210612
	-

DATE	INVOICE #	
11/15/2019	63337	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Freight-In	Freight - wheel bearing/Nilos ring/bushing mount	1	25.94	25.94T
Parts/Materials	Wheel bearing inner race kit 050C 6011	2	44.80	89.60T
Parts/Materials	Nilos ring, outer 3/4" ID 050C 7501	2	12.60	25.20T
Parts/Materials	Nilos ring, inner 1.06" ID 050C 7502	2	14.00	28.00T
Parts/Materials	HD diff bushing mount (pair) 050R 6001HD	1	203.00	203.00T
Parts/Materials	Torque rod Poly isolator R026C 6036	4	4.88	19.52T
Parts/Materials	Drive pegs, 26 R wheels R026G 0011	8	15.37	122.96T
Parts/Materials	Uni torque nuts M16, pack	1	19.58	19.58T
Parts/Materials	U joint p/n PRE 344 (Spicer 1300)	4	29.21	116.84T
Parts/Materials	Rear wheel bearings AXS6007 2RSC3 EMQ	4	8.218	32.87T
Magnaflux - Lo	Magnetic Particle Check, rear axles, half shafts etc	1.5	150.00	225.00T
Labor - Bryce	11/6 put on lift, remove rear wheels, begin removing diff, etc.	0	103.00	0.00T
Labor - Bryce	11/6 remove rear bumper, remove rear portion of the exhaust, remove tail lights	0	103.00	0.00T
Labor - Bryce	11/7 remove fuel tank, remove fuel lines, drill out rivets and move wiring, remove fuel pressure reg., prep for repair	0	103.00	0.00T
Labor - Bryce	11/7 remove diff, remove rear uprights, remove front hubs. order parts, disassemble right rear upright, clean parts, mark and index parts, etc.	6	103.00	618.00T
Labor - Bryce	11/8 disassemble rear axles, order parts, disassemble front hubs, clean parts and prep for crack check, research parts, disassemble left rear upright, clean and bag hardware, etc.	6	103.00	618.00T
Labor - Dennis	11-12 Inspect rear end; check breakaway torque of diff	2	103.00	206.00T
Labor - Dennis	11-13 Order axle bearings	0.25	103.00	25.75T
Shop Supplies	Shop Supplies	1	57.94	57.94T
			Total:	



	2019
BILL TO:	1210612
	-

DATE	INVOICE #		
11/15/2019	63337		
BILLING PERIOD			

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
	Sales Tax 9.9%		9.90%	240.99
			T-4-1	Ø2 /75 10
			Total:	\$2,675.19



yallup, WA 983/1 3.845.0617	1019
BILL TO:	1111512

DATE	INVOICE #		
10/15/2019	63269		
BILLING PERIOD			

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Filter, Oil B253	Oil Filter B253	1	22.42	22.42T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	0.5	13.28	6.64T
Antifreeze, con	Auto extra all season CONCENTRATE	1	14.91	14.91T
Labor - Curtis	10/9- Started to winterize car: Warmed up, did engine checks (compression and leakdown), inspected and replaced oil filter, drained coolant, pumped out fuel	4	103.00	412.00T
Labor - Curtis	10/9- started winterizing car: warmed up motor, compression and leakdown test, pumped out gas, pulled oil filter, inspected and replaced	4	103.00	412.00T
Labor - Curtis	10/10- Finished winterizing car by adding anti freeze, warming and fogging motor, charge battery and disconnect	1.5	103.00	154.50T
Shop Supplies	Shop Supplies Sales Tax 9.9%	1	29.36 9.90%	29.36T 104.13
			Total:	\$1,155.96



yallup, WA 98371 3.845.0617	1019
BILL TO:	1012112

DATE	INVOICE #	
9/30/2019	63235	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Parts/Materials	6.5" x 23" - 13" Avon FF A25	4	390.00	1,560.00T
Parts/Materials	Spark plug, NGK CR10EIX	8	12.50	100.00T
Race Fuel, Tric	Race Fuel, Trick 114	5	12.93	64.65T
Chassis Dyno	9/16/19 Strap down car, connect sensors and set up fans. Check fluids, fire up engine and warm up. Run dyno computer during several pulls. Replace spark plugs and replace sensor cable. Run car again to verify operation. Move car back to main shop.	1.5	265.00	397.50T
Labor - Bryce	9/17 install fire bottle, add fuel, charge battery, etc.	1.5	103.00	154.50T
Labor - Juan	09/19/19 clean the car inside out, the wheels and the body	1.5	70.00	105.00T
Shop Supplies	Shop Supplies	1	33.07	33.07T
	Sales Tax 9.9%		9.90%	239.06
			Total:	\$2,653.78



	2019
BILL TO:	07/2212

DATE	INVOICE #	
6/30/2019	62987	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Parts/Materials	St -43 Compound Brake Pads	2	280.126	560.25T
	Sales Tax 9.9%		9.90%	55.46
	1			
			Total:	\$615.71



allup, WA 98371 .845.0617	2019
BILL TO:	0710812
	_

DATE	INVOICE #	
6/15/2019	62949	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Parts/Materials	2 Feet 5/16 Fuel Line	1	7.42	7.42T
Parts/Materials	Super Starter XLT (New Starter on engine, 1 in your spares box)	2	701.73	1,403.46T
Parts/Materials	MS21250-6008 3/8 Bolt	16	8.05	128.80T
Parts/Materials	MS2002C6 Washer	8	0.16	1.28T
Seal, CR6125	Seal, CR6125 .625 x .933 x .188 SL	1	12.45	12.45T
Parts/Materials	MS20002-6 Washer	8	0.12	0.96T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	6	13.29	79.74T
Lubricant, Cos	Cosworth Coolant	1	14.58334	14.58T
Brake Bleeder	Brake Bleeder Valve	1	6.10	6.10T
Filter, B253	Baldwin Oil Filter	1	22.43	22.43T
Nut, Jet 5/16	5/16" K-Nuts (Jet Nuts)	4	1.86	7.44T
<i>Nut, Jet 3/8</i>	3/8" Jet Nuts	8	1.71	13.68T
Race Fuel, Tric	Race Fuel, Trick 114	3	12.93	38.79T
Brake Clean	Brake Clean 14 oz can	5	4.89071	24.45T
Labor - Juan	06/04/19	3.5	70.00	245.00T
	clean the car inside out, under the car, the wheels and the body			
Labor - Curtis	6/5- Put on lift, drained both oil and coolant tanks, talked to Bryce about color of oil in catch tanks, drained oil, pulled filter, cut filter open and stood up to drain out of element, pulled transponder, inspected throttle cable, inspected cable mounts and return springs, blew out and inspected radiator and oil cooler, inspected/crank checked/nut and bolt exhaust, pressure tested cooling system and cap, nut and bolt Carbs, inspected fuel lines and nut and bolt AN fittings, nut and bolt/inspect oil pan, nut and bolt/inspected oil lines and fittings	5.25	103.00	540.75T
			Total:	



yanup, WA 98371 3.845.0617	- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
BILL TO:	0710812

DATE INVOICE		
6/15/2019	62949	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Curtis	6/6- Inspected oil filter element, put new oil in car, inspected and cleaned bottom of car for leaks, started nut and bolt on axles, Shook suspension down, found a poorly seated upper shock bushing on right front and reseated, Full nut and bolt/inspection suspension, inspected brake hard and soft lines, inspected brake rotors, spun spindles to feel wheel bearings, nut and bolt/inspection of steering wheel and shaft, pulled all brake pads, inspected pads with Brian, installed new front pads, reinstalled rear pads, ordered new front pads for spares, replaced nuts that secure the pads in caliper, inspected brake and clutch master cylinders, inspected bias bar, found slop in brake pedal and asked Louie about it, inspected rest of pedals, bled brakes and clutch, replaced RF bleeder screw, inspected ignition box and coil, filled out parts sheet	6.5	103.00	669.50T
Labor - Brian M	6/6/19 Assist Curtis with replacing damaged brake bleeder and bleeding brakes/clutch.	0.5	103.00	51.50T
Labor - Brian M	6/7/19 Assist Curtis with inspection of starter engagement.	0.25	103.00	25.75T
			Total:	



	2019
BILL TO:	0710812

DATE	INVOICE #	
6/15/2019	62949	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Curtis	6/7- scraped off old brake paint and painted on new, inspected gearbox and diff fluid levels, safety wired fill plugs, put new starter motor in spares box, attached adaptor to other new starter motor, mocked up in car, spec out new bolt for top of adaptor, ran tap through capture nut on adaptor, Loctite capture nut on adaptor, installed starter, connected power and exciter lines, tested starter, pulled starter back out and reclock, tested again, talked to Brian about starter engagement issue	6	103.00	618.00T
Labor - Bryce	6/10 remove radiator, remove exhaust, disconnect engine components, remove engine, remove shifter and gearbox, clean parts, etc.	3	103.00	309.00T
Labor - Curtis	6/10- Talked to Eddie and Louie about oil leak and plan of attack, made a made a big change in starter motor clocking, mocked up and found that solenoid hit trans tunnel, reclock and installed, looked at engagement of starter and flywheel with both Bryce and Brian, started car and warmed up, preformed leakdown and compression tests, inspected spark plugs, decision was made to pull motor, removed starter, removed headers, removed air box	5	103.00	515.00T
Labor - Louie	06-10 Reseal Malone 26R gearbox front plate; inspect gears, replace nose seal	1	103.00	103.00T
Labor - Louie	06-11 Clean gearbox case, refit shifter housing cap	0.5	103.00	51.50T
	-1		Total:	



yallup, WA 98371 3.845.0617	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
BILL TO:	07108120

DATE	INVOICE #	
6/15/2019	62949	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Bryce	6/12 install trans, set engine in car, install exhaust, install cooling system, hook up engine components, install shifter, run and warm up car, etc.	6.5	103.00	669.50T
Labor - Brian M	6/12/19 Assist Bryce with engine installation.	0.25	103.00	25.75T
Labor - Bryce	6/13 change inner axle bolts and modify hardware, top off fluids, install wheels and set on ground, put on dyno, run car, double check fluid levels, wipe down car, install hood, etc.	5	103.00	515.00T
Labor - Curtis	6/13- installed new axle bolts on both sides, had to modify all bolts to fit	1	103.00	103.00T
Shop Supplies	Shop Supplies		114.33	114.33T
Labor Credit	Michael, the seal failed in the front of the gearbox and had to be replaced. It started leaking in the last race Sunday at the Speed Festival. Had to pull the engine to replace it because it is in the front of the transmission. I gave you a break on the labor, as we had just put the fresh engine in. Also, if you are wondering about the starter for your spares, Your spare was pretty much junk and the one on the car came back from Sears broken in 2 pieces. The twin Cam engines have an extreme vibration in them so it is rough on starters. We have been keeping the one on the car and the one in your spares going but they have reached the end of their life.	-7	103.00	-721.00T
	Sales Tax 9.9%		9.90%	554.12
			Total:	\$6,151.28



yallup, WA 98371 3.845.0617	19
BILL TO:	06105120

DATE	INVOICE #	
5/15/2019	62871	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	Engine Mount (curved Sides)	1	67.21	67.21T
Parts/Materials	Engine Mount (Straight Sides)	1	49.01	49.01T
Labor - Brian M	5/13/19 Inspect engine mounts, flywheel, oil	5	103.00	515.00T
	lines and oil cooler. Clean oil lines and oil			
	cooler. Order new engine mounts. Inspect			
	swirl pot- found that filler neck needs to be			
	replaced. Clean swirl pot and remove hoses for			
	welding. Measure clutch plate thickness and			
	floaters for warpage. Clean clutch drive ring			
	and assemble clutch for installation. Inspect			
	radiator and begin straightening fins. *Several			
Labor - Brian M	rows of fins needed work.	0.5	103.00	5.1.50T
Labor - Brian M Labor - Evan	5/14/19 Finish straightening radiator fins. 5/15/19	0.5		51.50T
Labor - Evan		I	103.00	103.00T
	-Cut radiator filler neck off swirl pot, cleaned up welds and welded new neck on.			
Shop Supplies	Shop Supplies		15.45	15.45T
Shop Supplies	Sales Tax 9.9%		9.90%	79.32
	Suics Tux 7.770		7.7070	77.32
			Total:	\$880.49
			1 Otal:	φοσυ.49



845.0617	1019
BILL TO:	0710812
	_

DATE INVOICE		
5/31/2019	62580	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Lubricant, Joe	Lubricant, Joe Gibbs XP6	7	13.286	93.00T
Filter, B253	Baldwin Oil Filter	1	22.43	22.43T
Lubricant, Cos	Cosworth Coolant	1	14.58334	14.58T
Race Fuel, Tric	Race Fuel, Trick 114	4	12.93702	51.75T
Brake Clean	Brake Clean 14 oz can	2.5	4.89071	12.23T
Lubricant, Gea	Valvoline 80w90 gear oil	2.5	11.746	29.37T
Parts/Materials	New Throttle Cable Assembly	1	29.75	29.75T
Spark Plug, BR	Spark Plug, NGK BR9EIX	4	12.50	50.00T
Brake, Fluid A	Brake, fluid AP600 / R-2 - 1/2 liter bottles	0.5	49.73	24.87T
Freight - Out	Shipping - Fire Bottle	1	27.97	27.97T
Parts/Materials	Exhaust Gasket 1 Set of 2	1	46.61	46.61T
Tire Disposal	Tire Disposal	8	5.00	40.00T
Mount & Balan	Tire Mount and Balance	8	28.50	228.00T
Dismount	Tire Dismount	8	7.50	60.00T
Outside Service	inspect and re certify bottle	1	154.00	154.00T
Chassis Dyno	Chassis Dyno (Initial setup, warmup, and 1 hour of dyno time)	1	265.00	265.00T
Labor - Bryce	5/20 remove engine from crate, order parts, install gearbox and driveshaft, install clutch lines, put car on lift, etc.	3	103.00	309.00T
Labor - Eddie	5/21/2019 helped Bryce install motor	1	103.00	103.00T
Labor - Bryce	5/21 install flywheel and clutch, install carbs, modify engine mounts and install, set engine into car, remove and realign clutch, set engine back in, bolt gearbox to engine, check endfloat and bleed clutch	8	103.00	824.00T
			Total:	



yallup, WA 98371 3.845.0617	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
BILL TO:	07108120

DATE INVOICE		
5/31/2019	62580	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Bryce	5/22 install oil cooler and lines, install cooling system, order parts, install exhaust, install air box, begin making new throttle cable, install starter and wiring, install new spark plugs, fill engine with coolant and oil, test fit hood, modify engine mounts, verify hood clearance, etc.	8	103.00	824.00T
Labor - Curtis	5/23- Sanded and paint prepped foot well drivers side	1.5	103.00	154.50T
Labor - Bryce	5/23 install shifter, add gearbox oil and check DIFF oil, nut and bolt front and rear suspension, finish making new throttle cable, run car, Dyno, change tires, Dyno again, clean car, go through spares, etc.	8	103.00	824.00T
Labor - Juan	05/23/19 clean the car inside out, under the car, the wheels and the body	3.5	70.00	245.00T
Labor - Santos	5.24.19 cleaned and take off wheel wights on 1 set of wheels	1	70.00	70.00T
Labor - Bryce	5/24 switch out tires for Avon, paint floor, install bodywork, install camera mount	1	103.00	103.00T
Labor - Santos	5.25.19 clean and take wheel wights of 2nd wheels set	1	70.00	70.00T
Shop Supplies	Shop Supplies Sales Tax 9.9%	1	105.80 9.90%	105.80T 473.40
			Total:	\$5,255.26



	2019
BILL TO:	01/2212

DATE	INVOICE #	
12/15/2018	62545	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Louie	12-05 Finish gearbox assembly; rebuild clutch slave cylinder and install	2.5	103.00	257.50T
Shop Supplies	Shop Supplies Sales Tax 9.9%		7.73 9.90%	7.73T 26.26
			Total:	\$291.49



	12019
BILL TO:	01 021
	•

DATE	INVOICE #	
11/15/2018	62461	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Dennis	11-15 Start rebuild of transmission	4	103.00	412.00T
Shop Supplies	Shop Supplies	1	12.63	12.63T
	Sales Tax 9.9%		9.90%	42.04
	•	1	Total:	\$466.67

J&L Fabricating

T			•	
	n	$J \cap$	110	Δ
L	ш	ľV	11	~

DATE	INVOICE #	
10/15/2018	62398	
BILLING PERIOD		

	W 41051	
BILL TO	4.0	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Bearing & kit	1	14.21	14.21T
Parts/Materials	T/O Bearing for 8288	I	52.36	52.36T
Parts/Materials	O-Ring kit for 8288	1	6.86	6.86T
	Sales Tax 9.9%		9.90%	7.27
			Total	\$80.70

PO Box 70 Puyallup, WA 98371 253-845-0617

DATE	INVOICE #		
9/30/2018	62356		
BILLING PERIOD			

	0122120		
BILL TO	40.		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Discs, seals, gaskets.	1	116.80	116.80T
Parts/Materials	22E9Z310 1/2, 4 dog drive disc	2	487.90	975.80T
Parts/Materials	22 903 Rear seal	2	29.12	58.24T
Parts/Materials	22 904 Front seal	2	7.84	15.68T
Parts/Materials	22 0002 Gasket Set	2	21.36	42.72T
Parts/Materials	E9Z 209 17T 3 dog input gear	2	565.25	1,130.50T
Parts/Materials	E9Z411 3/4 4 dog drive disc	2	321.30	642.60T
Parts/Materials	E9Z119* 1/2 fork	1	470.05	470.05T
Labor - Brian M	9/27/18 Install wheels and tighten using dead blow, air up tires, remove drive shaft and lower car using air lifters.	0.75	103.00	77.25T
Shop Supplies	Shop Supplies	1	2.32	2.32T
	Sales Tax 9.9%		9.90%	349.66
	•		Total	\$3,881.62


 DATE
 INVOICE #

 9/15/2018
 62321

 BILLING PERIOD

BILL TO

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Freight - Out	Engine, Shipped out for rebuild	1	366.24	366.24T
Parts/Materials	5/16 fuel injection rubber gas line	3		12.18T
Labor - Erik	09/04 Car up on high stands, remove hood, drain oil, drain coolant, remove radiator, remove trumpets, remove exhaust system, remove headers, remove all sensors to motor, remove breathers, remove starter, loosen transmission, disconnect all oil lines, install engine lift, separate engine and transmission, remove engine, remove motor mounts, remove carburetors, remove clutch and flywheel assembly, drain cooling system, clean all fluids from engine and cap and seal. Source crate and install engine into crate, brace engine.	8		824.00T
Labor - Erik	09/05 Build lid for crate, wrap carburetors and trumpets, install lid, load onto shipping truck. Remove oil lines, cooler and clean lines. Clean transmission, engine bay, visual crack check motor mounts frame. Remove oil filter, clean oil filter housing. Remove transmission	4	103.00	412.00T
Labor - Larry	09/05/18 Begin race prep for Charity Challenge	4	103.00	412.00T
Labor - Larry	09/06/18 Continue with race prep sheet	6.5	103.00	669.50T
Labor - Louie	09-07 Disassemble gearbox, examine components, order new dog rings and 1 slider	5.5	103.00	566.50T
Shop Supplies	Shop Supplies	1	88.07	88.07T
			Total	



	0051201	В
BILL TO	40.	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
	Michael, The prep work for the Charity Challenge was already done before you had told me that you weren't going.			
	me that you weren't going. Sales Tax 9.9%		9.90%	331.70
			Total	\$3,682.19



yallup, WA 983/1 3.845.0617	101B
BILL TO:	4010412

DATE	INVOICE #	
8/31/2018	62259	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Outside Service	Tire disposal	4	9.80	39.20T
Outside Service	Mount & Balance	12	49.00	588.00T
Parts/Materials	Hoosier 22.5/6.0-13 Tires	8	248.75	1,990.00T
Vent Tank, She	Vent Tank, Sheet Metal Mount 1/4 NPT	1	62.80	62.80T
Aeroquip FBM	Non-Adj 90* Alum	1	37.61	37.61T
Tie, Self-Locki	Tie Self Locking 11.08 TY 26M	10	0.17	1.70T
Tie, Self-Locki	Tie Self Locking 4"	20	0.19	3.80T
Tie, Self-Locki	Tie Self Locking 7.31" TY25M	20	0.14	2.80T
Tie, Self-Locki	Tie Self Locking 8.00 TY232M	10	0.11 9.90%	1.10T
	Sales Tax 9.9%			269.97
			Total:	\$2,996.98



845.0617	2018
BILL TO:	0911712
	_

DATE	INVOICE #	
8/15/2018	62217	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Freight-In	Gauges	1	35.07	35.07T
Outside Service	Install new gauge line and bulb for oil	1	329.00	329.00T
	pressure/water temp gauge. Calibrate as			
	necessary.	,	200.00	200.00
Outside Service	Service and install new gauge line and bulb on	1	308.00	308.00T
Donales Elected	oil temp gauge. Calibrate as necessary.	1	31.248	21 25T
Brake, Fluid A Filter, B253	Brake, fluid AP600 / R-2 - 1/2 ltr bottles Baldwin Oil Filter	1	21.574	31.25T 21.57T
· · · · · · · · · · · · · · · · · · ·	Race Fuel, Trick 114	4.5	12.38245	55.72T
	Mobile One 75w 90 Gear Oil	7.3	11.83217	11.83T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	1	13.706	13.71T
Labor - Bryce	8/6 complete engine status sheet, check	8	103.00	824.00T
	electrical system, check exhaust sytem, check	-	- 3 - 3 - 3	
	cooling system, nut and bolt suspension, check			
	all fluid levels, check brakes, change gauges,			
	etc.			
Labor - Juan	08/07/18	3.5	70.00	245.00T
	clean the car inside out, under the car, the			
	wheels and the body			
Labor - Bryce	8/7 run car check timing, complete race prep,	4	103.00	412.00T
I 1 F ·1	gather spares, order parts, clean car, etc.	0.75	102.00	77.25T
Labor - Erik	08/08	0.75	103.00	77.25T
Labor - Larry	Install wheels, inspect, safety wire 08/09/18	1.5	103.00	154.50T
Lubor - Lurry	Tune and adjust idle with air-fuel ratio meter.	1.5	105.00	134.301
	Balance carbs.			
Shop Supplies	Shop Supplies	1	51.38	51.38T
T T T T T T T T T T T T T T T T T T T	Sales Tax 9.9%		9.90%	254.46
			Totale	\$2,824.74
			Total:	\$2,024.74



yallup, WA 98371 3.845.0617	1018
BILL TO:	0911712

DATE	INVOICE #	
7/31/2018	62163	
BILLING PERIOD		

P.O. No. TERMS		PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Freight-In	Tube and jets	1	58.80	58.80T
Parts/Materials	Weber F16 Emulsion tubes	4	12.10	48.40T
Parts/Materials	Weber 55 F8 Idle Jets	4	6.65	26.60T
Freight - Out	Gauges	1	52.40	52.40T
Labor - Eddie	7/25/2018 drove car on chassis dyno	1	103.00	103.00T
Chassis Dyno	7/25/18 Strap down car, connect sensors, set up dyno computer and place fans. Run dyno computer and inspect car during several dyno pulls.	1.75	265.00	463.75T
Labor - Larry	07/25/18 Dyno tuning and carb calibration	2	103.00	206.00T
Labor - Brian M	7/27/18 Clean car, charge battery, repair valve cover leak, replace #2 header gasket and fill with fuel. Remove faulty temp/pressure gauge and install new part. Pressure check cooling system and run engine and check operation of gauge. Nut and bolt axles, check wheel torque and tire pressures. Clean car.	3	103.00	309.00T
Shop Supplies	Shop Supplies	1	54.082	54.08T
	Sales Tax 9.9%		9.90%	130.88
			Total:	\$1,452.91



yallup, WA 98371 3.845.0617	2018
BILL TO:	0911712

DATE	INVOICE #	
7/15/2018	62055	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Tubes	1	11.13	11.13T
Parts/Materials	F-2 Part #61450.027 F-2 Weber Emulsion tubes	4	11.82	47.28T
Parts/Materials	F-7 Part #61450.091 F-7 Weber Emulsion tubes	4	12.81	51.24T
Labor - Brian M	6/6/18 Add fuel, check axle bolts and check rear wheel torque for dyno.	0.75	103.00	77.25T
Labor - Larry	-6/06/18 Per Louie, Remove valve cover. Check valve lash, intake and exhaust cams, check timing chain tension. Replace spark plugs with recommended NGK heat range.	4	103.00	412.00T
Shop Supplies	Shop Supplies	1	23.94	23.94T
	Sales Tax 9.9%		9.90%	61.66
			Total:	\$684.50



yallup, WA 983/1 3.845.0617	1 1 1 1 1 B
BILL TO:	0710212

DATE	INVOICE #	
6/15/2018	62027	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Outside Service	(4) Aluminum wheels for dye penetrant crack check.	1	278.25	278.25T
Freight-In	Hubs, brg kit, clip, rings	1	139.43	139.43T
Parts/Materials	Alum/Brz hub LH	1	880.60	880.60T
Parts/Materials	Alum/Brz Hub RH	1	880.60	880.60T
Parts/Materials	Wheel brg kit	2	46.20	92.40T
Parts/Materials	Circlip, int	6	2.72	16.32T
Parts/Materials	Nilos Ring, Outer	2	12.60	25.20T
Parts/Materials	Nilos Ring, inner	2	14.00	28.00T
Outside Service	Mount & Balance	4	42.00	168.00T
Outside Service	Tire disposal	4	9.80	39.20T
Parts/Materials	Tires, Avon 6.5/23.0-13	4	382.50	1,530.00T
	Sales Tax 9.9%		9.90%	403.72
			Total:	\$4,481.72



yallup, WA 98371 3.845.0617	1018
BILL TO:	06126120

DATE	INVOICE #	
5/31/2018	61981	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Aeroquip FBM	-8 Steel Braid Line (per foot)	16	12.64	202.24T
Clamp, Lined #	# 10 Lined Hose Clamp	1	3.92	3.92T
Aeroquip FBM	-4 Banjo Fittings	1	47.42	47.42T
Key, Locking I	92070A120 5/16-18	1	8.65	8.65T
Lubricant, Gea	Lubricant, Gear Oil Valv 75/90	1	13.01	13.01T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	1	19.19	19.19T
Dismount	Tire Dismount	4	7.50	30.00T
Mount & Balan	Tire Mount and Balance	4	27.00	108.00T
Outside Service	paint 4 wheels inside out	4	33.46	133.84T
Freight-In	indicator	1	22.58	22.58T
Parts/Materials	clear Lucas indicator lens	2	58.80	117.60T
Freight-In	Head light covers	1	25.72	25.72T
Parts/Materials	Left headlight cover & right head light cover	1	280.00	280.00T
Parts/Materials	Repair all damaged fiberglass structure in engine bay, repair fiberglass front fender, repair fiberglass damage on rear fender and inside trunk area, repair front and rear bumpers, prep for paint, paint green and yellow colors, color sand and buff, paint inside engine bay and trunk area and under side black Polane	1	6,858.33	6,858.33T
Parts/Materials	Light Bulbs	1	3.40	3.40T
Parts/Materials	Head light	1	14.55	14.55T
Parts/Materials	1 1/2 radiator hose	1	37.30	37.30T
Parts/Materials	RH thread Winged wheel nut	1	275.50	275.50T
Freight-In	plastic washer	1	9.69	9.69T
Parts/Materials	10-32 plastic washer	1	14.50	14.50T
Shop Supplies	Shop Supplies	1	185.20	185.20T
Chassis Dyno	Chassis Dyno (Initial setup, warmup, and 1 hour of dyno time)	I	265.00	265.00T
			Total:	



yanup, w A 98371 3.845.0617	1018
BILL TO:	0612612

DATE INVOICE		
5/31/2018	61981	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Labor - Brian M	5/21/18 Begin checking engine mechanical, lubrication, cooling, air/fuel, exhaust, electrical, ignition and differential.	6.75	103.00	695.25T
Labor - Juan	05/21/18 clean the car inside out, under the car, the body and the wheels	3.5	70.00	245.00T
Labor - Bryce	5/21 begin prep, mock up rear bumper, modify body to fit, check fuel regulator and fuel cell, double check rear light install, assist Brian, etc.	7	103.00	721.00T
Labor - Dennis	05-22 Inspect 4.9 rear end; repair bolt thread and reassemble; add oil	1.5	103.00	154.50T
Labor - Brian M	5/22/18 Continue race preparation. Found differential mounts are cracked. Un-bolt axles and rear suspension and assist Bryce with removal of differential. Make new Differential vent line. Nut and bolt car excluding rear suspension and axles. Clean windshield and remove adequate number of tech stickers as requested by owner. Assist Bryce with getting oil pressure and filling cooling system. Pressure check cooling system and cap. Run engine and perform leakdown. Inspect hubs and wheels nuts- order new left rear nut to replace worn part. Install rear bolts for top and clean threads of forward mount nuts. Begin installation of differential.	11.5	103.00	1,184.50T
Labor - Bryce	5/22 fit headlights, trim headlight covers, fit front bumper, fit front lights, prep and touch up black paint, install front grill and air intake, assist Brian, etc.	9.5	103.00	978.50T
			Total:	



yallup, WA 98371 3.845.0617	2018
BILL TO:	0612612

DATE	INVOICE #	
5/31/2018	61981	
BILLING PERIOD		

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Labor - Brian M	5/23/18 Finish installation of differential, install axles and rear control arms. Had issue with alignment of left rear control arm-removed control arm and checked for straight on granite table. Reinstall arm with Assistance from Eddie. Install tail light wiring p-clamp. Nut and bolt rear end of car. Bleed brakes and clutch. Assist Bryce with assembly of parts removed for paint. Move car to alternate bay for alignment. Set up and level pads. Check cambers, ride heights and corner weights.	6	103.00	618.00T
Labor - Evan	5/23/18 -Welded cracks in chassis at rear end mounts.	1.25	103.00	128.75T
Labor - Bryce	5/23 assist Brian with finishing prep	3	103.00	309.00T
Labor - Brian M	5/24/18 Finish alignment- set caster, camber, toe, cornerweights and ride heights. Zero anti roll bar and lock down all adjusters. Drill new wheel nut for safety wire. Hammer on all wheel nuts and safety wire. Remove driver weight and set tire pressures for dyno. Had issue with leaky cooling system hose during warmup on dyno. Drain cooling system and reposition clamp. Refill system and pressure check system. Warm up car and check timing. Move car back to main shop after dyno runs. Recheck oil level and safety wire oil fill cap. Add fuel and finish paperwork for car preparation.	8.5	103.00	875.50T
	Sales Tax 9.9%		9.90%	1,443.98
			Total:	\$16,029.62

DATE	INVOICE #		
5/15/2018	61940		
BILLING PERIOD			

	510412018	
BILL TO	go.	

P.O. No.	P.O. No. TERMS	
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Jerome	05/15/18 -Pick-up the 26R at Byer's	I	70.00	70.00T
Labor - Erik	05/16 Remove hood and trunk lid, remove all tape and plastic covers, vacuum all compartments, blow out engine compartment, wash and scrub trunk and engine compartments. Install fuel pressure regulator, fuel lines, fuel breather, rivet wire harness back in, rear bumper, and trunk lid. Rivet in front fuel pressure regulator, install oil filter housing, oil lines, oil cooler, oil temp sensor and harness.	6	103.00	618.00T
Labor - Bryce	5/16 assist erik with install of rear bumper, wiring routing, component locations, rtc.	2	103.00	206.00T
Shop Supplies	Shop Supplies Sales Tax 9.9%		26.82 9.90%	26.82T 91.16
	•	,	Total	\$1,011.98

DATE	INVOICE #		
4/30/2018	61897		
BILLING PERIOD			

	612512018
BILL TO	0,5,

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	Mount, Balance & Disposal	1	196.00	196.00T
Parts/Materials	2 PK 32GB	I	75.94	75.94T
Mount & Balan	Tire Mount and Balance	4	27.00	108.00T
Dismount	Tire Dismount	4	7.50	30.00T
Tire Disposal	Tire Disposal	4	5.00	20.00T
Labor - Erik	04/16 Remove rear deck lid, rear lights, rear bumper, left front headlight and assembly, front lower lights, left front headlight cover, front bumper.	1.75	92.00	161.00T
Labor - Erik	04/17 Remove oil filter assembly, oil cooler and lines, air intake, trumpets, radiator (drained cooling system), swirlpot, wiring, and fuel regulator. Cap all lines from engine and holes tape off. Remove rear fuel regulator, fuel breather, and wiring. Cap all lines and holes. Cover engine and accessories with plastic	5.5	92.00	506.00T
Labor - Santos	4.19.18 load 26r and take to painter for fiberglass repairs and paint	2	60.00	120.00T
Shop Supplies	Shop Supplies	1	23.61	23.61T
	Sales Tax 9.9%		9.90%	122.81
		[,	Total	Ø1 262 26
			Total	\$1,363.36

PO Box 70 Puyallup, WA 98371 253-845-0617

DATE	INVOICE#	
4/20/2018	61869	
BILLING PERIOD		

345-0617	S12512018
BILL TO	024

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Fuel Regulator	Fuel Regulator, 10663	1	63.686	63.69T
Weber, Float D	Weber Float DCOE 45	1	83.818	83.82T
Chassis Dyno	Chassis Dyno (Initial setup, warmup, and 1 hour of dyno time)		265.00	265.00T
Labor - Bryce	4/2 Repair carbs, change carb float, reset, change fuel regulator, gather spares, etc.	4.5	92.00	414.00T
Labor - Juan	03/31/18 clean the car inside out, under the car and the wheels	3	60.00	180.00T
Shop Supplies	Shop Supplies	1	25.87	25.87T
			Total	\$1,134.59

PO Box 70 Puyallup, WA 98371 253-845-0617

DATE	INVOICE#	
3/31/2018	61831	
BILLING PERIOD		

	6101120	
BILL TO	0.5.	

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Freight-In	Retainer	1	6.73	6.73T
Freight-In	Compound	1	16.88	16.88T
Parts/Materials	Brake Pad Retainer	4	9.76	39.04T
Parts/Materials	Sets Rear Pads	2	162.40	324.80T
Outside Service	New tach cable	1	87.20	87.20T
Credit	Credit Tach cable from INV 61392	-1	111.99	-111.99T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	8	12.94	103.52T
Filter, B253	Baldwin Oil Filter	1	21.57	21.57T
Brake, Fluid A	Brake, fluid AP600 / R-2 - 1/2 ltr bottles	1.5	30.46	45.69T
Spark Plug, N	Spark Plug, NGK CR10EIX (4 in the engine, 4 in the spares box)	8	8.71	69.68T
Lubricant, Cos	Cosworth Coolant	1	13.42	13.42T
Race Fuel, Tric	Race Fuel, Trick 114	7	12.17	85.19T
Chassis Dyno	Chassis Dyno (Initial setup, warmup, and 1 hour of dyno time)	1	265.00	265.00T
Labor - Larry	03/22/16 Perform engine compression test and cylinder leakage test.	1.5	92.00	138.00T
Labor - Bryce	3/26 install spark plugs, order parts, check fuel system, fill tank with fuel, drain oil and coolant, replace oil filter, fill with water and check cooling system, fill with oil and crank for oil pressure, check oil system, remove tach cable, etc.	8	92.00	736.00T
Labor - Bryce	3/27 check electrical system, nut and bolt front and rear suspension, check fluids in Trans and diff, remove brake pads and inspect/deglaze, remove brake fluids, drain catch tanks, check exhaust, nut and bolt interior, clean parts, etc.	8	92.00	736.00T
Labor - Bryce	3/28 bleed brakes and clutch, send out tach cable to be made, install wheels and set on ground, load test battery, etc.	2.5	92.00	230.00T
	•		Total	

PO Box 70 Puyallup, WA 98371 253-845-0617

DATE	INVOICE #	
3/31/2018	61831	
BILLING PERIOD		

	1011E	
BILL TO	0.5.	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R
Quantity	Rate	Amount
2.5	92.00	230 00T

Item	Description	Quantity	Rate	Amount
Labor - Bryce	3/30 install new rear brake pads, safety wire wheels, install new tach cable, run car	2.5	92.00	230.00T
Shop Supplies	Shop Supplies	1	62.10	62.10T
Labor - Eddie	4/2/2018 ran car on dyno found carb float leaking, installed new float, adjusted float levels ran car changed fuel regulator	4.5	92.00	414.00T
	Sales Tax 9.9%		9.90%	347.77
		,	Total	\$3,860.60

	DATE	INVOICE #
	11/30/2017	61602
	BILLING	PERIOD
ı		

	12112017
BILL TO	12.

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Bryce	11/14 drain coolant and add anti-freeze, fog	2.5	92.00	230.00T
	engine, run car, etc.			
Shop Supplies	Shop Supplies	1	6.90	6.90T
	Sales Tax 9.9%		9.90%	23.45
		,	Total	\$260.35

DATE INVOICE #

8/31/2017 61392

BILLING PERIOD

	010212017
BILL TO	10.

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Cable	1	14.08	14.08T
Parts/Materials	96 inch smith's tach cable	I	111.99	111.99T
	Sales Tax 9.9%		9.90%	12.48
	1	<u> </u>		0.1.0
			Total	\$138.55

 DATE
 INVOICE #

 8/15/2017
 61342

 BILLING PERIOD

	1 000	12017
BILL TO	Q.a.	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Pins	1	8.67	8.67T
Parts/Materials	1/4" x 4" cotter pins (pkg)	1	12.36	12.36T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	2	12.94	25.88T
Brake, Fluid A	Brake, fluid AP600 / R-2 - 1/2 ltr bottles	1	30.45	30.45T
Filter, B253	Baldwin Oil Filter	1	21.57	21.57T
Labor - Larry	08/02/17	1.5	92.00	138.00T
	Assist Bryce with suspension and brake bleeding			
Shop Supplies	Shop Supplies	1	15.18	15.18T
	Sales Tax 9.9%		9.90%	24.96
		,	Total	\$277.07

PO Box 70 Puyallup, WA 98371 253-845-0617

INVOICE #
61301
PERIOD

45-0617	010112017
BILL TO	02.

		İ	İ	
		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Filter, B253	Baldwin Oil Filter	1	21.574	21.57T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	5.5	12.9353	71.14T
Brake Clean	Brake Clean 14 oz can	4	5.70092	22.80T
Race Fuel, Tric	Race Fuel, Trick 114	3	12.1735	36.52T
Spark Plug, 65	Champion G59C	4	11.50	46.00T
Labor - Louie	07/29 Prep and weld starter mounting flange, clean threads	1	92.00	92.00T
Labor - Bryce	07/29 Start race prep; address and repair starter issues; replace and reposition chassis ground strap; remove, inspect and replace oil filter; start car and warm up; perform engine leakdown test	6.5	92.00	598.00T
Labor - Bryce	7/31 Con't race prep, check fuel system, check cooling system, remove oil cooler, clean and test oil cooler, reinstall oil cooler, check exhaust system, nut and bolt front suspension, remove right front shock to be repaired, nut and bolt rear suspension, charge battery, add fuel, etc.	8	92.00	736.00T
Labor - Evan	8/1/17 -Cut damaged sway bar stud off shocks, then welded on new studs.	1.5	92.00	138.00T
Labor - Bryce	8/1 machine bolts for shock repair, nut and bolt Trans and diff, check fluids, paint parts, check brake system, deglaze brake pads, etc.	3	92.00	276.00T
Labor - Juan	08/01/17 clean the car inside out, under the car, the wheels and the body	2	60.00	120.00T
	Sales Tax 9.9%		9.90%	213.64
			Total	\$2,371.67

DATE INVOICE #

6/15/2017 61188

BILLING PERIOD

	210512017
BILL TO	0,1,

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Bryce	6/6 put wheels on car and put in back storage	1	92.00	92.00T
Shop Supplies	Shop Supplies	1	2.76	2.76T
	Sales Tax 9.9%		9.90%	9.38
			Total	\$104.14
			I Utai	Ψ107.17

INVOICE #			
61151			
BILLING PERIOD			

	7105	2017
BILL TO	Q.r.	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Bryce	5/18 put car on lift, start race prep, wheels off	1.5	92.00	138.00T
Labor - Juan	05/20/17 clean the car inside out, under the car and the wheels	3	60.00	180.00T
Shop Supplies	Shop Supplies	1	6.78	6.78T
snop supplies	Sales Tax 9.9%		9.90%	32.15
],	T-4-1	#25 × 02
			Total	\$356.93

DATE	INVOICE #
5/15/2017	61113
BILLING	PERIOD

	5126	2017
BILL TO	00.	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R


Item	Description	Quantity	Rate	Amount
Dismount	Tire Dismount	4	7.50	30.00T
Mount & Balan	Tire Mount and Balance	4	27.00	108.00T
Tire Disposal	Tire Disposal	4	5.00	20.00T
Freight-In	Freight, Inbound	1	21.00	21.00T
Outside Service	Fire bottle for service	1	133.00	133.00T
Freight-In	Freight, Inbound	-1	50.57	-50.57T
	Sales Tax 9.9%		9.90%	25.88
		,	Total	\$287.31

DATE	INVOICE #		
4/15/2017	61043		
BILLING PERIOD			

		12017
BILL TO	O ^{ra} ti	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	220002 gasket set	1	17.92	17.92T
Parts/Materials	22121 Thrust washer	2	41.44	82.88T
Parts/Materials	22900 oil pump ring	1	87.36	87.36T
Freight-In	Freight, Inbound	1	94.64	94.64T
Parts/Materials	22E9Z 307 2nd Gear main 22T	1	329.28	329.28T
Parts/Materials	22E9Z 306 1st gear-main 25T	1	340.48	340.48T
Parts/Materials	22E9Z 118 3/4 Fork	1	448.00	448.00T
	Sales Tax 9.9%		9.90%	138.66
		,	Total	\$1,539.22




0412712017

BILL TO


		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Freight-In	Freight, Inbound	1	33.75	33.75T
Parts/Materials	22E9Z 308 3rd gear main 19T	1	333.87	333.87T
Parts/Materials	22E9Z310 1st/2nd drive disc	1	498.15	498.15T
Parts/Materials	22E9Z 411 3rd/4th drive disc	1	332.33	332.33T
Parts/Materials	22110 Bearing - input	1	58.55	58.55T
Parts/Materials	22120 Bearing mainshaft	1	105.62	105.62T
Parts/Materials	22903 Rear seal	1	29.12	29.12T
Parts/Materials	22904 front seal	1	7.84	7.84T
Parts/Materials	30x40x7 seals	2	4.45	8.90T
Parts/Materials	1/1-28x1 stud	1	1.95	1.95T
Brake, Master	.750 Remote	1	174.99	174.99T
Freight-In	Freight, Inbound	1	20.342	20.34T
Parts/Materials	Set Differential Bushings	1	19.544	19.54T
Parts/Materials	1/16" steel cable	8	0.826	6.61T
Parts/Materials	Tires, 6.5x23-13 Avon Treaded	4	428.40	1,713.60T
Washer, AN Th	5/16" AN Thin	14	0.3744	5.24T
Washer, Lockw	Lockwasher 5/16"	6	0.24	1.44T
Nut, Nyloc 5/1	Nyloc 5/16-18	2	0.2547	0.51T
Nut, Jet 1/4	1/4" Jet Nut	4	1.26	5.04T
Brake, Fluid A	Brake, fluid AP600 / R-2 - 1/2 ltr bottles	1.5	31.5406	47.31T
Lubricant, Cos	Cosworth Coolant	0.5	12.67778	6.34T
Bolt, Hex 1/4-2	$1/4-20 \times 1/2$	1	0.696	0.70T
Washer, AN Th	1/4" AN Thin	1	0.0558	0.06T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	7.5	13.70084	102.76T
Labor - Dennis	03-09 Disassemble gearbox, wash and inspect parts; order new parts; clean and regrease T/O bearing	4.5	92.00	414.00T
Labor - Dennis	03-10 Open rear end and inspect R&P order and install new seals; improve rear end breather; repair threads in gearbox extension	3.5	92.00	322.00T

Total



BILL TO 0412712017

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Labor - Dennis	03-13 Inspect shifter shaft for full travel into 2nd gear and determine if modification is necessary; follow up on transmission parts	2	92.00	184.00T
Labor - Bryce	03-20 Fit diff, remove and replace new vent banjo after installation; modify and fit new diff strut bushings; reposition fuel pressure regulator with more secure mount; start race prep	4.5	92.00	414.00T
Labor - Bryce	03-21 Nut and bolt suspension; make and install spacer for LR strut/shock mount; remove brake pads and grind flat; remove fire bottle and send for service and Recertification	5.75	92.00	529.00T
Labor - Bryce	03-22 Bleed brakes, check pads for piston contact; paint rotors; complete prep sheet items not engine/transmission related	3	92.00	276.00T
Labor - Dennis	03-24 Rebuild gearbox; get selector shaft welded, straighten, modify detent slots	5.5	92.00	506.00T
Labor - Dennis	03-25 Finish gearbox	4	92.00	368.00T
Labor - Brian M	03-27 Install engine and gearbox; fit LR wishbone; remake and refit front brake line; replace starter, swap nose housings;	8.5	92.00	782.00T
Labor - Bryce	3/27 install diff, install Trans and clutch,install engine, install exhaust, made new throttle cable, rerouted wiring, installed oil lines, installed Trans crossmember, etc.	5.5	92.00	506.00T
Labor - Brian M	03-28 Finish installation details; bleed brakes; clutch master cylinder would not pressure, replace clutch master cylinder; bleed clutch and check release; start engine, check systems; reposition throttle cable clevis on pedal. Finish and run on chassis dyno. Prep for load	6.5	92.00	598.00T
Shop Supplies	Shop Supplies	1	258.06	258.06T
			Total	



BILL TO

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
	Sales Tax		9.40%	815.13
		<u> </u>	<u> </u>	
		ļ	Total	\$9,486.75

PO Box 70 Puyallup, WA 98371 253-845-0617

Item

Labor - Bryce

Labor - Juan

Labor - Brian M

Labor - Bryce

Shop Supplies

Invoice

PROJECT

\$1,247.39

DATE	INVOICE #		
2/28/2017	60912		
BILLING PERIOD			

3 2123
05.

	Due on Receipt	Lotus 26R
Quantity	Rate	Amount
,	92.00	368.00T
3.5	60.00	210.00T
0.75	92.00	69.00T
,	92.00	460.00T
1	33.21	33.21T
	9.40%	107.18
	3.5 0.75 5	Quantity Rate 4 92.00 3.5 60.00 0.75 92.00 5 92.00

Total

TERMS

P.O. No.

PO Box 70 Puyallup, WA 98371 253-845-0617

DATE	INVOICE#		
10/31/2016	60708		
BILLING PERIOD			

45-0617	12812016
BILL TO	47.

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Antifreeze, yell	Antifreeze, Prestone Yellow	2	8.75	17.50T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	2	13.70	27.40T
Labor - Larry	10/5/16	2	92.00	184.00T
	prep for winter storage			
Labor - Larry	10/27/16	2.5	92.00	230.00T
	Top off engine oil and coolant. Go thru warm up,			
	bring engine to normal operating temperature.			
	Perform compression and leak down tests to			
	determine current engine condition.			
Shop Supplies	Shop Supplies	1	15.17	15.17T
	Sales Tax		9.40%	44.56
	Total			



DATE	INVOICE#	
9/30/2016	60619	
BILLING PERIOD		

	4102120	
BILL TO	4.4.	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Juan	09/20/16	3.5	60.00	210.00T
	clean the car inside out, under the car, the wheels			
	and the body	0.5	02.00	46.007
Labor - Brian M	9/22/16 Install exhaust pipe and put car on the	0.5	92.00	46.00T
Shop Supplies	ground using air lifters. Shop Supplies	1	7.22	7.22T
σπορ σπρριτές	Sales Tax	1	9.40%	24.74
	Sares 1an		7.1070	21.71
		<u> </u>		000
		ľ	Total	\$287.96

DATE INVOICE #

6/15/2016 60311

BILLING PERIOD

	1 131	2016
BILL TO	05.	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Freight, Inbound	1	5.77	5.77T
Parts/Materials	Tires, 6.5/23-13 Avon	8	382.50	3,060.00T
Parts/Materials	Distributor cap for Lotus twin cam - 526M7360	1	32.20	32.20T
	Sales Tax		9.40%	291.21
			Total	\$3,389.18

 DATE
 INVOICE #

 5/31/2016
 60281

 BILLING PERIOD

	1 15	2016
BILL TO	02.	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Outside Service	Spin balance	2	25.20	50.40T
	Sales Tax		9.40%	4.74
	•		Total	\$55.14
			Total	φ33.14

DATE INVOICE #

5/15/2016 60240

BILLING PERIOD

	10612016
BILL TO	0,1,-

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In Parts/Materials	Freight, Inbound	1	14.17	14.17T
Parts/Materials	set front brake pads	I	267.68	267.68T
	Sales Tax		9.40%	26.49
			Total	\$308.34
			10001	

 DATE
 INVOICE #

 4/30/2016
 60209

 BILLING PERIOD

	210612016
BILL TO	Qr.

			-	
		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Race Fuel, Tric	Race Fuel, Trick 114	4	12.17	48.68T
Filter, B253	Baldwin Oil Filter	1	21.57	21.57T
Brake Clean	Brake Clean 14 oz can	2	5.95	11.90T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	8	13.70	109.60T
Nut, Nyloc 1/4	1/4-28" Nyloc Nuts	8	0.30	2.40T
Washer, AN Th	1/4" AN Thin	8	0.05	0.40T
Brake, Bleeder	Bleeder Screw 3/8-24	2	2.65	5.30T
Brake, Fluid A	Brake, fluid AP600 / R-2 - 1/2 ltr bottles	2	31.56	63.12T
Labor - Juan	04/23/16	3.5	60.00	210.00T
	clean the car inside out, under the car, and the wheels			
Labor - Bryce	4/25 continued race prep, removed valve cover for valve adjust check and cleaned, nut and bolt rear susp., check fuel system, check exhaust, charge battery, check rear brakes, etc.	5	92.00	460.00T
Labor - Bryce	4/26 check front brakes, nut and bolt left front, replace left front bleeder screw on caliper	2	92.00	184.00T
Labor - Bryce	5/2 measure track width for CRF, bleed brakes, install valve cover, finish race prep except for oil and run	4	92.00	368.00T
Labor - Bryce	5/3 add oil, run and check timing, install wheels, install hood and wipe down, set on ground and safety wire wheels, install exhaust pipe, etc.	3	92.00	276.00T
Shop Supplies	Shop Supplies	1	29.62	29.62T
	Sales Tax		9.40%	168.32
			Total	\$1,958.91

INVOICE #		
60159		
)		

	6131120
BILL TO	Q.s.

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Labor - Rafe	4/14 - Placed 26R on stands. Removed	1	92.00	92.00T
	exhaust/tires/wheels.			
	- Placed hood in mezzanine			
Shop Supplies	Shop Supplies	1	2.76	2.76T
	Sales Tax		9.40%	8.91
	•		Total	\$103.67



DATE	INVOICE #		
3/31/2016	60115		
BILLING PERIOD			

	6102120
BILL TO	Q.S.

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Lubricant, Cos	Cosworth Coolant	1	13.30	13.30T
Race Fuel, Tric	Race Fuel, Trick 114	1	12.17	12.17T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	1	13.70	13.70T
Labor - Rafe	3/26 - Drained antifreeze; checked oil. Filled with l gal of gas. Cleaned radiator and flushed block Filled with water/cosworth - Warmed up and ok'd - Mounted 26r Wheels.	5	92.00	460.00T
Shop Supplies	Shop Supplies	1	13.80	13.80T
	Sales Tax		9.40%	48.22
		,	Total	\$561.19

DATE	INVOICE #	
11/30/2015	59839	
BILLING	PERIOD	

	12912016
BILL TO	074

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Jerome	11/17 - 1 set 26R wheel clean front / back and take off the old sticky foam from the weigths.	0.75	60.00	45.00T
Shop Supplies	Shop Supplies	1	1.35	1.35T
	Sales Tax		9.40%	4.36
		1	Total	\$50.71

PO Box 70 Puyallup, WA 98371 253-845-0617

DATE	INVOICE #	
11/15/2015	59774	
BILLING PERIOD		

	2129
BILL TO	0,5

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Rafe	11/2 - Turned Engine Over	0.25	92.00	23.00T
Shop Supplies	Shop Supplies	1	0.4599	0.46T
	Sales Tax		9.40%	2.21
		,	Total	\$25.67

PO Box 70 Puyallup, WA 98371 253-845-0617

		•	
ln	V()1(ce

DATE	INVOICE #		
10/31/2015	59725		
BILLING PERIOD			

	2129120	
BILL TO	02	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Juan	10/13/15	3	60.00	180.00T
	clean the car inside out, under the car, the wheels			
	and the body			
Shop Supplies	Shop Supplies	1	5.40	5.40T
	Sales Tax		9.40%	17.43
			Total	\$202.83

PO Box 70 Puyallup, WA 98371 253-845-0617

DATE	INVOICE #			
10/15/2015	59664			
BILLING PERIOD				

	4119120		
BILL TO	0.1.		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Freight, Inbound	1	8.596	8.60T
Parts/Materials	Pkg cotter pins	I	4.844	4.84T
Parts/Materials	Clevis pin	1	11.20	11.20T
Antifreeze, yell	Antifreeze, Prestone Yellow	1	18.186	18.19T
Labor - Bryce	10/12 did light prep: nut and bolt, check brakes, check oil system, drained coolant and replaced with anti-freeze, ran car etc	4.5	92.00	414.00T
Labor - Rafe	10/14 - Picked up remaining 26r Spare parts on shelves, threw away damaged parts. Placed remaining pedicels in boxes. pieces and placed on the spares shelf.	1	92.00	92.00T
Shop Supplies	Shop Supplies	1	21.62	21.62T
	Sales Tax		9.40%	53.62
		,	Total	\$624.07

PO Box 70 Puyallup, WA 98371 253-845-0617

INVOICE #			
59588			
BILLING PERIOD			

45-0617	011412015		
BILL TO	12		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	oil temp gauge Sminths	1	237.902	237.90T
Dismount	Tire Dismount	4	7.50	30.00T
Mount & Balan	Tire Mount and Balance	4	27.00	108.00T
Tire Disposal	Tire Disposal	4	5.00	20.00T
Freight - Out	Freight, Outbound - overcharge	-1	13.86	-13.86T
	Sales Tax		9.40%	35.91
		<u> </u>	Total	\$417.95

PO Box 70 Puyallup, WA 98371 253-845-0617

DATE	INVOICE #		
9/15/2015	59544		
BILLING PERIOD			

	4109120		
BILL TO	4.1.		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	Misc nuts & bolts	1	14.028	14.03T
Freight-In	Freight, Inbound	1	26.138	26.14T
Outside Service	Smiths oil temp. gauge for repair	1	189.00	189.00T
Freight-In	Freight, Inbound	1	84.00	84.00T
Parts/Materials	Avon tires 6.5-23-13	4	428.40	1,713.60T
Freight-In	Freight, Inbound	1	12.67	12.67T
Parts/Materials	Set rear pads	1	143.038	143.04T
	Sales Tax		9.40%	205.15
		,	Total	\$2,387.63

DATE	INVOICE #		
8/31/2015	59472		
BILLING PERIOD			

	012612015
BILL TO	10.

L		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Brake, Fluid A	Brake, fluid AP600 1/2 ltr bottles	1	32.58763	32.59T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	1	13.38	13.38T
Brake Clean	Brake Clean	2	5.39	10.78T
Filter, B253	Baldwin Oil Filter	1	20.944	20.94T
	Race Fuel, Trick 114	2	12.1735	24.35T
Freight - Out	Freight, Outbound - temp gauge	1	13.86	13.86T
Labor - Bryce	8/24 began race prep, completed engine status sheet, checked oil system, cut open oil filter, checked cooling system, checked exhaust system, nut and bolted front and rear suspension, checked electrical system, removed front brake pads and ground flat	5.5	92.00	506.00T
Labor - Bryce	8/25 continued race prep, replace rear pads, bleed brakes and clutch, fueled car, ran checked timing etc. finished race prep	3	92.00	276.00T
Labor - Juan	08/25/15 clean the car inside out, under the car, the body and the wheels	3.5	60.00	210.00T
Labor - Rafe	8/28 - Placed wheels back on 26R, lowered on ground and safety wired.	1.5	92.00	138.00T
Shop Supplies	Shop Supplies	1	33.90	33.90T
	Sales Tax		9.40%	120.30
			Total	\$1,400.10

DATE INVOICE #

8/15/2015 59409

BILLING PERIOD

	012412015
BILL TO	02.

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Freight, Inbound	4	10.276	41.10T
Parts/Materials	Tires, 6.5/23.0-13 Avon	4	382.50	1,530.00T
Freight-In	Freight, Inbound	1	12.754	12.75T
Parts/Materials	Trans mount S2/3/4	2	38.486	76.97T
Freight - Out	Freight, Outbound - temp gauge	1	13.86	13.86T
Labor - Zach	7/30/15 Finished up the race prep on the car, set the timing, put fuel in it, put the wheel and tires on, bolted the half shafts in.	2.5	92.00	230.00T
Shop Supplies	Shop Supplies	1	9.66	9.66T
	Sales Tax		9.40%	179.95
		,	Total	\$2,094.29

PO Box 70 Puyallup, WA 98371 253-845-0617

Invoice

DATE	INVOICE #		
7/31/2015	59382		
BILLING PERIOD			

	9131120	
BILL TO	On.	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Freight, Inbound	1	60.90	60.90T
Parts/Materials	BD sump seals kit	2	22.246	44.49T
Parts/Materials	Front sump seal	1	3.78	3.78T
Parts/Materials	Rear sump seal	1	3.78	3.78T
<i>Nut, Jet 5/16 - 24</i>	5/16" - 24 Jet Nut	4	2.34	9.36T
Washer, AN Th	3/8" Thick AN Washer	2	0.1017	0.20T
Washer, AN Th	AN 5/16" Thick	6	0.07404	0.44T
Washer, AN Th	Washer, AN Thick 1/2"	4	0.18	0.72T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	1	13.38	13.38T
Brake, Fluid A	Brake, fluid AP600 1/2 ltr bottles	1	32.58763	32.59T
Parts/Materials	Distributor cap black 90*	1	39.75	39.75T
Parts/Materials	Rotor	1	16.50	16.50T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	1	13.38	13.38T
Tubing, 4130 1	Tubing 4130 1-3/8" x .120 (per foot)	4	16.07998	64.32T
Race Fuel, Tric	Race Fuel, Trick 114	3.5	12.17338	42.61T
Mount & Balan	Tire Mount and Balance	4	27.00	108.00T
Nut, Nyloc AN	Nyloc AN 3/8-24	2	1.0851	2.17T
	Nyloc AN 5/16-24	2	1.50	3.00T
Nut, Nyloc 1/2"	1/2"-20 Nyloc Nuts	8	3.3678	26.94T
Labor - Rafe	07/24 - Lifted car onto stands, removed tires/wheels. Removed the hood. - Cleaned all body panels.	1.5	92.00	138.00T
Labor - Juan	07/26/15 clean the car inside out, under the car, the body and the wheels	4	60.00	240.00T
Labor - Dan	07/27 Cut out diagonal tube in top of cage, clean up attachment areas.	1.5	92.00	138.00T
Labor - Rafe	07/27 - Removed the 26R roof. Re-attached the roofs weather stripping with weather stripping adhesive. Taped off cockpit in preparation for the cage modification.	2	92.00	184.00T

Total

PO Box 70 Puyallup, WA 98371 253-845-0617

DATE	INVOICE #		
7/31/2015	59382		
BILLING PERIOD			

-043-0017	913112015	
BILL TO	On.	
1		

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Labor - Evan	7/28/15 -Set up and welded roll bar brace in place.	0.5	92.00	46.00T
Labor - Dan	07/28 Lay out and bend and fit new diagonal tube in top of cage, prep and paint tube and tack into place, reinstall top, run engine checks and start race prep.	6.5	92.00	598.00T
Labor - Dan	07/29 Continue with race prep, finish all except bleeding brakes and clutch and checking timing, remove rear end gear and replace with proper one for Monterey.	9	92.00	828.00T
Labor Credit	Labor Credit for top roll bar brace redo	-6.5	92.00	-598.00T
Labor - Rafe	07/31 - Removed the air intake cowl; in predation to remove the oil temp gauge line. Pulled gauge from dash then pulled wire through firewall Fed new gauge through dash and then through firewall. Hooked back up to the fitting at the oil filter. Placed air intake cowl back on and tightened back down.		92.00	92.00T
Shop Supplies	Shop Supplies	1	78.25	78.25T
	Sales Tax		9.40%	209.67
			Total	\$2,440.23

PO Box 70 Puyallup, WA 98371 253-845-0617

DATE	INVOICE #
7/15/2015	59320
BILLING PERIOD	
BILLING	PERIOD

345-0617	013112015
BILL TO	0.5.

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Freight, Inbound	1	81.69	81.69T
Parts/Materials	Diff top mount kit	I	198.702	198.70T
Parts/Materials	Pair diff top mount tp	1	154.546	154.55T
Parts/Materials	Pair diff torque rods	I	121.436	121.44T
Parts/Materials	Torque rod bush kit	1	48.566	48.57T
Outside Service	Lotus lid mask and reclear, polish to match	1	377.30	377.30T
Freight-In	Freight, Inbound	1	17.752	17.75T
Parts/Materials	3/8 12pt head bolts	16	8.372	133.95T
Parts/Materials	3/8 Washers for 12pt head	16	0.14	2.24T
	Sales Tax		9.40%	106.80
			Total	\$1,242.99

PO Box 70 Puyallup, WA 98371 253-845-0617

Invoice

DATE	INVOICE #	
6/30/2015	59283	
BILLING PERIOD		

BILL TO	08/70

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Freight, Inbound	1	17.318	17.32T
Freight-In	Freight, Inbound	1	73.976	73.98T
Parts/Materials	CB633 3x3 Black belts (set)	1	541.786	541.79T
Parts/Materials	RF 26R Hub	1	880.60	880.60T
Outside Service	#37 - Graphics	4	15.40	61.60T
Freight-In	Freight, Inbound	1	140.00	140.00T
Parts/Materials	LT LB3 Balance D/L	3	120.40	361.20T
Parts/Materials	Misc nuts/bolts	1	21.00	21.00T
Chassis Dyno	Chassis Dyno (Initial setup, warmup, and I hour of dyno time)	1	265.00	265.00T
Labor - Dyno	Additional dyno time	2.5	125.00	312.50T
Labor - Eddie	6/20/2015 complete set up and alinment, set ride heights, weight balance, set front castor, set front camber, set rear camber, set front and rear thrust, adjust and set front rear toe's	9	92.00	828.00T
Labor - Zach	6/23/15 Replaced all Nylock nuts, nut and bolted the whole car, fixed the steering column, removed the right front hub.	8.5	92.00	782.00T
Labor - Zach	6/23/15 Worked on the right front hub, worked on the throttle, bleed the brakes, worked on a race prep, finished mounting the wind shield frame, painted the messed under side of the trunk.	8.5	92.00	782.00T
Machine - Evan	6/24/15 -Set up and machined inner bore on nw RF hub so bearing race would fit.	0.5	102.00	51.00T
Labor - Evan	6/24/15 -Installed bearing race in hub. Helped Zach come up with solution to fix steering column clearance on pedals.	0.5	92.00	46.00T

Total

PO Box 70 Puyallup, WA 98371 253-845-0617

DATE	INVOICE #	
6/30/2015	59283	
BILLING PERIOD		

345-0617	011012015
BILL TO	05.

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Labor - Zach	6/24/15 Machined steer shaft clamp to clear the clutch pedal, worked on a race prep. installed the right front hub.	8.5	92.00	782.00T
Labor - Juan	06/25/15 clean the car inside out, under the car and the wheels	2.5	60.00	150.00T
Labor - Zach	6/25/15 Made a new trottle cable and installed it, Moved brake lines, set the toe, straighted the steering wheel, fixed roof trip, fit the wind shield, warmed the car up and checked the fluids.	9	92.00	828.00T
Labor - Evan	6/25/15 -Fabricated tabs to hold rear springs in perches, then installed on car. Masked off body, sanded and polished drip rail trim pieces. Bled brakes. Hooked up front sway bar. Re-positioned steering joint on rack. Put car on ground, checked front toe. Fired engine, and checked timing.	7	92.00	644.00T
Labor - Evan	6/26/15 -Test drove car. Found vibration, inspected rear end and drivetrain.	0.75	92.00	69.00T
Labor - Louie	06/27 Seek out vibration problem from rear of car, remove halfshafts, driveline and send out for balancing, dial in rear brake rotors, remachine new rear hub/rotor/yoke fitment, set front/rear brake balance	6.5	92.00	598.00T
Labor - Louie	06/29 Install driveshaft, rearend assembly, halfshafts and take car to dyno and test. Vibration gone.	4.5	92.00	414.00T
Shop Supplies	Shop Supplies Sales Tax	1	170.94 9.40%	170.94T 829.07
			Total	\$9,649.00

 DATE
 INVOICE #


 5/31/2015
 59178

 BILLING PERIOD

0811012015

BILL TO	0.0.

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Freight-In	Freight, Inbound	1	29.15	29.15T
Parts/Materials	1/8 x 5/8 RH Male rod end (price adjustment for rod ends purchased in February)	2	157.53	315.06T
Freight-In	Freight, Inbound	1	105.71	105.71T
Parts/Materials	Set Belts 2378 Black	1	484.39	484.39T
Parts/Materials	-10 Fitting 120*	1	36.72	36.72T
Parts/Materials	Set hood plugs	1	16.23	16.23T
Parts/Materials	Throttle springs	1	4.23	4.23T
Parts/Materials	Misc nuts	1	1.68	1.68T
Labor - Jordan	5/18 install wire harness, install brake, turn & clearance lights, battery & tray repair all needed connections & test	8.5	92.00	782.00T
Labor - Jordan	5/19 assemble deck lid & install, Fab latch spring, install cell cage & install cell, pump & all fuel lines, put 5 gall in & pressurize system check for leaks	8.5	92.00	782.00T
Labor - Zach	5/20/15 Made a rear end cooler air duct. Made little things for Jordan and gave him a hand on the car.	5	92.00	460.00T
Labor - Jordan	5/20 assemble & install left side door, install hood pins & Fab clip tethers, bleed brakes & clutch, install heat shield around exhaust to body	8.5	92.00	782.00T
Labor - Jordan	5/21 Fab & install diff cooler assy, assemble & install RT side door, install welting around bottom of top, install rear glass & rear view mirror	8.5	92.00	782.00T
Labor - Zach	5/21/15 Installed the rear window and made a new window strap, helped put in the doors and mount the top.	4	92.00	368.00T
Labor - Jordan	5/22 put car on ground move to scales, begin corner weight & alignment	8.5	92.00	782.00T
	•		Total	<u> </u>



	W 10	2015
BILL TO	Op.	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Juan	05/24/15	2	60.00	120.00T
	clean the car inside out, and the wheels			
Shop Supplies	Shop Supplies	1	151.93	151.93T
	Sales Tax		9.40%	564.29
			T-4-1	06.567.20
			Total	\$6,567.39

PO Box 70 Puyallup, WA 98371 253-845-0617

DATE	INVOICE #		
5/15/2015	59121		
BILLING PERIOD			

45-0617	011012015
BILL TO	Qn.

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Parts/Materials	Headlight 4412	1	23.38	23.38T
Parts/Materials	Brake lines	3	6.916	20.75T
Parts/Materials	Coupler	1	7.042	7.04T
Parts/Materials	5/16 Fuel line (per ft	6	5.08	30.48T
Parts/Materials	45" Steel hose crimp -10	2	46.23	92.46T
Outside Service	coat new tail pipe extension to match existing	1	80.85	80.85T
Freight-In	Freight, Inbound	1	21.31	21.31T
Parts/Materials	Speedo Adaptor	1	16.13	16.13T
Parts/Materials	Cir Clip	1	7.25	7.25T
Labor - Jordan	5/4 repair & Fab new pieces for battery box, box up all useable spare parts, and box up all damaged parts	2	92.00	184.00T
Labor - Santos	5.5.15 pick up the auto body work at Byers	1	60.00	60.00T
Labor - Jordan	5/6 begin assembly of car, bolt down body to frame, install pedal box, masters & reservoirs. install ignition box, & misc. other parts	8.5	92.00	782.00T
Labor - Chip	5/8 helped prep motor for install. helped install motor and misc tasks	3	75.00	225.00T
Labor - Jordan	5/8 install roll cages assy, Fab rear brake line, install clutch on engine, install engine assy,	8.5	92.00	782.00T
Labor - Chip	5/11 helped install exhaust, helped put car on stands and other misc tasks	1	75.00	75.00T
Labor - Zach	5/11/15 Made a new straight pipe and worked on fitting the muffler.	2	92.00	184.00T
Labor - Jordan	5/11 assemble car	8.5	92.00	782.00T
Labor - Chip	5/12 helped Jordan install steering column, center steering wheel and misc tasks	1	75.00	75.00T
Labor - Zach	5/12/15 Extended the muffler, made a slip joint, remade muffler brackets.	4	92.00	368.00T
Labor - Jordan	5/12 assemble car	7.5	92.00	690.00T
Labor - Jordan	5/13 assemble car	8.5		782.00T
	•		Total	

PO Box 70 Puyallup, WA 98371 253-845-0617



	DATE	INVOICE #	
	5/15/2015	59121	
	BILLING PERIOD		
1			

	9 al 101		
BILL TO	On.		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Zach	5/14/15 Made backing plates for the fuel cell	0.5	92.00	46.00T
	mount.			
Labor - Jordan	5/14 assemble car	8.5	92.00	782.00T
Labor - Jordan	5/15 assemble car	8.5	92.00	782.00T
Shop Supplies	Shop Supplies	1	197.97	197.97T
	Sales Tax		9.40%	667.08
	•	,	Total	\$7,763.70

DATE INVOICE #

4/30/2015 59025

BILLING PERIOD

	11312015
BILL TO	01.

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Outside Service	1 Fuel tank mount and 2 fuel tank straps for	1	161.70	161.70T
	polane Sales Tax		9.40%	15.20
	1	T		
		[Total	\$176.90

PO Box 70 Puyallup, WA 98371 253-845-0617

. #]	DATE		
		3/31/2015		
BILLING PERIOD				
_	 G PI			

45-0617	512212015
BILL TO	00.

P.O. No.		TERMS	PROJECT
		Due on Receipt	Lotus 26R
	0	D - 4 -	A

Item	Description	Quantity	Rate	Amount
Freight-In	Freight, Inbound	1	31.50	31.50T
Parts/Materials	300lb 7" spring	2	96.39	192.78T
Parts/Materials	175lb 8" springs	2	96.39	192.78T
Parts/Materials	M10 x 1.0 Nyloc	4	1.05	4.20T
Miscellaneous	Dump fees for OD body	1	38.64	38.64T
Dismount	Tire Dismount	3	7.50	22.50T
Mount & Balan	Tire Mount and Balance	4	27.00	108.00T
Tire Disposal	Tire Disposal	3	5.00	15.00T
Labor - Chip	3/25 sorted through spares box, took inventory and updated list	1.5	60.00	90.00T
Shop Supplies	Shop Supplies	1	4.14	4.14T
		,	Total	\$765.30

PO Box 70 Puyallup, WA 98371 253-845-0617



DATE	INVOICE #			
3/15/2015	58911			
BILLING PERIOD				

	6122120
BILL TO	go.

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Freight-In	Freight, Inbound	1	12.52	12.52T
Parts/Materials	90576A131 Nuts	1	15.58	15.58T
Parts/Materials	86195K57 Foam	1	64.69	64.69T
Outside Service	fuel cell framework to be blasted	1	42.00	42.00T
Parts/Materials	Bolts 7/16-20	2	3.08	6.16T
Parts/Materials	Bolts, 1/2-20	2	4.76	9.52T
Freight-In	Freight, Inbound	4	12.39	49.56T
Parts/Materials	Tires, 6.5/23.0-13	4	382.50	1,530.00T
Outside Service	complete body to be prepped & painted (2 bumpers, 2 doors, boot, bonnet, windscreen frame & roof)	I	14,885.00	14,885.00T
Credit	Invoiced 02/15 #58828	1	-12,500.00	-12,500.00T
Labor - Chip	3/6 cut up 26r body	2.25	60.00	135.00T
Shop Supplies	Shop Supplies	1	13.11	13.11T
		,	Total	\$4,663.88

 DATE
 INVOICE #

 2/28/2015
 58870


 BILLING PERIOD

0411312015

BILL TO

		Ī	
	P.O. No.	TERMS	PROJECT
		Due on Receipt	Lotus 26R
Description	Quantity	Rate	Amount
22 parts to be electroless nickel plated	1	492.80	492.80T
Bearing set up 6007	1	6.58	6.58T
Freight, Inbound	1	32.97	32.97T
5/8 x 1/2 Rod end	4	78.76	315.04T
1/2x182 rod end	2	145.60	291.20T
Nuts	10	1.47	14.70T
Bolts	10	1.54	15.40T
Bolts AN7-27A	7	1.12	7.84T
Bolts, AN7-31A	2	4.76	9.52T
AN7-26A Bolts	4	3.77	15.08T
Freight, Inbound	1	21.43	21.43T
	2	32.21	64.42T
AN5-21A Bolts	5	0.94	4.70T
16" Roundel Templates	4	7.00	28.00T
Valvoline 75w90 gear oil	0.5	12.17	6.09T
1/2-13 Nyloc Nut	10	1.05	10.507
1/2" AN Thin Washers	14	0.09	1.267
5/8" Jam Nut	4	2.07	8.28T
5/16" K-Nuts (Jet Nuts)	8	2.34	18.727
5/16" AN Thin	16	0.41	6.56T
3/8-16 Nyloc Nuts	6	0.75	4.50T
Nut Nyloc Shear 1/2-20	4	1.60	6.407
Nyloc AN Shear 7/16-20	4	1.43	5.727
AN Thick 7/16	8	0.18	1.44T
5/16-24 x 1" Bolts	4	1.11	4.447
5/16-24 x 1-1/2"	2	1.31	2.62T
3/8-24 x 1" bolt	4	1.26	5.04T
2/16 assemble axles, file slip joints to fit properly	5	92.00	460.00T
2/17 finish fitting of axles, start to assemble rear lower & all front control arms, order parts as		92.00	644.007
	22 parts to be electroless nickel plated Bearing set up 6007 Freight, Inbound 5/8 x 1/2 Rod end 1/2x182 rod end Nuts Bolts Bolts AN7-27A Bolts, AN7-31A AN7-26A Bolts Freight, Inbound Ball Joints - Upper AN5-21A Bolts 16" Roundel Templates Valvoline 75w90 gear oil 1/2-13 Nyloc Nut 1/2" AN Thin Washers 5/8" Jam Nut 5/16" K-Nuts (Jet Nuts) 5/16" AN Thin 3/8-16 Nyloc Nuts Nut Nyloc Shear 1/2-20 Nyloc AN Shear 7/16-20 AN Thick 7/16 5/16-24 x 1" Bolts 5/16-24 x 1" bolt 2/16 assemble axles, file slip joints to fit properly 2/17 finish fitting of axles, start to assemble rear	Description Quantity 22 parts to be electroless nickel plated 1 Bearing set up 6007 1 Freight, Inbound 1 5/8 x 1/2 Rod end 4 1/2x182 rod end 2 Nuts 10 Bolts 10 Bolts AN7-27A 7 Bolts, AN7-31A 2 AN7-26A Bolts 4 Freight, Inbound 1 Ball Joints - Upper 2 AN5-21A Bolts 5 16"Roundel Templates 4 Valvoline 75w90 gear oil 0.5 1/2-13 Nyloc Nut 10 1/2"AN Thin Washers 14 5/8" Jam Nut 4 5/16" K-Nuts (Jet Nuts) 8 5/16" AN Thin 16 3/8-16 Nyloc Nuts 6 Nut Nyloc Shear 1/2-20 4 Nyloc AN Shear 7/16-20 4 AN Thick 7/16 8 5/16-24 x 1" Bolts 4 5/16-24 x 1" bolt 4 2/17 finish fitting of axles, start to assembl	Due on Receipt

Total



BILL TO

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Labor - Jordan	2/19 assemble rear stub axle/hub assy, machine	8	92.00	736.00T
Labor - Jordan	spacers to properly set pre load & center rotor 2/20 assemble complete left rear upright assembly, heat/shrink in shock tubes, install strut & coil spring, install axle assembly into upright hang wishbone, torque all fasteners, install onto	7.5	92.00	690.00T
Labor - Santos	chassis. Bolt axle to diff 2.23.15 load the car and take it to the paint shop	1	60.00	60.00T
Labor - Jordan	2/23 assemble complete right rear upright assembly, heat/shrink in shock tube, install strut & coil spring, install axle assembly into upright hang wishbone, torque all fasteners, install onto chassis. install diff assy bolt axles to diff	8	92.00	736.00T
Labor - Jordan	2/24 assemble front spindle assemblies, hang front calipers, pack front wheel bearings, torque to spec, install front shocks, , install front & rear brake lines, install steering rack	6.5	92.00	598.00T
Labor - Jordan	2/25 machine spacers for rear lower wishbones, remove wishbones to set up length based on old set up as starting point, hone rear uprights, order new front upper ball joints, replace all front suspension bolts to AN, call RK Graphics to order 16" roundel paint masks	8	92.00	736.00T
Labor - Dan	02/26 Go to body shop and inspect progress and work being done, help Jordan with suspension install.	1	92.00	92.00T
Labor - Jordan	2/26 swap out front upper ball joints, measure & install RT lower wishbone	4	92.00	368.00T
Shop Supplies	Shop Supplies Sales Tax	1	161.88 9.40%	161.88T 628.21
			Total	\$7,311.34

PO Box 70 Puyallup, WA 98371 253-845-0617

Invoice

DATE	INVOICE #	
2/15/2015	58828	
BILLING PERIOD		

	6126120		
BILL TO	0:5%		

	P.O. No.	TERMS	PROJECT
		Due on Receipt	Lotus 26R
	Quantity	Rate	Amount
im		1 12,500.00	12,500.00T

Item	Description	Quantity	Rate	Amount
Outside Service	Complete paint of body (This is so I can pay him upon completion, small shop and will need to be paid right away)	I	12,500.00	12,500.00T
Freight-In	Freight, Inbound	1	982.67	982.67T
Freight-In	Freight, Inbound	1	6.26	6.26T
Parts/Materials	Nuts	2	6.76	13.52T
Outside Service	Paint misc chassis/suspension parts	1	387.25	387.25T
Labor - Jordan	2/2 fit fuel cell framework, oil cooler, catch tanks, & all master cyl reservoirs,	8	92.00	736.00T
Labor - Jordan	2/3 Fab tabs & fit headlight covers, Fab vent screens in engine compartment/wheel wells	7.5	92.00	690.00T
Labor - Jordan	2/4 fit windscreen, remove broken windscreen stud, remove rest of windscreen frame studs Fab new (better design), Fab windscreen hold down tabs, prep to glass muffler cutout, brake master cyl cut out & new windscreen hold down studs	8	92.00	736.00T
Labor - Dan	02/04 Lay out and Fab. aluminum mold pieces to make fiberglass parts for muffler clearance and clutch master cylinder clearance in body.	4	92.00	368.00T
Labor - Dan	02/05 Prep area around clutch master cylinder for fiberglass recess, prep mold for muffler recess and lay up fiberglass.	2.5	92.00	230.00T
Labor - Jordan	2/6 fiberglass in muffler cut out in trunk, brake master cut out in engine compartment & windscreen studs	7	92.00	644.00T
Labor - Dan	02/06 Help Jordan with fiberglass lay up on new body.	2	92.00	184.00T

Total

PO Box 70 Puyallup, WA 98371 253-845-0617



DATE	INVOICE #		
2/15/2015	58828		
BILLING PERIOD			

	6/26/
BILL TO	Q ₂₀

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Labor - Jordan	2/9 flip over body to glass muffler cut out, master cyl cut out & tunnel from underside. glass above sections & fill as needed. flip body back over re assemble (doors, roof, bumpers, windscreen frame, boot & bonnet) get body ready to send out for paint			736.00T
Labor - Jordan	2/12 sand blast all parts back from plating to dult finish	2.5	92.00	230.00T
Shop Supplies	Shop Supplies Sales Tax		151.05 9.40%	151.05T 1,747.91
	1		Total	\$20,342.66

PROJECT

DATE INVOICE #

1/31/2015 58798

BILLING PERIOD

TERMS


P.O. No.

0211812015

BILL TO	0,5


		1.0.1.0.	TEILING	INOULCI
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Freight-In	Freight, Inbound	1	19.12	19.12T
Parts/Materials	Brake reservoirs	2	124.60	249.20T
Freight-In	Freight, Inbound	1	16.83	16.83T
Outside Service	Customs/Duty	1	1,432.21	1,432.21T
Parts/Materials	ABWT-7 bearings	4	35.31	141.24T
Parts/Materials	6206 PP Bearing	3	5.52	16.56T
Parts/Materials	30 x 40 x 7C Seals	2	4.03	8.06T
Freight-In	Freight, Inbound	1	48.94	48.94T
Parts/Materials	Lower front wishbone bush	4	42.57	170.28T
Freight-In	Freight, Inbound	1	15.83	15.83T
Parts/Materials	Seal #026R 6017	1	32.26	32.26T
Parts/Materials	#036D 6006 Internal snap rings	2	2.90	5.80T
Parts/Materials	AN6H7A Bolt	6	2.73	16.38T
Freight-In	Freight, Inbound	1	93.72	93.72T
Parts/Materials	Nut door	1	51.73	51.73T
Parts/Materials	Door trim	10	5.25	52.50T
Parts/Materials	Drip rails	2	153.15	306.30T
Parts/Materials	Windscreen	1	684.60	684.60T
Parts/Materials	Headlight cover	2	167.30	334.60T
Parts/Materials	Nuts	1	20.29	20.29T
Washer, AN Th	Washer, AN Thick 1/2"	4	0.18	0.72T
Bolt, Buttonhe	5/16-18 x 1/2	1	0.69	0.69T
Washer, AN Th	AN 5/16" Thick	7	0.21	1.47T
Nut, Nyloc AN	Nut, Nyloc AN 5/16	7	0.69	4.83T
Bolt, Hex 3/8-2	3/8-24 x 1-1/4" Bolts	2	0.58	1.16T
Bolt, Hex 3/8-1	3/8-16 x 1"	6	1.47	8.82T
Washer, AN Th	3/8" Thick AN Washer	2	0.24	0.48T
Washer, SAE 3	3/8" SAE	6	0.37	2.22T
Parts/Materials	1-3/16 Ext snap rings	3	1.45	4.35T
Labor - Jordan	1/16 continue to fit body to chassis & begin to fit roll cage	8	92.00	736.00T
	i	1	1	

Total



BILL TO 0211812015

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Labor - Chip	1/16 help Jordan fit roll cage to chassis and body	2	75.00	150.00T
Labor - Dennis	01-16 Install bearings and seals in diff housing	1	92.00	92.00T
Labor - Dennis	01-22 Order parts and start reassemble of 4.9 rear end with upgraded axles and diff; have pinion spacer welded for reground; heat carrier and install pinion bearing races	5.5	92.00	506.00T
Labor - Dennis	01-23 Grind pinion bearing spacer and set preload; set backlash and check pattern; take photos of new diff(part # and view of internals)	3	92.00	276.00T
Labor - Chip	1/26 helped Jordan removed roll cage and fit misc panels	0.5	92.00	46.00T
Labor - Jordan	1/26 finish fitting roll cage into body & frame, fit windscreen, fit hardtop, start to fit boot lid,	7.5	92.00	690.00T
Labor - Jordan	1/27 finish fitting boot lid, fit bonnet, fit brake/tail lights, front marker lights & all turn signal lights, fit diff cooler scoop & Fab new inner plate for assy, transfer access hole for gearbox & shifter hole	7	92.00	644.00T
Labor - Chip	1/27 helped Jordan remove cage and mark where to trim body and panels	1	92.00	92.00T
Labor - Jordan	1/28 fit both doors & latch assy	7	92.00	644.00T
Labor - Dennis	01-29 Fit new ring gear bolts to diff, safety wire bolt heads	0.5	92.00	46.00T
Labor - Jordan	1/29 fit dash, steering column & rack, MSD box & misc wiring	7	92.00	644.00T
Labor - Chip	1/29 helped Jordan fit doors and misc tasks	1	92.00	92.00T
Labor - Santos	1.30.14 drop off the frame at Byers paint shop	1.5	60.00	90.00T
Labor - Dennis	01-30 Finish assembly of 4.9 rear end with upgraded axles and diff; add shims to diff housing bearing; set diff bearing preload and pinion backlash; add oil; safety wire plug	4	92.00	368.00T
невиневиневиневиневиневиневиневинев	1		Total	



	1 18	2015
BILL TO	0.2	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Jordan	1/30 fit headlights, id plate & engine compartment vent holes	7.5	92.00	690.00T
Shop Supplies	Shop Supplies	1	186.24	186.24T
	Sales Tax		9.40%	914.94
	•		Total	\$10,648.37

0211812015

DATE	INVOICE #		
1/15/2015	58766		
BILLING PERIOD			

	W 21481	
BILL TO	0,2"	

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Parts/Materials Parts/Materials Outside Service Labor - Jordan	Body/suspension parts coming from UK (Balance, deposits of \$3500.00 and \$4045.50 were previously invoiced) (Main body shell (superlight), Double skin and foam, headlamp walls, exhaust tunnel, flat boot floor, light weight bonnet, boot lid, pair doors, hardtop, bumpers, rear window, alloy boot hinges, windscreen frame, set front adjustable wishbones, pair rear adjustable wishbones, pair rear djustable wishbones, pair front Koni double adjust shocks, pair rear Koni double adjust shocks, complete drivetrain (halfshafts), rear uprights, rear strut tubes, 1 mag rear wheel, rear rodend spacer kit, pair rear brake rotors, three 4 bolt output drive flanges, rear LDS differential, packaging and freight) 2.25 liter Slimline mechanical fire system Exhaust to be stripped & re coated, 6 pcs 1/14 Unload crate from delivery truck, open crate & inventory all parts delivered, get list of parts still needed, sort all parts for plating, start to disassemble prop shafts to prep for plating 1/15 Begin to fit body to chassis, cut holes for rollcage mounting, trim flanges for chassis		625.80 388.80 92.00	19,985.66T 625.80T 388.80T 368.00T
	mounting, drill mounting holes, level and square to chassis		20.64	20.54
Shop Supplies	Shop Supplies Sales Tax		38.64 9.40%	38.64T 2,077.11
			Total	\$24,174.01

PO Box 70 Puyallup, WA 98371 253-845-0617

DATE	INVOICE #		
12/15/2014	58735		
BILLING PERIOD			

	2117120		
BILL TO	O.A.		

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Outside Service	parts for polane	6	18.82534	112.95T
Outside Service	driveshaft parts to be polaned	3	37.65066	112.95T
Outside Service	clean and test, repair as needed and re certify	1	617.33	617.33T
Labor - Jordan	12/1 rebuild steering rack, clean & polish parts to prep for reassembly	6	92.00	552.00T
Labor - Jordan	12/2 dissasemble pedal box, bead blast send out for polane. clean & inspect all master cys, clean & prep more parts for install	6	92.00	552.00T
Labor - Jordan	12/10 hone pivot bushings on pedal box & pedals, re assemble padal box	2.5	92.00	230.00T
Shop Supplies	Shop Supplies	1	40.02	40.02T
	Sales Tax		9.40%	208.42
	1	,	Total	\$2,425.67

PO Box 70 Puyallup, WA 98371 253-845-0617

DATE	INVOICE #		
11/30/2014	58705		
BILLING PERIOD			

	21171201		
BILL TO	U.F.		

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Outside Service	parts to be crack checked	75	6.08646	456.48T
Freight-In	Freight, Inbound	1	23.506	23.51T
Parts/Materials	Upright Assy L&R	2	189.91	379.82T
Parts/Materials	Set Nilo Seal F	1	55.44	55.44T
Parts/Materials	SEt Nilo Seal R	1	55.944	55.94T
Parts/Materials	Capiper bkts L&R	2	245.00	490.00T
Parts/Materials	U joint	1	27.398	27.40T
Parts/Materials	U Joint	1	25.242	25.24T
Parts/Materials	Toggle Switch	1	3.122	3.12T
Freight - Out	Freight, Outbound fuel tank	1	24.15	24.15T
Labor - Jordan	11/19 go through all parts back from crack check, complete list of parts needed for re assembly	3.5	92.00	322.00T
Labor - Jordan	11/20 disaasemble & clean all brake calipers, clean all wheel bearings to inspect, go through list of parts needed & order some front suspension components (dave bean), measure & order drive shaft u joints, de glaze brake all pads	8.5	92.00	782.00T
Labor - Jordan	11/21 disassemble steering rack assy clean & inspect, clean and polish fuel lines, clean exhaust parts, start dissasembly & inspectin of all master cyls & fuel ststem, drain fuel tank, clean & box, ship for re certification & test	6.5	92.00	598.00T
Shop Supplies	Shop Supplies	1	51.06	51.06T
	Sales Tax		9.40%	309.65
	•		Total	\$3,603.81

PO Box 70 Puyallup, WA 98371 253-845-0617

Invoice

DATE	INVOICE #		
10/31/2014	58638		
BILLING PERIOD			

Total

\$5,237.42

413012		
BILL TO	0.1.	

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Outside Service Parts/Materials	strip nichol plating of suspension Deposit on New Body	1		505.00T 4,045.50T
Labor - Dennis	10-16 Take photos of broken stub axle and e-mail to Lou for submittal to CSRG; e-mail photos to Ken at Dave Bean, call and discuss alternate axles	I	92.00	92.00T
Labor - Jordan	10/31 gather parts received from stripper, inventory with other parts to be sent out for crack check & ship	1.5	92.00	138.00T
Shop Supplies	Shop Supplies Sales Tax	1	6.90 9.40%	6.90T 450.02

PO Box 70 Puyallup, WA 98371 253-845-0617



DATE	INVOICE #	
10/15/2014	58583	
BILLING PERIOD		

45-0617	13012015
BILL TO	0.1.

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Parts/Materials	Deposit for new body, suspension	1	3,500.00	3,500.00T
Labor - Jordan	10/2 re organize all parts on shelves in prep for re assembly, continue removal of parts off of body		92.00	368.00T
Labor - Jordan	10/7 continue to remove parts off of wrecked body to inventory for transfer to new one	3		276.00T
Labor - Jordan	10/8 continue removal & catalogue of components off of wrecked body	2		184.00T
Labor - Jordan	10/9 finish removal of all components & lines off of wrecked body	6.5	92.00	598.00T
Labor - Dennis	10-14 Disassemble rear end; clean parts for crack check	1	92.00	92.00T
Labor - Jordan	10/14 lay out all parts to be cracked checked, separate parts that need to be stripped of nickel coat & send out.	5	92.00	460.00T
Shop Supplies	Shop Supplies	1		59.34T
	Sales Tax		9.40%	520.51
	•		Total	\$6,057.85

DATE	INVOICE #		
9/30/2014	58563		
BILLING PERIOD			

	1112	120
BILL TO	4.1.	

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Outside Service	Straighten and repair frame and cage, paint assembly	1	5,875.625	5,875.63T
	Sales Tax		9.40%	552.31
	•	<u> </u>	Total	\$6,427.94
			ı viai	ψ0,127.21

 DATE
 INVOICE #

 9/15/2014
 58516

 BILLING PERIOD

	11212014
BILL TO	4.4.

			P.O. No.	TERMS	PROJECT
				Due on Receipt	Lotus 26R
Ite	em	Description	Quantity	Rate	Amount
Labor - J	Jordan	9/9 contine removal of components on body to	8	92.00	736.00T
Labor - J	Iordan	transfer over to new body after wreck 9/10 contine dissasembly of components left on	4	92.00	368.00T
Lubor - 5	Joraan	body, send out fire bottle for service/re charge	7	92.00	300.001
Labor - J	Jordan	9/11 begin complete tear down & cleaning of all	8.5	92.00	782.00T
		suspension components, hub assemblies & drive			
7 1	т 1	shafts to be sent out for mag,	0.5	02.00	702.007
Labor - J	Jordan	9/12 continue tear down of suspension & hub assemblies for cleaning & mag, dissassemble rear	8.5	92.00	782.00T
		end & housing, measure all rod end spacing on			
		suspension for re assembly, gather part numbers			
		from all aplicable parts for reorder			
Shop Sup	pplies	Shop Supplies	1	80.04	80.04T
		Sales Tax		9.40%	258.32
				Tatal	Ø2.007.27
				Total	\$3,006.36

DATE	INVOICE #			
8/31/2014	58483			
BILLING PERIOD				

	W 1 1 2 1	2014
BILL TO	47*	

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Freight - Out	Freight, Outbound Tube brace	1	12.838	12.84T
Ü	Sales Tax		9.40%	1.21
			T / 1	01405
			Total	\$14.05

PO Box 70 Puyallup, WA 98371 253-845-0617

T			•		
In	V	0	1	C	e

INVOICE #			
58395			
BILLING PERIOD			

	9 0129	
BILL TO	0.2.	

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Labor - Jordan	8/4 strip rest of frame, re-install roll cage assy to frame, prep to be sent out for repair	4	92.00	368.00T
Labor - Chip	8/4 Pressure washed 26r chassis	1	92.00	92.00T
Shop Supplies	Shop Supplies	1	13.80	13.80T
	Sales Tax		9.40%	44.54
		,	Total	\$518.34

 DATE
 INVOICE #

 12/1/2010
 53875

 BILLING PERIOD

	211312010
BILL TO	12

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Outside Service	Lotus Elan S2 body section R door shut pillar, half sill, half quarter	1	245.00	245.00T
Labor - Brett L.	11-17-10 Finish mounting roll cage back in car. Drain water from motor and radiator. Final prep for glass shop	2	80.00	160.00T
Shop Supplies	Shop Supplies	1	4.80	4.80T
	Sales Tax		9.30%	38.11
	<u> </u>			_
		'	Total	\$447.91

J&L Fabricating

PO Box 70 Puyallup, WA 98371 253-845-0617

T	•	
ln'	voi	ce

DATE	INVOICE #	
7/31/2014	58361	
BILLING PERIOD		

	3 0129
BILL TO	O.s.

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Engine Sales Tax	1	543.088	543.09T
	Sales Tax		9.40%	51.05
		r	Total	\$594.14

J&L Fabricating

PO Box 70 Puyallup, WA 98371 253-845-0617

		•	
ln	V()1(ce

INVOICE #		
58301		
BILLING PERIOD		

	91281	
BILL TO	05.	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Jordan	7/1 Separate body from frame, clean frame, move	4	92.00	368.00T
	cars around to move body & chassis to other side			
	of shop			
Labor - Santos	7.11.14 washed one set of wheels	1	60.00	60.00T
Shop Supplies	Shop Supplies	1	12.84	12.84T
	Sales Tax		9.40%	41.44
	•	Ι,	T-4-1	@402.20
			Total	\$482.28

 DATE
 INVOICE #

 6/30/2014
 58262

 BILLING PERIOD

10Al2014
0.0.

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Labor - Jordan	6/30 remove dash assy, seats, firebottle, & roll	8.5	92.00	782.00T
	cage assy			
Shop Supplies	Shop Supplies	1	23.46	23.46T
	Sales Tax		9.40%	75.71
		,	Total	\$881.17
			า บเลา	φοσ1.1/

DATE	INVOICE #				
5/31/2014	58162				
BILLING PERIOD					

	11612014
BILL TO	0.1.

•			P.O. No.		TERMS	PROJECT
					Due on Receipt	Lotus 26R
	Item	Description	Quantity		Rate	Amount
Lab	or - Jordan	5/28/2014 Move car into place to for teardown remove all wheels, rear corner assay's, radiato exhaust, fuel cell		4	92.00	368.00T
Lab	or - Jordan	5/29/2014 Remove engine,transmission,rear en exhaust,left front suspension assy. prep and package motor with carbs for shipping.	d	9.5	92.00	874.00T
Shoi	o Supplies	Shop Supplies		1	30.36	30.36T
- 1	11	Sales Tax			9.40%	119.60
***************************************			•	,	Total	\$1,391.96
					L	J

 DATE
 INVOICE #

 3/31/2014
 58006

 BILLING PERIOD

	612212014
ILL TO	0.5

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Parts/Materials	Ball Joints	2	42.455	84.91T
Freight-In	Engine	1	597.338	597.34T
Balance Only	Tire Balance Only	4	10.00	40.00T
Nut, Jet 5/16	5/16" K-Nuts (Jet Nuts)	8	1.86	14.88T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	6	13.38	80.28T
Filter, B253	Baldwin Oil Filter	1	20.944	20.94T
Race Fuel, Tric	Race Fuel, Trick 114	5	11.8375	59.19T
Lubricant, Cos	Cosworth Coolant	1	11.641	11.64T
Brake, Fluid A	Brake, fluid AP600	0.5	26.53	13.27T
Brake Clean	Brake Clean	3	5.39	16.17T
Chassis Dyno	Chassis Dyno (Initial setup, warmup, and 1 hour of dyno time)	1	265.00	265.00T
Labor - Eric	03/19 Removed motor from crate, cleaned and inspected clutch, installed clutch on motor, started installing in chassis	4	92.00	368.00T
Labor - Eric	03/20 Installed motor, hooked up all oil lines, installed radiator, installed exhaust. Checked thrust clearance, started motor, checked timing.	7.5	92.00	690.00T
Labor - Eric	03/21 Bolt checked chassis, filled car with fuel, bled brakes, checked all fluids, charged battery, deglaze brake pads.	8	92.00	736.00T
Labor - Eric	03/24 Installed new front upper ball joints	2.5	92.00	230.00T
Labor - Brett L.	3-26-14 Set car up on alignment platform and set heights, weight balance and alignment.	5	92.00	460.00T
Labor - Eric	03/28 Installed new oil filter, checked all fluids and load tested battery.	1	92.00	92.00T
Shop Supplies	Shop Supplies	1	89.15	89.15T
	Sales Tax		9.40%	363.66
			Total	\$4,232.43

DATE INVOICE #

3/15/2014 57946

BILLING PERIOD

	512212014
BILL TO	0.5*

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Dismount	Tire Dismount	4	7.50	30.00T
Mount & Balan	Tire Mount and Balance	4	27.00	108.00T
Tire Disposal	Tire Disposal	4	5.00	20.00T
	Sales Tax		9.40%	14.85
		,	Total	\$172.85

 DATE
 INVOICE #

 1/15/2014
 57774

 BILLING PERIOD

	212612014
BILL TO	02

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Outside Service	Grind 44615 to 1.988 OD +.00050000 (bearing races)	4	10.85	43.40T
Freight - Out	Engine Sales Tax		503.636 9.40%	503.64T 51.42
		<u> </u> ,	Total	\$598.46

INVOICE #			
57667			
BILLING PERIOD			

	2116120
BILL TO	12

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Tire Disposal	Tire Disposal	4	5.00	20.00T
Filter, B253	Baldwin Oil Filter	1	20.34	20.34T
Brake, Fluid A	Brake, fluid AP600	1	26.53	26.53T
Labor - Brett L.	11/11 Drained oil and coolant from engine. Started engine removal.	2	92.00	184.00T
Labor - Brett L.	11/13 Removed engine from chassis, prepped for shipping and crated	4.5	92.00	414.00T
Labor - Evan	11-13-13 Help with removal of motor.	1	92.00	92.00T
Labor - Brett L.	11/14 Completed race prep, bled brakes, deglaze brake pads, nut and bolted front and rear suspension, removed oil cooler and lines, cleaned and re installed.	6.5	92.00	598.00T
Shop Supplies	Shop Supplies	1	38.64 9.40%	38.64T 130.99
	•	,	Total	\$1,524.50

DATE	INVOICE #	
10/15/2013	57566	
BILLING PERIOD		

	2146120
BILL TO	12

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Output Flanges	1	20.944	20.94T
Parts/Materials	O36R 0006 Output flanges (This now puts new	2	600.60	1,201.20T
	output flanges on both 26R rearends)			
Filter, B253	Baldwin Oil Filter	1	20.34	20.34T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	6.5	13.38	86.97T
Race Fuel, Tric	Race Fuel, Trick 114	1.5	11.8375	17.76T
Retaining Ring	Retaining Ring, int 1-1/8"	1	0.9372	0.94T
	Sales Tax		9.40%	126.73
	ı	,	Total	\$1,474.88

DATE	INVOICE #	
10/1/2013	57514	
BILLING PERIOD		

		12013
BILL TO	12	

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Freight-In	Bearing & o-ring kit	1	10.794	10.79T
Parts/Materials	82882 T/O Bearing	1	51.31	51.31T
Parts/Materials	82881 o-ring kit	1	6.72	6.72T
Labor - Dennis	09-17 Call vendor and order repair parts for (spare) T/O bearing; dismantle and clean components	0.5	92.00	46.00T
Labor - Dennis	09-25 Rebuild throw-out bearing assembly removed at Rd America, put in spares	0.5	92.00	46.00T
Shop Supplies	Shop Supplies	1	2.76	2.76T
	Sales Tax		9.40%	15.38
		,	Total	\$178.96


DATE INVOICE #

9/15/2013 57475


BILLING PERIOD

1210912013


		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Freight-In	Bolts and washers	1	17.416	17.42T
Freight-In	Washers	1	7.18	7.18T
Parts/Materials	MS 12pt bolt	8	10.192	81.54T
Parts/Materials	3/8 MS 20002 C6 washers	16	0.154	2.46T
Parts/Materials	1/16 Nord-,ock washers (pack of 10)	1	12.754	12.75T
Labor - Dennis	08/20 Assemble front and rear calipers; remove diff; check front hubs/rotor mount for true; start replacing stub axles in 4.9 diff; grease bearings and assemble LR hub and rotor	7.5	92.00	690.00T
Labor - Dennis	08/21 Set up front wheel hubs in mill, center and true up inner bore for new bearing races; order new hardware for rear stub axles and brake rotors; grind spare (used) brake pads to parallel	8	92.00	736.00T
Labor - Dennis	08/22 Continue work on brakes and rear end	6.5	92.00	598.00T
Labor - Dennis	08/26 Order stub axle bearings; follow up on PO's, send bearing cups for grinding	1	92.00	92.00T
Labor Credit	Labor Credit	-4.5	92.00	-414.00T
Parts/Materials	Timken JL44615 cup	4	36.078	144.31T
Parts/Materials	Timken L44649 Cone	4	10.192	40.77T
Parts/Materials	6206RS Bearing	2	5.516	11.03T
Freight-In	ST-43 sets	1	17.122	17.12T
Parts/Materials	Set (4) GD 504-ST43	1	267.68	267.68T
Parts/Materials	Set (4) GD 524 ST 43	1	162.40	162.40T
Outside Service	Turn Rotor	1	28.00	28.00T
Parts/Materials	Graphics - #37	1	55.00	55.00T
Labor - Brett L.	09-03 Do compression and leakdown tests; follow up on parts orders	3	92.00	276.00T
Labor - Brett L.	09-06 Assemble front wheel hubs, check rotor runout; fit calipers; install new diff output flange; install diff	8	92.00	736.00T
			Total	



		i	ı	
		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Labor - Brett L.	09-07 Assemble rear suspension, halfshafts and brakes; safety wire as required	6	92.00	552.00T
Labor - Brett L.	09-09 Finish race prep; start engine and check systems, test drive car with fresh brakes	5	92.00	460.00T
Labor - Juan	09/09/13 clean the car inside out, under the car and the wheels	4	60.00	240.00T
Shop Supplies	Shop Supplies	1	73.44	73.44T
Labor Credit	Labor Credit	-6.5	92.00	-598.00T
	Sales Tax		9.40%	403.18
			Total	\$4,692.28



		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Outside Service	Turn Rear Rotors	2	32.00	64.00T
Freight-In	Pistons	1	19.474	19.47T
Freight-In	Pistons, seals	1	19.474	19.47T
Parts/Materials	1.34 Pistons	4	44.086	176.34T
Parts/Materials	Grilling AR Caliper pistons Alum	4	44.268	177.07T
Parts/Materials	1.34 seals	8	5.866	46.93T
Parts/Materials	050C-7501 Nilos seal	4	7.63	30.52T
Parts/Materials	050C-7502 Nilos seal	4	8.316	33.26T
Parts/Materials	Coop-CS6748 Nilos seal	8	13.986	111.89T
Brake Clean	Brake Clean	2.5	6.39	15.98T
Labor - Dennis	08-05 Remove rear brake rotors; check u-joints	1.5	92.00	138.00T
Labor - Dennis	08-06 Remove fire bottle, inspect pressure gauge, weigh, label and reinstall; send rotors for	3.5	92.00	322.00T
	turning; order new clutch discs; get cable and measure for dipstick; check front hubs and wheel bearing races for looseness			
Labor - Dennis	08-07 Make new oil dip stick/cable; take rear rotors to 2nd vendor for turning; dismantle calipers for inspection and new seals; measure front wheel hubs and check on availability and price; check on availability of oversize wheel bearing races; clean wheel bearings; remount rear rotors to hubs	6.5	92.00	598.00T
Labor - Dennis	08-08 Wash front and rear calipers; install new seals in front calipers; order new seals and pistons for rears, and pistons only for fronts; wash and inspect wheel bearings; order new Nilos grease seals; check front hubs for runout; pull brake pads from spares box, compare compounds	5.5	92.00	506.00T
Shop Supplies	Shop Supplies	1	53.82	53.82T
	•		Total	



P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
	Sales Tax		9.40%	217.40
				02.520.35
			Total	\$2,530.15

DATE	INVOICE #	
8/1/2013	57329	
BILLING	PERIOD	

W 171	20 ⁴³
02.	

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	

Item	Description	Quantity	Rate	Amount
Freight-In	Bearing	1	46.37	46.37T
Parts/Materials	8288 Racing throw out bearing	1	184.80	184.80T
Freight-In	Clutch	1	59.82	59.82T
Parts/Materials	Disc 7.25, 1 x 23 AP Clutch	2	166.012	332.02T
Labor - Dennis	07-31 Put car on lift and remove wheels; file paperwork from Tremblant and Rd America; start job list; order new spare brake pads; order cotter pins to replace stock brake pad retainers; start removal of rear rotors to get turned	4	92.00	368.00T
Shop Supplies	Shop Supplies	1	11.04	11.04T
	Sales Tax		9.40%	94.19
	•		Total	\$1,096.24

DATE	INVOICE #	
7/15/2013	57273	
BILLING PERIOD		

	01091
BILL TO	0.2.

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Brett L.	7/1 Removed muffler from Portland run, installed straight pipe exhast. started inspection of car	3.25	92.00	299.00T
Labor - Brett L.	7/2 Completed inspection, bled brakes, installed wheels and tires.	4.5	92.00	414.00T
Labor - Juan	07/02/13 clean the car inside out, under the car and the wheels	3.5	60.00	210.00T
Labor - Dan	07/15 Go through records and find what type of clutch throw release bearing was used, locate and order new and have shipped to Wisconsin.	I	92.00	92.00T
Shop Supplies	Shop Supplies	1	30.45	30.45T
	Sales Tax		9.40%	98.27
		[Total	\$1,143.72

INVOICE #		
57234		
BILLING PERIOD		

	010512013
BILL TO	Qp.

P.O. No.	TERMS	PROJECT	
	Due on Receipt	Lotus 26R	


Item	Description	Quantity	Rate	Amount
Freight-In	Tires	1	96.306	96.31T
Parts/Materials	Avon FF 6.5/23.0-13	4	365.00	1,460.00T
Race Fuel, Tric	Race Fuel, Trick 114	0.5	11.8375	5.92T
Bolt, Hex 1/4-2	1/4-28 x 1-1/2" Bolt	I	0.58	0.58T
Nut, Jet 1/4 -28	Nut, Jet 1/4 -28	1	1.02	1.02T
Parts/Materials	Pop Rivet	I	0.16	0.16T
Labor - Juan	06/19/13 clean the car inside out, under the car and the wheels	3.5	60.00	210.00T
Labor - Zach	6/19/13 Put car on jack stands and removed wheels and tires for cleaning.	0.25	92.00	23.00T
Labor - Brett L.	6/24 Topped off fuel from dyno run, installed muffler for Portland, installed wheels and safety wired. found the hardware holding the center console in was broken, repaired so center console doesn't move.	3.5	92.00	322.00T
Shop Supplies	Shop Supplies	I	16.65	16.65T
	Sales Tax		9.40%	200.75
			Total	\$2,336.39

DATE	INVOICE #	
6/15/2013	57180	
BILLING PERIOD		


	7/10/20
BILL TO	a.

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	Rebuild Temp gauge	1	119.70	119.70T
Lubricant, Gea	Valvoline 75w90 gear oil	1	12.166	12.17T
Filter, B178	Baldwin Oil Filter	1	9.39	9.39T
Labor - Brett L.	6/6 Completed race prep	1	92.00	92.00T
Labor - Dennis	06-07 Reassemble diff with new axle snap ring	1	92.00	92.00T
Labor - Dennis	06-10 Add oil to 4.9 rear end, safety wire plug, tag and put in storage	0.5	92.00	46.00T
Labor - Eric	06/14 Dynoed car to verify that vibration was fixed, Vibration was better, but still there a little bit, changed out rear tires and vibration was gone.	2	125.00	250.00T
Shop Supplies	Shop Supplies	1	14.40	14.40T
	Sales Tax		9.40%	59.75
	ı	,	Total	\$695.41



		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Brake Bleeder	Bleeder Valve	2	4.42	8.84T
Chassis Dyno	Chassis Dyno (Initial setup, warmup, and 1 hour of dyno time) Ran Car on dnyo to isolate vibration	1	265.00	265.00T
Freight - Out	Temp gauge	1	12.586	12.59T
Labor - Eric	05/20 Investigated axles droop length, removed rear axles and disassembled	2	92.00	184.00T
Labor - Eric	05/21 Finished modifying axles half shafts. finished installing diff and axles in chassis	7	92.00	644.00T
Labor - Brett L.	05/24 Continued race prep, bled brakes, de glazed brake pads and nut and bolted car.	6.25	92.00	575.00T
Labor - Brett L.	05/25 Continued race prep, did not complete due to water temp and oil pressure gauge getting repaired, will complete when gauge comes back.	2.5	92.00	230.00T
Shop Supplies	Shop Supplies	1	51.75	51.75T
	Michael, What we found that could have caused the snap ring failure in the rear end was that when the wheels are at full droop (car jacked up) the halfshafts were fully extended which then would pull on the stub axle in the rearend and put pressure against the snap ring and could cause it to fail. What we did was machine the axle slightly to allow greater clearance in the halfshaft when jacked up, thus not pulling on the stub axle. You are probably asking why this all of a sudden showed up, can't fully answer that other than it has probably been like this for a long time and finally failed. Should not have this problem again. Louie			
	1		Total	



	110	2013
BILL TO	Qr.	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Sales Tax 9.40% 185.29 Total \$2,156.47	Item	Description	Quantity	Rate	Amount
Total 82,156.47		Sales Tax		9.40%	185.29
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2.156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
Total \$2,156.47					
1 otal \$2,156.4/				T-4-1	#2 157 47
1				ı otai	\$2,130.4/

DATE	INVOICE #			
5/15/2013	57079			
BILLING PERIOD				

	511412013
BILL TO	0.0

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Chassis Dyno	Chassis Dyno (Initial setup, warmup, and 1 hour of dyno time)	1	265.00	265.00T
Labor - Denni		2	92.00	184.00T
Labor - Brett I		4	92.00	368.00T
Labor - Eric	05/13 Removed differential, performed leak down test and compression test. Inspected oil filter, and replaced.	6.5	92.00	598.00T
	Sales Tax		9.40%	133.01
			Total	\$1,548.01

DATE INVOICE #

5/1/2013 57038

BILLING PERIOD

	6120	2013
BILL TO	G ₂₀ .	

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	Weber DCOE plastic float Sales Tax	2	41.93	83.86T
	Sales Tax		9.40%	7.88
			<u> </u>	<u> </u>
		,	Total	\$91.74
			I Utai	Ψ/1./Τ

DATE INVOICE #

4/15/2013 56991

BILLING PERIOD

	\$ 12012013
BILL TO	0.5

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Tires	1	237.9125	237.91T
Parts/Materials	Hoosier Street TDS 205/60-13	8	225.00	1,800.00T
Freight-In	Setrab	1	69.944	69.94T
Parts/Materials	Setrab to -10 adapter	2	13.09	26.18T
	Sales Tax		9.40%	200.60
		,	Total	\$2,334.63

DATE	INVOICE #			
4/1/2013	56960			
BILLING PERIOD				

	612012013
BILL TO	0:5*

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Oil Cooler, 25	25 row, 235m oil cooler (Cooler was found to be leaking when run on dyno)	1	277.76	277.76T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	1	13.37934	13.38T
Labor - Brett L.	3-28-13 Set up on dyno and run through all gears, bring up all temps, check for leaks.	2.5		230.00T
Labor - Brett L.	3-29-13 Replace oil cooler where leak was found, top off oil and run again checking for leaks, none found.	3	92.00	276.00T
Labor - Dyno	03/29 Dynoed car to verify systems, found that car was not running well through out the entire RPM range, found sunk float on front carb, replaced float, Replace Floats with composite style floats	5.5	125.00	687.50T
Shop Supplies	Shop Supplies	1	39.35	39.35T
	Sales Tax		9.40%	143.26
			Total	\$1,667.25

E #				
3				
BILLING PERIOD				

	211212013
BILL TO	O'A.

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In Parts/Materials	Shift boot	1	14.39	14.39T
Parts/Materials	Shift Boot	I	25.186	25.19T
	Sales Tax		9.40%	3.72
			T	0.12.22
			Total	\$43.30

DATE INVOICE #

1/15/2013 56788

BILLING PERIOD

	210712013
BILL TO	02

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Brake, Fluid A	Brake, fluid AP600	0.5	26.53	13.27T
Lubricant, Joe	Joe Gibbs XP3 Racing Oil	0.5	13.38	6.69T
Race Fuel, Tric	Race Fuel, Trick 114	1.5		17.76T
Brake Clean	Brake Clean	1	6.39	6.39T
Labor - Evan	1/2/13 -Cut return tube off of radiator, then welded on larger tube that is correct size. (inlet tube in radiator has always been undersize and needed to be changed to match engine)	I	92.00	92.00T
Labor - Brett L.	1-2-13 Minimal race prep from Monterey, nut and bolt suspension, bleed brakes, deglaze brake pads, pump fuel and replace, clean fuel filter, charge battery, fill with all fluids, turn over for oil pressure, start and run.	6.5	92.00	598.00T
Labor - Brett L.	1-8-13 Start and warm up, check to make sure new throwout bearing is working correctly. Check motor for leaks.	1	92.00	92.00T
Shop Supplies	Shop Supplies	1	27.60	27.60T
	Sales Tax		9.40%	80.25
	I		Total	\$933.96


INVOICE #

56762

DATE 1/1/2013 **BILLING PERIOD**

01/3/1/2013 BILL TO

		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Freight-In	Bearing	1	40.558	40.56T
Parts/Materials	Clutch release bearing hydraulic	1	269.85	269.85T
Parts/Materials	-04 to 1/8 NPT female bulkhead	1	0.644	0.64T
Parts/Materials	-04 to 1/8 NPT male 45* Elbow	1	4.088	4.09T
Parts/Materials	2501-04 MJ-MP 90*	1	2.128	2.13T
Parts/Materials	$M6-10 \times 65$	4	0.6405	2.56T
Parts/Materials	M6 1.0x70	4	0.7105	2.84T
Washer, Lockw	Lockwasher 5/16"	12	0.15	1.80T
Fuel Line 5/16	5/16 Rubber Fuel line	24	0.76104	18.26T
Bolt, Buttonhe	10-24 x 1/2 Button HD Socket	2	0.27	0.54T
Washer, AN Th	10-32 Thick	2	0.09	0.18T
Riv-Nut, 10-32	10-32" Steel Riv-Nut	2	1.0416	2.08T
Heat Shrink Tu	1/2" Heat Shrink Tube (Per FT)	3	2.69892	8.10T
Washer, AN Th	5/16" AN Thin	6	0.41	2.46T
Lubricant, Gea	Mobile One 75w 90 Gear Oil	1.5	12.04	18.06T
Brake, Fluid A	Brake, fluid AP600	0.5	26.53	13.27T
Nut, Nyloc 3/8"	3/8"-24 Nyloc Nut	6	0.99	5.94T
Washer, AN Th	3/8" Thick AN Washer	8	0.12	0.96T
Aeroquip 9005	-4 Ferrule, Brass	1	2.5186	2.52T
Washer, Lockw	Lockwasher 10-32	2	0.114	0.23T
Aeroquip Hose	AQP Steel braid racing hose -04	3	4.6032	13.81T
Aeroquip FBM	-4 Steel Straight	2	6.43	12.86T
Tubing, 4130	Tubing 4130 5/8" x .188 wall (per foot)	1	17.54434	17.54T
Tubing, 4130 1	Tubing 4130 1.375 x .095 Wall	0.5	10.15	5.08T
Washer, Lockw	Lockwasher 3/8"	4	0.21	0.84T
Machine - Dan	12/17 Set up and machine mounting spools for release bearing.	3	105.00	315.00T
Labor - Dan	12/17 Measure up and lay out mounts for new hydraulic release bearing assembly and trial fit.	1.5	92.00	138.00T
			Total	



		P.O. No.	TERMS	PROJECT
			Due on Receipt	Lotus 26R
Item	Description	Quantity	Rate	Amount
Labor - Dan	12/18 Coat new clutch release bearing mount studs to prevent rust, install trans snout and studs check fit of bearing housing, clearance bellhousing for studs and install bellhousing, check clearance from bearing to clutch.	1.5	92.00	138.00T
Labor - Dan	12/19 Install fittings in new clutch release bearing and lay out lines for master cylinder and remote bleeder.	0.5	92.00	46.00T
Labor - Brett L.	12-20-12 Fill gearbox with oil and reseal top of box, install into car, make new clutch line and hook up, make bleeder line and mounting bracket mount to firewall. Remove clutch from motor, clean and measure.	,	92.00	736.00T
Labor - Brett L.	12-21-12 Put clutch back on motor, clean engine bay. Intall motor and bleed clutch, make sure clutch works properly.	4	92.00	368.00T
Shop Supplies	Shop Supplies	1		51.06T
	Sales Tax		9.40%	210.49
	•		Total	\$2,449.75

DATE	INVOICE #		
12/15/2012	56728		
BILLING PERIOD			

	13112013
BILL TO	0.4

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight - Out	Returned parts	1	11.676	11.68T
Labor - Dan	12/12 Attempt to install new hydraulic clutch	1	92.00	92.00T
	release bearing on gearbox, ship received			
C1	bearing back and order different bearing.		2.74	2.7.5
Shop Supplies	Shop Supplies	1	2.76	2.76T
	Sales Tax		9.40%	10.01
		,	Total	\$116.45
			ı viai	Ţ3.7 0

J&L Fabricating

PO Box 70 Puyallup, WA 98371 253-845-0617

DATE	INVOICE #	
12/1/2012	56683	
BILLING PERIOD		

	211912
BILL TO	15

P.O. No.	TERMS	PROJECT
	Due on Receipt	Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Dan	11/30 Help Brett measure for hydraulic clutch release bearing, research and locate bearing that will work and order.	2	92.00	184.00T
Shop Supplies	Shop Supplies	1	5.52	5.52T
	Sales Tax		9.40%	17.81
			Total	\$207.33

J&L Fabricating

PO Box 70 Puyallup, WA 98371 253-845-0617

Item

Labor - Brett L.

Labor - Brett L.

Labor - Dennis

Shop Supplies

Invoice

DATE	INVOICE #	
11/15/2012	56648	
BILLING PERIOD		

043-0017	119	2012
BILL TO	12	

	P.O. No.	TERMS	PROJECT
		Due on Receipt	Lotus 26R
Description	Quantity	Rate	Amount
11-7-12 Unhook all lines going to motor, drain water and remove radiator, remove airbox.	2	92.00	184.00T
11-8-12 Remove header and exhaust, remove engine and gearbox from car, remove bellhousing from gearbox, check to see what is needed to adapt new throwout bearing to gearbox.	4.5	92.00	414.00T
11-13 Remove gearbox top cover and inspect gear train; remove front bearing retainer, adapter ring and front plate; review installation of hydraulic T/O bearing	2	92.00	184.00T
Shop Supplies	1	23.46	23.46T
Sales Tax		9.40%	75.71

Total

\$881.17

 DATE
 INVOICE #

 8/15/2012
 56410

 BILLING PERIOD

0911412012

BILL TO	UP

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Nut, Nyloc 3/8	3/8-16 Nyloc Nuts	4	0.75	3.00T
<i>Nut, Jet 3/8</i>	3/8" Jet Nuts	10	1.26	12.60T
Washer, AN Th	3/8" Thick AN Washer	10	0.12	1.20T
Nut, Nyloc 1/2"	1/2"-20 Nyloc Nuts	2	1.59	3.18T
Washer, AN Th	AN 5/16" Thick	4	0.09	0.36T
Nut, Nyloc 5/1	5/16"-24 Nyloc Nuts	2	0.66	1.32T
Nut, Jet 5/16	5/16" K-Nuts (Jet Nuts)	4	0.812	3.25T
Brake, Fluid A	Brake, fluid AP600	0.5	26.432	13.22T
Brake Clean	Brake Clean	2	6.39	12.78T
Lubricant, Gea	Valvoline 75w90 gear oil	1.5	12.166	18.25T
Race Fuel, Tric	Race Fuel, Trick 114	7	11.8375	82.86T
Labor - Brett L.	8-13-12 Change diff to 4.9, go through prep sheet, nut and bolt entire car, make ground strap for motor, bleed brakes, run on dyno, pump out fuel and fill with new.	9.5	92.00	874.00T
Labor - Dan	08/13 Help Brett with rear end change and dyno, fab. tie down plates to put in rental truck for transport and help load and tie down car.	3.5	92.00	322.00T
Labor - Zach	8/13/12 Helped bleed brakes and finish the race prep, picked up rental truck, made tie downs, helped loaded the cars and ran to the hardware store for hardware.	4	60.00	240.00T
Shop Supplies	Shop Supplies	1	40.02	40.02T
	Sales Tax		9.40%	153.04
			Total	\$1,781.08


0212712012

DATE	INVOICE #		
1/15/2012	55003		
BILLING PERIOD			

BILL TO	0212

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In Parts/Materials	Gear	1	20.93	20.93T
Parts/Materials	307 2nd Gear 4 lug	1	298.48	298.48T
	Sales Tax		9.30%	29.71
		,	Total	\$349.12



	212712012
BILL TO	O.F.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Dennis	12-22 Dismantle, clean and service transmission shifter mechanism; make shims to remove play in shift lever sherical install seals in input bearing	3	80.00	240.00T
	retainer and rear extension			
Shop Supplies	Shop Supplies	1	7.20	7.20T
	Sales Tax		9.30%	22.99
			Total	\$270.19

DATE	INVOICE #	
12/15/2011	54945	
BILLING PERIOD		

	212712012
BILL TO	0.2

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	drive disc, Mainshafts, input gear, bearing, bolt, seal	I	27.524	27.52T
Parts/Materials	Drive disc - dog ring 3rd/4th dog lug	1	292.74	292.74T
Parts/Materials	19T 3rd Mainshaft gear 1.125:1 4 dog lug	1	285.852	285.85T
Parts/Materials	25T 1st Mainshaft gear 2.04:1 4 dog lug rocket	1	308.812	308.81T
Parts/Materials	17T input gear short 7 in 22E22Z143	1	522.34	522.34T
Parts/Materials	Bearing front mainshaft pilot; dog engagement; rocket and sierra	1	20.664	20.66T
Parts/Materials	bolt 6 x 1 x 20 mm sock head	1	0.336	0.34T
Parts/Materials	Input shaft seal rocket and sierra	1	7.84	7.84T
Parts/Materials	Seal tailshaft rocket and sierra	1	26.88	26.88T
Labor - Eric	12/01 Removed motor and transmission	8	80.00	640.00T
Labor - Dennis	12-07 Begin dismantling gearbox	2	80.00	160.00T
Labor - Dennis	12-08 Finish dismantling gearbox, then clean components; order new parts	4.5	80.00	360.00T
Shop Supplies	Shop Supplies	1	34.80	34.80T
Tota			Total	\$2,937.74

DATE INVOICE #

10/15/2011 54772

BILLING PERIOD

	100	12011
BILL TO	4.10	

P.O. No.	TERMS	PROJECT
		Lotus 26R

	Item	Description	Quantity	Rate	Amount
Labor - Dennis 10-11 Fit new stub axle to spare rear end 1 80.00 80.00T Shop Supplies 1 2.40 2.40T Sales Tax 9.30% 8.59	Tire Disposal	Tire Disposal		5.00	10.00T
Sales Tax 9.30% 8.59	Labor - Dennis	10-11 Fit new stub axle to spare rear end	1		80.00T
	Shop Supplies	Shop Supplies	1	2.40	2.40T
Total \$100.99		Sales Tax		9.30%	8.59
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
Total \$100.99					
			ļ	Total	\$100.99

 DATE
 INVOICE #

 9/15/2011
 54679

 BILLING PERIOD

	012112011
BILL TO	10.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Shafts	1	17.36	17.36T
Parts/Materials	Diff O/P Shafts, 4bolt (Broken one from RA)	1	591.808	591.81T
	Sales Tax		9.30%	56.65
		<u> </u> ,	Total	\$665.82

DATE	INVOICE #		
8/1/2011	54535		
BILLING PERIOD			

	0121	120
BILL TO	10.	

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Tire Disposal	Tire Disposal	8	5.00	40.00T
Mount & Balan	Tire Mount and Balance	8	27.00	216.00T
Dismount	Tire Dismount	8	7.50	60.00T
	Sales Tax		9.30%	29.39
			T. 4.1	02.45.20
			Total	\$345.39

DATE INVOICE #

7/15/2011 54463

BILLING PERIOD

	010812011
BILL TO	Q _D .

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Engine	1	980.62	980.62T
Labor - Dyno	06/28 Additional Dyno time. Worked on jetting,	3.5	125.00	437.50T
	adjusted throttle linkage, set timing, made a total			
	of 12 pulls			
Shop Supplies	Shop Supplies	1	18.75	18.75T
	Sales Tax		9.30%	133.63
		,	Total	\$1,570.50
			Total	\$1,5/0.50

DATE	INVOICE #		
7/1/2011	54420		
BILLING PERIOD			

	712112011	
BILL TO	01.	

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Tires	8	8.40	67.20T
Parts/Materials	<i>Tires, 6.5 / 23-13 7290</i>	8	336.25	2,690.00T
Filter, B253	Baldwin Oil Filter	1	20.342	20.34T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	7	13.20518	92.44T
Nut, Nyloc 3/8"	3/8"-24 Nyloc Nut	2	0.63	1.26T
Washer, AN Th	3/8" Thick AN Washer	4	0.15	0.60T
Chassis Dyno	Chassis Dyno (Initial setup, warmup, and 1 hour of dyno time)	1	265.00	265.00T
Race Fuel	Race Fuel	3	10.30763	30.92T
Freight - Out	Flywheel returned	1	15.106	15.11T
Labor - Zach	6/27 Worked with installing header and exhaust	3	80.00	240.00T
Labor - Evan	6/27/11 -Installed flywheel, clutch, and air ram tubes on engine. Installed engine in car, hooked up oil lines, throttle linkage. Filled engine with fluids and primed up. Fired engine, ran up to temp, checked timing and fluids. Installed right front marker light, and wired into system. Installed new set of tires.	8	80.00	640.00T
Labor - Evan	6/28/11 -Helped Eric strap down and dyno car. Re-installed airbox post dyno. Checked fluids. Wiped down car.	3.5	80.00	280.00T
Shop Supplies	Shop Supplies	1	32.40	32.40T
1 11	Sales Tax		9.30%	406.90
			Total	\$4,782.17

DATE	INVOICE #			
5/1/2011	54239			
BILLING PERIOD				

	6120120		
BILL TO	Q.s.		

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight - Out	Engine	1	400.568	400.57T
Freight-In	Front side marker lens clear	1	15.82	15.82T
Parts/Materials	Front side marker lens clear	1	65.282	65.28T
	Sales Tax		9.30%	44.80
			Total	\$526.47

DATE INVOICE #

5/1/2011 54198

BILLING PERIOD

	12012011
BILL TO	0.3.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Jeffery	04/11 Removed engine.	2	80.00	160.00T
Labor - Jeffery	04/12 Continue removing engine. Cleaned and	3.5	80.00	280.00T
	preped engine for shipping. Load in crate and			
~ .	create paperwork.		1.	14 .00
Shop Supplies	Shop Supplies	1	12.60	12.60T
	Sales Tax		9.30%	42.09
	•	<u> </u>		
		[Total	\$494.69

DATE INVOICE #

4/1/2011 54159


BILLING PERIOD

0512012011

BILL TO


		P.O. No.	TERMS	PROJECT
				Lotus 26R
Item	Description	Quantity	Rate	Amount
Freight-In	Male Rod ends	1	12.572	12.57T
Parts/Materials	ART8-ECR 1/2 x 1/2 male rod ends	2	130.13	260.26T
Freight-In	Tires	4	9.212	36.85T
Outside Service	12 pcs Suspension parts out for crack check	I	161.70	161.70T
Parts/Materials	Tires, 6.5x23.0-13	4	336.25	1,345.00T
Hose, Coolant	Gates Green Strip 3/4" (per inch)	2	0.742	1.48T
Radiator, Wate	Water Wetter	0.5	17.41	8.71T
Lubricant, Joe	Lubricant, Joe Gibbs XP6	7	11.89	83.23T
Bolt, AN5-16A	AN 5-16A	4	0.96	3.84T
Washer, AN Th	3/8" Thick AN Washer	16	0.15	2.40T
Nut, Jet 3/8 - 24	<i>Jet Nut 3/8" x 24</i>	8	1.31	10.48T
Nut, Jet 5/16 - 24	<i>Jet Nut, 5/16" - 24</i>	4	1.29	5.16T
Race Fuel, Tric	Race Fuel, Trick 114	2	10.02527	20.05T
Radiator, Cap	Radiator Cap 21-25 lbs	1	29.134	29.13T
Brake, Fluid A	Brake, fluid AP600	1.5	23.27	34.91T
Chassis Dyno	Chassis Dyno (Initial setup, warmup, and 1 hour of dyno time)	1	265.00	265.00T
Labor - Juan	03/12/11 clean the car inside out, under the car and the wheels	3	50.00	150.00T
Labor - Evan	3/16/11 -Hooked up breather hoses to engine. Installed radiator and hooked up radiator hoses. Checked crank shaft end plate. Filled engine with oil and water. Spun over engine for oil pressure. Fired engine and ran up to temp. Set timing. Removed rear end gear and installed sears point gear.	7	80.00	560.00T

Total



BILL TO 0512011

		P.O. No.	TERMS	PROJECT
				Lotus 26R
Item	Description	Quantity	Rate	Amount
Labor - Evan	3/17/11 -Hooked up drive line, and half shafts to rear end Masked off and painted inner fender wells. Removed and de-glazed rear brake pads. Checked over rear suspension bolts for tightness. Removed and disassembled left front suspension. Cleaned up suspension pieces and prepped for crack check. Installed front marker lights and wired in. Started fitting new headlight covers.	d	80.00	600.00T
Labor - Evan	3/18/11 -Fueled up car. Fit left and right headlight covers and installed on car. Drilled oil drain plug for safety wire. Installed muffler. De-glazed front brake pads. Painted brake rotors with temp paint		80.00	480.00T
Machine - Louie	3/21/11 -Machined threaded spud for new left front upper control arm.	0.5	92.00	46.00T
Labor - Evan	3/21/11 -Jigged up front control arm to make new one. Made new control arm pieces, fit to jig, then welded up control arm. Started re-assembling LF suspension.	5.5	80.00	440.00T
Labor - Evan	3/22/11 -Finished up re-assembling left front suspension. Cleaned wheel weight glue off of insides of wheels. Re-balanced tires. Made new headrest pad and glued on to roll cage. Installed wheels and tires on car and put car on ground.	7	80.00	560.00T
Labor - Dyno	03/24 Ran car on dyno. Found cylinders 1 and 2 had water in them and water system was being pressurized, removed from dyno	2	125.00	250.00T
	•		Total	•



BILL TO

L		P.O. No.	TERMS	PROJECT
				Lotus 26R
Item	Description	Quantity	Rate	Amount
Labor - Louie	03/25 Ran compression checks, ran leak down tests, pressurized cylinder 1 & 2, bore scoped looking for leak.	3.5	80.00	280.00T
Labor - Louie	03/26 Car up on stands, drained water system, removed radiator, cam cover off, removed cylinder head and inspect head gasket for leak. Talk with Dave, talk with Michael	4.5	80.00	360.00T
Shop Supplies	Shop Supplies	1	106.50	106.50T
Labor Credit	Labor Credit (cylinder head leaking when engine returned from Dave)	11	-80.00	-880.00T
	Michael, I have credited you the time spent trying to repair and diagnois the problem with the cylinder head leak into cylinders 1 & 2.	е		
Labor Credit	Labor Credit (Dave asked that we send him the engine after the crash in Seattle because it was burning oil and smoking out the exhaust)	9	-80.00	-720.00T
	Michael, I have given you a credit for partial time taking the engine out/in because of the oil smoke issue Dave wanted to repair after the crass weekend at Seattle.	'n		
	Sales Tax		9.30%	419.73
			Total	\$4,933.00

DATE INVOICE #

3/15/2011 54124

BILLING PERIOD

0512612011

Description

03/10 Clean car back from paint. Clean interior,

clean under side, suspension, front and rear,

-Flushed out oil lines and cooler. Cleaned out catch tanks. Installed and adjusted headlights. Installed window drip rails. Fastened down roof and windshield frame. Installed new diff cooler

Freight, In - Engine

Headlight

Nut Nylon 304x

5/16-24 x 1" Bolts 5/16"-24 Nyloc Nuts

Stop Light Switch

10-32 Nyloc Nuts

Jet Nut, 5/16" - 24 AN 5/16" Thick

clean engine compartment

hose. Cleaned up engine bay.

SAE 5/16"

10-32 x 5/8

3/11/11

5/16" AN Thin

Marker light and front badge

Front Nose Badge 2-1/4" dia

5/32 Aluminum Pop Rivet

5/32" Alum Backup Washer 4" Aeroduct (per foot)

Marker light assy, amber lense 6175

BILL TO

Item

Parts/Materials

Parts/Materials

Parts/Materials

Rivet, Aluminu...

Washer, Backu...

Brake, Duct Ae...
Bolt, Hex 5/16-...

Nut, Nyloc 5/1... Washer, SAE 5...

Switch, SLS24 ...

Bolt, Buttonhe...

Washer, AN Th...

Nut. Nyloc 10-32

Nut, Jet 5/16 - 24

Washer, AN Th...

Labor - Juan

Labor - Evan

Freight-In

Freight-In
Parts/Materials

	P.O. No.	TERMS	PROJECT
			Lotus 26R
•	Quantity	Rate	Amount
	1	425.236	425.24T
	1	16.128	16.13T
	1	15.90	15.90T
	1	3.25	3.25T
	1	81.41	81.41T
	1	154.96	154.96T
	20		5.40T
	20		0.63T
	3		38.40T
	4	1.1112	4.44T
	4		3.96T
	8		1.86T
	1	14.616	14.62T
	14		4.43T
	18		7.38T
	8		3.12T
	8	1.98	15.84T

4.5

8

0.28

50.00


80.00

2.24T

225.00T

640.00T

Total



	612612011
BILL TO	024

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Evan	3/14/11 -Installed front and rear windows. Installed trim around bottom of roof piece. Installed oil cooler. Installed overflow tanks. Drilled in and installed transponder mounting bracket. Installed seats and seat belts. Installed dash board mounting hardware. Honed out pilot bushing in crank shaft to fit input shaft.	8	80.00	640.00T
Labor - Evan	3/15/11 -Installed clutch, throttle cable mount, and motor mounts on engine. Installed engine in car. Installed headers, starter, air box, hooked up oil lines, hooked up throttle linkage.	8	80.00	640.00T
Shop Supplies	Shop Supplies Sales Tax	1	57.60 9.30%	57.60T 279.17
	•	1	Total	\$3,280.98

INVOICE #			
54102			
BILLING PERIOD			

	6120120	
BILL TO	Q.S.	

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Outside Service	Complete Paint, repair misc cracks, DA entire car, fill and fair as needed, prime, sand, seal, prep for paint, paint base coat and clear coat, paint number circles, paint yellow stripe, clear coat, color sand and buff, reassemble as needed, paint black interior as needed	1	7,986.17	7,986.17T
Credit	Deposit on Paint, Invoice #54056	1	-5,200.00	-5,200.00T
Labor - Santos	2.25.11went to Seattle to pick up the 26r -blow out all the dust around the engine -blow out dust inside the car -spray some speedshine on the bodywork	3	50.00	150.00T
Shop Supplies	Shop Supplies	1	4.50	4.50T
	Sales Tax		9.30%	273.48
			Total	\$3,214.15

DATE	INVOICE #	
2/15/2011	54056	
BILLING PERIOD		

	212412011
BILL TO	0.5

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	Headlight covers (pr)	1	210.014	210.01T
Freight - Out	Engine, Freight Out	1	385.74	385.74T
Freight-In	Parts in from UK	1	167.97	167.97T
Outside Service	Rear Bumper	1	370.00	370.00T
Outside Service	Progress billing on paint	1	5,200.00	5,200.00T
	Sales Tax		9.30%	589.04
		,	Total	\$6,922.76

INVOICE #		
54022		
BILLING PERIOD		

	1 12	12011
ILL TO	O.A.	

		P.O. No.	TERMS	PROJECT
				Lotus 26R
Item	Description	Quantity	Rate	Amount
Outside Service	Repair Lotus 26R, Fiberglass repairs, install new Lf fender section, install new RF fender section, install new R rocker, install in section on RR quarter.	1	3,850.00	3,850.00T
Freight-In	Light Assy & Lens	1	16.926	16.93T
Parts/Materials	6174 light assembly with amber lens, single filament	1	81.41	81.41T
Parts/Materials	6386 Amber lens cap	1	30.786	30.79T
Freight-In	Clutch ring	1	12.53	12.53T
Parts/Materials	AP Twin disc outer clutch ring only	I	380.80	380.80T
Labor - Santos	1.18.11 went to Frank Martinez to pick up 26R	3.5	50.00	175.00T
Labor - Evan	1/25/11 -Drained fluids from engine, then removed engine. Removed air ram tubes, clutch, and prepped engine for shipping.	3.5	80.00	280.00T
Labor - Evan	1/26/11 -Washed off engine, boxed up and prepped for shipping. Cut holes in body for headlight, and front marker lights. Removed oil cooler and oil lines. Cleaned up input shaft on tranny where pilot bushing melted to it. Started fabricating tabs for headlight cover mounting.	8	80.00	640.00T
Labor - Evan	1/27/11 -Fabricated headlight cover mounting tabs, fit to car, then glued and fiberglassed in place. Finished removing parts and pieces on body to get ready for paint. Removed number decals	4.5	80.00	360.00T
Labor - Santos	1.28.11 pick up the trailer and load the 26r and take to Steve for paint	3	50.00	150.00T
Shop Supplies	Shop Supplies	1	48.15	48.15T
• • •	Sales Tax		9.30%	560.38
	•		Total	\$6,585.99

DATE INVOICE #

12/15/2010 53900

BILLING PERIOD

	212412011
BILL TO	0.2

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Filter, B253	Baldwin Oil Filter	1	18.59	18.59T
Labor - Santos	12.3.10 load the 26r and the parts and take them to Frank Martinez	3	50.00	150.00T
Shop Supplies	Shop Supplies	1	4.50	4.50T
	Sales Tax		9.30%	16.10
	1	,	Total	\$189.19

DATE	INVOICE #	
11/15/2010	53834	
BILLING PERIOD		

	011012010
BILL TO	12

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Outside Service	Foreign exchange fee	1	103.57	103.57T
Parts/Materials	Body Parts,RS Door, RS rearsection of front fender, LS front corner	1	3,451.78	3,451.78T
Labor - Brett L.	11-4-10 Check alignment. Remove headlights from nose, remove roof, driver seat, windshield.	2.5	80.00	200.00T
Labor - Brett L.	11-5-10 Remove windshield from support. Take passenger seat out and remove both harness's. Unbolt rollcage from chassis and try to remove, will not remove without cutting, bolt back in car.	7	80.00	560.00T
Labor - Brett L.	11-8-10 Remove all door latch parts from body and broken door.	1.5	80.00	120.00T
Labor - Brett L.	11-9-10 Remove rear window from roof, remove all rubber gaskets, and drill out side trim pieces from roof.	1.5	80.00	120.00T
Shop Supplies	Shop Supplies	1	30.00 9.30%	30.00T 426.44
			Total	\$5,011.79

DATE	53801	
11/1/2010		
BILLING PERIOD		

	2113120
BILL TO	15

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Dan	10/19 Fire engine and warm, pull plugs and run compression test and leak down, remove oil filter, cut and inspect.	1.5	80.00	120.00T
Shop Supplies	Shop Supplies	1	3.60	3.60T
	Sales Tax		9.30%	11.49
		,	Total	\$135.09

INVOICE #	
53714	
PERIOD	

		12010
BILL TO	40.	

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Evan	9/20/10	0.5	80.00	40.00T
	-Checked fluids, charged battery, fired engine			
	and ran up to temp.			
Shop Supplies	Shop Supplies	1	1.20	1.20T
	Sales Tax		9.30%	3.83
	1	<u>' </u>		A
		ľ	Total	\$45.03

DATE	INVOICE #	
8/15/2010	53571	
BILLING PERIOD		

	012912010
BILL TO	0,30,

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Evan	8/13/10	0.5	80.00	40.00T
	-Charged battery, checked fluids, fired engine			
	and ran up to temp.			
Shop Supplies	Shop Supplies	1	1.20	1.20T
	Sales Tax		9.30%	3.83
			Ī	
		'	Total	\$45.03

DATE	INVOICE #			
7/15/2010	53501			
BILLING PERIOD				

	012912010
BILL TO	Qa.

P.O. No.	TERMS	PROJECT	
		Lotus 26R	

Item	Description	Quantity	Rate	Amount
Parts/Materials	Ceramic Engine Seal 35500	1	28.28	28.28T
Parts/Materials	All Weather Engine Seal 35520	I	28.28	28.28T
Labor - Brett L.	6-28-10 Bleed brakes and fill out new prep sheet. Clean oil cooler and replace oil filter. Fill motor with oil and prime. Install air duct to intake and then bolt down oil cooler to body.	3.5	80.00	280.00T
Labor - Juan	06/28/10 clean the car inside out	2	50.00	100.00T
Labor - Brett L.	6-30-10 Gather all spares and supplies for the 26R and load into 24ft trailer. Take to Pacific Raceways for test day. Return from track and unload.	7	80.00	560.00T
Shop Supplies	Shop Supplies	1	69.23	69.23T
	Sales Tax		9.30%	99.12
	•		Total	\$1,164.91

DATE INVOICE #

7/1/2010 53476

BILLING PERIOD

1010412010

BILL TO	40.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	Stop Leak R6	1	3.49	3.49T
Freight-In	Freight In Willans Harness	1	49.00	49.00T
Parts/Materials	Willans Harness 3" 011102	1	332.248	332.25T
Parts/Materials	LX-301 Ignition Module	1	77.82	77.82T
Nut, Nyloc AN	Nyloc AN 3/8-24	3	0.81	2.43T
Nut, Nyloc AN	Nyloc AN 5/16-24	2	0.87	1.74T
Washer, AN Th	AN 5/16" Thick	2	0.28	0.56T
Nut, Jet 3/8 - 24	<i>Jet Nut 3/8" x 24</i>	10	1.31	13.10T
Lubricant, Gea	80w90 gear oil	1	5.92	5.92T
Switch, Toggle	Switch, 1TL1-2	1	31.78	31.78T
Nut, Nyloc AN	Nyloc AN 1/2"	4	1.62	6.48T
Race Fuel, Tric	Race Fuel, Trick 114	6	9.60	57.60T
Nut, Nyloc AN	Nyloc AN 1/4	8	0.42	3.36T
Radiator, Stop	Bar's Leaks	2	5.29	10.58T
Lubricant, Mot	Kendall 20W50 (used to run while testing for	14	8.29	116.06T
	water leak and flushing system)			
Lubricant, Joe	Joe Gibbs Racing Oil	6	13.89	83.34T
Filter, B253	Baldwin Oil Filter	3	18.592	55.78T
Chassis Dyno	Chassis Dyno (Initial setup, warmup, and 1 hour of dyno time)	1	265.00	265.00T
Labor - Dyno	Additional dyno time for intermittent fuel pump switch and runnability	3.5	125.00	437.50T
Labor - Evan	6/23/10 -Set up and welded crack on frame.	0.25	80.00	20.00T
Labor - Brett L.	6-23-10 Remove 4.9 diff. Drain fluid out of 4.4 diff. Inspect under side of car, found crack in rear of car, have Even weld.	3	80.00	240.00T

Total

DATE INVOICE #

7/1/2010 53476

BILLING PERIOD

BILL TO

		P.O. No.	TERMS	PROJECT
				Lotus 26R
Item	Description	Quantity	Rate	Amount
Labor - Brett L.	6-24-10 Fill 4.4 diff with oil and install, attach half shafts and driveline. Nut and Bolt all rear suspension. Check all fluids, run until warm, let cool, check fluids again. Found a lot of oil in water. Drain oil from motor, found lots of water in oil.	6.5	80.00	520.00T
Labor - Brett L.	6-25-10 Remove radiator and oil cooler and oil lines, clean and reinstall. Remove valve cover and try to flush foamy oil through motor with new oil. refill motor with new oil. Run until warm and drain oil to inspect. do this process twice.		80.00	640.00T
Labor - Dan	06/30 Help Brett with diagnosing runnability problems, remove and replace ignition module, help replace fuel pump switch.	3	80.00	240.00T
Labor - Dan	07/01 Remove car from dyno and put in main shop, drain coolant and remove radiator.	0.5	80.00	40.00T
Labor - Louie	07/01 Remove cylinder head, clean and prep for replace of head gasket. Install new head gasket, timc cams, install headers, radiator, hoses, water in, oil in, block sealer added, set timing, warm and prep for dyno. Diagnois fuel delivery problem and repair, diagnois oil in water problem	9.5	80.00	760.00T
Shop Supplies	Shop Supplies	1	51.00	51.00T
Labor Credit	Labor Credit	12.5	-80.00	-1,000.00T
	Sales Tax		9.30%	285.03
	•		Total	\$3,349.82

DATE INVOICE #

6/15/2010 53416

BILLING PERIOD

	710212010
BILL TO	O.c.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Evan	6/14/10	0.5	80.00	40.00T
	-Checked fluids, charged battery, ran engine up			
	to temp.			
Shop Supplies	Shop Supplies	1	1.20	1.20T
	Sales Tax		9.30%	3.83
		· ·	Total	\$45.03
			I VIAI	$\psi \tau J. UJ$

INVOICE #		
53339		
BILLING PERIOD		

	511012010).
BILL TO	go.	

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Evan	5/13/10	0.5	80.00	40.00T
	-Charged battery, checked fluids, fired engine			
	and ran up to temp.			
Shop Supplies	Shop Supplies	1	1.20	1.20T
	Sales Tax		9.30%	3.83
	•	<u>' I,</u>		Ø 45.00
		ľ	Total	\$45.03

DATE INVOICE #

2/15/2010 53115

BILLING PERIOD

	21041201
BILL TO	0.5*

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Evan	2/10/10	0.5	80.00	40.00T
	-Charged battery, checked fluids, ran engine.			
Shop Supplies	Shop Supplies	1	1.20	1.20T
	Sales Tax		9.30%	3.83
		l T	I	
		,	Total	\$45.03
			ı otai	Ţ. J.

DATE INVOICE #

11/15/2009 52943

BILLING PERIOD

	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2009
BILL TO	12	

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Evan	Charge battery, check fluids, start and run to	0.5	80.00	40.00T
	temp		9.30%	3.72
	Sales Tax		9.30%	3./2
		,	Total	\$43.72
			i otai	φ 43. /2

INVOICE #		
52842		
BILLING PERIOD		

	11012009
BILL TO	4.4.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Evan	9/18/09 -Charged battery, checked fluids, and ran engine up to temp.	0.5	80.00	40.00T
Shop Supplies	up to temp. Shop Supplies	1	1.20	1.20T
	Sales Tax		9.30%	3.83
			Total	\$45.03

DATE	INVOICE #		
8/15/2009	52693		
BILLING PERIOD			

	4110120		
BILL TO	4		

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Chassis Dyno	Chassis Dyno (Initial setup, warmup, and 1 hour of dyno time)	1	265.00	265.00T
Labor - Eric	08/06 Finished installing new float in rear carb. Checked float level in front carb. Removed throttle pedal, welded and gusseted arm, reinstalled	5.5	80.00	440.00T
Shop Supplies	Shop Supplies	1	18.90	18.90T
	Sales Tax		9.30%	67.32
		,	Total	\$791.22

DATE	INVOICE #		
6/15/2009	52531		
BILLING PERIOD			

	711512005
BILL TO	O.r.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Brass floats	1	18.578	18.58T
Parts/Materials	45 DCOE Floats - Brass	2	35.714	71.43T
Labor - Evan	6/3/09	1.5	80.00	120.00T
	-Fabricated new battery tray and hold down			
	strap.			
Labor - Brett L.	6-3-09 Check and set ride heights with driver	8	80.00	640.00T
	weight in car. Set wheelbase even side to side.			
	Weight balance car. Set all alignment			
Labor - Brett L.	adjustments. Record all specs. 6/4/09 Replace slave cly line, pulled right front	5	80.00	400.00T
Lubor - Bren L.	caliper off freed up piston, put collector on tail	J	80.00	400.001
	pipe			
Chassis Dyno	Chassis Dyno (Initial setup, warmup, and 1 hour	1	265.00	265.00T
, , , , , , , , , , , , , , , , , , , ,	of dyno time) Found front carb to have sunken			
	float.			
Shop Supplies	Shop Supplies	1	50.85	50.85T
	Sales Tax		9.30%	145.63
				01.517.40
			Total	\$1,711.49

DATE INVOICE #

6/1/2009 52510

BILLING PERIOD


0613012009

BILL TO

_			
	P.O. No.	TERMS	PROJECT
			Lotus 26R
	Quantity	Rate	Amount

Item	Description	Quantity	Rate	Amount
Freight-In	Freight In, Clutch Parts	1	20.636	20.64T
Parts/Materials	209502 Pressure Plate 2-Disk	1	165.97	165.97T
Parts/Materials	509506 Floater Plate	1	87.248	87.25T
Parts/Materials	226063 Clutch Pac 7.25 Two Disc 1" x 23"	1	134.288	134.29T
	spline			
Steel Sheet, CR	16ga	1	10.07184	10.07T
<i>Bolt, Hex 5/16</i>	5/16-18 x 1	8	0.58	4.64T
Washer, AN Th	AN 5/16" Thick	8	0.28	2.24T
Nut, Jet 5/16	5/16" K-Nuts (Jet Nuts)	8	1.62	12.96T
Brake Clean	Brake Clean	3	6.39	19.17T
Lubricant, Mot	Mobil One Race Oil	6	9.78716	58.72T
Bolt, Hex 5/16	5/16-24 x 1" Bolts	2	1.1112	2.22T
Nut, Jet 5/16	5/16" K-Nuts (Jet Nuts)	2	1.62	3.24T
Race Fuel, 112	Sunoco 112 Leaded Race Fuel	5	12.572	62.86T
Spring Extensi	3/8 x 3-1/4 Spring Extension	1	1.43685	1.44T
Labor - Evan	5/18/09	2.5	80.00	200.00T
	-Fabricated new spacer/dust shield to go in			
	between bell housing and engine block.			
Labor - Brett L.	5-18-09 Install diff and both half shafts. Install	8	80.00	640.00T
	and tighten driveline. Complete right rear			
	corner, brakes, control arm. Install left rear			
	upright and shock, attach control arm and half			
	shaft. Drill safety wire bolts for brake calipers.			
	Route brake and clutch lines through engine			
	compartment.			
Labor - Zach	5/18 Welded crack on support bracket.	1	80.00	80.00T
Labor - Brett L.	5-19-09 Finish installing rear suspension, brakes	2	80.00	160.00T
	and safety wire all bolts.			
Labor - Brett L.	5/22/09 Get motor out of crate, clean clutch disc	2	80.00	160.00T
	and inspect, pressure plate			

Total



	613012009
BILL TO	Go.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Brett L.	5/26/09 Clean, paint mounts, bolted to motor, drilled bolts for safety wire	2.5	80.00	200.00T
Labor - Brett L.	5/27/08 Put clutch on motor, Trans in tunnel, bolt mount to Trans, bleed brakes	8	80.00	640.00T
Labor - Brett L.	5/28/09 Set motor in, safety wire mounts put headers on, starter on, carbs	8	80.00	640.00T
Labor - Brett L.	5/29/09 Put tail pipe on, seats in, bleed clutch, add gas	8	80.00	640.00T
Shop Supplies	Shop Supplies	1	100.80	100.80T
			Total	\$4,422.84

 DATE
 INVOICE #

 2/15/2009
 52054

 BILLING PERIOD

0411412009

BILL TO

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Freight In Fuel Filter	1	7.105	7.11T
Parts/Materials	Fuel Filter Element, Filter King	1	24.206	24.21T
Bolt, Hex 7/16	7/16-20 x 1" bolt	6	1.66	9.96T
Washer, AN Th	AN Thick 7/16	14	0.34	4.76T
Washer, AN Th	Washer, AN Thick 1/2"	8	0.32	2.56T
Cotter Pin, 1/8	1/8 x 1-1/2"	4	0.15	0.60T
Washer, AN Th	1/2" AN Thin Washers	8	0.27	2.16T
Nut, Nyloc AN	Nyloc AN 1/2"	4	1.65	6.60T
Nut, Nyloc AN	Nyloc AN 7/16	4	1.204	4.82T
Labor - Brett L.	2-3-09 remove front hubs and bolt on new rotors, reinstall hubs and rotors. Install calipers, pads, and retaining clips, hook up brake lines. Grind washer on left front to achieve proper bearing preload. Install rear control arms and right rear upright with shock. Bolt rear rotors to hubs and reinstall back on spindles.	6	80.00	480.00T
Labor - Dennis	02-11 Disassemble 4.9 rear end (from Historics); examine and order new parts	1.5	80.00	120.00T
Labor - Dennis	02-13 Open gearbox, inspect, close and add oil; regrease T/O bearing	2	80.00	160.00T
Shop Supplies	Shop Supplies	1	22.80	22.80T
	Sales Tax		8.80%	74.41
			Total	\$919.99

DATE	INVOICE #		
2/1/2009	52033		
BILLING PERIOD			

	2145120
BILL TO	0

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	300-10016-01 -3 male inverted flare brake	4	5.60	22.40T
	caliper fitting			
Washer, Coppe	Sealing Washer 3/8 ID	4	0.54	2.16T
Brake, Bleeder	Bleeder Screw 3/8-24	4	17.78	71.12T
	3/8-24 x 1-1/4" Bolts	4	0.58	2.32T
	3/8"-24 Nyloc Nut	4	1.35	5.40T
	3/8" Thick AN Washer	4	0.15	0.60T
Labor - Brett L.	1/15/09 put shock /springs on front end /hooked	8	80.00	640.00T
	up sway bar,			
Shop Supplies	Shop Supplies	1	19.20	19.20T
	Sales Tax		8.80%	67.16
	<u> </u>			
			Total	\$830.36

DATE INVOICE #

1/15/2009 51298

BILLING PERIOD

	M 141200	9
BILL TO	O _{ra} .	

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Outside Service	Refresh Starter	1	69.75	69.75T
	Refresh Starter Sales Tax		8.80%	6.14
			T-4-1	Ø75.00
			Total	\$75.89

DATE INVOICE #

1/1/2009 51277

BILLING PERIOD

	MAI 12009
BILL TO	0***

P.O. No.	TERMS	PROJECT	
		Lotus 26R	

Item	Description	Quantity	Rate	Amount
Outside Service	Cut New Round Bottom Key Way In Shaft Where Marked Same Length As Old One. Hub Supplied	1	255.00	255.00T
Freight-In	For Fit. Freight In Mounting Block	1	10.15	10.15T
Parts/Materials	Tilton Mounting Block 54-530	1	162.75	162.75T
Freight-In	Freight In Shocks	1	25.284	25.28T
Outside Service	Rebuild Front & Rear Shocks	1	974.64	974.64T
Freight-In	Freight In Rotors	1	25.886	25.89T
Parts/Materials	Front Rotors, As Per Faxed Spec	2	196.35	392.70T
Parts/Materials	Rear Rotors, As Per Faxed Spec	2	196.35	392.70T
Brake, Caliper	2.00" Girling Seal	4	9.8924	39.57T
Brake, Caliper	Girling Caliper Seal 1.33	4	4.20	16.80T
Labor - Evan	12/16 Fit preloaded on bearings on rear	8	80.00	640.00T
Eucor Evan	uprights, turn spacers to size, assemble	O	00.00	070.001
Shop Supplies	Shop Supplies	1	19.20	19.20T
	Sales Tax		8.80%	260.01
Total		\$3,214.69		

DATE INVOICE #

12/15/2008 51240

BILLING PERIOD


0311212009

BILL TO

P.O. No.	TERMS	PROJECT
		Lotus 26R
Quantity	Rate	Amount
1	11.704	11.70T
4	00.73	272 177

Item	Description	Quantity	Rate	Amount
Freight-In	Freight In Rod Ends	1	11.704	11.70T
Parts/Materials	Rod Ends NHBB ART7ECR	3	90.72	272.16T
Freight-In	Freight In Master Cylinder	1	9.10	9.10T
Freight-In	Freight In Bearing & Race	1	8.82	8.82T
Parts/Materials	Girling 5/8 Remote Non Reservoir Master	1	102.984	102.98T
	Cylinder			
Parts/Materials	Bearing 15126	4	6.034	24.14T
Parts/Materials	Race 15245	4	15.386	61.54T
Freight-In	Freight In, Fuel Cell	1	13.02	13.02T
Freight-In	Freight In Seals	1	13.454	13.45T
Parts/Materials	New Fuel Cell Part # RB108 20" x 12" x 8.5"	1	579.60	579.60T
Parts/Materials	Seals 1-1/4 ID x 2-5/16 OD	3	13.986	41.96T
Freight-In	Freight In Reservoir & Fitting	1	10.682	10.68T
Parts/Materials	Reservoir W/-4 90* Fitting	1	77.35	77.35T
Parts/Materials	Hose End,-4 90* Push On	1	20.17	20.17T
Parts/Materials	Aeroquip FBBM1441	1	10.878	10.88T
Freight - Out	Shocks out for rebuild	1	15.358	15.36T
Bolt, Hex 5/16	5/16-24 x 2-1/2	4	1.20	4.80T
<i>Nut, Nyloc 5/1</i>	5/16"-24 Nyloc Nuts	6	0.6336	3.80T
Washer, AN Th	AN 5/16" Thick	12	0.28	3.36T
Bolt, Hex 1/4-2	1/4-28 x 1-1/2" Bolt	2	0.58	1.16T
Washer, AN Th	1/4" AN Thick Washer	2	0.15	0.30T
Clamp, Hose	8-12 Zebra Clamp	4	1.26	5.04T
Parts/Materials	Clear RTV Silicone	1	4.634	4.63T
Fuel Line 1/4"	1/4" Fuel Line	3	0.91	2.73T
Labor - Brett L.	12/1/08 Put front end on left /right, back wheel	8	80.00	640.00T
	bearings/upper/lower a-arms, made spacers			
Labor - Brett L.	12/2/08 Lap rear hubs for better fit pack rear	6.5	80.00	520.00T
	bearings, heat hubs to press cones in			
Labor - Brett L.	12/3/08 Steering rack assembled, installed	7	80.00	560.00T
		_		

Total



P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Brett L.	12/4/08 New fuel lines from tank to filter/filter to carb/press bearing out of starter	4	80.00	320.00T
Labor - Brett L.	12/5/08 Installed fuel cell in box, torque plate on tank, cut pick up to length put straps on	6	80.00	480.00T
Shop Supplies	Shop Supplies	1	84.00	84.00T
	Sales Tax		8.80%	343.44
		,	Total	\$4,246.17

DATE INVOICE #

12/1/2008 51214

BILLING PERIOD


0311212009

BILL TO

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight - Out	Engine Out For Rebuild	1	337.722	337.72T
Freight-In	Freight In Caliper O-Rings	1	13.23	13.23T
Freight-In	Freight In Suspension Parts	1	15.834	15.83T
Parts/Materials	O-Rings For Calipers	16	2.646	42.34T
Parts/Materials	Ball Joint Left & Right	2	32.214	64.43T
Parts/Materials	Tie Rod Left & Right	2	23.856	47.71T
Parts/Materials	Metalastic Bushings, Suspension	4	15.386	61.54T
Parts/Materials	Wheel Bearings & Race, Rear Inner	2	16.954	33.91T
Parts/Materials	Wheel Bearings & Race	2	10.92	21.84T
Parts/Materials	FBM 3091 -3 Fitting	2	17.668	35.34T
Outside Service	Crack Check 60 Pieces	1	326.172	326.17T
Freight-In	Freight In U-Joints	1	15.26	15.26T
Parts/Materials	Lower A-arm Metal Bushing	1	15.386	15.39T
Parts/Materials	U-Joints For Half Shafts	2	26.166	52.33T
Parts/Materials	U-Joints For Half Shafts	2	30.17	60.34T
Freight-In	Freight In Trunnion Assy	1	13.86	13.86T
Parts/Materials	LH Trunnion Assembly	1	76.986	76.99T
Parts/Materials	RH Trunnion Assembly	1	76.986	76.99T
Brake, Caliper	2.00" Girling Seal	4	9.8924	39.57T
Washer, Coppe	Sealing Washer 3/8 ID	4	0.54	2.16T
Brake, Bleeder	Bleeder Screw 3/8-24	2	17.78	35.56T
Brake, Caliper	Girling Caliper Seal 1.33	4	4.20	16.80T
Parts/Materials	1-3/4" Inside snap-ring	2	1.05	2.10T
Rod End, RH 7	Stainless Rod End	1	110.59	110.59T
Heat Shrink Tu	1/2" Heat Shrink Tube Per ft	5	1.04	5.20T
Filter, B253	Baldwin Oil Filter	1	19.80	19.80T
Labor - Brett L.	11/17/08 Pulled oil cooler, filter, cleaned lines,	6	80.00	480.00T
	rebuild brake calipers, front /rear, made parts list			
Labor - Brett L.	11/21/08 Glass bead steering rack, drive shaft,	4	80.00	320.00T
	tape off, paint			

Total



		P.O. No.	TERMS	PROJECT
				Lotus 26R
Item	Description	Quantity	Rate	Amount
Labor - Dennis	11-24 Examine RH rear axle and flange for taper fit and key tolerance	1.5	80.00	120.00T
Labor - Evan	11/24/08 Press joints in drive shafts, press bushings in a-arms, measure brake rotors for new ones	5.5	80.00	440.00T
Labor - Dennis	11-25 Research replacement LR axle for price and availability	1	80.00	80.00T
Labor - Dan	11/25 Help Mark with ordering and measuring brake rotors.	1		80.00T
Labor - Brett L.	11/25/08 Press bearing in front hubs installed snap rings, put oil cooler on/filter, pulled fuel tank, foam out of tank	8	80.00	640.00T
Labor - Dennis	11-26 Check dimensions on rotor sheet for manufacture; find formula, measure and calculate bolt circle for rear rotors	2.5	80.00	200.00T
Labor - Brett L.	11/26/08 Remove master cylinders, disconnect pedals, installed two new ones, installed two new joints in haft shafts.	8	80.00	640.00T
Labor - Mark	11/28/08 Heat shrink reservoir lines, strip old off, drilled pop rivets off tag, strip paint off under brake reservoirs, heat shield	4	80.00	320.00T
Shop Supplies	Shop Supplies Sales Tax	1	99.60 8.80%	99.60T 436.71
	•	•	Total	\$5,399.31

DATE	INVOICE #	
11/15/2008	51172	
BILLING PERIOD		

	211212009
BILL TO	0.5*

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Zach	11/4 Welded up engine stand for shipping motor.	0.5	80.00	40.00T
Labor - Brett L.	11/3 Pulled motor, Trans, tires, start to make mounts for shipping	8	80.00	640.00T
Labor - Brett L.	11/4 Made mounts for shipping, drilled plates, bent tubing, boxed for shipping	7.5	80.00	600.00T
Labor - Evan	11/5 Pulled brakes off, a-arms off, front to back	8	80.00	640.00T
Labor - Evan	11/6 Pressed out joints in haft shafts, drive shaft, pull steering rack out	8	80.00	640.00T
Labor - Evan	11/78 Disassemble front hubs pressed out bearings race out, cleaned	4	80.00	320.00T
Labor - Santos	11/10 Cleaned the engine area	0.75	50.00	37.50T
Labor - Santos	11/11 Take the seats off of the car, there were allot of gear oil under the seats I cleaned it, cleaned inside the car complete, cleaned inside the trunk, cleaned inside the fenders, cleaned under the car	6	50.00	300.00T
Labor - Mark	11/13 Clean parts , ready for crack check	4	80.00	320.00T
Labor - Evan	11/12 Pulled rear shocks out of towers, pressed bearing races out, pressed out front spindles	8	80.00	640.00T
Shop Supplies	Shop Supplies	1	126.53	126.53T
	Sales Tax		8.80%	378.75
		,	Total	\$4,682.78

INVOICE #	
51151	
PERIOD	
_	

	2112120
BILL TO	05.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Logan	10/21 Cleaned inside, outside and rims of car, covered car with plastic.	2	50.00	100.00T
Shop Supplies	Shop Supplies	1	103.00	103.00T
	Sales Tax		8.80%	17.86
		,	Total	\$220.86

 DATE
 INVOICE #

 10/15/2008
 51095

 BILLING PERIOD

	211312009
BILL TO	0,5

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Freight In	1	10.08	10.08T
Parts/Materials	Muffler, 14" Long	1	368.984	368.98T
Dismount	Tire Dismount	4	7.50	30.00T
Mount & Balan	Tire Mount and Balance	4	27.00	108.00T
Tire Disposal	Tire Disposal	4	5.00	20.00T
Parts/Materials	1-1/2 Stainless U Bend 2-1/2 x 4 R	1	43.092	43.09T
Labor - Mark	Malone 26R 9/19/08 gear change diff	8	80.00	640.00T
Labor - Evan	10/2/08 -Fabricated new muffler setup.	2.5	80.00	200.00T
Labor - Louie	10/03 Purge and weld new muffler	1	80.00	80.00T
Labor - Evan	10/3/08	2	80.00	160.00T
	-Ran car on dyno. Mounted new muffler.			
Chassis Dyno	10/3 Dyno Shakedown of 26R for CSRG Charity Event	I	265.00	265.00T
Labor - Dyno	10/03 Dyno car	I	125.00	125.00T
Shop Supplies	Shop Supplies	1	41.70	41.70T
	Sales Tax		8.80%	184.08
			Total	\$2,275.93

DATE	INVOICE #	
10/1/2008	51044	
BILLING PERIOD		

	11612009
BILL TO	0.1.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Washer, AN Th	3/8" Thick AN Washer	24	0.15	3.60T
Washer, AN Th	AN 5/16" Thick	12	0.28	3.36T
Nut, Jet 5/16	5/16" K-Nuts (Jet Nuts)	4	3.17	12.68T
<i>Nut, Jet 3/8</i>	3/8" Jet Nuts	10	2.01	20.10T
Labor - Evan W.	9/15 26R spares inventory	1	80.00	80.00T
Labor - Evan	9/19/08 Change diff to short ratio for Sears Point	7	80.00	560.00T
Shop Supplies	Shop Supplies	1	19.20	19.20T
	Sales Tax		8.80%	61.51
		,	Total	\$760.45

DATE	INVOICE #	
9/1/2008	50947	
BILLING PERIOD		

	112412008
BILL TO	4.4.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight - Out	Weber float replaced, borrowed	1	6.482	6.48T
	Sales Tax		8.80%	0.57
		,	Total	\$7.05
			I Utal	Ψ7.03

 DATE
 INVOICE #

 8/15/2008
 50883

 BILLING PERIOD

1012912008

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	Credit Over Charge Weber Float DCOE 45,	-1	27.272	-27.27T
	(Portland Track Side)			
Parts/Materials	U-Joints PUJ 344	2	40.00	80.00T
Parts/Materials	U-Joints PUJ 369	2	18.13	36.26T
Filter, B253	Baldwin Oil Filter	1	19.80	19.80T
Lubricant, Mot	Mobil One Race Oil	6	8.58122	51.49T
Nut, Jet 7/16-20	7/16"-20 Jet Nut	8	5.95	47.60T
Tie, Self-Locki	Zip Tie, 11.5"	2	0.21	0.42T
Hose, Heater 1	Cloth heater hose 1/2"	1	2.41	2.41T
Brake Clean	Brake Clean	2	6.39	12.78T
Brake, Fluid M	Motul RBF600	1	20.27312	20.27T
Labor - Brett L.	8-5-08 Remove oil filter and cut open and inspect. Replace filter with new filter. Begin race prep of car. Remove rear half shafts for replacement of U-joints.	3	80.00	240.00T
Labor - Brett L.	8-6-08 Perform engine status. Disassemble rear half shafts. Nut and Bolt suspension, pressure test cooling system.	7.5	80.00	600.00T
Labor - Brett L.	8-7-08 Order new U-joints, remove and repair overflow bottles, modify body so overflow tubes go all the way through body. Assemble half shafts with new U-joints.	7	80.00	560.00T
Labor - Brett L.	8-8-08 Install half shafts.	1	80.00	80.00T
Labor - Santos	8/11/8 cleaned under the car	1	50.00	50.00T
Labor - Brett L.	8-11-08 Finish install of half shafts, safety wire all bolts. Finish Race Prep.	4	80.00	320.00T
Shop Supplies	Shop Supplies	1	55.50	55.50T
1 11	Sales Tax		8.80%	189.13
			Total	\$2,338.39

 DATE
 INVOICE #

 7/15/2008
 50764

 BILLING PERIOD

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Nut, Nyloc 5/1	5/16"-24 Nyloc Nuts	1	0.6336	0.63T
Filter, B253	Baldwin Oil Filter	1	19.80	19.80T
Lubricant, Mot	Mobil One Race Oil	6	8.58122	51.49T
Washer, Stato	1/4" i.d. Stato-Seal	8	2.35	18.80T
Brake, Fluid M	Motul RBF600	0.5	20.27312	10.14T
Spark Plug, 68	Champion 686	4	8.50	34.00T
Labor - Guy	07/03 Remove rear differential and install different gear ratio one. The above consists of removing rear half shafts and part of the suspension to change the differential. Install muffler.	6	80.00	480.00T
Labor - Evan W.	7/3 MALONE 26R put on decals	1.5	80.00	120.00T
Labor - Evan	7/9/08 -Ran engine. Checked water and added oil to engine. Checked front and rear suspension bolts for tightness. Installed tires and wheels. Safety wired wheel nuts.	2.5	80.00	200.00T
Labor - Joseph	07/09 Speed shined outside, cleaned inside & vacuum, clean wheels.	1	50.00	50.00T
Shop Supplies	Shop Supplies	1	40.40	40.40T
	Sales Tax		8.80%	90.22
	1		Total	\$1,115.48

DATE	INVOICE # 50727	
7/1/2008		
BILLING	PERIOD	

	91211200
BILL TO	05.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	Universal Spring	1	3.416	3.42T
Labor - Mark	6/16/08 malone 26R pulled rad,oil cooler to clean cooling Finns	4	80.00	320.00T
Labor - Evan W.	6/17 MALONE 26R: Race prep, Grease fittings, bled brakes, cleaned out air box and fuel filter.	5	80.00	400.00T
Labor - Mark	6/17/08 race prep pulled radiator cleaned oil cooler	3	80.00	240.00T
Labor - Eric	06/30 Removed old numbers from hood, and both doors.	0.25	80.00	20.00T
Labor - Dennis	06-30 Discuss rear gear for Portland	0.25	80.00	20.00T
Shop Supplies	Shop Supplies	1	30.00	30.00T
			Total	\$1,124.36

DATE	INVOICE #	
6/15/2008	50662	
BILLING	PERIOD	

	0051200	В
BILL TO	Op.	

P.O. No.	O. No. TERMS	PROJECT	
		Lotus 26R	

Item	Description	Quantity	Rate	Amount
Parts/Materials	AV 6.5/23-13 Tires (7290M)	4	282.50	1,130.00T
Washer, Coppe	Sealing Washers	1	1.68939	1.69T
Filter, B253	Baldwin Oil Filter	1	19.80	19.80T
Lubricant, Mot	Mobil One Race Oil	6	8.43	50.58T
Spark Plug, 68	Champion 686	4	8.50	34.00T
Washer, Stato	1/4" i.d. Stato-Seal	8	2.35	18.80T
Labor - Evan W.	6/4 LOTUS 26R start race prep. Engine work	8	80.00	640.00T
	sheet, oil, etc			
Shop Supplies	Shop Supplies	1	19.20	19.20T
1 11	Sales Tax		8.80%	168.44
			Total	\$2,082.51

DATE INVOICE #

6/1/2008 50596

BILLING PERIOD

	1051200B
BILL TO	025.

P.O. No.	TERMS	PROJECT	
		Lotus 26R	


Item	Description	Quantity	Rate	Amount
Race Fuel	Race Fuel	2.5	9.45	23.63T
Labor - Evan W.	5/20 Malone 26R Repair sticking throttle cable	1	80.00	80.00T
	and ran to check for fluid leaks on water pump.			
Shop Supplies	Shop Supplies	1	4.80	4.80T
	Sales Tax		8.80%	9.54
		,	Total	\$117.97
			10001	

071171200B

DATE	INVOICE #	
5/15/2008	50541	
BILLING PERIOD		

BILL TO	

		P.O. No.	TERMS	PROJECT
				Lotus 26R
Item	Description	Quantity	Rate	Amount
Parts/Materials	U-Joint, 369	1	17.11	17.11T
Parts/Materials	U-Bolts	2	5.628	11.26T
Freight-In	O-Ring	1	6.594	6.59T
Parts/Materials	O-Ring 9452K141	1	11.704	11.70T
Parts/Materials	O-Ring	4	0.966	3.86T
Nut, Jet 5/16	5/16" K-Nuts (Jet Nuts)	4	3.17	12.68T
Nut, Jet 10-32	10-32 Jet Nuts	2	2.67	5.34T
Lubricant, Mot	Mobil One Race Oil	6	8.43	50.58T
Washer, Coppe	Sealing Washers	1	1.68939	1.69T
Spark Plug, 68	Champion 686	4	8.50	34.00T
Nut, Jet 3/8	3/8" Jet Nuts	2	1.86	3.72T
Radiator, Wate	Water Wetter	1	15.00	15.00T
Weather Pack,	1 prong male	1	1.52	1.52T
Weather Pack,	1 prong female	1	0.11	0.11T
Race Fuel	Race Fuel	5	9.45	47.25T
Outside Service	Repair & paint chips	-1	53.20	-53.20T
Labor - Evan W.	Malone 26R Got left outer marker light to fit properly.	0.5	80.00	40.00T
Labor - Evan W.	4/30 26R Mounted foam in the fender wells.	1	80.00	80.00T
Labor - Eric	05/01 Repaired drive line yoke and replaced from u joint.	1.5	80.00	120.00T
Labor - Evan W.	5/1 Malone 26R finished foam for fenders.	0.5	80.00	40.00T
Labor - Evan W.	5/1 26R Started to nut and bolt car. Opened hole to remove driveline inorder to fix freeze plug leak in u-joint.	7.5	80.00	600.00T
Labor - Evan W.	5/2 26R- Put u-joint together and put driveline in, finished nut and bolt of underside, put exhaust back on with straight pipe and changed oil.	8	80.00	640.00T
Labor - Evan W.	5/6 malone 26R race prep, put new u-bolt on tranny, weather pak on fuel pump.	7.5	80.00	600.00T
	•		Total	



	7112	000
BILL TO	. A. "	

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Evan W.	5/7 malone 26R- finished race prep, upon starting she showed a leak at top of water pump, drained coolant and resealed.	4	80.00	320.00T
Labor - Evan W.	5/9 Finished final prep on 26R cleaning wax, and painting inside light wells.	5.5	80.00	440.00T
Shop Supplies	Shop Supplies	1	105.60	105.60T
	Sales Tax		8.80%	277.62
			Total	\$3,432.43

Credit Memo

Date	Credit No.
5/1/2008	050508

Customer			
		P.O. No.	Project
	_		Lotus 26R
Description	Qty	Rate	Amount
Credit back on fender chip repairs.	-1	750.00	-750.00T
		Subtotal	-\$750.00
		Sales Tax (8.8%	6) -\$66.00
		Total	-\$816.00
		Invoices	\$816.00
		Balance Cre	edit \$0.00

DATE	INVOICE #		
5/15/2009	50471		
BILLING PERIOD			

	613012009	
BILL TO	00.	

P.O. No.	P.O. No. TERMS	
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Lubricant, Gea	80w90 gear oil	1	8.95	8.95T
Labor - Dennis	05-01 Start reassembly of 4.9 rear end; prep	3	80.00	240.00T
	R&P, mount ring gear on diff			
Labor - Dennis	05-04 Finish assembly of 4.9 rear end	6	80.00	480.00T
Shop Supplies	Shop Supplies	1	21.60	21.60T
	Sales Tax		9.30%	69.80
		,	Total	\$820.35

DATE INVOICE #

5/1/2009 50450

BILLING PERIOD

	613012009
BILL TO	Qo.

P.O. No.	P.O. No. TERMS	
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	6.5/23.0-13 Avon Tires	4	302.50	1,210.00T
Freight-In	Tires	4	8.9012	35.60T
-	Sales Tax		9.30%	115.84
1			<u> </u>	
			Total	\$1,361.44

DATE INVOICE #

4/1/2009 50314

BILLING PERIOD

	107	12009
BILL TO	0p.	

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Dennis	03-12 Follow up on Ring and Pinion	0.25	80.00	20.00T
Shop Supplies	Shop Supplies	I	0.60	0.60T
Freight-In	Freight In, Ring & Pinion	1	17.178	17.18T
Parts/Materials	4.9 Ring & Pinion For Lotus 26R	I	1,074.92	1,074.92T
	Sales Tax		8.80%	97.92
			Total	\$1,210.62

DATE	INVOICE #	
3/1/2009	50286	
BILLING PERIOD		

	010712009	
ILL TO	Qp.	

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Freight In, Rear End Parts	1	15.862	15.86T
Parts/Materials	Diff Carrier Bearings LM29749 W/LM29710,	2	30.772	61.54T
	For Gear Type Diff			
Parts/Materials	036R 6023 Pinion Bearing Cone	2	25.186	50.37T
Parts/Materials	036R 6026 Pinion Bearing Cup	2	6.986	13.97T
Parts/Materials	026R 6017 Seal	1	29.246	29.25T
Parts/Materials	036R 6007 Seal	2	14.308	28.62T
Labor - Dennis	02-16 Dismantle, inspect and reassemble	2.5	80.00	200.00T
	differential; repair stripped thread; install new diff bearings and seals			
Labor - Dennis	02-20 Prep rear end components for reassembly; shrink in pinion bearing races	1.5	80.00	120.00T
Shop Supplies	Shop Supplies	1	9.60	9.60T
	Sales Tax		8.80%	46.57
		,	Total	\$575.78

DATE INVOICE #

5/1/2008 26440

BILLING PERIOD

	51041200B
BILL TO	00.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	GE 4412 Head Lamp	1	14.02	14.02T
Outside Service	Repair Damage On Left Front Fender, Repair	1	1,534.38	1,534.38T
	Rock Chips/Stars On Right Front Fender			
Parts/Materials	Headlamp Wagner 4412	1	14.02	14.02T
Freight - Out	Headlamp	1	10.36	10.36T
Labor - Evan W.	4/14 Malone 26R- Removed lights, lower grille,	1.5	80.00	120.00T
	bumper cover, marker lights.			
Labor - Santos	4/15/8 I take 26r to Seattle to get work on.	2	50.00	100.00T
Labor - Santos	4/22/08 I pick up 26r at Seattle and take to shop	2	50.00	100.00T
Labor - Evan W.	4/23- 26R Started to reassemble front.	1.5	80.00	120.00T
Labor - Dennis	04-24 Work on marker light lens/bezel	0.25	80.00	20.00T
Labor - Evan W.	4/24 Finished 26R lights, marker lights and lower	2.5	80.00	200.00T
	grille.			
Shop Supplies	Shop Supplies	2	16.80	33.60T
	Sales Tax		8.80%	199.44
			Total	\$2,465.82

DATE INVOICE #

4/15/2008 26379

BILLING PERIOD

	W 12912008
BILL TO	40"

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	26 x 40 x 8 Seal Viton	1	6.02	6.02T
Parts/Materials	13527 Seal	1	8.33	8.33T
Outside Service	Tire Disposal	4	5.60	22.40T
Outside Service	Mount & Balance	4	42.00	168.00T
Outside Service	Spin Balance	4	10.50	42.00T
Parts/Materials	Avon 6.5/23-13 Tires	4	282.50	1,130.00T
Freight-In	Oil Seal	1	40.25	40.25T
Parts/Materials	C57 Spark Plugs	4	8.50	34.00T
Parts/Materials	SKF Oil Seal 13527	1	24.01	24.01T
Freight - Out	Return fuel pump	1	8.064	8.06T
Dismount	Tire Dismount	4	7.50	30.00T
Mount & Balan	Tire Mount and Balance	4	27.00	108.00T
Tire Disposal	Tire Disposal	4	5.00	20.00T
Labor - Eric	03/31 Helped prime motor and start. Test drove car.	2	80.00	160.00T
Labor - Evan	4/2/08 -Cut pieces of foam and glued to underside of front fenders. Cleaned interior and exterior of car.	1.5	80.00	120.00T
Shop Supplies	Shop Supplies Sales Tax		8.40 8.80%	8.40T 169.79
	•		Total	\$2,099.26

DATE INVOICE #

4/1/2008 26335

BILLING PERIOD

061041200B

BILL TO	go.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Brake, Caliper	Girling Caliper Seal 1.33	4	4.20	16.80T
Freight-In	Differential	1	16.562	16.56T
Parts/Materials	Salisbury Differential 026R1000	1	2,152.92	2,152.92T
Parts/Materials	Diff Bearings-Cones 036R 6024	2	30.772	61.54T
Freight-In	Gears	1	38.052	38.05T
Parts/Materials	17T Input Gear 22E9Z209	1	604.80	604.80T
Parts/Materials	19T 3rd Gear 22E9Z308	1	354.06	354.06T
Parts/Materials	Drive Disc 4-Dog 22E9Z411	1	361.62	361.62T
Outside Service	Repair Chips Left Rear Quarter Panel	1	53.20	53.20T
Parts/Materials	Exhaust Gasket	4	2.016	8.06T
Lubricant, Mot	Mobil One Race Oil	6	8.26	49.56T
Filter, B253	Baldwin Oil Filter	1	19.80	19.80T
Nut, Jet 1/4	1/4"	4	2.50	10.00T
Washer, AN Th	1/4" AN Thick Washer	4	0.15	0.60T
	2.00" Girling Seal	4	9.8924	39.57T
Nut, Jet 3/8	3/8" Jet Nuts	10	1.86	18.60T
Nut, Jet 5/16	5/16" K-Nuts (Jet Nuts)	4	3.17	12.68T
Tie, Self-Locki	Zip Tie, 13.38"	1	0.98	0.98T
Lubricant, Gea	Mobile One 75w 90 Gear Oil	2	9.95	19.90T
Brake, Fluid M	Motul RBF600	1	20.27312	20.27T
Race Fuel	Race Fuel	3	9.29	27.87T
Nut, Jet 5/16	5/16" K-Nuts (Jet Nuts)	8	3.17	25.36T
Washer, AN Th	AN 5/16" Thick	8	0.28	2.24T
Labor - Dennis	03-18 Help remove transmission, open cover and do preliminary inspection	1.5	80.00	120.00T
Labor - Eric	03/18 helped remove rear end and trans.	1	80.00	80.00T
Labor - Evan	3/19/08 -Disconnected half shafts from diff. Removed rear diff from car.	2.5	80.00	200.00T
Labor - Dennis	03-19 Dismantle rear end and inspect	3.5	80.00	280.00T

Total


DATE INVOICE #

4/1/2008 26335

BILLING PERIOD

061041200B

		P.O. No.	TERMS	PROJECT
				Lotus 26R
Item	Description	Quantity	Rate	Amount
Labor - Santos	3/20/8 I load the car in the trailer and I tight it down and I take it to get paint at Seattle.	2	50.00	100.00T
Labor - Dennis	03-20 Order diff parts; start dismantle of gearbox; make dummy layshaft tool	4.5	80.00	360.00T
Labor - Dennis	03-21 Finish dismantling gearbox; order new parts; relieve area around selector rod; clean parts; prep for reassembly	6.5	80.00	520.00T
Labor - Dennis	03-24 Dismantle new diff, verify ramps, lubricate clutch pack; mount ring gear; wash out case and housing; deburr case and housing; set up and check pattern	5.5	80.00	440.00T
Labor - Dennis	03-25 Start reassembly of transmission; make new retainer(split) collar	2.5	80.00	200.00T
Labor - Dennis	03-26 Finish build of transmission; fit bellhousing and clutch throw-out assembly	5	80.00	400.00T
Labor - Santos	3/26/8 I went to pick up the Lotus 26R at Seattle.	2	50.00	100.00T
Labor - Evan	3/26/08 -Removed brake calipers from car. Disassembled brake calipers. Looking for possible pulling problem.	2	80.00	160.00T
Labor - Evan	3/27/08 -Sand blasted front brake calipers. Cleaned brake calipers and pistons. Installed new seals and re-assembled brake calipers. Installed calipers on car. Installed gear shifter and hooked up transmission breather.		80.00	320.00T
Labor - Brett L.	3-27-08 In stall engine, gearbox, put drive line in place.	5.5	80.00	440.00T
	•		Total	<u> </u>



P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Brett L.	3-28-08 Install diff. attach half shafts and driveline. Fill gearbox and engine with oil. Hook up all oil and electrical lines. Begin Race Prep, Nut and Bolt car. Bleed brakes and clutch.	8	80.00	640.00T
Labor - Evan	3/31/08 -Installed header, collector/tail pipe, and muffler. Installed radiator hoses. Filled engine with water. Checked engine compression and leak down. Installed ground strap. Cranked engine for oil pressure. Ran engine and checked fluids.	8	80.00	640.00T
Shop Supplies	Shop Supplies Sales Tax	1	150.00 8.80%	150.00T 797.72
			Total	\$9,862.76

DATE	INVOICE #	
3/15/2008	26252	
BILLING PERIOD		

	6105120
BILL TO	02,

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Santos	3/4/8 I cleaned the inside of the car, cleaned around the motor, cleaned inside the trunk, cleaned the windows inside and outside, cleaned the wheels, cleaned the body work, covered the car.	2.25	50.00	112.50T
Labor - Dennis	03-06 Collect spares	0.25	80.00	20.00T
Labor - Evan W.	3/10 Took off old numbers and put on new.	1	80.00	80.00T
Labor - Evan W.	3/11 Removed white lettering from second set of tires on rack for Laguna Seca	0.5	80.00	40.00T
Shop Supplies	Shop Supplies	1	7.58	7.58T
1 11	Sales Tax		8.80%	22.89
	•		Total	\$282.97

 DATE
 INVOICE #

 3/1/2008
 26215

 BILLING PERIOD

	1201	200B
BILL TO	0.54	

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Tires	4	8.708	34.83T
Parts/Materials	Avon 6.5/23-13 A30 Compound	4	282.50	1,130.00T
Outside Service	Dyno & Calibrate Carbs	1	810.50	810.50T
Parts/Materials	O2 bung for 02 sensor	1	7.77	7.77T
Parts/Materials	Plug	1	7.742	7.74T
Labor - Brett L.	2-22-08 Chassis set-up. Weight Balance, Alignment. Remove exhaust tip, build new tabs to mount muffler, mount muffler.	6.5	80.00	520.00T
Labor - Evan	2/28/08 -Removed exhaust system from car. Drilled hole in collector and welded in O2 bung. Re-installed exhaust system on car.	1.5	80.00	120.00T
Labor - Brian R.	02/29 Load and take Lotus to chassis dyno. Work on carburetors. Clean up flat spot (too rich) 4000-6500rpm's. Major changes on jetting. Gain of 20% in torque/Hp in that range when done.	7	80.00	560.00T
Labor - Evan W.	2/29 Removed white Avon lettering from sidewalls of 2 sets Lotus 26R tires.	1	80.00	80.00T
Shop Supplies	Shop Supplies	1	38.40	38.40T
	Sales Tax		8.80%	291.21
	<u> </u>		Total	\$3,600.45

DATE INVOICE #

2/15/2008 26148

BILLING PERIOD

	212012008
BILL TO	0.54

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Tire Disposal	Tire Disposal	10	5.00	50.00T
	Sales Tax		8.80%	4.40
		,	Total	\$54.40
			I Utal	ψ54.40

DATE	INVOICE #		
2/1/2008	26079		
BILLING PERIOD			

210312008
0.5

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Tire Disposal	Tire Disposal	10	5.00	50.00T
Race Fuel	Race Fuel	4	9.29	37.16T
Labor - Brett L.	1-31-08 Start car and check timing, check for leaks, pressure check cooling system, fill with fuel. Complete remaining items on Race Prep.	2	80.00	160.00T
	Sales Tax		8.80%	21.75
		,	Total	\$268.91

 DATE
 INVOICE #

 11/15/2007
 25897

 BILLING PERIOD

1212612007

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	3/8 Pipe Lever Petcock	1	17.40	17.40T
Filter, B253	Baldwin Oil Filter	1	19.80	19.80T
Lubricant, Mot	Mobil One Race Oil	6	8.26	49.56T
Brake Clean	Brake Clean	2	6.39	12.78T
Brake, Fluid M	Motul RBF600	1	18.58	18.58T
Battery, Enersy	Battery, SBS 15	1	339.15	339.15T
Dismount	Tire Dismount	4	7.50	30.00T
Mount & Balan	Tire Mount and Balance	4	20.00	80.00T
Tire Disposal	Tire Disposal	4	5.00	20.00T
Labor - Brett L.	10-26-07 Begin Race Prep of car. Compression test, leak down test.	5.5	80.00	440.00T
Labor - Brett L.	10-29-07 Finish Race Prep of car. Oil/Filter change, cut open filter and inspect, nut and bolt entire car.	8	80.00	640.00T
Labor - Santos	10/30/7 cleaned around the motor and inside detail inside.	2.5	50.00	125.00T
Labor - Brett L.	10-30-07 Install new lever type petcock in overflow tank on oil side. Reinstall tanks back in car.	0.5	80.00	40.00T
Labor - Santos	10/31/7 I cleaned in the trunk, cleaned under the finder, cleaned disk, cleaned under the car, cleaned the body work, cleaned the windows the inside and the outside.	2	50.00	100.00T
Labor - Brett L.	11-1-07 Install new battery. Bleed brakes, clean bleeders.	1.5	80.00	120.00T
Labor - Santos	11/8/7 I pushed the car to the inside the back storage.	0.25	50.00	12.50T
Shop Supplies	Shop Supplies	1	40.73	40.73T
	Sales Tax		8.80%	185.28
			Total	\$2,290.78

DATE	INVOICE #	
10/15/2007	25863	
BILLING PERIOD		

	012612007
SILL TO	1.5

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
	Coronado - 26R			
Trackside Perd	Perdiem	3.5	35.00	122.50
Trackside Air T	Air Travel	1	430.80	430.80
Trackside Lodg	Hotel	3	130.25	390.75
Trackside Rent	Rental Car	1	146.96	146.96
	Sub-Total - Reimb exp - no tax			1,091.01
	•			
Trackside Tran	Transportation of Vehicle, Parts, etc.	1	1,950.00	1,950.00T
Fuel Sur Charge	Fuel Sur Charge	1	216.50	216.50T
Trackside Load	Load/Unload Trailer	3	50.00	150.00T
Trackside Supp	Trackside Support Services (Per Day)	3.5	525.00	1,837.50T
Race Fuel	Race Fuel	9	9.29	83.61T
Lubricant, Mot	Mobil One Race Oil	1	8.26	8.26T
	Sales Tax		8.80%	373.64
		,	Total	\$5,710.52

DATE	INVOICE #
10/15/2007	25848
BILLING	PERIOD

	212612007
BILL TO	12.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Mounting Block	1	6.734	6.73T
Parts/Materials	Starter Mounting Block 54-530	I	148.75	148.75T
	Sales Tax		8.80%	13.68
		,	Total	\$169.16
			Total	φ109.10


 DATE
 INVOICE #

 10/1/2007
 25815

 BILLING PERIOD

1012912007

		P.O. No.	TERMS	PROJECT
				Lotus 26R
Item	Description	Quantity	Rate	Amount
Lubricant, Mot	Mobil One Race Oil	6	8.26	49.56T
Filter, B253	Baldwin Oil Filter	1	19.80	19.80T
Electrical Ter	Terminal Ring 3/8 Stud 12-10 Ga	1	0.1876	0.19T
Brake Clean	Brake Clean	5	6.39	31.95T
Race Fuel	Race Fuel	3	9.29	27.87T
Brake Line, 1/4	1/4" Bundy Flex (per foot)	2	2.95	5.90T
Cap, Aluminu	Aluminum Cap -4	1	0.48	0.48T
Parts/Materials	-4 male fitting	1	3.50	3.50T
Parts/Materials	throttle cable	2	4.20	8.40T
Parts/Materials	Outer throttle cable casing	4	4.20	16.80T
Labor - Brett L.	8-17-07 Begin Pre Race Check List. Leak Down, Compression Test of engine. Change oil/filter. Repair hood pin lanyard, adjust passenger door, fix petcock on breather bottle.	8	80.00	640.00T
Labor - Brett L.	9-18-07 Complete Pre Race Check List. Change oil and filter.	2.5	80.00	200.00T
Labor - Brett L.	9-19-07 Retighten all drive shaft bolts. Remove carbs, remove throttle cable and begin to build new cable.	6.5	80.00	520.00T
Labor - Dan	09/20 Help Brett lay out and fab. engine dipstick and tube.	1	80.00	80.00T
Labor - Brett L.	9-20-07 Design new fitting for throttle cable. Finish and install new throttle cable. Fab new dipstick tube for engine so oil level can be checked when hot. Install dipstick tube.	6.5	80.00	520.00T
Labor - Brett L.	9-26-07 Inventory spare parts box, make list of parts.	1.5	80.00	120.00T
Labor - Brett L.	9-27-07 Swap wheel, paint rotors, safety wire wheels.	1	80.00	80.00T
Labor - Dan	09/28 Clean and grind out crack in starter snout and weld up.	0.25	80.00	20.00T
			Total	



P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Jeff	9/28/2007 cleaned car	3.5	50.00	175.00T
Shop Supplies	Shop Supplies	1	68.40	68.40T
	Sales Tax		8.80%	227.73
			Total	\$2,815.58

 DATE
 INVOICE #

 9/15/2007
 25711

 BILLING PERIOD


1012912007

BILL TO

P.O. No.	TERMS	PROJECT
		Lotus 26R
Quantity	Rate	Amount

Item	Description	Quantity	Rate	Amount
Freight - Out	Weber float	1	7.042	7.04T
Labor - Santos	8/28/7 I load the car inside the 24ft trailer and I tight it down and I take it to BYERS.	2	50.00	100.00T
Credit	Credit	2	-50.00	-100.00T
Labor - Evan	8/31/07 -Cleaned up engine compartment. Washed out all oil lines and oil cooler. Installed intake scoop on car. Installed oil filter mount and oil cooler.	2	80.00	160.00T
Labor - Santos	8/31/7 I went to pick up the car and I load it and tight it down and I take to the shop and unload the car and I push it in the shop.	I	50.00	50.00T
Credit	Credit	1	-50.00	-50.00T
Shop Supplies	Shop Supplies	1	9.30	9.30T
Freight-In	Motor In for Lotus	1	791.60	791.60T
Freight-In	Brake Pads	1	18.186	18.19T
Outside Service	Fiberglass Repair & Paint under side of nose	1	947.10	947.10T
Credit	Credit	1	-947.10	-947.10T
Parts/Materials	Spark Plugs C 59	8	6.85	54.80T
Parts/Materials	Spark Plugs C 57	8	6.85	54.80T
Parts/Materials	GD 524 Raybestos ST-43 (2 Axle Set)	2	138.60	277.20T
Parts/Materials	Seal, 13527	2	16.24	<i>32.48T</i>
Filter, B253	Baldwin Oil Filter	1	19.80	19.80T
Lubricant, Mot	Mobil One Race Oil	7	8.26	57.82T
Washer, Lockw	3/8" Lock Washer	6	0.21	1.26T
Nut, Nyloc 3/8"	3/8"-24 Nyloc Nut	4	1.35	5.40T
Washer, AN 3/	3/8" AN Washers	4	0.15	0.60T
Radiator, Wate	Water Wetter	1	15.00	15.00T
Brake, Pad GD	Porterfield GD 504	1	198.863	198.86T
Brake, Fluid M	Motul RBF600	1	18.58	18.58T
		Т	T	

Total



		P.O. No.	TERMS	PROJECT
				Lotus 26R
Item	Description	Quantity	Rate	Amount
Labor - Evan	9/4/07 -Installed engine in car. Re-greased throw out bearing. Hooked up oil lines. Hooked up electrical wires. Installed starter. Installed header. Installed over flow tanks.	8	80.00	640.00T
Labor - Dan	09/04 Help Evan with engine installation.	2.5	80.00	200.00T
Labor - Evan	9/5/07 -Installed air box. filled engine with oil and water. Ran engine and checked over. Removed rear end center section. Fit new rear end center section.	9	80.00	720.00T
Labor - Mark	9/5/07 Work on race prep, nut & bolt, pack LF wheel bearings, machine retainer washers to allow wheel bearing adjustment.	6	80.00	480.00T
Labor - Dennis	09-06 Install new throttle cable; finish assembly details; test drive	2.5	80.00	200.00T
Labor - Louie	9/05 Finish rearend install, replace transmission tail shaft seal, bleed brakes, de-glaze pads (rear) install new front pads, pack RF wheel bearings	4	80.00	320.00T
Machine - Louie	Machine retainer washers for front wheel bearing adjustment	1	92.00	92.00T
Shop Supplies	Shop Supplies	1	81.60	81.60T
	Sales Tax		8.80%	392.16
			Total	\$4,848.49

DATE	INVOICE #
8/15/2007	25660
BILLING	PERIOD

	0171200
BILL TO	0.5.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Evan	8/6/07 -Removed engine for rebuild. Removed oil cooler, oil filter adaptor, and intake scoop, clean engine bay, lines, cooler etc	6.5	80.00	520.00T
Labor - Mark	08/06 Worked with Evan on engine remove	3.5	80.00	280.00T
Labor - Santos	8/14/7 cleaned inside the car, cleaned the body work, cleaned the windows, cleaned the wheels.	2	50.00	100.00T
Shop Supplies	Shop Supplies	1	13.80	13.80T
	Sales Tax		8.80%	80.41
		,	Total	\$994.21

DATE	INVOICE #	
8/1/2007	25607	
BILLING PERIOD		

	0117120	
BILL TO	0.5.	

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Freight-In	Seal	1	12.516	12.52T
Parts/Materials	Diff Seal	2	13.006	26.01T
Outside Service	Mount & Balance	4	28.00	112.00T
Outside Service	Disposal, Tire	2	5.00	10.00T
Parts/Materials	Avon Racing Tires 6.5/23.0-13	12	268.75	3,225.00T
Parts/Materials	Avon Racing Tires 6.5/23.0-13 Mount	10	28.00	280.00T
Balance Only	Tire Balance Only	4	10.00	40.00T
,	Sales Tax		8.80%	326.09
			Total	\$4,031.62

DA	ГЕ	INVOICE #
7/15/2	2007	25565
BILLING PERIOD		

	011712001
BILL TO	0.2.

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	Spark Plugs (C-57) 686	12	8.50	102.00T
Parts/Materials	Petcock 3/8	2	11.186	22.37T
Labor - Dennis	07-04 Build cross bracket for 4.4 rear end	1	80.00	80.00T
Labor - Eric	07/04 Started race prep, changed motor oil, filter, inspected old filter, changed spark plugs, checked all fluids, fueled car, started rear end reassembly.	8	80.00	640.00T
Labor - Dennis	07-05 Test drive car	0.25	80.00	20.00T
Labor - Eric	07/05 Finished installing rear end and half shafts bolt checked chassis, installed tires and wheels, charged batt.	6.5	80.00	520.00T
Labor - Mike L.	7/5/7 Install valves on catch tanks.	2	80.00	160.00T
Labor - Santos	7/10/7 went to pick up the car at Malone office and take the car to storage.	4	50.00	200.00T
Shop Supplies	Shop Supplies	1	48.60	48.60T
	Sales Tax		8.80%	157.78
		,	Total	\$1,950.75

	DATE	INVOICE #	
	7/1/2007	25513	
F	BILLING PERIOD		

	011712	
BILL TO	Ga.	

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Outside Service	Repair & Paint Bumpers, Air Scoop	1	723.04	723.04T
Labor - Santos	6/25/7 went to pick up the 29R and load it in the	3	40.00	120.00T
	24ft trailer and I tight it down and take to the			
	shop.			
Shop Supplies	Shop Supplies	1	3.60	3.60T
	Sales Tax		8.80%	74.50
			Total	en21.14
			Total	\$921.14

DATE	INVOICE #			
6/15/2007	25457			
BILLING PERIOD				

	712612007
BILL TO	01

P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Parts/Materials	LM29749	2	14.756	29.51T
Parts/Materials	62062RS	2	14.042	28.08T
Lubricant, Gea	Mobile One 75w 90 Gear Oil	1	9.95	9.95T
Parts/Materials	7/16 Short time sert	1	1.946	1.95T
Labor - Eric	06/05 Removed right side tail lights and rear	1	73.00	73.00T
	bumper.			
Labor - Dennis	06-05 Build 4.4 rear end	8.5	73.00	620.50T
Labor - Dennis	06-04 Finish 4.4 rearend	2	73.00	146.00T
Shop Supplies	Shop Supplies	1	25.19	25.19T
Labor Credit	Labor Credit 4.4 Rearend	10.5	-73.00	-766.50T
	Sales Tax		8.80%	14.76
			Total	\$182.44


 DATE
 INVOICE #

 5/15/2007
 25356

 BILLING PERIOD

0612112007

		P.O. No.	TERMS	PROJECT
				Lotus 26R
Item	Description	Quantity	Rate	Amount
Parts/Materials	1/2 BSP Plug For Gear Box	1	6.048	6.05T
Freight-In	Ring & Pinion	1	155.246	155.25T
Parts/Materials	4.4 Ring & Pinion	1	837.20	837.20T
Freight-In	Seals	I	13.146	13.15T
Parts/Materials	026R 6017 Pinion Seal	1	26.586	26.59T
Parts/Materials	036R 6007 Seal	2	13.006	26.01T
Spark Plug, 68	Champion 686	4	8.50	34.00T
Lubricant, Mot	Mobil One Race Oil	6	8.26	49.56T
Gauge, Hourm	Hourmeter, Mini 10-80v	1	77.58	77.58T
Labor - Dennis	05-02 Install axles in 4.9 rear end; spotface case for crossbrace; order 4.44 ring and pinion; discuss setup with supplier	3	73.00	219.00T
Labor - Brett	05-02 Finished cleaning block and installed oil pan. Mated trans to motor and installed starter, anti-sway bar and cross member. Pulled mountingbracket for starter off and fixed crack in flange.	7	73.00	511.00T
Labor - Dennis	05-07 Follow up on 4.4 R&P	0.5	73.00	36.50T
Labor - Rob	05/08/07 finalize engine service. fill with oil. install spark plugs and spark plug wires. Make bracket and wiring for hour meter. install hour meter. dismount rear tires and mount and balance new rubber on the rears. install center console. remove muffler-resonator assembly and install glass pack muffler.	8	73.00	584.00T
Labor - Dennis	05-08 Reassemble 4.11 rear end; start calling alternate sources for 4.44	1	73.00	73.00T
Labor - Rob	5/9/07 install rear end in the 26R. Test drive and button up the car.	4	73.00	292.00T
			Total	



P.O. No.	TERMS	PROJECT
		Lotus 26R

Item	Description	Quantity	Rate	Amount
Labor - Dennis	05-09 Help install rear end	0.25	73.00	18.25T
Labor - Rob	5/10/07	4	73.00	292.00T
	perform run-ability tuning with Brian. Tune carbs			
	and timing.			
Labor - Rogelio	05/10/07	1.75	40.00	70.00T
	i cleaned the inside the outside and the wheels			
Labor - Brian R.	05/10 Work with Rob on tuning carbs and test	2	73.00	146.00T
	drive to reduce the flat spot in RPM range.			
Labor - Dennis	05-14 Remove rear end to convert to 4.4 R&P	5	73.00	365.00T
	dismantle and make list of bearings and seals for			
	conversion and place order; look into alternate			
	ratios for Leeson gearbox			
Shop Supplies	Shop Supplies	1	78.21	78.21T
	Sales Tax		8.80%	344.11
		<u> </u>	L	
			Total	\$4,254.46

DATE	INVOICE #		
5/1/2007	25321		
BILLING PERIOD			

0513112007

P.O. No.	TERMS	PROJECT
		Lotus 26R
Quantity	Rate	Amount
Ĭ.	38.57	38.57T

Item	Description	Quantity	Rate	Amount
Freight-In	Rear End Parts	1	38.57	38.57T
Parts/Materials	Rear End Parts, complete parts for 4.9 ratio rear	1	5,742.67	5,742.67T
	end. Mag rear cover, alum main case,			
	Differential, ring and pinion, stub axles, bearings,			
	pinion yoke, etc			
Freight-In	Diff Shaft	1	13.58	13.58T
Parts/Materials	Diff O/P Shaft, 4-Bolt	1	538.006	538.01T
Labor - Dennis	04-16 Open and inspect 4.12 rear end; reseal and add oil	3	73.00	219.00T
Labor - Brett	04 20 Split bellhousing from block and removed	8	73.00	584.00T
	oil pan. pulled rod and main bearings and			
	inspected. reassembled and checked end play.			
Labor - Dennis	04-24 Inspect rear end parts; make set up	3	73.00	219.00T
	bearings; prep ring and pinion; mount ring gear			
	on diff; check case for areas to be clearance			
Labor - Dennis	04-25 Start build of 4.9 rear end; clearance	5	73.00	365.00T
	cover and case for ring gear, bolts and bearing			
	cap bolts			
Labor - Dennis	04-26 Continue rear end build; check ring gear	1.5	73.00	109.50T
	pattern			
Labor - Dennis	04-27 Make rear end stand; install pinion	5.5	73.00	401.50T
	bearings; set backlash; set pinion preload; set diff			
	bearing preload; install pinion flange; assemble			
	available stub axle and bearing; install rear			
	cover studs			
Labor - Brett	04-27 Cleaned block and pan surfaces and end	3.5	73.00	255.50T
	rail gaskets.			• • • • • • •
Labor - Dennis	04-30 Mate third member to case; remove and	3.5	73.00	255.50T
G1 G 1:	relievering gear area of case; reassmemble	,	72.27	50.05T
Shop Supplies	Shop Supplies	1	72.27	72.27T
	Sales Tax		8.80%	775.64
	•			
			Total	\$9,589.74

INVOICE #		
25286		
BILLING PERIOD		

	\$ 1012007
BILL TO	0.5.

P.O. No.	No. TERMS	PROJECT	
		Lotus 26R	

Item	Description	Quantity	Rate	Amount
Filter, B253	Baldwin Oil Filter	1	19.80	19.80T
Brake Clean	Brake Clean	3	6.39	19.17T
Race Fuel	Race Fuel	2	8.90	17.80T
Labor - Rob	3/21/07	0.75	73.00	54.75T
	help with setup inspection and driveability testing			
	of Lotus 26R.			
Labor - Rogelio	04/02/07	2.5	40.00	100.00T
	i cleaned the inside, windows body, cover for			
	headlights, trunk and cleaned the engine		40.00	
Labor - Rogelio	04/03/07	2.25	40.00	90.00T
T 1 D 1	i cleaned the car engine/body/trunk/inside	11.5	72.00	020 507
Labor - Rob	4/11/07	11.5	73.00	839.50T
	Race Prep on the 26R. engine analysis, chassis			
	inspection and nut and bolt. inspect, scuff and bleed brakes. begin removing rearend.			
Labor - Rob	4/12/07	2	73.00	146.00T
Lucor - Roo	remove rear end assembly from the 26R.	2	75.00	140.001
Labor - Dennis	04-12 Discuss rearend and transmission ratios	1	73.00	73.00T
	with Mike; Call Dave Vegher and discuss same;	-	, 2.00	, 2.001
	call Dave Bean			
Shop Supplies	Shop Supplies	1	31.44	31.44T
1 11	Sales Tax		8.80%	122.45
			Total	\$1,513.91
			i otai	$\varphi_1, J_1J_1J_1$

DATE	INVOICE #		
4/1/2007	25250		
BILLING PERIOD			

	611412007
BILL TO	Q.o.

P.O. No.	No. TERMS	PROJECT	
		Lotus 26R	

Item	Description	Quantity	Rate	Amount
Freight-In	Freight In, Tires	4	15.00	60.00T
Parts/Materials	Hoosier, P205/60D-13	4	185.00	740.00T
Labor - Rob	3/19/07	1	73.00	73.00T
	check front suspension for looseness. fix wheel bearing preload.			
Labor - Rob	3/20/07 remove straight pipe and install muffler. run and warm up, test transmission and clutch. inspect and clean. ready for the track.	3	73.00	219.00T
Labor - Dennis	03-21 Test drive	0.5	73.00	36.50T
Labor - Eric	0.3/21 Corner balance car for Infineon and check alignment	2.5	73.00	182.50T
Shop Supplies	Shop Supplies	1	15.33	15.33T
	Sales Tax		8.80%	116.72
	1	<u> </u>	Total	\$1,443.05