DENNISONINTERNATIONAL

MOTORSPORTS DIVISION

Quality that GOES!

mom can the

INVOICE

Qty	Description	Unit Price	TOTAL
400			14 1
2	pts Castrol brake fluid	\$ 3.95	7147
4	qts Mobile One 15W50	\$ 6.99	\$ 27,96
	set rear brake pads for track box	\$ 130.57	\$ 130.57
	Starter Solenoid	\$ 90.41	\$ 90.41
0	Battery AV7290M tires	\$ 38.94	ARE ASSAULTED TO THE PROPERTY OF THE PARTY O
0		\$ 259.21	A STANDARD BY THE PARTY OF THE
	Special wrench for half shaft	\$ 26.08	\$ 26.08
		1 57	一点,那种种
1			25 W. W.
496		种型影響	
19.35	Labor hours - see attached	\$ 74.50	\$ 1,441.58
1	misc shop supplies	\$ 64.87	MODEL: UKSTATA - TRANSPORTATION AND AND AND AND AND AND AND AND AND AN
Manager Street			
- AND	THE RESIDENCE OF THE PARTY OF T	1 1 1	
2. Bulleton.	THE STATE OF THE PARTY OF THE P	118	
198	人,这是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个		
		111	
使用的工具不 是	国际发展的 全国经济发展的经济发展的 网络拉拉斯 经现代证 "我们是我们是一个人的。"	SubTotal	\$ 3,901.99
4323000		8.1.1	
Remit To:	Sales Tax	8.80%	\$ 343.37
""一大流。 在2	Dennison International Motorsports		1 113 4
光 原	11203 Benston Dr E #500	TOTAL	0 4045 00
	日本の表現した。1917年1月1日 - 1918年 -	TOTAL	\$ 4,245.36
land the second second	Puyallup, WA 98372		
Terms:			· 子·等
Terms.	BENEFIC TO THE FOR THE SECOND SECTION OF THE SECOND	PROPERTY.	
	Due Upon Receipt		

April 2006

DATE	MECHANIC	PROJECT	OWNER	WORK DESCRIPTION	HRS	RATE	TOTAL
4/12/06	Yamamoto, Pete	L-26R		Put car on stands. Clean and inspect rear suspension. Nut and bolt drive shaft, half shafts, and rear suspension.	1.50	\$74.50	\$111.75
4/13/06	Yamamoto, Pete	L-26R		Deglaze brake pads and rotors. Install new rear pads. Flush and bleed brake system. Change fluid in clutch reservoir. Nut and bolt front suspension and fasteners on engine and oil pump. Drain catch tanks. Prepare new battery for installation.	5.60	\$74.50	\$417.20
4/14/06	Yamamoto, Pete	L-26R		Clean wheels and tires. Mount on car, Clean residue from lower half of body. Put car on ground. Drill new drain hole for catch tank overflow line. Check fluid levels. Add 1 qt Mobil 1. Roll car out to start engine. Starter keeps running with no starter button. Trouble shoot system. Remove starter and bench test. Solenoid is defective. Needs to be replaced. Order new solenoid. Remove 2 stage muffler. Install straight pipe for Reno.	5.60	\$74.50	\$417.20
4/15/06	Yamamoto, Pete	L-26R		Tear down and inspect starter for damage. Reassemble and test. Finish repair on spare starter flange. Do leak down test on engine. Add oil to bring to full mark.	3.85	\$74.50	\$286.83
4/18/06	Yamamoto, Pete	L-26R		Install starter in car. Warm up engine and check for leaks. Test drive car around parking lot. Organize and pack race box. Get spare wheels and tires and mufflers out to go to race.	2.45	\$74.50	\$182.53
4/19/06	Yamamoto, Pete	L-26R		Help load car and spares.	0.35	\$74.50	\$26.08

\$1,441.58 \$1,441.58 TOTALS 19.35

INTERNATIONA MOTORSPORTS DIVISI

Quality that GOES!

INVOICE

Customer Invoice # L26R - L018 Name Date 3/31/06 Address Project Lotus 26R City Phone

Qty	Description	U	nit Price		TOTAL
1	Oil filter	\$	16.55	s	16.55
1	1/2" x 3/4" copper washer	\$	0.65	S	0.65
7	qt Mobile 1 15/50	\$	6.99	S	48.93
1 2	qt Valvoline gear oil	\$	3.95	S	3.9
	pt Castrol LMA brake fluid	\$	4.25	S	8.5
1	can Brake kleen	\$	3.99	\$	3.99
12.65	Labor hours - see attached	\$	74.50	\$	942.4
1	misc shop supplies	\$	42.41	\$	42.4
	Approval Company to Pay Acct#		- - -		
	Class			8	
	Class		SubTotal	\$	1,067.4
mit To:		Sales Tax	SubTotal 8.80%	\$	1,067.4 93.9

Puyallup, WA 98372

Due Upon Receipt

Terms:

March 2006

DATE	MECHANIC	PROJECT	OWNER	WORK DESCRIPTION	HRS	DATE	TOTAL
3/10/06	Pete	L26R		Put car on stands. Remove and charge battery. Bring out all wheels and tires and race box. Remove wheel assemblies from car. Change over from Avon to Hoosier tires on one set of wheels.		RATE	TOTAL
3/16/06	Pete	L26R		Change oil and filter. Wipe down engine compartment. Clean and	2.63	\$74.50	\$195.56
3/20/06	Data	1000	<u> </u>	inspect suspension.	2.25	\$74.50	\$167.63
ř	Pete	L26R		Nut and bolt suspension and drive train. Tighten half shaft and drive shaft fasteners. Wipe down suspension and under side of car. Refill and safety wire diff. Deglaze brake pads and rotors. Flush and replace brake fluid and bleed system. Install and safety wire wheels. Drive test and check clutch, brakes, and transmission for correct operation. Finish race prep on car. Speed shine body. Clean windshield.		674.50	
3/21/06	mark	L26R	_	bleed brakes clean tires, balance	6.00	\$74.50	\$447.00
3/21/06	Pete	L26R			1.40	\$74.50	\$104.30
	, 0.0	LEUIT		Help BC load car and go over maintenance procedures.	0.38	\$74.50	\$27.94
				TOTALS	12.65		\$942.43

\$942.43 \$942.43



DENNISON INTERNATIONAL

MOTORSPORTS DIVISION

Quality that GOES!

INVOICE

Customer	Invoice #	L26R - L014
Name	Date	8/1/05
Address	Project	Lotus 26R
City		
Phone		
	U-W D-L-	TOTAL

Qty	Description	Ur	nit Price		TOTAL
1	trip permit	\$	20.00	\$	20.00
6	gts Mobil 1 15-50	\$	6.99	\$	41.94
2	pts Castrol brake fluid	\$	3.95	\$	7.90
1	Oil filter	\$	16.91	\$	16.91
1	GD 524 racing brake pads*	\$	113.71	\$	125.60
1	Mag bell housing*	\$	543.68	\$	554.50
1	Alum rad 26r 12x22 10#	\$	445.94	\$	456.76
1	Eng Mount, elan, weber, R/H*	\$	28.59	\$	36.39
1	Ignition Module*	\$	436.25	\$	439.98
1	Distributor Gear*	\$	58.90	\$	62.63
1	Battery	\$	46.96	\$	46.96
11.5	Hours labor - see attached	\$	67.50	\$	776.25
1	Misc shop supplies Approval	S	34.93	\$	34.93
	Company to Pay Acct# Class	(≈)		0	
reight cha	rges are included in item totals		SubTotal	\$	2,620.75
emit To:	Sales Tax		8.80%	\$	230.63
	Dennisen International Meteroparts			1	
	Dennison International Motorsports PO Box 842		TOTAL	\$	2,851.38

Terms:

Due Upon Receipt

DENNISON INTERNATIONAL

MOTORSPORTS DIVISION

Invoice #

Quality that GOES!

Customer

INVOICE

L26R - R012

lame Address			Date Project	7/15/05 Lotus 26	R
ity hone				SOVRE	V
Qty	Description		Unit Price	To	OTAL
1 4 17	mileage to Kent, WA (includes fuel surcharge) days Mechanic Race Gas		\$300.00 \$400.00 \$4.50	\$	300.00 f 1,600.00 76,50
	Posma	Approval Company to P	ay	3-	
lote: Charges	s above are reimbursement of exact expenses		SubTotal	\$	1,976.50
temit To:		Sales Tax	8.80%	\$	173.93
	Dennison International Motorsports PO Box 842 Sumner WA 98390		TOTAL	\$	2,150.43
erms:	Due Upon Receipt				

DENNISONINTERNATIONAL

MOTORSPORTS DIVISION

Invoice #

Quality that GOES!

Customer

Terms:

Due Upon Receipt

INVOICE

L26R - L013

We Appreciate Your

Business!

ime			ate roject	7/1/05 Lotus 2	6R)
idress			4		
ity hone					
none		A)			
Qty	Description		Unit Price		TOTAL
6	gts Mobile One 15-50	9	6.99	\$	41.94
1	Napa 13 - 12 oz	5	3.99	\$	3.99
4	7/16 NF nylocks		0.70	\$	2.80
1	Barsleak		3.49	S	3.49
8	3/8 NF nylocks	5	0.65	\$	5.20
10	5/16 NF nylocks	5	0.45	\$	4.50
12	3/8 jet nuts	5	0.75	\$	9.00
12	5/16 jet nuts		0.45	\$	5.40
1	5/16 x 1 NC allen bolt		6.99 6.3.99 6.0.70 7.0.65 7.0.65 7.0.65 7.0.45 7.0.45 7.0.45 7.0.45 7.0.50	\$	0.45
1	3/8 x 3/4 Gr 5 bolt	:	0.50	\$	0.50
4	3/8 flat washers		0.10	\$	0.40
16	3/8 AN washers		0.20	\$	3.20
12	5/16 AN washers		\$ 0.15	\$	1.80
1	4 spd gasket set		\$ 5.75	\$	5.75
1	3rd gear 23T		\$ 149.00	\$	149.00
1	layshaft		\$ 549.00	\$	549.00
1	2nd gear 21T	A	\$ 149.00	\$	149.00
1	4th gear 25T	12000	\$ 159.00	S	159.00
1	1st gear 2.04		\$ 209.00	\$	209.00
1	2nd gear 22T		\$ 199.00	\$	199.00
1	3rd gear 1.21		\$ 279.00	\$	279.00
1	drive disc, 4 dog		\$ 409.00	\$	409.00
1	7" input shaft		\$ 369.00	\$	369.00
1	drive dies 3.1		\$ 269.00	\$	269.00
1	shipping on gear parts Approval	and the latest devices the lates	\$ 31.87 \$ 13.29	\$	31.87
a 1	rear trans seal Company 10	- Committee of the Comm	\$ 13.29	\$	13.29
1	Radiator hoses Acct#		\$ 21.99	\$	21.99
1	oil seal* Class_		\$ 4.00	\$	10.38
2	oil filters		\$ 15.91	\$	31.83
57.58	Hours Labor - see attached		\$67.50	\$	3,886.31
1	Misc shop supplies		\$174.88	\$	174.88
Freight chan	ges are included in item totals		SubTotal	\$	6,998.97
Remit To:		Sales Tax	8.80%	\$	615.91
territ 10:	4	Gales Tax	0.0070		
52.498	Dennison International Motorsports		MOT.	0	7.044.00
	PO Box 842		TOTAL	\$	7,614.88
	Sumner WA 98390	22			

426 Petaluma Blvd. North COM TO BE DE VIA MAIL

OK TO GOT 26. H

Keel fords

Lin File Petaluma, CA 94952-2873 ph. (707) 765-1326 fax (707) 765-1314

July 2, 2005

SUBJECT:

LOTUS 26R TWIN CAM ENGINE

As you are aware, we have completed the re-build on the twin cam engine, and have sent it to Dennison for installation on your car.

Here is a copy of the dyno sheet showing the engine's performance on our dynamometer. The STPTrq column shows peak torque of 130 lb.ft at 6500 rpm. The STPPwr column shows peak power of 185 hp from 8000 to 8300 rpm, where our test stopped. This combination should prove nicely drivable for you.

Dave identified that he had discussed the condition of the engine's head with you. It has apparently been traumatized by the attention we have given it, and has responded with a small leak at the #4 spark plug hole. We have recommended that Dennison stop it up with "stop leak", and believe this should do the trick. We highly recommend that the engine by given a new head for its next birthday.

We have also included an invoice for our services. Please do not hesitate to contact me, or Dave Vegher, with any questions or concerns about this package.

Respectfully,

VELOCE MOTORS WEST

Todd Nydam

encl. Engine Dyno Services dyno sheet - run date June 27, 2005 Veloce Motors West invoice #1533

CUSTOMER: ENGINE: TWIN CAM (2GR) RUN DATE: JUN. 27, 2005

ENGINE DYNO SERVICES 1308 Dynamic Street, Suite 7 Petaluma, CA 94954 ph. (707) 765-1326

Listing of: (memory data)

Channel Group: Corr Torque & Power Page 1

Printed on Jun 27, 2005 at 12:16:40

Test Description: Accel. Test - 200 rpm/second

6100	EngSpd	STPTrq	STPPwr	STPCor	AirTmp	Air 1	A/F	FulA+B	BSFC
	RPM	Clb-ft	CHp	Factor	degF	scfm	Ratio	lb/hr	lb/hph
8100 119.9 184.9 1.017 77 0 0.00 77.4 0.42	6100 6200 6300 6400 6500 6600 6700 6800 7000 7100 7200 7300 7400 7500 7600 7700 7800 7900 8000 8100 8200	124.0 126.8 127.4 129.4 130.0 130.5 129.2 129.2 129.1 129.0 127.4 126.8 125.9 124.8 124.9 122.9 123.6 123.2 129.1	144.0 149.7 152.8 157.6 160.8 164.0 164.9 167.3 169.7 172.0 172.3 173.8 175.0 175.8 175.0 175.8 177.9 181.1 183.0 183.7 185.7 184.9 185.9	1.017 1.017 1.017 1.017 1.017 1.017 1.017 1.017 1.017 1.017 1.017 1.017 1.017 1.017 1.017 1.017 1.017	77 77 77 77 77 77 77 77 77 77 77 77 77	000000000000000000000000000000000000000	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	64.7 70.0 72.5 72.7 73.7 70.6 69.7 70.7 69.3 76.2 75.8 74.7 75.6 74.3 75.8 74.6 73.0 74.6 77.4	0.408 0.457 0.476 0.466 0.466 0.438 0.430 0.430 0.415 0.422 0.450 0.432 0.431 0.432 0.431 0.425 0.431 0.426 0.408 0.408 0.418

354

155

Sist.

426 Petaluma Blvd. North, Petaluma, CA 94952-2873 ph. (707) 765-1326 fax (707) 765-1314 e-mail; velocemotors@sbcglobal.net

INVOICE

Page 1 of 3

INVOICE # DATE

1533 28-Jun-05

WRITTEN BY

NYDAM

BILL TO:	T	SHIP TO: Dennison International 11203 Benston Drive East, #500	
		Puyallup, WA 98372 Attn: Pete ph. (253) 435-9143	fax
E-MAIL CUST.#		E-MAIL	

DROER DATE	TERMS OF PAYMENT	SHIP DATE 6/27/2005	
Spring '05	upon receipt	SHIP VIA	
CUST. PO. NO.	FOB POINT	BAX Global	
verbal	destination PAYMENT TYPE	WAY BILL#	
RESALE NO.	company check okay	703 560 126	
n/a	company check okay		

Lotus 26R twin cam engine: To invoice for labor, parts & materials to re-build engine. NOTES:

ALL VALUES SHOWN IN US DOLLARS

		DESCRIPTION	UNIT PRICE	EXTENSION
TY.	PART NUMBER		80.00	/hr standard rate
		LABOR	85.00	/hr machinist rate
1				incl.
1	lot	Disassemble & clean engine components		incl.
1	lot	Inspect engine components to determine purchasing		
		requirements	50.00	50.00
1	hr	Pressure check head; result: okay	85.00	
5.75	hr	Remove existing valve seats; source new seats &	00.00	
SMOR III		valves; bore head for new seats; install seats in		
l		head; cut seats to proper height	85.00	127.50
1.5	hr	Machine intake follower bores for spacer removal	85.00	
1.25	hr	Hone valve guides	00.0	incl.
1	lot	Perform precision valve job	85.00	212.50
2.5	hr	Blend valve seats to ports	85.0	
2.5	hr	Machine valves to correct length for head	50.0	0 50.00
1	hr	Pressure check head; #4 leaking slightly at		
		spark plug threads; advised Dennison & Malone Machine pistons for proper piston to valve clearance	85.0	
2.5	hr	Remove & replace 1 head stud & helicoil block	80.0	
1.25	hr	Remove & replace I head stud & Helicon bross	3000.0	
1	lot	Perform professional engine re-build	800.0	0.008
1	lot	Engine dyno session		incl
1	lot	Post dyno inspection LABOR - TOTAL		5360.00
				1
		OUTSIDE SERVICES	100.0	100.0
1	lot	Mag check & polish crank	40.0	
1	lot	Mag check rods	67.5	
1	lot	Coating on bearings		13.6
2	lot	Shipping on bearings for coating	0	
	12-	OUTSIDE SERVICES - TOTAL		221.1

INVOICE Page 2 of 3

426 Petaluma Blvd. North, Petaluma, CA 94952-2873 ph. (707) 765-1326 fax (707) 765-1314 e-mail: velocemotors@sbcglobal.net

INVOICE# 1533

DATE 28-Jun-05

WRITTEN BY NYDAM

			WKILLENDI	
		PARTS & MATERIALS		
1	set	bearings, rod, wide, coated, (see Outside Services)	38.00	38.00
1	set	bearings, main, coated, (see Outside Services)	85.00	85.00
1	set	bearings, thrust	16.00	16.00
- A 10 - 10 - 10 - 10 - 10 - 10 - 10 - 1	SCL	valve	24.00	192.00
8		spring, valve	44.00	352.00
8		retainer, valve spring, titanium	15.00	120.00
8		keeper, valve spring retainer	2.20	35.20
16		seat, valve	10.41	83.28
8		guide, valve, exhaust	9.50	38.00
4			80.00	240.00
3		sprocket, cam	275.00	275.00
1		jackshaft	425.00	425.00
1		pump, oil	7.50	30.00
4		plug, spark	0.80	3.20
4		spacer, copper, for spark plugs	5.00	40.00
8		cap, lash	25.00	25.00
1		follower, cam	18.00	18.00
1		gasket, cam cover	36.00	36.00
1		gasket, oil pan	185.00	185.00
1	set	rings, piston	7.65	7.6
1		gasket, front chest	5.95	5.9
1		gasket, top	125.00	125.0
1		gasket, head	10.50	10.5
1		stud, head	2.00	2.0
1		helicoil	7.25	36.2
5		stud, stepped, for cam caps	3.25	9.7
3		stud, regular cam cap	5.50	22.0
4		gasket, exhaust	2.50	7.5
3		washer, Dowdy, 5/8"		33.0
1		chain, timing	33.00	5.2
1		link, master, for timing chain	5.20	15.1
1		belt, water pump	15.10 17.50	17.5
1		seal, front	37.00	37.0
1		seal, rear	8.50	102.0
12		bolt, flywheel	7.50	7.5
1		rotor, distributor		22.9
1		cap, distributor	22.95	1.9
1		o-ring, distributor	1.95	15.9
2		dowel, offset cam	7.95	
1	lot	hardware, new	20.00	20.
'	100	PARTS - TOTAL		2741.
		MATERIALS		
0.5	tube	silicone, pure, white	16.00	8.
5	gal	Gas	7.50	37.
12	qt	Engine oil	2.95	35.
5	can	Brake/sensitive surface cleaner	4.00	20.
1	lot	Hazardous waste disposal fee	5.00	5.
	177	MISCELLANEOUS - TOTAL		105.

426 Petaluma Bivd. North, Petaluma, CA 94952-2873 ph. (707) 765-1326 fax (707) 765-1314 e-mail: velocemotors@sbcglobal.net

INVOICE

Page 3 of 3

INVOICE#	1533
DATE	28-Jun-05
WRITTEN BY	NYDAM

				5360.00
	TOTAL LABOR			221.19
	TOTAL OUTSIDE SERVICES			2741.38
	TOTAL PARTS TOTAL MATERIALS			105.90
		SUB-TOTAL	Ī	8428.47
		SHIPPING	1	587.14
		TAX	7.75%	out of state
		TOTAL		\$ 9,015.60
		DEPOSIT		0.00
		BALANCE DUE		\$ 9,015.60

Please remit to: Veloce Motors West, 426 Petaluma Blvd. North, Petaluma, CA 94952-2873

THANK YOU FOR YOUR BUSINESS!

01

MOTORSPORTS DIVISION

Quality that GOES!

INVOICE

Customer	Invoice # L26R - L011
Name	Date 5/31/05
Address	Project (Lotus 26R)
City	
Phone	

Qty	Description		Unit Price		TOTAL
1	BAX freight charges for engine on 5-19-05		\$ 297.04	\$	297.04
1	Resonator and connector pipe		\$ 45.50	\$	45.50
1	Exhaust pieces		\$ 70.79	\$	70.79
2	oil seals*		\$ 6.50	\$	17.62
1	drivers suit cleaning		\$ 23.00	\$	23.00
56.38	Hours Labor - see attached		\$67.50	S	3,805.31
1	Misc shop supplies		\$171.24	S	171.24
		POST			
Freight char	ges are included in item totals		SubTotal	\$	4,430.50
Remit To:	Dennison International Motorsports	Sales Tax	8.80%	\$	389.88
	Liennigon International Motorgnorts			16	

Sumner WA 98390

Terms:

Due Upon Receipt