

Name Addr.	
Phone B- Name B-Addr.	
B-Phone Alarm data V.I.N. #	19804210002538

Service Description	Hrs.	Lab\$
LUBE OIL AND FILTER		
REMOVE SPARK PLUGS AND TURN ENGINE OVER BY HAND THEN CRANK ENGINE WITH PLUGS OUT TO GET OIL PREASURE		
INSTALL PLUGS AND ATTEMPT TO START ENGINE, CAR WOULD NOT START, CHECK TIMMING AND DWELL, SET AS NEEDED, CHECK INJECTION PUMP TIMMING, FOUOD PUMP INSTALLED 180 DEGREES OUT OF TIMMING, REMOVE DRIVE SHAFT FOR PUMP AND RESET TIMMING, CAR RAN AFTER SETTING PUMP TIMMING		
IGNITION SWITCH DEFECTIVE, SHUTS CAR OFF A TIMES REPLACED SWITCH WITH NEW FACTORY SWITCH		
COMPLETE CHECK OVER AND ESTIMATE ( NO CHARGE )		

Inv. Date	02/15/99	Year	1960
S.O. Date	01/13/99	Make	MERCEDES
QC'd by	10	Model	300SL ROD
Salesman	GROVER	Color	RED/BLACK
Division	RE	Miles	25823
		Lic.#	

Qty	Part Number	Part Description	Price
6	003 159 11 03	W8DCO SPARK PLUGS	
2	COPP	SEAL RING COPPER	
3	915035-000008	EXHAUST SEAL RING	
1	000 477 36 15	FUEL FILTER	
1	000 477 43 15	EARLY FUEL FILTER ELEMEN	
1	009 545 41 28	PLUG	
2	ALUM	SEAL RING ALUMINUM	
1	000 545 25 13	IGNITION SWITCH	

Additional Items	Sublet or Add'l Services
	FUEL TOW
Total Items	Total Sublets

Recommendations
Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Add. Items
Subtotal
Tax
<b>Total</b>

YOUR SATISFACTION IS OUR GREATEST PRIORITY. PLEASE CONTACT US IMMEDIATELY WITH ANY QUESTIONS OR CONCERNS. THANKS FOR SERVICING YOUR CAR WITH HATCH & SON'S RESTORATION.







Name Addr.	
Phone B- Name B-Addr.	
B-Phone Alarm data V.I.N. #	19804210002538

Service Description	Hrs.	Lab\$
INSTALL REAR PLATE FRAME		
PREP CAR AND EXHAUST PIPE FOR INSTALL OF NEW REAR MUFFLER, PAINT NEW MUFFLER		
INSTALL REAR MUFFLER		
LUBE OIL AND FILTER		
CHANGE ALL FLUIDS AND FILTERS, ADJUST VALVES, LUBE DOOR HINGES THROTTLE LINKAGE, SET DWELL AND TIMMING		
R&R RADIATOR FOR REPAIR		
REPLACE DRIVE BELT		
REPLACE TRANSMISSION MOUNT, INSTALL NEW SHIFTER BUSHINGS AS NEEDED		
ADJUST AND REPAIR BOTH HEATER VALVES		

Inv. Date	06/21/99	Year	1960
S.O. Date	03/08/99	Make	MERCEDES
QC'd by	10	Model	300SL
Salesman	GROVER	Color	RED/BLACK
Division	RE	Miles	26225
		Lic.#	

Qty	Part Number	Part Description	Price
1	198 491 01 99	REAR MUFFLER	
2	201 817 00 11	FRONT PLATE BRACKET	
2	8MM BOLT	GOLD BOLT	
2	107 987 01 42	LICENSE PLATE SPACER	
4	124 990 12 36	SCREW	
2	8MMNUT	8MM GOLD NUT	
2	128 490 00 37	EXHAUST HANGER KIT	
1	183 492 02 82	RUBBER PAD,EXHAUST,	
1	124 490 02 41	CLAMP EXHAUST	
1	181 220 00 17	MOUNT,TRANSMISSION	
4	121 071 01 80	GASKET,INJECTION	
8	121 071 00 76	RUBBER SHIM	
3	915035-000003	VALVE COVER COPPER SEAL	
1	10X970	V-BELT	
1	186 018 00 80	GASKET,VALVE COVER	
2	111 267 00 83	BUSHING,SHIFTER WHITE	
2	000 835 58 98	SEAL RING	
1	000 477 35 80	FUEL FILTER O'RING	
1	000 477 19 80	GASKET,FUEL FILTER	
1	000 477 43 15	FUEL FILTER,EARLY	

Additional Items	Sublet or Add'l Services
	RADIATOR REPAIR
	SEAT BELTS
Total Items	Total Sublets

**Recommendations**

Next service due on: ???

<b>Totals</b>
Labor
Parts
Supplies
Sublets
Addl. Items
Subtotal
Tax
<b>Total</b>

YOUR SATISFACTION IS OUR GREATEST PRIORITY. PLEASE CONTACT US IMMEDIATELY WITH ANY QUESTIONS OR CONCERNS. THANKS FOR SERVICING YOUR CAR WITH HATCH & SON'S RESTORATION.



Name Addr.	
Phone B- Name B-Addr.	
B-Phone Alarm data V.I.N. #	19804210002538

Service Description	Hrs.	Lab\$
REPLACE COMPLETE POWER ANTENNA HARNESS, REPAIR RADIO HARNESS AND OTHER MISC MELTED WIRES		
INSTALL NEW CONV TOP REPLACE STRAPS AND REWARP ALL BOWS, STRAIGHTEN BENT BOW		
INSTALL NEW BRASS RIVOTS ON CONV TOP FRAME BOW		
REMOVE TACH, REPLACE CAP ON PIVOT		
CLEAN AND LUBE TOP FRAME 25		
REPLACE WINDSHIELD WASHER PUMP AND HOSE		
REPLACE FUEL TANK SENDER AND FUEL PICKUP TUBE GASKETS		
REPLACE REAR FUEL PUMP SWITCH OVER GATE VALVE		

Inv. Date	06/21/99	Year	1960
S.O. Date	03/08/99	Make	MERCEDES
QC'd by	10	Model	300SL
Salesman	GROVER	Color	RED/BLACK
Division	RE	Miles	26225
		Lic.#	

Qty	Part Number	Part Description	Price
1	000 477 36 15	FUEL FILTER	
1	040621-008200	INSULATING HOSE	
1	2WBULB	2W BULB	
2	Q10 300 02	ANTIFREEZE,MB FACTORY	
1	SOFT TOP 300SL	SOFT TOP 57-63 300SL	
10	OIL	20/50W CASTROL OIL	
3	G/O	GEAR OIL	
4	ATF	AUTOMATIC TRANS-FLUID	
4	636 074 00 73	PLATES	
2	183 492 00 18	MOUNT PLATE EXHAUST	
1	183 492 02 82	RUBBER PAD,EXHAUST	
1	EPOXY	EPOXY 2000 10-4GR CUPS	
1	115 725 09 65	WINDOW BRUSH PILL DOORS	
1	115 860 01 69	WASHER NOZZLE W/HOSE	
3	243-410	CLEAR W/WASHER HOSE	
1	115 869 01 21	WASHER PUMP	
1	110 471 01 80	GASKET,FUEL SENDER UNIT	
1	072601-012702	10W BULB	
1	186 460 09 03	STEERING WHEEL WHITE	
1	187 460 02 44	EMBLEM,STEERING WHEEL	

Additional Items	Sublet or Add'l Services
	RADIATOR REPAIR
	SEAT BELTS
Total Items	Total Sublets

**Recommendations**

Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Add. Items
Subtotal
Tax
<b>Total</b>

(Page 2 of 3)

YOUR SATISFACTION IS OUR GREATEST PRIORITY. PLEASE CONTACT US IMMEDIATELY WITH ANY QUESTIONS OR CONCERNS. THANKS FOR SERVICING YOUR CAR WITH HATCH & SON'S RESTORATION.



Name	
Addr.	
Phone	
B- Name	
B-Addr.	
B-Phone	
Alarm data	
V.I.N. #	19804210002538

Service Description	Hrs.	Lab\$
INSTALL EXHUAUST EXTENSION AND STEERING WHEEL		
INSTALL NEW HEADLIGHTS		

Inv. Date	06/21/99	Year	1960
S.O. Date	03/08/99	Make	MERCEDES
QC'd by	10	Model	300SL
Salesman	GROVER	Color	RED/BLACK
Division	RE	Miles	26225
		Lic.#	

Qty	Part Number	Part Description	Price
1	180 460 00 40	HORN RING	
1	127 268 01 42	KNOB, SHIFTER WHITE	
1	189 490 00 27	EXHAUST CHROME TIP 300SL	
2	COPP	SEAL RING COPPER	
2	70476	HELLA 7"ROUND H/L BULB	
2	64191	BULB H4 12V 100/55W	
2	111 267 00 86	RING, SHIFTER TOP	
4	198 268 01 50	SHIFTER BUSHING	
2	092-26R	BOWDRILL	
1	198 470 02 93	SLIDE VALVE	
1	136 758 00 98	PAD, TRUNK LOCK BASE	
1	FUEL RETURN ASSEMBLY	REBUILT F/RETURN	
1	198 770 99 02	RIVET SET	
3	COTTER PIN	COTTER PIN	
2	000 983 89 10	FELT LENGTH	

Additional Items	Sublet or Add'l Services
	RADIATOR REPAIR SEAT BELTS
Total Items	Total Sublets

Recommendations
Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Add. Items
Subtotal
Tax
<b>Total</b>

(Page 3 of 3)

YOUR SATISFACTION IS OUR GREATEST PRIORITY. PLEASE CONTACT US IMMEDIATELY WITH ANY QUESTIONS OR CONCERNS. THANKS FOR SERVICING YOUR CAR WITH HATCH & SON'S RESTORATION.



# Hatch & Sons Automotive

Service Invoice: 8230

Name Addr.	
Phone B- Name B-Addr.	
B-Phone Alarm data V.I.N. #	19804210002538

Service Description	Hrs.	Lab\$
CHANGE OIL; FILTER & LUBE CHASSIS. CHECK ALL FLUIDS, TIRE PRESSURES & LIGHTS		
IDLER ARM HAD SOME PLAY, ADJUST		

Inv. Date	10/03/00	Year	1960
S.O. Date	09/25/00	Make	MERCEDES
QC'd by	27	Model	300SL
Salesman	COTE	Color	RED/BLACK
Division	RE	Miles	26991
		Lic.#	

Qty	Part Number	Part Description	Price
1	1045	OIL FILTER, SPIN ON	
14		OIL 20/50 CASTROL OIL	
1		GREASE CHASSIS GREASE	
1	915035-000025	COPPER SEAL	
1	181 994 00 10	WASHER	
2		COTTER PIN	

Additional Items	Sublet or Add'l Services
Total Items	Total Sublets

Recommendations
Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Add. Items
Subtotal
Tax
<b>Total</b>

(Page 1 of 1)

YOUR SATISFACTION IS OUR GREATEST PRIORITY. PLEASE CONTACT US IMMEDIATELY WITH ANY QUESTIONS OR CONCERNS. THANKS FOR SERVICING YOUR CAR WITH HATCH & SON'S RESTORATION.

533 Boston Post Road, Wayland, MA. 01778 508-358-8094



# Hatch & Sons Automotive

Service Invoice: 12927

Name	
Addr.	
Phone	
B- Name	
B-Addr.	
H Phone	
Alarm data	
V.I.N. #	198.042.10.002538

Inv. Date	06/28/02	Year	1980
S.O. Date	04/12/02	Make	MERCEDES
QC'd by	27	Model	300SL
Salesman	COTE	Color	RED/BLACK
Division	RE	Miles	27249
		Lic.#	

Service Description	Hrs.	Lab \$
REMOVE FUEL TANK. DISSASSEMBLE, CLEAN AND SEND OUT FOR REPAIR. CLEAN OUT ALL FUEL LINES AND REPLACE ALL FUEL FILTERS. REPLACE ALL FUEL HOSES. REMOVE GAS TANK STRAPS.		
GET FUEL TANK BACK FROM REPAIR SHOP. MAKE REPAIR PANEL WHERE TANK RUSTED THROUGH. FLUSH WELD IN REPAIR AND FINISH WITH LEAD. BOX AND SHIP BACK TO REPAIR SHOP FOR INTERIOR PROTECTIVE COATING.		
INSTALL NEW SHOCK ABSORBERS		
REMOVE GLASS FROM SPEEDOMETER AND TACHOMETER, CLEAN AND REASSEMBLE. R&R PALSTIC FROM CENTER INSTRUMENT GAUGE, BUFF AND POLISH PLASTIC FACE.		
DISSASSEMBLE CAR FOR PAINTING. REMOVE FRONT AND REAR BUMPERS. REMOVE LOWER ROCKER PANEL ALUMINUM TRIM. REMOVE ALL LOWER ROCKER PANELS. REMOVE ANTENNA, VENT CHROME, TAILLIGHTS AND REFLECTORS. REMOVE ALL TRIM FROM TRUNK LID. REMOVE HOOD EMBLEM. REMOVE HEADLIGHTS AND FENDER SPEARS.		

Qty	Part Number	Part Description	Price
0		FREIGHT CHARGE	
1	188 580 01 07	TOOL KIT BAG	
20	000 994 13 45	NUT PLATE	
20	000 990 88 91	CAGE NUT	
2	000 323 49 00	SHOCK ABSORBER FRONT	
2	000 328 59 00	SHOCK ABSORBER REAR	
2	000 166 84 01	CONDENSER	
1	000 477 43 15	FUEL FILTER EARLY	
1	000 477 35 80	FUEL FILTER O'RING	
1	1045	OIL FILTER SPIN ON	
1	000 824 01 27	WIPER INSERT, 11 INCH SET	
3	198 476 02 26	HOSE, FUEL	
1	198 476 00 26	FUEL HOSE	
1	198 476 01 26	FUEL HOSE	
1	198 476 04 26	FUEL HOSE	
1	000 477 36 15	FUEL FILTER	
1	000 477 19 80	GASKET, FUEL FILTER	
2	115 725 09 85	WINDOW BRUSH PILL DOORS	
3	915035-000003	VALVE COVER COPPER SEAL	
2	110 451 01 80	GASKET, FUEL SENDER UNIT	

Additional Items	Sublet or Add'l Services
	CARPET KIT
	QUARTZ CLOCK CONVERSION
	FUEL TANK REPAIR
Total Items	Total Sublets

Recommendations
Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Add. Items
Subtotal
Tax
<b>Total</b>

(Page 1 of 2)

YOUR SATISFACTION IS OUR GREATEST PRIORITY. PLEASE CONTACT US IMMEDIATELY WITH ANY QUESTIONS OR CONCERNS. THANKS FOR SERVICING YOUR CAR WITH HATCH & SON'S RESTORATION.

533 Boston Post Road, Wayland, MA. 01778 508-358-8094



# Hatch & Sons Automotive

Service Invoice: 12927

Name	
Addr.	
Phone	
B- Name	
B-Addr.	
B-Phone	
Alarm data	
V.I.N. #	198.042.10.002538

Service Description	Hrs.	Lab
REMOVE CHROME TRIM FROM TOP WELL COVER. REMOVE GRILL.		
DISSASSEMBLE LEFT AND RIGHT DOORS. REMOVE LEATHER		
PANELS, EXTERIOR CHROME TRIM, WINDOW GLASS, DOOR HANDLES		
AND LOCKS. REMOVE DOOR JAMB TRIM. REMOVE DASH PANEL AND		
WINDSHIELD FRAME. BAG AND ORGANIZE ALL REMOVED TRIM AND		
HARDWARE. DISSASSEMBLE, CLEAN AND SEND OUT CHROME TRIM FOR		
PLATING. GROUP AND LIST EXTERIOR COMPONENTS FOR REPLACEMENT		
REMOVE ALL CARPETING AND FRONT SEATS. REMOVE		
CONVERTIBLE TOP ASSEMBLY. REMOVE WASHER NOZZLE FROM HOOD.		
REMOVE ALL RUBBER GASKETS - DOORS, TRUNK, HOOD ETC.		
DRILL OUT RIVETS IN DOORS FOR DOOR PANEL LOWER MOLDING.		
VACUUM OUT LOOSE INSULATION FROM DASH		

Inv. Date	06/28/02	Year	1960
S.O. Date	04/12/02	Make	MERCEDES
QC'd by	27	Model	300SL
Salesman	COTE	Color	RED/BLACK
Division	RE	Miles	27249
		Lic.#	

Qty	Part Number	Part Description	Price
1	120 470 01 86	PLUG STRAINER	
1	136 997 06 40	SEAL RING	
10	198 698 00 14	BRACKET, MOULDING'	
8	198 690 00 71	BOLT PLATE, MOULDING	
12	910001-003100	POP RIVOT	
6	2WBULB	2W BULB	
1	198 671 00 20	SEAL, WINDSHIELD	
1	198 687 00 93	SEAL, HOOD	
1	198 758 00 98	TRUNK SEAL	
1	198 720 01 78	WEATHERSTRIP, L/DOOR	
1	198 720 02 78	WEATHERSTRIP, R/DOOR	
1	198 779 00 95	SEAL, TOP WELL	
1	000 987 38 51	WELTING	
1	B300GSR	MIRROR, RIGHT CONVEX	
1	198 817 00 16	HOOD BADGE	

Additional Items	Sublet or Add'l Services
	CARPET KIT
	QUARTZ CLOCK CONVERSION
	FUEL TANK REPAIR
Total Items	Total Sublets

Recommendations
Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Add. Items
Subtotal
Tax
<b>Total</b>

(Page 2 of 2)

YOUR SATISFACTION IS OUR GREATEST PRIORITY. PLEASE CONTACT US IMMEDIATELY WITH ANY QUESTIONS OR CONCERNS. THANKS FOR SERVICING YOUR CAR WITH HATCH & SON'S RESTORATION.

4165 B  
7500 E

533 Boston Post Road, Wayland, MA. 01778 508-358-8094











# Hatch & Sons Automotive

Service Invoice: 13653

Name	
Addr.	
Phone	
B- Name	
B-Addr.	
B-Phone	
Alarm data	
V.I.N. #	198.042.10.002538

Service Description	Hrs.	Lab\$
BLOCK SAND LEFT AND RIGHT DOORS FOR C/B PRIMER		
BLOCK SAND BODY FOR C/B PRIMER		
COLOR BUILD PRIME LEFT AND RIGHT DOORS		
STRIP AND REPAIR BOTTOM SIDE OF TRUNK LID & PRIME		
DO FINISH BODY WORK ON COWL PANEL		

Inv. Date	07/31/02	Year	1980
S.O. Date	06/28/02	Make	MERCEDES
QC'd by	DAVE	Model	300SL
Salesman	DAVE	Color	RED/BLACK
Division	AB	Miles	0
		Lic.#	

Qty	Part Number	Part Description	Price
1	100 826 00 52	TAIL LENS SET	
1	FEE	PAINT & MATERIALS	

Additional Items	Sublet or Add'l Services
1 CAR COVERS	
Total Items	Total Sublets

<b>Recommendations</b>
Next service due on: ???

<b>Totals</b>
Labor
Parts
Supplies
Sublets
Add. Items
Subtotal
Tax
<b>Total</b>

(Page 1 of 1)



# Hatch & Sons Automotive

Service Invoice: 13977

Name	
Addr.	
Phone	
B- Name	
B-Addr.	
B-Phone	
Alarm data	
V.I.N. #	198.042.10.002538

Service Description	Hrs.	Lab\$
MASK BODY FOR PRIMER		
SPRAY COLOR BUILD PRIMER ON BODY		
EPOXY PRIME HOOD		
BLOCK SAND HOOD FOR C/B PRIMER		
COLOR BUILD PRIME HOOD		
COLOR BUILD PRIME TRUNK LID		
EPOXY PRIME LEFT AND RIGHT ROCKER PANELS		
BLOCK SAND AND PRIME LEFT AND RIGHT ROCKER PANELS		
TEST FIT CROME ON BODY PANELS		
MASK BODY FOR PAINT		

Inv. Date	08/30/02	Year	1960
S.O. Date	07/31/02	Make	MERCEDES
QC'd by	DAVE	Model	300SL
Salesman	DAVE	Color	RED/BLACK
Division	AB	Miles	0
		Lic.#	

Qty	Part Number	Part Description	Price
1	FEE	PAINT & MATERIALS	

Additional Items		Sublet or Add'l Services	
1	CAR COVERS		
Total Items		Total Sublets	

Recommendations
Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Add. Items
Subtotal
Tax
<b>Total</b>

(Page 1 of 2)

6

--



# Hatch & Sons Automotive

Service Invoice: 13977

Name	
Addr.	
Phone	
B- Name	
B-Addr.	
B-Phone	
Alarm data	
V.I.N. #	198.042.10.002538

Service Description	Hrs.	Lab\$
SPRAY BASE-COAT PAINT ON BODY		
SPRAY THREE COAT CLEAR ON BODY		
WET SAND CLEAR COAT PAINT ON BODY FOR BUFF		
BUFF AND POLISH BODY CLEAR COAT		
BLOCK SAND BODY PARTS FOR PAINT		

Inv. Date	08/30/02	Year	1960
S.O. Date	07/31/02	Make	MERCEDES
QC'd by	DAVE	Model	300SL
Salesman	DAVE	Color	RED/BLACK
Division	AB	Miles	0
		Lic.#	

Qty	Part Number	Part Description	Price

Additional Items	Sublet or Add'l Services
1 CAR COVERS	
Total Items	Total Sublets

Recommendations
Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Addl. Items
Subtotal
Tax
<b>Total</b>

(Page 2 of 2)

--



# Hatch & Sons Automotive

Service Invoice: 14296

Name Addr.	
Phone B- Name B-Addr.	
B-Phone Alarm data V.I.N. #	198.04.2.10.002538

Service Description	Hrs.	Lab\$
PAINT BODY PARTS CHECK FIT OF AND MAKE ADJUSTMENTS TO L&R HEADLIGHT MOLDINGS WHILE IN COPPER. PICK AND FILE FLAWS AND FIT TO CAR. FINISH WITH 200 GRIT SAND PAPER SAND, PREP AND PAINT STEERING COLUMN REPAIR DRIVER DOOR CHECK. CUT AND SPLICE USED CHECK AND REPAIR ORIGINAL. CLEAN, PREP AND PAINT ALL DOOR HINGE HARD WARE AND DOOR CHECK COMPONENTS. BLOCK SAND BODY PARTS FOR BUFFING BUFF AND POLISH PAINTED BODY PARTS INSTALL LEFT AND RIGHT DOORS INSTALL TRUNK AND WEATHER STRIP INSTALL HOOD AND WEATHER STRIP		

Inv. Date	09/13/02	Year	1960
S.O. Date	08/30/02	Make	MERCEDES
QC'd by	DAVE	Model	300SL
Salesman	DAVE	Color	RED/BLACK
Division	AB	Miles	27249
		Lic.#	

Qty	Part Number	Part Description	Price
4	111 987 17 40	RUBBER BUFFER GAS DOOR	
2	121 987 02 37	RUBBER SUPPORT, LOCK ROD	
1	FEE	PAINT & MATERIALS	

Additional Items	Sublet or Add'l Services
1 CAR COVERS	
Total Items	Total Sublets

Recommendations
Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Add. Items
Subtotal
Tax
<b>Total</b>

(Page 1 of 1)



# Hatch & Sons Automotive

Service Invoice: 14315

Name  
Addr.

---

Phone  
B- Name  
B-Addr.

---

B-Phone  
Alarm data  
V.I.N. #

193.042.10.002538

Service Description	Hrs.	Lab\$
PLATING: 2 UPPER & LOWER WINDSHIELD TRIM, 2 L&R W/S BACKING PLATES, 2 L&R W/S PILLAR COVERS, 2 L&R W/S PILLAR GASKET CHANNELS, 2 L&R TOP OF DOOR MOLDINGS, 2 L&R QUARTER PANEL MOLDINGS, 2 WINDSHIELD WIPER BASE COVER, 8 FENDER AND DOOR SPEARS, 1 ANTENNA TOP ASSEMBLY, 1 MIRROR BASE, 2 L&R HEADLIGHT RIMS, 2 L&R TAIL LIGHT FRAMES, 2 HEADLIGHT RIVETS ALL WORK TO PLATE ABOVE. STRIP AND PREP ALL: (BEAD BLAST), (CHEMICAL STRIP), (PICK, DOLLY & FILE), (POLISH), (COPPER), (CUT & BUFF). PLATING: COPPER, NICKLE & CHROME.		
SAND, PREP AND PAINT FUEL TANK		
CUT AND FIT NEW LOWER WINDSHIELD GASKET. NOTCH FOR CURVE AS NECESSARY. INSTALL WINDSHIELD FRAME AND CHROME TRIM MOLDINGS. SEAL MOLDINGS TO FRAME. REGLUE LEATHER TO SURROUND.		
R&R ASH TRAY, REAR VIEW MIRROR AND DEFROSTER VENT TRIM. CLEAN, SCUFF AND MASK DASH LEATHER. MIX LEATHER DYE		

Inv. Date 09/13/02 Year 1960

S.O. Date 09/03/02 Make MERCEDES

QC'd by 27 Model 300SL

Salesman COTE Color RED/BLACK

Division RE Miles 27249

Lic.#

Qty	Part Number	Part Description	Price
	FREIGHT CHARGE		
4	186 401 00 25	HUB CAP	
1	2WBULB	2W BULB	
3	CHROME SCREW	CHROME SCREW	
3	198 462 01 60	RING, STEERING COLUMN	

Additional Items	Sublet or Add'l Services
	CHROME PLATING
Total Items	Total Sublets

**Recommendations**

---

Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Add. Items
Subtotal
Tax
<b>Total</b>

(Page 1 of 2)

YOUR SATISFACTION IS OUR GREATEST PRIORITY. PLEASE CONTACT US IMMEDIATELY WITH ANY QUESTIONS OR CONCERNS. THANKS FOR SERVICING YOUR CAR WITH HATCH & SON'S RESTORATION.



# Hatch & Sons Automotive

Service Invoice: 14315

Name	
Addr.	
Phone	
B- Name	
B-Addr.	
B-Phone	
Alarm data	
V.I.N. #	198.042.10.002538

Service Description	Hrs.	Lab\$
TO MATCH ORIGINAL. TINT FOR CORRECT SHEEN. DYE DASH AND SURROUNDING AREA AS NECESSARY FOR DASH ASSEMBLY. STEEL WOOL AND CONDITION LEATHER. CLEAN ALL DASH COMPONENTS TO BE INSTALLED. INSTALL MIRROR, VENT TRIM AND ASH TRAY.		
REMOVE STEERING COLUMN FOR DASH INSTALLATION. INSTALL DASH AND ALL CONTROLS. INSTALL PAINTED STEERING COLUMN. INSTALL CHROME COVER PLATES. INSTALL CLOCK. (CLOCK CONVERTED TO QUATZ MOVEMENT). CLEAN ALL DASH COMPONENTS PRIOR TO INSTALLATION. LUBE HEATER CONTROLS.		
DISMOUNT ALL TIRES. CLEAN GREASE OFF RIMS AND SAND BLAST ALL RIMS FOR PAINT.		

Inv. Date	09/13/02	Year	1960
S.O. Date	09/03/02	Make	MERCEDES
QC'd by	27	Model	300SL
Salesman	COTE	Color	RED/BLACK
Division	RE	Miles	27249
		Lic.#	

Qty	Part Number	Part Description	Price

Additional Items	Sublet or Add'l Services
Total Items	Total Sublets

Recommendations
Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Add. Items
Subtotal
Tax
<b>Total</b>

(Page 2 of 2)

YOUR SATISFACTION IS OUR GREATEST PRIORITY. PLEASE CONTACT US IMMEDIATELY WITH ANY QUESTIONS OR CONCERNS. THANKS FOR SERVICING YOUR CAR WITH HATCH & SON'S RESTORATION.







Name Addr.	
Phone B- Name B-Addr.	
B-Phone Alarm data V.I.N. #	198.042.10.002538

Inv. Date	09/27/02	Year	1960
S.O. Date	09/17/02	Make	MERCEDES
QC'd by	27	Model	300SL
Salesman	COTE	Color	RED/BLACK
Division	RE	Miles	0
		Lic.#	

Service Description	Hrs.	Lab\$
REPAIR FUEL PICK UP FOR GAS TANK. REMOVE CLOGGED AND CORRODED SCREEN. CLEAN DEBRIS OUT OF PICK UP TUBES AND BEAD BLAST ASSEMBLY. MAKE NEW SCREEN CYLINDER AND SOLDER TO PICK UP.		
PREP AND INSTALL FUEL TANK. SAND BLAST MOUNTING STRAPS, PRIME AND PAINT. GET HARDWARE FOR STRAPS. INSTALL INSULATION ON GAS TANK. INSTALL RUBBER BUFFER ON TANK STRAPS. INSTALL FUEL SENDER AND PICK UP SCREEN. INSTALL FUEL TANK AND CONNECT FUEL LINES AND WIRING. SAND BLAST AND PAINT FUEL FILLER NECK. CUT NEW CONNECTOR HOSE AND INSTALL. INSTALL NEW RUBBER GASKET ON BODY AROUND FILLER NECK. INSTALL NEW CAP AND SEAL. CLEAN, LUBE AND INSTALL FUEL FILLER DOOR LOCK.		
INSTALL ORIGINAL POWER ANTENNA		
SAND AND POLISH LEFT AND RIGHT DOOR HANDLES		
ASSEMBLE RIGHT DOOR COMPONENTS AND INSTALL INTO DOOR.		

Qty	Part Number	Part Description	Price
2	198 698 05 80	MOULDING	
1	198 698 06 80	MOULDING,CHROME	
1	198 698 07 80	MOULDING	
6	123 720 01 14	WINDOW REG. REPAIR KIT	
6	000 987 35 40	GAS DOOR STOPS	
4	NIP	VALVE STEM SEAL	
1	111 910 50 64	CHROME RETURN RUBBERS	
2	110 471 01 80	GASKET,FUEL SENDER UNIT	
1	309 470 00 05	GAS CAP	
1	138 997 06 40	SEAL RING	
2	900262-005100	HOSE CLAMP	
2	900262-005000	HOSE CLAMP,BERU 5MM	
2	STRAPPING 9MM	CLAMP STRAPPING 9MM	
2	STRAPPING 4MM	STRAPPING 4MM	
6	900056-003507	COUNTER SUNK WASHER	

Additional Items	Sublet or Add'l Services
	CHROME PLATING HEAD/TAIL LIGHTS
Total Items	Total Sublets

Recommendations
Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Add. Items
Subtotal
Tax
<b>Total</b>

(Page 1 of 3)

YOUR SATISFACTION IS OUR GREATEST PRIORITY. PLEASE CONTACT US IMMEDIATELY WITH ANY QUESTIONS OR CONCERNS. THANKS FOR SERVICING YOUR CAR WITH HATCH & SON'S RESTORATION.











# Hatch & Sons Automotive

Service Invoice: 14529

Name	
Addr.	
Phone	
B- Name	
B-Addr.	
B-Phone	
Alarm data	
V.I.N. #	198.042.10.002538

Service Description	Hrs.	Lab\$
INSTALL HOOD PROP AND MAKE ADJUSTMENTS TO SAFETY CATCH. CLEAN AND INSTALL FRESH AIR GRILL INTO COWL. INSTALL WINDSHIELD WASHER NOZZLE AND ADJUST SPRAY PATTERN.		
FILL FUEL TANK WITH FUEL AND CRANK ENGINE TO GET OIL PRESSURE. START AND RUN ENGINE TO OPERATING TEMPERATURE AND CHECK DASH GAUGES. CHECK ALL DASH LIGHTING WIRING AND INSTALL TACHOMETER AND SPEEDOMETER.		
CLEAN ALL RADIO COMPONENTS FOR INSTALLATION AND INSTALL RADIO.		
STRIP AND PAINT ALUMINUM CHANNELS FOR DOOR PANEL. RIVET CHANNELS ONTO LEFT AND RIGHT DOORS		
ASSEMBLE AND INSTALL DRIVER EXTERIOR REAR VIEW MIRROR		
INSTALL LEFT AND RIGHT REAR LOWER BODY PANELS AND NEW ALUMINUM TRIM MOLDINGS. MODIFY NEW MOUNTING HARDWARE AS NECESSARY TO FIT. CLEAN AND INSTALL CHROME EXHAUST TIP.		

Inv. Date	10/24/02	Year	1960
S.O. Date	09/27/02	Make	MERCEDES
QC'd by	27	Model	300SL
Salesman	COTE	Color	RED/BLACK
Division	RE	Miles	0
		Lic.#	

Qty	Part Number	Part Description	Price
2	072601-012701	BULB,12V/5W SHORT	
2	FUSE	FUSE	
1	FUSE SHORT WHITE	SHORT FAT WHITE FUSE	
1	000 889 18 47	WINDSHIELD WASHER NOZZLE	
2	000 826 15 80	GASKET, TAIL LIGHT	
1	001 987 24 51	RUBBER STRIP	
2	000 997 31 81	GROMMET, RUBBER	
1	198 671 00 10	WINDSHIELD	
2	000 987 10 36	GASKET, BUMPER BRACKET	
1	186 997 07 81	GROMMET/FIREWALL DRAINS	
1	187 460 02 44	EMBLEM, STEERING WHEEL	
4	900056-003507	COUNTER SUNK WASHER	
2	198 885 02 99	BUMPER STRUT GAURD	
1	001 987 24 51	RUBBER STRIP	
2	000966-004031	DOOR LATCH CVR SCREW	
25	007983-002203	SHEET METAL SCREW	
30	900056-006001	WASHER, CHROME 6MM	
30	000966-006007	COUNTER SUNK SCREW	

Additional Items	Sublet or Add'l Services
	FUEL
	WINDSHIELD INSTALL
Total Items	Total Sublets

Recommendations
Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Addl. Items
Subtotal
Tax
<b>Total</b>

(Page 1 of 3)

YOUR SATISFACTION IS OUR GREATEST PRIORITY. PLEASE CONTACT US IMMEDIATELY WITH ANY QUESTIONS OR CONCERNS. THANKS FOR SERVICING YOUR CAR WITH HATCH & SON'S RESTORATION.

533 Boston Post Road, Wayland, MA. 01778 508-358-8094











# Hatch & Sons Automotive

Service Invoice: 14608

Name	
Addr.	
Phone	
B- Name	
B-Addr.	
B-Phone	
Alarm data	
V.I.N. #	198.042.10.002538

Service Description	Hrs.	Lab\$
INSTALL SOFT TOP AND ADJUST TOP FIT TO WINDOWS. REMOVED REAR LOCKING BAR FROM TOP CANVAS, STRAIGHTENED AND REGLUED INTO CANVAS.		
INSTALL AND FIT NEW WINDSHIELD PILLAR GASKETS		
DISSASSEMBLE FRONT SEATS FOR CLEANING AND RE-COLORING STRIP, CLEAN, MASK AND COLOR DOOR PANELS, SEATS, VISORS AND TOP OF DOOR PANEL		
INSTALL REMAINING INTERIOR TRIM SCREWS. CLEAN ALL DOOR PANEL HARDWARE AND CHROME TRIM. REPLACE SCREWS AND CHROME WASHERS AS NECESSARY.		
INSTALL LEFT AND RIGHT SPEAR MOLDING TRIM. FILE HOLES IN BODY PANELS AND FILE TABS ON MOLDINGS TO FIT. PRIME ALL EXPOSED METAL FROM FILING AND INSTALL MOLDINGS. REPLACE NUTS HARDWARE AS NECESSARY.		
MAKE NEW PLASTIC VAPOR BARRIERS FOR L&R DOORS.		

Inv. Date	10/25/02	Year	1960
S.O. Date	10/04/02	Make	MERCEDES
QC'd by	27	Model	300SL
Salesman	COTE	Color	RED/BLACK
Division	RE	Miles	0
		Lic.#	

Qty	Part Number	Part Description	Price
1	001 983 23 10	FELT STRIP	
1	000 824 01 27	WIPER INSERT, 11 INCH SET	
2	121 725 00 66	SEAL, A-PILLAR	
8	900058-006001	WASHER, CHROME 8MM	
1	NIP	VALVE STEM SEAL	
18	8MM BOLT	GOLD BOLT	
18	8MM NUT	8MM GOLD NUT	
24	8MM WASHER	8MM GOLD FLAT WASHER	
4	8MM LOCK	8MM GOLD LOCK WASHER	
5	000 994 13 45	NUT PLATE	
1	COTTER PIN	COTTER PIN	
3	COPP	SEAL RING COPPER	
12	900056-003507	COUNTER SUNK WASHER	
12	900056-004002	WASHER COUNTERSUNK	
16	CHROME SCREW	CHROME SCREW	
2	111 776 80 97	SOFT TOP GROMMET	
8	000966-008007	COUNTER SUNK SCREW	
2	Q68 800 05	PLATE FRAME CHROME	
2	180 760 01 81	COVER, DOOR HANDLE CHROME	
10	198 698 00 14	BRACKET, MOULDING	

Additional Items	Sublet or Add'l Services
	INSPECTION STICKER
Total Items	Total Sublets

Recommendations
Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Addl. Items
Subtotal
Tax
<b>Total</b>

(Page 1 of 4)

YOUR SATISFACTION IS OUR GREATEST PRIORITY. PLEASE CONTACT US IMMEDIATELY WITH ANY QUESTIONS OR CONCERNS. THANKS FOR SERVICING YOUR CAR WITH HATCH & SON'S RESTORATION.

533 Boston Post Road, Wayland, MA. 01778 508-358-8094



# Hatch & Sons Automotive

Service Invoice: 14608

Name	
Addr.	
Phone	
B- Name	
B-Addr.	
B-Phone	
Alarm data	
V.I.N. #	198.042.10.002538

Inv. Date	10/25/02	Year	1980
S.O. Date	10/04/02	Make	MERCEDES
QC'd by	27	Model	300SL
Salesman	COTE	Color	RED/BLACK
Division	RE	Miles	0
		Lic.#	

Service Description	Hrs.	Lab\$
INSTALL LEFT AND RIGHT DOOR PANELS AND TOP LEATHER PANELS. INSTALL WINDOW CRANK HANDLES. REPLACE SCREWS AND CUP WASHERS IN DOOR PANELS.		
CLEAN, STEELWOOL AND APPLY LEATHER CONDITIONER TO SUNVISORS AND INSTALL.		
CLEAN, STEEL WOOL AND APPLY LEATHER CONDITIONER TO INTERIOR LEATHER AND SEATS.		
REPLACE WIPER BLADE INSERTS. INSTALL AND ADJUST L&R WIPER BLADES. CHECK OPERATION OF W/S WASHER. CLEAN OUT ALL LINES AND RESERVOIR BAG AND FILL WITH FLUID AND ADJUST NOZZLE		
CLEAN AND LUBE SEAT TRACKS. ASSEMBLE AND INSTALL SEATS INTO CAR. REGLUE LOOSE FELT ONTO SEAT FRAMES		
MOUNT SPARE TIRE ON TO RIM AND INSTALL INTO TRUNK. FIT PLYWOOD TRUNK FLOOR AND RECESS METAL TABS INTO PANEL.		

Qty	Part Number	Part Description	Price
2	180 723 05 24	CHROME EDGING	
6	000 988 38 78	CLIP	
1	000 987 91 40	RUBBER BUFFER	
2	000 997 11 41	O-RING	
1	MIRROR BASE	USED	
1	TOOL KIT TOOLS		
1	FEE	PAINT & MATERIALS	

Additional Items	Sublet or Add'l Services
	INSPECTION STICKER
Total Items	Total Sublets

Recommendations
Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Add. Items
Subtotal
Tax
<b>Total</b>

(Page 2 of 4)

YOUR SATISFACTION IS OUR GREATEST PRIORITY. PLEASE CONTACT US IMMEDIATELY WITH ANY QUESTIONS OR CONCERNS. THANKS FOR SERVICING YOUR CAR WITH HATCH & SON'S RESTORATION.

533 Boston Post Road, Wayland, MA. 01778 508-358-8094















<b>Name</b> Addr.	
<b>Phone</b> B- Name B-Addr.	
<b>B-Phone</b> Alarm data V.I.N. #	198.042.10.002538

<b>Inv. Date</b>	07/03/03	<b>Year</b>	1960
<b>S.O. Date</b>	06/24/03	<b>Make</b>	MERCEDES
<b>QC'd by</b>	27	<b>Model</b>	300SL
<b>Salesman</b>	COTE	<b>Color</b>	RED/BLACK
<b>Division</b>	RE	<b>Miles</b>	27580
		<b>Lic.#</b>	

Service Description	Hrs.	Lab\$
CHANGE OIL, FILTER AND LUBE CHASSIS. CHECK ALL LIGHTS AND TIRE PRESSURES. CHECK AND TOP ALL FLUIDS.		
PERFORM ENGINE SERVICE. R&R IGNITION DISTRIBUTOR, DISSASSEMBLE AND CLEAN. CHECK CENTRIFICAL WEIGHTS AND LUBE DISTRIBUTOR. INSTALL NEW FIBER WASHERS AND OIL SEAL RING. ASSEMBLE AND INSTALL DISTRIBUTOR & INSTALL NEW IGNITION POINTS AND SPARK PLUGS. SET IGNITION DWELL, CHECK AND ADJUST IGNITION TIMING AS NECESSARY. R&R FRONT UNDERSHIELDS		
TOUCH UP WHEEL WELLS WITH BLACK PAINT TO MATCH WHAT IS THERE. WILL MAKE APPOINTMENT TO PAINT WHEEL WELLS BODY COLOR AS ORIGINAL.		
OPEN AND BLOW OUT INTERIOR VENTS. ACCESS FROM ENGINE COMPARTMENT WITH AIR NOZZLE.		
R&R REAR FUEL PUMP AND DISSASSEMBLE. BENCH TEST MOTOR AND CHECK AMP DRAW. REMOVE TOP COVER, CLEAN AND LUBE BEARINGS. DISSASSEMBLE HOUSING AND REMOVE DRIVE GEARS. GEARS		

Qty	Part Number	Part Description	Price
4	85364	TUBE,185/195R15 TR-13	
4	NIP	VALVE STEM SEAL	
8	W/W	FACTORY WHEEL WEIGHTS	
1	915035-000025	COPPER SEAL	
1	1045	OIL FILTER,SPIN ON	
14	OIL	20/50 CASTOL OIL	
1	GREASE	CHASSIS GREASE	
6	003 159 10 03	W9DCO SPARK PLUGS	
4	FIBER WASHER	FIBER WASHER,DISTRIBUTOR	
1	011 997 05 48	SEAL RING	
4	57980	670/R15,MICH X 91S TT	
1	900262-005000	HOSE CLAMP,BERU 5MM	
1	STRAPPING 4MM	STRAPPING 4MM	
2	123 997 16 81	BOOTIE,FUEL PUMP	
1	000 158 10 90	POINT UNIT	

Additional Items	Sublet or Add'l Services
Total Items	Total Sublets

Recommendations
Next service due on: ???

Totals
Labor
Parts
Supplies
Sublets
Addl. Items
Subtotal
Tax
<b>Total</b>

(Page 1 of 2)

YOUR SATISFACTION IS OUR GREATEST PRIORITY. PLEASE CONTACT US IMMEDIATELY WITH ANY QUESTIONS OR CONCERNS. THANKS FOR SERVICING YOUR CAR WITH HATCH & SON'S RESTORATION.









D

1960 300 SL Roadster #  
 19804210002538  
 Invoice # 2150 5-28-06

Work to clean up engine bay leads to removing the engine for nicer looking job. Lots of scaly rust down low as well as dirt/grease.

Remove engine and check over all components. Clutch pressure plate badly grooved and "hot spotted". Release bearing feels terrible. Trans leaks input/output. Driveshaft u-joints loose. Many oil leaks at engine. Rear main seal leaking, need to replace "rope" seal by removing crankshaft.

-Remove oil pan from engine. 2" sludge in front part of casting near oil pump pick-up. Oil pick up nearly plugged with sludge. Inspect oil pump for wear. Remove crankshaft in order to replace the rear main seal. Inspect all main and some rod bearings. Clean out oil pan and replace with new gaskets. Bolt on new clutch pieces.

Replace distributor O-ring

30hr

-Replace transmission seals. Assemble trans to engine

3hr

-Install injection pump and injectors.

2hr

-Replace bearings and seal in fan and replace water pump coupler as original is cracked

3hr

-Remove water jacket cover on side of block to replace gasket. Upon cleaning piece rust holed appear. Repair rust holes, repaint in gold cad look. Replace gasket

4hr

-Degrease engine bay, cross member and suspension arms.

5hr





-“Pull back” entire wiring harness from engine bay to facilitate cleaning/sanding panels. Clean red overspray from all wires. Bead blast all clips and re-paint. Clean and repaint numerous parts for sympathetic “freshen up” of engine bay area. Remove all electrical terminals at junctions to clean and add contact oil. Clean and paint Radiator. Re-paint and re-assemble all pieces.

20hr

Louvered screen in front of radiator is cracked and bent. Straighten and weld. Sand and re-paint

4hr

-Make all heat/vent controls work properly. Lubricate all cables/housing for smooth function

4hr

-Fit K&N air filter into original foam filter housing

1hr

-Remove soft top cover seal and trunk seal for replacement. Spend considerable time to remove all old glue without hurting the paint for proper adhesion of new seal.

Talked to 300SL restorers for proper glue/application. 2 different restorers tell me that this is a 2 day job!!!

15hr

-Assemble engine/trans to car. Re-assemble firewall, interior, radio

20hr

-Replace driveshaft u-joints with proper shims. Install to car and road test. Adjust shims for less vibration.

5h

-Test drive car checking for all functions working properly. Chase coolant leaks at the water jacket. Dial in injection pump and ignition timing.

Two large oil hoses leaking slightly at ends. Remove and replace

1hr

Total hours 114 @ \$... per hour =



QTY. PART NO. AND DESCRIPTION PRICE

1	Fuel Inj Pump Rebuild kit	
1	F-I Diaphragm Vitor	
2	Ext. Pump Combust 386	
6	Reman Plurgers	
6	Injectors Reman	
2	Fan Pilot B&G 6002	
2	Seal Rings Transmiss	
1	Pinion Seal 36mm	
1	Seal - Fan blade	
1	Crank end Sealing Rope	
1	Fan Main Seal Vitor	
1	Release Bearing	
1	Seal Ring Release Bag	
1	Clutch Disc	
1	Pressure Plate Reman	
	Bronze Face Needle Case	
1	Water Pump Coupler Pump	
1	K-N Air Cleaner Element	
2	Lengths Tank Seal-Boot Seal	
2	V-Joint w/shims	
2	Large Oil Hoses S.S.	

(MAY BE CONTINUED ON OTHER SIDE) TOTAL PARTS

ACCESSORIES

1	Inj Pump O-Haul	
1	Starter O-Haul	
1	Generator o-haul	
1	Radiator Core	
	Job w/ Paper M-B Core	

TOTAL ACCESSORIES



RESTORATION & PERFORMANCE

MOTOR CARS

462 Monkton Rd.

VERGENNES, VERMONT 05491

Ph/Fax (802) 877-2645

2150

MEMOR'S ORDER NO.		DATE
WRITTEN BY		PROPOSED
EXT		ODOMETER IN
YEAR, MAKE AND MODEL		ODOMETER OUT
SERIAL NUMBER	MOTOR NUMBER	TERMS

DESCRIPTION OF WORK		AMOUNT
<input type="checkbox"/> LUBE	<input type="checkbox"/> CHANGE OIL	<input type="checkbox"/> OIL FILTER
<input type="checkbox"/> TUNE-UP	<input type="checkbox"/> TRANS.	<input type="checkbox"/> DIFF.
Worksheet attached		

_____ LITERS/GALS. OF GAS ☉	TOTAL LABOR
_____ LITERS/QTS. OF OIL ☉	TOTAL PARTS
_____ kg/LBS. OF GREASE ☉	ACCESSORIES
	GAS, OIL AND GREASE
	SUBLET REPAIRS
	EPA / WASTE DISPOSAL
	TAX
	TOTAL
	THANK YOU

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

SIGNATURE \_\_\_\_\_

SAVE OLD PARTS?  YES  NO

Advance



QTY.	PART NO. AND DESCRIPTION	PRICE
6	1/2" 38.5 Span P/g	
1	Gas Pan Gasket	
1	Water Pump	
1	W/P Seal Ring	
1	Oil Pressure gauge hose	
5	Banding For Cooling Fan	
1	Engine Stalk Kit	
6	Clas Chan/ Degreaser	
1	Paint Blue Primer	
1	Paint Semi Black	
2	Span of 15/16 Rad Hose	
2	Seal 1/2" water hose	
12	Hose Clamps misc sizes	



RESTORATION & PERFORMANCE  
MOTOR CARS  
462 Monkton Rd.  
VERGENNES, VERMONT 05491  
Ph/Fax (802) 877-2645

2100

HP	NO	DATE
RE		11-18-05
CF		PROMISED
		A.M.
		P.M.
HOME PHONE	BUS PHONE	EXT.
		ODOMETER IN
YEAR, MAKE AND MODEL	LICENSE NUMBER	ODOMETER OUT
SERIAL NUMBER	MOTOR NUMBER	TERMS
	19804210002530	

DESCRIPTION OF WORK	AMOUNT
<input type="checkbox"/> LUBE <input type="checkbox"/> CHANGE OIL <input type="checkbox"/> OIL FILTER <input type="checkbox"/> TUNE-UP <input type="checkbox"/> TRANS. <input type="checkbox"/> DIFF.	
Check over - Car Runs "Slappy" Work To Clean/detail engine Bay, Water pump Seals And/ Lots of Leaks around bottom of Radiator. Send Off Gen/Radiator For O-rings Send Inj Pump With injectors For Check over Replace all water Hose Clamps Valve Adj Check Distributor	30 hr 460

(MAY BE CONTINUED ON OTHER SIDE)	TOTAL PARTS		
ACCESSORIES			
TOTAL ACCESSORIES			

_____ LITERS/GALS. OF GAS ☉	TOTAL LABOR
_____ LITERS/QTS. OF OIL ☉	TOTAL PARTS
_____ kg/LBS. OF GREASE ☉	ACCESSORIES
	GAS, OIL AND GREASE
	SUBLET REPAIRS
	EPA / WASTE DISPOSAL
	TAX
SAVE OLD PARTS? <input type="checkbox"/> YES <input type="checkbox"/> NO	TOTAL
SIGNATURE	THANK YOU

*inj Pump Shipping*

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.



ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

**FOREIGN AUTO TECH, INC.**

No. 6151

12 PAUL GORE STREET  
P. O. BOX 125  
JAMAICA PLAIN, MA 02130  
(617) 500 7000

(WK) 8-10-00

①

QUAN.	PART NO.	DESCRIPTION	SALE AMOUNT
6		1/2 hose clamp	
4		3/4" hose clamp	
1		hose	
1		rubber Grommet	

NAME:

ADDRESS:

CITY:

STATE:

ZIP:

YEAR:

MAKE:

MODEL:

SERIAL NUMBER:

LICENSE NUMBER:

COPIES:

60

M-B

3005L

5L1960

28445

REPAIR ORDER - LABOR INSTRUCTIONS

ORDER WRITTEN BY

TUNE-UP  LUBRICATE  CHANGE OIL  FLUSH RADIATOR  BRAKES SHOCKS  TIRES  WASH POLISH  \$

- Remove Air Filter + Air Box
- Replace upper-Radiator hose clamps + water tank hose clamps
- Install rubber Grommet in Generator wiring harness bracket.
- Replace Oil cooler by-pass hose with original type hose
- Make up and install bracket to anchor left upper Radiator support

Remove wiring from Generator + magnet for wiring job

190/180 jets

H-508-785-2247

617-610-5007 cell

Chess. # 002638  
Eng. # 002591

610

RETAIN PARTS  DESTROY PARTS

TOTAL PARTS

ESTIMATE AMOUNT	PARTS LABOR
ADD'L. AUTH. AMT.	TIME BY
ADD'L. AUTH. AMT.	
ADD'L. AUTH. AMT.	
ESTIMATE TOTAL	

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERE TO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.

AUTHORIZED BY \_\_\_\_\_

RECEIVED BY \_\_\_\_\_

GAL. GASOLINE @	
QTS. OIL @	
LBS. GREASE @	
TOTAL GAS - OIL - GREASE	

TOTAL LABOR

TOTAL PARTS

GAS, OIL, GREASE

OUTSIDE WORK

STATE TAX

TOTAL AMOUNT

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. THE SELLER (ABOVE NAMED DEALERSHIP) HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.



FOREIGN AUTO TECH, INC.

No. 6155

12 PAUL GORE STREET

P. O. BOX 125

JAMAICA PLAIN, MA 02130

(617) 522-7863

NAME

DATE

ADDRESS

TIME RECEIVED

TERMS

A.M.

P.M.

TIME PROMISED

CUSTOMER'S PHONE

A.M.

P.M.

NO.

CITY

STATE

ZIP

YEAR

MAKE

MODEL

SERIAL NUMBER

LICENSE NUMBER

ODOMETER

10

M-B

300SL

## REPAIR ORDER - LABOR INSTRUCTIONS

ORDER WRITTEN BY

TUNE-UP LUBRICATE CHANGE OIL FLUSH RADIATOR BRAKES SHOCKS TIRES WASH POLISH 

\$

Engine Area- Remove spark plugs - threads  
carboned up- Remove Valve cover to adj. valves  
& access spark plug holes in head

- clean &amp; thread - check spark plug holes

- Properly torque Camshaft Gear  
anchor bolt

- check &amp; adjust Valve Clearance

- check Timing Chain Guide  
rails and chain tension (415)RETAIN PARTS DESTROY PARTS 

## TOTAL PARTS

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THEREON. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.

TOTAL LABOR

ESTIMATE AMOUNT

PARTS  
LABOR

TOTAL PARTS

ADD'L. AUTH. AMT.

TIME

BY

GAS, OIL, GREASE

ADD'L. AUTH. AMT.

AUTHORIZED BY \_\_\_\_\_

OUTSIDE WORK

ADD'L. AUTH. AMT.

RECEIVED BY \_\_\_\_\_

GAL. GASOLINE @

QTS. OIL @

LBS. GREASE @

TOTAL GAS - OIL - GREASE

STATE TAX

TOTAL AMOUNT

ESTIMATE TOTAL

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. THE SELLER (ABOVE NAMED DEALERSHIP) HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSURES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.

②

last 1/4 inch  
of cyl. head  
spark plug threads  
were badly clogged











12 PAUL GORE STREET

P. O. BOX 125

JAMAICA PLAIN, MA 02130

(617) 522-7863

5

NAME

DATE

ADDRESS

TIME RECEIVED

TERMS

A.M.

P.M.

TIME PROMISED

CUSTOMER'S PHONE

A.M.

P.M.

NO.

CITY

STATE

ZIP

YEAR

MAKE

MODEL

SERIAL NUMBER

LICENSE NUMBER

ODOMETER

10

M-B

3005L

## REPAIR ORDER - LABOR INSTRUCTIONS

ORDER WRITTEN BY

TUNE-UP LUBRICATE CHANGE OIL FLUSH RADIATOR BRAKES SHOCKS TIRES WASH POLISH 

\$

Injection

Inj. pump timing off. Perform full glow timing procedure

Remove return line check valve - Adjust spring tension + Replace end cap for proper sealing

Re-route fuel return flex hose

check all fuel fittings and connections

4.5

RETAIN PARTS DESTROY PARTS 

TOTAL PARTS

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIAISON IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THEREON. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.

TOTAL LABOR

ESTIMATE AMOUNT

PARTS LABOR

TOTAL PARTS

ADD'L. AUTH. AMT.

TIME

BY

GAS, OIL, GREASE

ADD'L. AUTH. AMT.

AUTHORIZED BY \_\_\_\_\_

OUTSIDE WORK

ADD'L. AUTH. AMT.

RECEIVED BY \_\_\_\_\_

GAL. GASOLINE @

QTS. OIL @

LBS. GREASE @

TOTAL GAS - OIL - GREASE

STATE TAX

TOTAL AMOUNT

Injection pump drive shaft installed improperly booties O.K.

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. THE SELLER (ABOVE NAMED DEALERSHIP) HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.



12 PAUL GORE STREET  
P. O. BOX 125  
JAMAICA PLAIN, MA 02130  
(617) 522-7863

NAME

DATE

ADDRESS

TIME RECEIVED

TERMS

A.M.

P.M.

TIME PROMISED

CUSTOMER'S PHONE

A.M.

P.M.

NO.

CITY

STATE

ZIP

YEAR

MAKE

MODEL

SERIAL NUMBER

LICENSE NUMBER

ODOMETER

60

MB

300SL

## REPAIR ORDER - LABOR INSTRUCTIONS

ORDER WRITTEN BY

TUNE-UP LUBRICATE CHANGE OIL FLUSH RADIATOR BRAKES SHOCKS TIRES WASH POLISH 

\$

Ignition + Distributor

— Remove Distributor + bench check  
— points, conds. Fine-mechanical  
advance return gears work

— Dist. drive gear ① tooth off.  
Pull alum. dist. mount to  
align shaft properly

— Dist. Cap + wires are arcing voltage?  
Rotor is internally burned. Replace  
Cap + Rotor - Recodition ignition  
wiring harness complete.

RETAIN PARTS  DESTROY PARTS 

TOTAL PARTS

TOTAL LABOR

ESTIMATE AMOUNT

PARTS  
LABOR

TOTAL PARTS

ADD'L. AUTH. APT.

TIME

BY

GAS, OIL, GREASE

ADD'L. AUTH. APT.

ADD'L. AUTH. APT.

OUTSIDE WORK

ESTIMATE TOTAL

GAL. GASOLINE @

QTS. OIL @

LBS. GREASE @

TOTAL GAS - OIL - GREASE

STATE TAX

TOTAL AMOUNT

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. THE SELLER (ABOVE NAMED DEALERSHIP) HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.







