METRIC MOTORS, INC.

REMANUFACTURED MERCEDES-BENZ ENGINES

7630 Alabama Ave. Canoga Park, CA 91304

tel: 818-712-9881 fax: 818-712-9932

metricmotors@earthlink.net


800-622-6867

www.mercedesengines.net



INVOICE

DATE '	INVOICE #		
4/6/2018	22531		



3.5 QTY.	PART#	3.5 (M	DEL	4/12/2018	244	116,980-12-		O06025
		3.5 (M		DESC				
11	l6-LB	3.5 (M		DESC	RIPTION		COST	AMOUNT
		REBUI ENG#: per ch COMP INCLU RINGS LIFTE	116.980-12- passi #: 111 0 PLETELY R JDE ALL M J, BEARING RS, WATER	PRIGINAL AS 006025 026 12 004445 EMANUFAC ACHINE WO S, OIL PUMF R PUMP, GAS	TURED PER WEBSI RK PLUS NEW: PIS P, CHAINS, RAILS, V SKET SET ETC.	9,250.00	9,250.00	
MI	INCLUDES TRANSPORTATION CREDIT NEW PARTS SALAVAGED FROM OTHER "REBUILT" LONGBLOCK. PISTONS, OIL PUMP, SOME VALVES, RAILS AND TENSIONER				R SOME	-1,800.00	-1,800.00	
MISC. CREDIT: NEW PARTS MISC: 6.3 PISTONS, BALL CORE BITS			.3 PISTONS, BALL	STUDS,	-3,800.00	-3,800.00		
MISC. CREDIT GOOD WILL					-400.00	-400.00		

*CODE N-NEW U-USED R-REBUILT OTY * PART NO. OR DESCRIPTION N INCEAN VALLE RAD SENSOR GASKET		Independent Mercedes Benz Dept. Since 1295 Rollins Road Since 1979 BURLINGAME, CA 94010-2416 Promised A.M. Phone when (650) 343-8858 Fax (650) 343-9261 EPA #CAL 000398238 BAR # ARD275257 Home Phone Cell Phone 4/5 9 7/ 3	ready No E Discard INITIAL INITIAL
		REPAIR ORDER — LABOR INSTRUCTION CAR TOWER IN — WORLE— CHECK FUEL PRESSURE - 29 PSI— CHIECK COMPRESSION FOUND 1/7/E AIR VALUE STUCK OPEN, RUSS VERY RICH REPAIR ORDER — MAP SECUS OR	LABOR CHG.
TOTAL PARTS TIRE PRESSURE CHECK SERVICE COMPLETED 8 TIRE PRESSURE: LF RF LR RR DECLINED 8 Initial REASON: SUBLET REPAIRS	1414 80 0 _ (psi)	WARRANTY ON PARTS & LABOR 3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST. 9 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST. 1 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 1 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 2 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 3 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 3 NOT GUARANTEED - NEED ADDITIONAL SERVICE(S). WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT. WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT. WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT. WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT. WERLICLE IS NOT PICKED UP AFTER 49 HRS OF COMPLETION OF REPAIRS QTS. OIL QTS. OIL QTS. OIL GREASE TOTAL LABOR A PARTS SUBLET REPAIRS OIL & GREASE GAS SALES TAX WARRANTY WORK MUST BE COMPLETION OF REPAIRS THE PARTS SUBLET REPAIRS OIL & GREASE GAS SALES TAX WARRENING OF VICINITY AND DOES NOT BE SOME AND	100 /