

1960 PORSCHE

Ex - .006" 5LL 22774 Corvan New plugs
 IN - .004 7-15-66 23596 OIL & FILTER CD2
 PLUGS - .025 11-16-66 24150 GREASE JOB
 POINTS - .016"

Corvan 10694 12-7-62 - The Works
 11944 5-4-63 - "
 13136 8-23-63 - "
 14323 1-11-64 " " New plugs, file gear
 15467 5-8-64 " " "
 18950 10-20-64 " " CD2 IN OIL
 17896 2-21-65 " " CD2 IN OIL
 18733 5-18-65 " " CD2 IN OIL
 10801 8-21-65 " " NEW BATT 4/21/66
 20316 10-7-65 OIL CH.
 22166 3-20-66 OIL CH LUBE

| DATE LUBE | 1500 | | 3000 | | | | 6000 | | REMARKS | |
|-----------|-----------------|------------|------------------|-----------|-----------------|---------------|-------------|----------------------|------------|--|
| | CHASSIS LUBE | OIL CHANGE | CK TRANS | BATT | VALVES | TLP TOE IN | BRAKE FLUID | OIL FILTER | | PACK WHEELS |
| 5-5-60 | 333 | 333 | CHANGE 354 | 354 | 333 | 391 | 391 | - | 391 | NEW PLUGS - 777 |
| 6-24-60 | 949 | 949 | - | - | - | - | 949 | - | - | - |
| 11-13-60 | 1451 | 1451 | CHANGE 1451 | 1451 | 1451 | 1451 | 1451 | - | - | Wash wa. 2039 12/4/60 |
| 1-14-61 | 3143 | 2945 | 3143 | 3143 | 2633 | - | 3143 | - | - | - |
| 3-11-61 | MOS. CHECK 4588 | - | - | - | 4034 | - | - | 5TTO | - | #4 EX VALVE - 2 MILS - 4100 |
| 5-9-61 | 5979 | 5979 | 6045 | 6020 | 6077 | TLP 6020 | 5979 | SCREEN & MAGNET 5979 | 6020 | PTS & TIMING (FILE & CHK) CK plugs 5928 Fix ODO 7800 |
| 6-24-61 | 7345 | - | - | - | - | - | - | - | - | - |
| 8-26-61 | 8846 | 8159 | 8846 | 8846 | - | TLP OK 8846 | - | - | - | 9044 ADJ PLUGS & PTS 9548 LUBE DOOR MECHANISM 9625 NEW PLUGS (10/17/61) |
| 10-12-61 | 103487 | - | - | - | - | - | 103487 | - | - | 10192 MOS2 IN OIL 103487 DOOR WINGES 990 |
| 11-13-61 | 11284 | 11284 | clean plug 11284 | 11284 | - | - | 11284 | 11284 | - | - |
| 1-10-62 | 13124 | 13124 | - | - | ALL SPEC. 13725 | - | 13124 | - | - | START SERIES OIL 13124 FILE PTS & TIME CK STEERING BOX 1516 |
| 3-18-62 | 15156 | - | - | 15156 | - | SET TLP 15156 | 15156 | - | 15156 | - |
| 5-7-62 | 16571 | 16571 | clean plug 16571 | 16542 | - | - | - | - | - | GAP PLUGS 17024 |
| 6-25-62 | 17924 | - | - | - | - | - | - | - | - | - |
| 8-25-62 | 19581 | 19581 | 19051 | 18851 | - | TLP 18406 | 18851 | 19581 | CKWB 18406 | URGENT BRAKE CAPS 18067 |
| 10-6-62 | 20701 | - | - | NEW 20362 | - | TOE IN 18851 | 19581 | - | - | Receipts, approx 19000 FILE PTS & TIME 19681 |
| 1-19-63 | 22166 | 22166 | clean plug 22166 | 2192 | - | - | - | - | - | LUBE THROTTLE LINKAGE NEW AIR FILTER 21431 20205 NEW PLUGS - FILE PTS - TIME 21792 - WAX JOB |
| 4-7-63 | 23359 | - | - | - | - | - | 23359 | - | - | NEW CLUTCH - BOOTS - 24107 |
| 6-13-63 | 24508 | 24508 | 24158 | 24508 | - | TLP 24508 | 24508 | - | - | CK STEERING BOX 24508 WAX - 24828 |
| 9-2-63 | 26036 | - | - | - | - | - | - | 26036 | - | FILE PTS - TIME 26036 |
| 10-11-63 | 27580 | 27580 | 27580 | 27580 | 27580 | - | 27580 | - | - | - |
| 1-5-64 | 29047 | 29047 | - | - | - | TLP 29047 | - | - | - | { Bal carl cool pumps inject new plugs 29113 |
| 4-12-64 | 30593 | - | CHANGE 30593 | 30593 | - | - | 30593 | - | - | FILE STEER BOX - MOS2 IN TRANS LUBE - GREASE BRAKE CABLES 30593 |
| 7-13-64 | 31381 | 31381 | - | - | - | - | 31381 | 31381 | - | WAX 31349 9-22-64 FRONT SHOCKS 31381 CK TIMING 31381 REAR SHOCKS 32161 |
| 10-13-64 | 32881 | - | 32881 | 32881 | - | - | 32881 | - | - | WAX 33802 |
| 1-10-65 | 34232 | 33719 | - | - | - | - | - | - | - | INCR INJ PUMPS AT ON TURNBUCKLE (SHORTER) CK TIMING 34232 AIR FILTERS NEW 34232 GAP PLUGS 34762 CK CLEAN PTS |
| 4-25-65 | 35257 | 35257 | 35257 | 35257 | - | - | - | SCREEN & MAG 35257 | - | LUBE MOTOR SAID LUBES SPEEDO CABLES NB - 35257 NEW BATT |
| 7-15-65 | 36575 | - | - | 36688 | - | - | 36575 | 36575 | 36688 | - |

PO + 2491A4

1960 PORSCHE
 EX. .006"
 IN. .004"
 PLUGS .025"
 POINTS .016"
 FILTER C3 FRAM

MICHELINS
 24F 24R
 (19-22 normal)
 MICH (PORSCHE CLUB) F8-21 FOR 165-15X

TOE IN FRONT .020" - .090"
 TOE IN REAR +.024" - -.024"

OHV II PLUGS NEW
 9-13-69 4000 57857
 39700
 18157

| DATE LUBE | 1500 | | 3000 | | | | | 6000 | | REMARKS |
|-----------|-----------------|----------------|--------------------------------------|--------------|------------------|--------------------------------|--------------------------------------|---------------|----------------|---|
| | CHASSIS MILE | OIL CHANGE | CK TRANS | BATT | ADJ VALVES | TLP & TOE-IN | BRAKE FLUID | OIL FILTER | PACK WHEELS | |
| 11-21-65 | 37950 | 37950 | 35257 | NEW 37869 | 37950 | 38223 | 37950 | 36595 | 38223 | INSPECT FRONT BRAKES 38223 - LIKE NEW CLEAN FUEL TANK LUBE 4 MICH X 39700 39129 |
| 3-19-66 | 39500 | 39500 | - | 39500 | - | - | 39500 | - | - | NEW 45FAL PLUGS 40781 WAY 41683 NEW CLUTCH CABLE 42600 |
| 7-10-66 | 41053 | 41053 | 41053 | 41053 | - | TOE IN 1/32 - 1/16 39921 | - | - | - | WAY 43060 SET AT GAP 44444 - REPLACE PETS STP OIL 45324 STP OUT 45324 ADJ BRAKES 45324 |
| 11-27-66 | 42600 | 42600 | - | 42600 | - | - | 42600 | 42600 | - | X TIRES 45524 ADV SPARK 45426 WAY 46088 7-10-67 CK REAR TOE IN = 0 46136 |
| 3-11-67 | 44144 | 44144 | - | 44144 | - | - | - | - | - | STP OIL 45324 STP OUT 45324 ADJ BRAKES 45324 |
| 5-27-67 | 45524 | 45524 | CHANGE 45397 | 45524 | #4 .004 | - | - | - | - | X TIRES 45524 ADV SPARK 45426 WAY 46088 7-10-67 CK REAR TOE IN = 0 46136 |
| 9-30-67 | 47073 | 47073 | - | 47073 | - | - | 47073 | - | - | NEW BATT 48265 |
| 12-22-67 | 48487 | 10-30 48111 | 48487 | 48265 | - | TLP 48487 | 48487 | - | ADJ LF | - |
| 3-22-68 | 49932 | 49932 | 49932 | 49932 | - | - | - | - | - | - |
| 6-8-68 | 51436 | 51436 | - | 51436 | - | TOE IN 51436 | - | 51436 | - | + TURN - FRONT SPRINGS NEW AIR FILTERS 51436 REVERSE TIRES ON WHEELS 52717 |
| 9-14-68 | 52717 | 52717 | 52717 | 52717 | - | - | 52717 | - | - | INSP & CLEAN FRONT BRAKES EXC SHAPE (SLIGHT) GAP PLUGS .055 51647 NEW PLUGS 55420 .025" |
| 11-8-68 | 54000 | 54000 | - | 54000 | - | - | - | - | 54000 | NEW POINTS 56029 - TIME 2-165-15 MICH X oil 57857 (10/31) BACK |
| 2-22-69 | 55656 | 55656 | - | 55656 | - | - | 55656 | - | - | NEW VALVE COVER GASKETS & OIL COOLER SCALES |
| 5-24-69 | 57175 | 57175 | 57175 | 57175 | #4 .004 | TLP | - | - | - | NEW CLUTCH DISC SPRING & T.O. BEARING. LUBE ALL LINKAGES RECAPS (HOOVER) ON FRONT. 10/32" NEW RETAR ENG WEATHERSTRIP |
| 7-25-69 | 58519 | 58519 | - | 58519 | 58519 | 58519 | 58519 | - | - | ELEC IGN 59346 PLUGS .040" ELEC PTS 59346 FILE PTS - TIME 59952 |
| 8-22-69 | - | - | CLEAN MAG PLUG 59027 & FILL | - | - | - | - | - | - | REMOVE CLUT IGN 63000 |
| 12-20-69 | 59952 | 59952 | - | 59952 | - | - | - | 59952 | - | 67003 GAP PLUGS .025" FILE PAINTS |
| 3-21-70 | 61487 | 61487 | - | 61487 | - | - | 61487 | - | - | - |
| 6-13-70 | 62938 | 62938 | 62938 | 62938 | - | TLP 62938 | - | - | - | - |
| 9-28-70 | 64633 | 64633 | - | 64633 | - | - | - | - | - | - |
| 12-5-70 | 66203 | 66203 | - | 66203 | - | - | - | - | - | - |
| 2-20-71 | 67636 | 67636 | 67636 | 67636 | - | - | CLEAN MASTER CYL 1/32 67636 | - | - | - |
| 5-1-71 | 68909 | - | - | 68909 | - | - | - | - | - | INSPECT RF - OK 68909 |
| 8-15-71 | 70351 | 69516 | - | 70351 | - | TOE IN & TLP 70351 | - | - | - | X TIRES 68909 INSP BRAKES RF - EXC (9265) - WAX JOB 71168 NEW PLUGS INSPECT FRONT TIRES 717 |
| 10-24-71 | 71759 | 72027 | 71759 | 71759 | #4 .004 72027 | - | 71759 | - | - | NEW AIR FILTS 72 |
| 12-5-71 | 72843 | - | - | 72843 | - | - | - | - | - | RETIME 73671 |
| 1-17-72 | 74155 | 10-30 73671 | - | 74155 | - | TLP 73671 | - | 73671 | - | - |

1960 PORSCHE
 EX. .006" } Mmm-
 IN. .004" } WRENCH
 PLUGS .025" - ~~3/32~~
 PTS .016"
 FILT C3FRAM

TOE-IN FRONT .020" - .090"
 TOE-IN REAR .024" - .024"
 TIRES 24F 26R (19-22 NORMAL) MICH.
 MICH (PORSCHE CLUB) (18-21)
 CHAMPION L88A
 AC 45F PLUGS
 CHAMP L85

AUSTIN-15527 OIL-LUBE-TOE
 AUSTIN-15290 REPAIR PLUGS
 1966 OIL LUBE FILT TOE IN
 20465 ADD IGN TIMING - BRACKES
 21223-OIL, LUBE, GAP PLUGS, ROTATE TIRES
 24722-TRAINING REAR BRAKES SHOE
 RANDED.
 23728-PLUG SMOG PUMP-NEW DISC DADS
 24000-ROTATE TIRES, CHANGED
 PLUGS, GAD PONS
 ADJ TOE IN
 24700 OIL AND LOBE

PAN = 19MM WRENCH
 XMISSION = 19MM WRENCH

| DATE | 1500 | | CHECK TRANSMISS. | BATT | 3000 ¹⁴⁷ MM | | BRAKE FLUID | 6000 OIL FILTER | REMARKS |
|----------|--|---------------|---------------------|--------|------------------------|---------------|----------------|-----------------------|--|
| | CHASSIS LUBE | OIL CHANGE | | | ADJ VALVS | TLP TOE-IN | | | |
| 2-17-72 | 74155 | 73671 | 71759 | 74155 | 72027 | 73671 | 71759 | 73671 | NEW AIR FILTS 72843 MURRAY MICH RETAPS FRONT 77000 |
| 5-12-72 | 75740 | 75478 | - | 75740 | - | - | - | - | ② 155-15 1932" 9-4-72 |
| 10-6-72 | 77591 | 77591 | - | 77165 | - | - | - | - | ② 165-15 10/32" 9-18-72 77210 CK GEN BRUSHES OK 77591 BACK |
| 1-7-73 | 78904 | 78904 | - | 78904 | - | - | 78904 | - | CHAMPION L88A PLUGS .020 77591 WAX JOB 78796 CYCLEBAT 78796 |
| 3-14-73 | 80115 | 80115 | - | 80015 | - | - | - | - | 79439-33" FAN BELT INSTALL / OFF MAIL 80478-LUBE BOTH DOORS & COAT INSIDE WITH UNDERSEAL |
| 6-10-73 | 81640 | 81610 | 81610 | 81610 | - | 81610 | 81610 | 81610 | 81610-OLD OIL FILT NOT DIRTY REMEET CRACKED BATTERY TAR NEW 45F PLUGS 82629 8/26/73 COMP CHECK ROT 115-120-113-130 |
| 9-7-73 | 82951 | 82951 | - | 82418 | 82629 | 82951 | 82951 | - | CLEAN RECARB - GEN BRUSHES OK CLEAN ALL SCRAPERS IN FUEL LINE FUEL PUMP FLOW OK 10/4/83 |
| 10-2-73 | 85138 | 85138 | 85138 | 85138 | 85138 | - | 85138 | - | NEW .006 OVERHAUL: NEW GEN BRUSHES - NEW POINTS - KNURL GUIDES - GRIND VALVES - NEW FUEL PUMP RING GAP .002 OVER NEW RINGS - CLEAN CARBS - LUBE HEATER & THROTTLE LINKAGES. L85 PLUGS NEW AXLE BOOTS NEW BATT 5YR SET FUEL PUMP TO 2 PSI |
| 10-2-73 | OVERHAUL: NEW GEN BRUSHES - NEW POINTS - KNURL GUIDES - GRIND VALVES - NEW FUEL PUMP RING GAP .002 OVER NEW RINGS - CLEAN CARBS - LUBE HEATER & THROTTLE LINKAGES. L85 PLUGS NEW AXLE BOOTS NEW BATT 5YR SET FUEL PUMP TO 2 PSI | | | | | | | | |
| 12-15-73 | 86456 | - | 86456 | 86456 | 86108 | - | - | - | |
| 3-9-74 | 87841 | 87161 | - | 87841 | 87541 | - | - | - | |
| 7-12-74 | 89366 | - | 89958 | 89366 | - | - | 89366 | - | TIGHTEN AXLE BOOT 89958 LEFT CHANGE LR BOOT |
| 9-21-74 | 90716 | 90716 | - | 90405 | - | 90716 | - | 90716 | RR WHEEL CYL REBUILD 91038 |
| 11-20-74 | 92244 | - | - | 92244 | - | - | 92244 | - | |
| 2-15-75 | 93703 | 93703 | - | 93703 | - | - | - | - | L85 PLUGS (WERE NEW 85138) GAP PLUGS - NEW #3 93703 ADJ PAN BELT 95106 |
| 5-3-75 | 95106 | 95106 | 95106 | 95106 | - | - | 95106 | - | |
| 8-9-75 | 96608 | 96608 | - | 96608 | 96608 | - | - | - | NEW RIGHT REAR BOOT 97587 4 MICH ZX 165SR15 9/32 CTR 10-18-75 97557 |
| | | | CLEAN MAGNET | 97587 | 97557 | - | 10-18 | 97557 | |
| 12-2-75 | 98293 | 98293 | - | - | - | - | - | - | |
| 2-22-76 | 100071 | 99570 | - | 99570 | - | - | - | - | TIRES 25/32 98485 12/13/75 1 QC 98615 ADV TIMING 99062 1 QC 99062 NEW L87 PLUGS 1 QC 99062 ADJ SPARK 20 (C) 99570 99326 ADJ CLUTCH FREE PLAY 99570 RESET NORMAL SPARK 101131 1/32" TOE IN 2628 |
| 5-15-76 | 101131 | 101131 | - | 101131 | - | - | 101131 | 101131 | NO DIRT! |
| 8-5-76 | 2628 | 2628 | - | 02280 | - | 2628 | - | - | |
| 11-24-76 | 4137 | 4137 | - | 4137 | - | 4137 | 4137 | - | |
| 1-8-77 | 5604 | 5604 | - | 5604 | - | - | - | - | 5727 ELECTRONIC INSTALL GAP L87Y PLUGS TO .040 6825X TIRES - FRONT BRACKES 1/3 WORN - ADJ BRAKES |
| 3-4-77 | 6900 | 6900 | 1PT | 6900 | 6900 | 6900 | 6825 | - | |
| 3-27-77 | | | | | 7278 | | | | NEW PAN BELT TIRES 18/21 7399 |

1960 PORSCHE

EX = .006" } 14 mm
 IN = .004" } WRENCH
 PLUGS = .025"
 PTS = .016"
 PAN & XMISSION = 19mm (3/4")
 TOE IN FRONT = .020"-.090"
 TOE IN REAR = ±.024"

TIRES 24F 26R
 (19-22 NORMAL)
 MICH (PORSCHE CLUB) (18-21)
 PLUGS = CHAMP L85
 OIL FILT FRAM C3-R

7/8"
 WRENCH

| DATE | 1500 | | 3000 | | | | 6000 | REMARKS | |
|----------|---|------------|------------------|-------------------------------|------------------|------------------------|--------------|----------------------------|---|
| | CHASSIS LUBE | OIL CHANGE | CHECK XMISSION | BATT | ADJ VALVES | TLP & TOE-IN | BRAKE FLUID | | OIL FILTER |
| 3-4-77 | 6900 | 6900 | 6900 | 6900 | #4E=.004 7278 | TLP 6900 | ADJ 6825 | NO DIRT 1131 | ELEC. IGVN ~ 7900 - |
| 5-28-77 | 8500 | 8500 | 8500 | 8500 | - | - | - | - | 45F AC PLUGS (USED) 1040" GAP ADD RRAY 9500 9-25-77 |
| 11-21-77 | 9909 | 9909 | - | 9909 | - | - | 9909 | - | 24/26 PSI 9909 PLUGS .027" 10087 REMOVE ELEC IGVN 12134 |
| 1-29-78 | 11526 | 11526 | 11526 | 11526 | - | TLP+TOE-IN 10986 | 11526 | - | ADJ CLUTCH 12134 24/26 PSI NEW WINDSHIELD 12397- |
| 4-29-78 | 12972 | 12972 | - | 12972 | - | TLP LEFT 12972 | - | - | TIRES 24/26 PSI NEW AIR FILTS 13382 |
| 9-3-78 | 14469 | 14469 | - | 14469 | 15088 | TLP LEFT FILL 15056 | 14469 | 14469 | 16527 - X TIRE - NEW SPEEDO CABLE 24/26 PSI |
| 12-16-78 | 16066 | 16066 | - | 16066 | - | OK 16066 | - | - | |
| 4-20-79 | 17487 | 17487 | 17487 | 17487 | - | - | - | - | |
| 8-20-79 | - | - | - | 17762 | - | - | - | - | FILL BATT 10-19-79 + 12-23-79 + 2-21-80 ON BATT CH. ~ 35 ma @ 6.6V |
| 6-29-80 | 18306 | 18306 | 18306 BUTS OK | 18306 | - | - | - | - | FILL BATT 5-8-80 / 6-29-80 / 1-12-81 ADD IQ# 18602-19067 / 4-20-81 ADJ CLUTCH 18695 1-17-81 |
| 4-15-82 | 20325 | 20325 | - | 20325 | - | TLP LEFT OK 20325 | 20325 | - | FILL PTS - CK TIMING 8-19-81 19504 FILL BATT 11-1-81 FILL BATT 9-11-82 |
| 4-10-86 | 20818 | 20818 | 20818 NEW | 20818 | 20818 | BOTH SIDES OK 20818 | 20818 | - | FILL BATT 12-20-82 FILL BATT 5-5-83 FILL BATT 10-13-83 FILL BATT 3-9-84 FILL BATT 9-10-84 / 12-29-84 / 11-9-85 20818 40.8 NEW BATTERY |
| 4-10-86 | NEW RINGS, NEW MUFFLER, NEW OIL COOLER, NEW BATTERY | | | | | | | | NEW L85 PLUGS, CK TIMING 20818 |
| 2-18-89 | - | 21220 | - | 21225 21101 | - | - | - | - | 21965-6-24-87 FILL BATT WATER 21965-11-18-87 FILL BATT WATER 21101-11-1-88 FILL BATT WATER 21225-2-28-89 FILL BATT WATER 21418-10-16-89 FILL BATT WATER |
| 6-27-90 | - | - | - | 21499 NEW BATT 24" GUAR | - | - | - | - | 21499 - NEW BATT 6-27-90 21638-1-27-91 CK BATT, 3/8" OK - FILL ALL TIRE |
| 3-28-91 | - | - | ADD 21651 | 9-8-91 21693 | - | - | - | NO DIRT 8-3-91 21690 | 21693-9-8-91 FILL BATT 21706-11-15-91 TIRE 21-24 |
| 11-21-91 | 21731 | 21731 | 21731 OK | 3-2-92 21731 | - | - | ADD 21731 | - | 21740 3-2-92 FILL BATT CK TIRE 24/26 21800 5-1-92 CK TIRE - ADJ FRONT BRKES 21876 5-7-92 REAR LF UPPER WHEEL CYL |
| 10-10-92 | - | - | OK 22067 | 10-10-92 22067 | - | - | - | - | 10-10-92 FILL BATT 22067 TIRE 23/26 24 SPARE 10/10/92 22080 TIRE 23/26 25 SPARE 5/11/93 |

| <u>Date</u> | <u>Mileage</u> | <u>Description</u> |
|-------------|----------------|--|
| 5/12/93 | 22,080 | Drove car home; noise from left front. |
| 5/14/93 | 22,150 | Replaced front shocks (\$230). Saved old ones. |
| 8/5/94 | 22,900 | Inspect & adj. brakes |
| 8/20/94 | 22,950 | Replaced rear shocks (\$230), saved originals. Replaced master cyl (\$100), flushed brake lines. Washed & polished, added H ₂ O to battery. Checked oil, adj. clutch @ pedal. Tires 24/28. Inspect brakes. |
| 8/27/94 | 23,000 | Drove to Laguna Seca. |
| 9/15/94 | 23,152 | New L.F. TS sense + gasket (\$15) |
| 11/11/94 | 23,175 | New Koni st. damper (\$100). Checked st. box fluid (OK). Saved original damper. |
| 8/20/95 | 23,328 | Cleaned battery; added H ₂ O |
| 11/15/95 | 23,433 | Inspect brakes (again; pulls hard right). LF upper cylinder leaking severely, lower cylinder frozen. Inner ^{LF} wheel brng. slightly pitted, outer OK. |
| 12/20/95 | 23,433 | Replaced LF upper (\$100) & lower (\$100) wheel cylinders, LR wheel cylinder (\$55) inner & outer wheel bearings (\$35) brng. seal (\$10), LF rubber brake line (\$30). Cleaned shoes w/ solvent & torch. Kept orig. parts. |
| 1/7/96 | 23,433 | Replaced RF upper (\$100) & lower (\$100) wheel cylinders, RF rubber brake line (\$30) inner & outer wheel bearings (\$35) bearing seal (\$10). Adj. LF & RF brakes. Pulled hard to right left @ first, evened out @ \approx 5 miles. |
| 4/8/96 | 23,460(?) | Vapor lock on first tank of higher O ₂ fuel. Hot day (85°). Towed to Oakland. |
| 4/21/96 | 23,470 | Checked fuel pump pressure (2.6 PSI) & output (750 cc @ 4500 RPM for 1 minute). Shielded fuel lines. Drove home from Oakland @ 80 MPH. No vapor lock, restarted OK after 2-min shutdown. |
| 5/4/96 | 23,530 | New battery (\$55) |

| <u>Date</u> | <u>Mileage</u> | <u>Description</u> |
|-------------|----------------|---|
| 6/9/96 | 23,596 | Change oil (Castrol 10-40w), filter (MAHLE OX-79), adj. valves (1 & 2 in & ex. tight), clean plugs (rich but not fouled) & gapped @ .025. Checked dwell (56°), timing (5° BTDC). |
| 9/18/96 | 23,705 | Changed points (#8), plugs (BOSCH W7BC, #9), rotor (#7), condenser (#7), plug wires (#25; new: 8K-Ω, old: 15K-Ω), air filters (#20). Set dwell @ 56°, timing @ 5° BTDC. Checked oil (clean, full). |
| 9/22/96 | 24,215 | Returned from Cambria, checked oil (full). |
| 9/27/96 | 24,217 | Accident. Repairs over next 2 years for: collision damage, rocker panel rust (4 spots approx. 1" x 4"), roof ripples, engine lid pressed in. All new seals, weather stripping, trim. Body stripped to bare metal, repainted Astra blue w/ clear coat. New interior including grey carpet, blue dash pad, grey headliner, grey vinyl seats (F & R), door panels, rear compartment panels, visors, rubber mats. Replacement body parts: F bumper (used), bumper brackets, horn grilles (NOS), fog lamp grilles, hood handle w/ crest, headlight bezels, interior nose support trim, windshield, overriders, deco strip w/ insert. |
| 8/7/98: | 24,217 | Changed oil (Castrol 10-40w), gapped plugs (.025), set dwell (.016) timing (3° BTDC). Replaced bowl cover gasket on L carb. |
| 8/12/98 | 24,217 | New tires, battery (two Michelin X2X 165R-15). Lubed front end. Replaced LR wheel cylinder. Bled brakes. |
| 8/16/98 | 24,500 | Returned from Monterey. Washed car. |
| 9/15/98 | 24,550 | Waxed w/ Griot's Garage wax (by hand). Lubed window mechanisms. |
| 9/26/98 | 24,577 | Waxed w/ Griot's Garage wax (by machine). |

1960 Porsche 356B

Maintenance Summary 1993 - 2024

CA License: BRL095

VIN: 112239

Engine: P603127

Transmission: 38217

| Date | Mileage | Oil/ Filter | Other Service | Done By* |
|-----------------|---------|----------------|--|-------------|
| 5/12/93 | 22,080 | | Received car | JB, PB |
| 5/14/93 | 22,150 | | Replace front shocks (Koni). | EL |
| 8/5/94 | 22,900 | | Inspect/adjust brakes. | EL |
| 8/20/94 | 22,950 | | Replace rear shocks (Koni), replace master cylinder, bleed brakes. | EL |
| 9/15/94 | 23,152 | | Replace LF turn signal lens. | EL |
| 11/11/94 | 23,175 | | Replace steering damper (Koni), check steering box fluid. | EL |
| 8/20/95 | 23,328 | | Clean battery, add water. | EL |
| 11/15/95 | 23,433 | | Inspect brakes and front wheel bearings. LF upper cylinder leaking, LF lower frozen. LF inner wheel bearing pitted. | EL |
| 12/20/95 | 23,433 | | Replace LF upper and lower, LR wheel cylinders. Replace LF inner/outer wheel bearings and seal. Replace LF rubber brake line. Clean shoes with solvent and torch. | EL |
| 4/7/96 | 23,433 | | Replace RF upper and lower wheel cylinders, RF rubber brake line. Replace RF inner/outer wheel bearings and seal. Adjust brakes. | EL |
| 4/21/96 | 23,470 | | Shield fuel line at fuel pump to address suspected vapor lock. Measure fuel pump pressure (2.6 PSI) and output (750cc @4500 RPM for 1 minute). | EL |
| 5/4/96 | 23,530 | | Replace battery. | EL |
| 6/9/96 | 23,596 | X | Change oil and filter, adjust valves, clean spark plugs, set dwell (56 deg) and timing (5 deg BTDC). | EL |
| 9/18/96 | 23,705 | | Replace points, spark plugs, rotor, condenser, spark plug wires, air filters. Set dwell and timing. Drive to Cambria, San Simeon. | EL |
| 9/27/96 | 24,217 | | Front end collision. | |
| 9/96 to 8/98 | 24,217 | | Repair collision damage, rocker panel rust, slight roof ripples, engine lid pressed in. Bare metal respray in Aetna Blue (original color). Replacement parts: front bumper and brackets, horn grilles (NOS), fog lamp grilles, hood handle, headlight bezels, nose support tin, overriders, windshield. Work done by Del's Auto Body (Del Sessions). | DAB |
| 9/96 to 8/98 | 24,217 | | Replace entire interior (carpet, headliner, seat upholstery, dash pad, door and rear compartment panels, visors, rubber mats). Replace weatherstripping, rubber seals on all windows. Work done by Jeda Marketing. | JM |
| 8/7/98 | 24,217 | X | Change oil and filter, gap spark plugs, set dwell and timing. | EL |

| | | | | |
|----------|--------|---|---|---------|
| 8/12/98 | 24,217 | | Replace tires, battery. Lube front end. Replace LR wheel cylinder. Bleed brakes. Drive to Monterey Historics. | EL |
| 8/16/98 | 24,500 | | Return from Monterey. Wash car. | EL |
| 9/15/98 | 24,550 | | Hand wash/wax with Griot's. | EL |
| 9/26/98 | 24,577 | | Hand wash, machine wax with Griot's. | EL |
| 10/25/04 | 25,594 | | Remove engine for rebuild due to slight knock when decelerating. | EL |
| 2/10/06 | 25,594 | | Disassemble engine. First time the case has ever been split. | EL, LL |
| 10/26/08 | 25,594 | | Clean pistons and cylinders. Cylinders good, piston tops slightly pitted. | EL |
| 4/18/10 | 25,594 | | Transport car from San Jose house to Oakland house. | LL |
| 7/15/15 | 25,594 | | Give disassembled engine to Church of the Aircooled (Chris Jansens) for rebuild. See COA receipts for details. | EL |
| 7/15/15 | 25,594 | | Begin engine rebuild. | COA |
| 4/20/18 | 25,594 | | Replace front outer wheel bearings, clean and polish drums. | EL |
| 3/7/19 | 25,594 | | Have wheels powder coated (Reliable Powder Coating). | RPC |
| 1/6/20 | 25,594 | | Replace tires (Tidewater Tire). | TT |
| 5/1/20 | 25,594 | | Flush all metal brake lines. Have original brake shoes relined (J&G Relining), replace all wheel cylinders, master cylinder, rubber brake lines, reassemble brakes. Repack front wheel bearings. Lube all front suspension and chassis zerk fittings. | EL |
| 5/15/20 | 25,594 | | Have car towed to COA in SF for transaxle rebuild, engine installation. See COA receipts for details. | EL |
| 7/20/20 | 25,594 | | Have wheels painted using correct paint codes (Dante's Paint?). | Dante |
| 6/1/21 | 25,594 | X | Change oil and filter, adjust valves after 20 minute breakin run. | COA |
| 7/1/21 | 25,700 | X | 100 mile service. Change oil and filter, adjust valves. | COA |
| 8/7/21 | 25,750 | | Get car back from Church of the Aircooled. | COA |
| 6/22/22 | 25,803 | | Replace turn signal relay. | EL |
| 12/16/23 | 25,909 | X | 300 mile service. Adjust valves, change oil and filter, clean sump screen. | EL |
| 6/20/24 | 26,415 | | Remove speedometer, bring to Palo Alto Speedometer for rebuild. Drove car ~100 miles without speedo, so actual miles are 100 more than indicated. | EL, PAS |
| 7/2/24 | 26,418 | X | 1000 mile service. Adjust valves, change oil and filter, change trans. oil, install rebuilt speedo. (Eason Auto Works) | EAW |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |