BAR #: ARD 00287273 EPA #: CAL000428253

1421 FRANCISCO BOULEVARD EAST

Suite 2

San Rafael, CA 94901

Phone: 415 259-5488 FAX: 415 259-6380

Invoice No.

11786

Order Date 02/24/22 12:10 pm Completed: 04/01/22 01:04 pm

I acknowledge notice & oral approval of an increase in the original estimated price.

Page 1

SIGNATURE

00 FE Mileage Lic: ? Vi Vin: ZFF Eq:

00 FERRARI 360 SILVER

Mileage in:17933 out: Lic: ? V8Cyl 3.6 Eng

Vin: ZFFYU51A8Y0121397

Quotes
1 02/24/22 12:22pm 1043.20

2 03/02/22 09:40am 7000.00

HEAT EXCHANGER 1, 2, 3 3 03/02/22 09:41am 3100.00

GEARBOX MOUNT, SERVICE, WATERP

Job01 SHIF	T QUALITY			Labor	\$419.20
75W90S 10404	SYNTHETIC GEAR OIL-N REDLINE RACING OIL 40W-N	7.0 @ 12.0 @	29.40 =\$ 10.99 =\$	205.80 131.88	
MP-100	SOLVENT-N	1.0 @	9.68 =\$	9.68	347.36

CLIENT STATES THAT VEHICLE HAS POOR SHIFT QUALITY WHEN WARM. ESPECIALLY IN 1ST, 2ND, AND 3RD GEARS. REQUESTS CABLES, BUSHINGS, AND OIL QUALITY BE INSPECTED DURING DIAGNOSIS. DIAGNOSE AND ADVISE.

UNABLE TO DRIVE CAR DUE TO COOLANT INTERMIX AND OVERHEAT CONCERN. GEARBOX HEAT EXCHANGER MUST BE REPLACED WITH MULTIPLE OIL CHANGES BEFORE SHIFTING CAN BE ADDRESSED. AFTER COOLANT INTERMIX REPAIRS WERE MADE, GEARBOX WAS FLUSHED THREE TIMES WITH 40WT OIL AND RAN IN BETWEEN ON RACK, ALL SHIFTING IS CONFIRMED OK AFTER FINAL FILL.

Job Subtotal: \$766.56

Job02 TEM	PERATURE GAUGE			Labor: \$	4,716.00
889692	RADIATOR FLUSH-N	2.0 @	14.82 =\$	29.64	
ZAF	COOLANT/SHELLZONE-N	4.0 @	26.20 =\$	104.80	
183758	THERMOSTAT 360-N	1.0 @	186.99 =\$	186.99	
149279	THERMOSTAT O-RING-N	1.0 @	15.48 =\$	15.48	
5901	COOLING SYSTEM SERV KI-N	1.0 @	40.33 =\$	40.33	
137873	GASKET/THERMOSTAT-N	1.0 @	12.74 =\$	12.74	
181802	WATER HOSE-N	1.0 @	227.50 =\$	227.50	
176322	TEMP SWITCH-N	1.0 @	77.76 =\$	77.76	
H-149	HTR HOSE-N	10.0 @	1.32 =\$	13.20	708 44

CLIENT STATES THAT DURING 5 MINUTES OF LIGHT DRIVING THE TEMPERATURE GAUGE WENT TO RED. CLIENT STOPPED DRIVING IMMEDIATELY. DIAGNOSE AND ADVISE.

INSPECTION FOUND COOLANT AND GEAR OIL INTERMIXED IN COOLING SYSTEM. RECOMMEND PERFORM MULTIPLE COOLING SYSTEM FLUSHES WITH A THERMOSTAT REPLACEMENT, DISCONNECTING PIPES AT

----->--->--->--->--->--->

Invoice No.

11786

Page 2

BAR #: ARD 00287273 EPA #: CAL000428253

1421 FRANCISCO BOULEVARD EAST

Suite 2

San Rafael, CA 94901

Phone: 415 259-5488 FAX: 415 259-6380

Order Date 02/24/22 12:10 pm Completed: 04/01/22 01:04 pm

# Job02 TEMPERATURE GAUGE

BOTH RADIATORS AND ENGINE, AND RETEST.

FOUND CRACKED LOWER LEFT WATER HOSE AT RADIATOR AND REPLACED.

FOUND HEATER CORE PLUGGED SOLID. DISCONNECTED FROM WATER CIRCULATION PUMP AND HOOKED UP EXTERNAL FLUSHING PUMP. CLEARED AND GOT FLOWING AFTER SOME TIME.

REMOVED FRONT BUMPER AND BOTH RADIATORS. SENT OUT RADIATORS TO CLEAR OIL/COOLANT INTERMIX GUNK. PERFORMED MULTIPLE CHEMICAL AND FRESH WATER FLUSHES. FOUND RADIATORS PARITALLY RE-CLOGGED. REMOVED AND SENT OUT A SECOND TIME. ALSO FOUND RESTRICTED FLOW TO COOLANT TANK FROM RETURN HOSES. HOSES WERE RUBBER AND SMALL DIAMETER, THE OIL CAUSED DETERIORATION AND SWELLING. REPLACED BOTH RETURN HOSES FROM TSTAT HOUSING AND FROM RIGID PIPE IN CHASSIS. FOUND COOLING FANS WOULD RUN ONLY AT HIGHER TEMPERATURES. REPLACED FAULTY FAN SWITCH TO REMEDY.

ASSEMBLED ALL AND CONFIRMED ALL OPERATIONAL.

NOTE THAT CAR MAY NEED CONTINUED ANNUAL COOLING SERVICES TO PURGE REMAINING OIL IN SYSTEM.

Job Subtotal: \$5,424.44

Sublet: \$377.00

# Job03 RADIATOR FLUSH

SEND RADIATORS OUT TO BE FLUSHED. OIL FLUSHED FROM RADIATORS. SEND OUT FOR SECOND FLUSH.

Job04 HEA	T EXCHANGER			Labor: S	\$1,676.80
180846	HEAT EXCHANGER-N	1.0 @	1032.24 =\$	1032.24	
145192	GASKET-N	8.0 @	31.27 =\$	250.16	
101044	O-RING/WATER PUMP-N	1.0 @	10.58 =\$	10.58	
MP-100	SOLVENT-N	1.0 @	9.68 =\$	9.68	1302.66

CLIENT STATES THAT HE FOUND GEARBOX OIL MIXED WITH COOLANT AND SHIFTING ISSUES. CLIENT SUSPECTS HEAT EXCHANGER ISSUE. DIAGNOSE AND ADVISE. INSPECTION FOUND GEARBOX FUILL OF COOLANT AND INTERMIX INTO COOLING SYSTEM. RECOMMEND REPLACE HEAT EXCHANGER AND SERVICE COOLING SYSTEM AND GEARBOX TO CLEAR INTERMIX.

REMOVED WATER PUMP HOUSING AND REPLACED FAILED HEAT EXCHANGER.

Job Subtotal: \$2,979.46

Job05 GEA	RBOX MOUNT 360/430			Labor:	\$979.45
237531	GEARBOX MOUNT-N	1.0 @	117.38 =\$	117.38	117.38
MICOSCOTICALI			1000		

INSPECTION REVEALED GEARBOX MOUNT IS TORN. RECOMMEND REPLACE. REMOVED SUBFRAME AND REPLACED MOUNT WITH UPDATED PART.

Job Subtotal: \$1,096.83

----->----->----->---->

Invoice No. 11786

Page 3

BAR #: ARD 00287273 EPA#: CAL000428253

1421 FRANCISCO BOULEVARD EAST

Suite 2

San Rafael, CA 94901

Phone: 415 259-5488 FAX: 415 259-6380

Order Date 02/24/22 12:10 pm Completed: 04/01/22 01:04 pm

Job06 ANNU	JAL-360/STRADALE			Labor	\$525.00
5W40R	5W40 Pennzoil Ultra Euro-N	10.0 @	15.33 =\$	153.30	
197654	FILTER/OIL 348-355-360-N	1.0 @	57.99 =\$	57.99	
115	BG OIL IMPROVER-N	1.0 @	20.63 =\$	20.63	
MP-100	SOLVENT-N	1.0 @	9.68 =\$	9.68	
2913	ETHANOL DEFENSE KIT-N	1.0 @	33.00 =\$	33.00	
460.22.29	COPPER WASHER-N	2.0 @	3.80 =\$	7.60	
DOT4	EURO BRAKEFLUID-N	2.0 @	25.62 =\$	51.24	333.44

PERFORM ANNUAL SERVICE. CHANGE ENGINE OIL AND FILTER, POWER FLUSH AND CHANGE BRAKE FLUID. CHECK CONDITION OF AIR AND POLLEN FILTERS. CHECK AND ADJUST ALL FLUID LEVELS. CONDUCT COMPLETE VEHICLE INSPECTION INCLUDING NOTING BRAKE AND TIRE WEAR. PERFORMED SERVICE PER CHECK SHEET. TEST DROVE TO CONFIRM REPAIRS.

Job Subtotal: \$858.44

### Job07 WATERPUMP REPLACEMENT

176173D PUMP/WATER-550-N

Labor: \$167.68 1.0 @ 549.35 =\$ 549.35 549.35

CLIENT REQUESTS WATERPUMP BE REPLACED WHEN REMOVED FROM VEHICLE DURING HEAT EXCHANGER REPLACEMENT.

REMOVED WATER PUMP FROM WATER PUMP HOUSING. DISCONNECTED AND SWAPPED PULLEYS TO NEW WATERPUMP, INSTALLED NEW WATERPUMP IN HOUSING, REINSTALLED IN VEHICLE,

Job Subtotal: \$717.03

Recommendations: \*\*\*ADVISED 4/2022\*\*\*

TIRES: FRONT AND REAR 7/32" BRAKES: FRONT AND REAR 5MM

CAM COVER GASKETS LEAKING ON BOTH SIDES 6/10

TIRE PRESSURE SET TO: LF[32] RF[32] LR[32] RR[32]

12 MONTH UNLIMITED MILEAGE PARTS AND LABOR WARRANTY ON NEW INSTALLED PARTS; WEARABLE ITEMS CARRY 12-MONTH WORKMANSHIP WARRANTY, USED PARTS SUBJECT TO SUPPLIERS WARRANTY, 12 MONTH WORKMANSHIP WARRANTY. CUSTOMER SUPPLIED PARTS NOT ACCEPTED. VEHICLES LEFT IN SHOP PAST COMPLETION DATE WITHOUT PRIOR ARRANGEMENTS MADE WILL BE SUBJECT TO STORAGE FEES OF \$35 PER DAY.

WE GLADLY ACCEPT CASH, CHECK, DEBIT AND ALL MAJOR CREDIT CARDS. ALL CREDIT CARD TRANSACTIONS ADD A 2.5% PROCESSING FEE.

----->--->--->--->--->--->

BAR #: ARD 00287273 EPA#: CAL000428253

1421 FRANCISCO BOULEVARD EAST

Suite 2

San Rafael, CA 94901

Phone: 415 259-5488 FAX: 415 259-6380

Invoice No.

11786

Page 4 Order Date 02/24/22 12:10 pm Completed: 04/01/22 01:04 pm

Payments to San Rafael European	Cost Summar	y
Status: Completed Work Order	Labor	8484.13
	Parts	3358.63
Payments:	Sublet	377.00
	Haz Waste	16.00
	OIL/COOL DIS	POS AL 150.00
	Tax	310.67
	Total	\$12696.43
	Payments	0.00
	Bal Due	12696 43

Thank you for choosing San Rafael European

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.



1421 Francisco Blvd E San Rafael, CA 94901 415-259-5488 www.sfmotorsports.com service@sfmotorsports.com

#### **ANNUAL SERVICE 360 Modena**

Renew engine oil and filter Add BG Fuel Improver Add BG Oil improver Renew Brake/Clutch fluid (bleed if necessary) Check window, sunroof, and/or convertible top operation Inspect dashboard instruments and lighting Check horn operation Check A/C and climate control system operation Inspect condition of body Inspect chassis for oil and fluid leaks Diagnosis system: read out fault memory Leonardo Check exterior light operation, replace failed bulbs Inspect air filters and pollen filter condition Install windshield washer solvent/anti-freeze Inspect cooling system connections and lines Check blow-by system Inspect brake pipes/hoses, calipers, connections Inspect ignition system cables and connections Inspect air injection connections and pipe valves Inspect exhaust system for leaks and damage Set clock	Inspect brake pipes/hoses, calipers, connections Check and adjust parking brake Inspect wear condition of the brakes
Recommendations / Comments:	
Technician Edgar C.	

For the immediate and long-term benefit of your vehicle, the suggested service/maintenance recommendations by San Francisco Motorsports meet and exceed factory maintenance schedules. Service suggestions in this schedule have been determined by the manufacturer's recommendations and our years of automotive experience in normal and under severe driving conditions.

NEXT SERVICE DUE April 2023

Invoice No.

11848

Page 1

BAR #: ARD 00287273

EPA#: CAL000428253

1421 FRANCISCO BOULEVARD EAST

Suite 2

San Rafael, CA 94901

Phone: 415 259-5488 FAX: 415 259-6380

Order Date 04/04/22 11:30 am Completed: 04/06/22 04:12 pm

00 FERRARI 360 SILVER

Mileage in: 18070 out: Lic: ? V8Cyl 3.6 Eng

Vin: ZFFYU51A8Y0121397

Last in 2/24/2022

Quotes 1 04/04/22 12:26pm 820.93

Job01 REP	LACE FLUIDS			Labor	\$419.20
ZAF 5901	COOLANT/SHELLZONE-N COOLING SYSTEM SERV KI-N	2.0 @ 1.0 @	26.20 =\$ 42.44 =\$	52.40 42.44	
75W90S	SYNTHETIC GEAR OIL-N	6.0 @	29.40 =\$	176.40	271.24

CLIENT REQUESTS COOLANT AND GEARBOX OIL BE FLUSHED.

FLUSHED AND REFILLED COOLANT. FLUSHED AND REFILLED GEARBOX OIL. ALL LOOKS GOOD AT THIS TIME.

Job Subtotal: \$690.44

Job02 SMOG

Sublet: \$60.00

CLIENT REQUESTS VEHICLE BE SMOG TESTED. VEHICLE PASSED SMOG. SMOG

CERTIFICATE NUMBER: SO408322C.

Recommendations: \*\*\*ADVISED 4/2022\*\*\*

TIRES: FRONT AND REAR 7/32" BRAKES: FRONT AND REAR 5MM

CAM COVER GASKETS LEAKING ON BOTH SIDES 6/10

TIRE PRESSURE SET TO: LF[32] RF[32] LR[32] RR[32]

12 MONTH UNLIMITED MILEAGE PARTS AND LABOR WARRANTY ON NEW INSTALLED PARTS; WEARABLE ITEMS CARRY 12-MONTH WORKMANSHIP WARRANTY, USED PARTS SUBJECT TO SUPPLIERS WARRANTY, 12 MONTH WORKMANSHIP WARRANTY. CUSTOMER SUPPLIED PARTS NOT ACCEPTED. VEHICLES LEFT IN SHOP PAST COMPLETION DATE WITHOUT PRIOR ARRANGEMENTS MADE WILL BE SUBJECT TO STORAGE FEES OF \$35 PER DAY.

WE GLADLY ACCEPT CASH, CHECK, DEBIT AND ALL MAJOR CREDIT CARDS. ALL CREDIT CARD TRANSACTIONS ADD A 2.5% PROCESSING FEE.

-->--->--->---->--->

Invoice No.

11848

Order Date 04/04/22 11:30 am Completed: 04/06/22 04:12 pm

Bal Due

799.69

BAR #: ARD 00287273 EPA #: CAL000428253

1421 FRANCISCO BOULEVARD EAST

Suite 2

San Rafael, CA 94901

Phone: 415 259-5488 FAX: 415 259-6380

Payments to San Rafael European	Cost Summary	
Status: Completed Work Order	Labor	419.20
	Parts	271.24
Payments:	Sublet	60.00
	Haz Waste	5.40
	2.5CC	18.76
	Tax	25.09
	Total	\$799.69
	Payments	0.00

Thank you for choosing San Rafael European

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature)			

# Smog Check Vehicle Inspection Report (VIR)

#### Vehicle Information

Test Date/Time: 04/06/2022 @ 8:46 AM

Model Year:

License Plate:

License State:

XX

VIN (scanned from vehicle): Fuel Type:

Gasoline

ZFFYU51A8YO121397

Certification Type: California

Odometer:

18075

#### Overall Test Result PASS

Congratulations! Your vehicle passed the Smog Check inspection, which helps California reach its daily goal of removing smog-forming emissions from the air. Thank you for performing the needed emissions-related repairs to your vehicle.

Visual Inspection: PASS Functional Inspection: PASS

Smog Check Certificate Number: SO408322C

DMV ID Number: 9618O239S297

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance.

Please keep this copy for your records.

#### Visual Inspection Result Information

Result PASS	Inspection Category	Result	Inspection Category
PASS	Air Injection System	PASS	Catalyst
PASS	Computers, Sensors, Switches, and Wiring	PASS	Crankcase Emission Controls
NOT APPLICABLE	Exhaust Gas Recirculation (EGR)	PASS	Fuel Evaporative System (EVAP)
PASS	Fuel Metering System	PASS	Other Emission Related Components/Systems
NOT APPLICABLE	Turbocharger/Supercharger	PASS	Vacuum Lines to Sensors/Switches

# **Emission Control Systems Functional Check Results**

Result PASS

Liquid Fuel Leak Check

Result PASS

OBDII

PASS

Smoke Check

## Smog Check Inspection Station Information

Station ID:

RC255742

AUTO REPAIR SPECIALIST

Inspector Name/ID: Software Version/OIS ID:

BARCOURT, YVENER/E0154451

21.2.1249.0/CV007219

1421 FRANCISCO BOULEVARD EAST SAN RAFAEL, CA 94901

(415) 459-0900 (415) 459-0910

> I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Inspector's Signature

1