



Mercedes-Benz

Mercedes-Benz of San Francisco
1480 FOLSOM STREET
SAN FRANCISCO, CALIFORNIA 94103
(415) 673-1700 • FAX (415) 553-9912
www.sfbenz.com

693149

SF
Benz

693149



0101IMBCS693149

24 HOURS

ROADSIDE ASSISTANCE SERVICE
1-800-222-0100

CUSTOMER NO. 108923	ADVISOR JON KEARNS	TAG NO. 2432	INVOICE DATE 07/08/19	INVOICE NO. MBCS693149
	LICENSE NO. SLSGLW	MILEAGE 20,867	COLOR AMG IMOLA G	STOCK NO.
	YEAR / MAKE / MODEL 11/MERCEDES-BENZ/SLS AMG/2DR CPE		DELIVERY DATE 07/20/10	DELIVERY MILES
	VEHICLE I.D. NO. W D D R J 7 H A 8 B A 0 0 1 7 1 7		SELLING DEALER NO.	PRODUCTION DATE 05/31/10
	P.T.E. NO.	P.O. NO.	R.O. DATE 07/03/19	
COMMENTS E# 15998060001729			MO: 20868	

PERFORM MANDATORY CALIFORNIA STATE LAW AB32 "TIRE INFLATION CHECK AND CORRECTION"

Notice to our guests; We will check and correct your front and rear tire pressures when inflated with air. Nitrogen is unavailable at this service center; tire pressures will not be corrected on any vehicle that is identified as Nitrogen inflated. Nitrogen inflated tires are identified by a green valve stem cap. Green valve stems caps is the industrial identification standard for Nitrogen inflated tires.

AS PER AB32, CHECK AND CORRECTED TIRE INFLATION TO MANUFACTURE SPECIFICATIONS.

TIRES INFLATED TO (PSI);
FRONT 31
REAR 35

JOB# 3 TOTALS-----

JOB# 3 JOURNAL PREFIX MBCS JOB# 3 TOTAL 0.00

JOB# 4 CHARGES-----

LABOR-----
J# 4 08MBZ-WASH CAR WASH EXTERI.ONLY TECH(S):002 INTERNAL
PERFORM COMPLIMENTARY CAR WASH - VALUE \$19.95
WASHED AND VACUUMED VEHICLE

JOB# 4 TOTALS-----

JOB# 4 JOURNAL PREFIX MBCS JOB# 4 TOTAL 0.00

ESTIMATE-----
CLIENT HEREBY ACKNOWLEDGES RECEIVING
ORIGINAL ESTIMATE OF \$500.00 (+TAX)

COMMENTS-----
RECOMMENDED NOT DONE/ DECLINED SERVICES-----

TOTALS-----

PLEASE CALL 415-673-1700 TO SCHEDULE YOUR NEXT APPOINTMENT!

MERCEDES BENZ OF SAN FRANCISCO THANKS YOU FOR YOUR BUSINESS
*****DRIVE SAFELY AND HAVE A GREAT DAY*****

[]CASH []CHECK#.....[]CHARGE [X]VISA []MC []AMX []DISCOVER

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE.

CLIENT SIGNATURE

TOTAL LABOR.... 203.00
TOTAL PARTS.... 240.00
TOTAL SUBLET... 0.00
TOTAL G.O.G.... 0.00
TOTAL MISC CHG. 1.01
TOTAL MISC DISC 0.00
TOTAL TAX..... 20.40

TOTAL INVOICE \$ 464.41

PAID
JUL 08 2019

BY:

B.A.R. # AK041274

EPA # CAD 982021008

EPA # CAC 002584953

EPA # CAL 000258049

PLEASE READ ALL WARRANTY, PROP 65 AND ADDITIONAL IMPORTANT INFORMATION ON REVERSE SIDE



Mercedes-Benz

Mercedes-Benz of San Francisco

1480 FOLSOM STREET
SAN FRANCISCO, CALIFORNIA 94103
(415) 673-1700 • FAX (415) 553-9912
www.sfbenz.com

693149

SF
Benz

693149



0101IMBCS693149

24 HOURS

ROADSIDE ASSISTANCE SERVICE
1-800-222-0100

CUSTOMER NO. 108923	ADVISOR JON KEARNS	TAG NO. 340	INVOICE DATE 07/08/19	INVOICE NO. MBCS693149
	LICENSE NO. SLSGLW	MILEAGE 20,867	COLOR AMG IMOLA G	STOCK NO.
	YEAR / MAKE / MODEL 11/MERCEDES-BENZ/SLS AMG/2DR CPE		DELIVERY DATE 07/20/10	DELIVERY MILES
	VEHICLE I.D. NO. W D D R J 7 H A 8 B A 0 0 1 7 1 7		SELLING DEALER NO.	PRODUCTION DATE 05/31/10
	F.T.E. NO.	P.O. NO.	R.O. DATE 07/03/19	
COMMENTS E# 15998060001729			MO: 20868	

JOB# 1 CHARGES-----

LABOR-----
J# 1 19MBZ2019030017 REPL DR/PASS-SIDE AB TECH(S):2640 WARRANTY

PERFORM OPEN RECALL CAMPAIGN 2019030017, REPLACE DRIVER-SIDE
AND FRONT PASSENGER-SIDE AIRBAG. MODEL 204, X204 AND 197,
MODEL YEAR 2011 - 2015.
DC# 91 940 017, LOP:02-2942 (W204) 1.4, 02-2942 (X204) 1.0
OR 02-2942 (197) ZM. AIR BAG NOT IN STOCK. ORDER AIRBAGS
AIRBAGS ORDERED. NO ETA.

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	LIST PRICE-UNIT PRICE-	
	1	000-860-55-02-9116	DRIVER S AIRBA		WARRANTY
	1	197-860-00-00-05	FRONT PASSENGE		WARRANTY
				TOTAL - PARTS	0.00

JOB# 1 TOTALS-----

JOB# 1 JOURNAL PREFIX MBCS JOB# 1 TOTAL 0.00

JOB# 2 CHARGES-----

LABOR-----
J# 2 54MBZ-BATT *REPAIR/REPL BATTERY TECH(S):2640 203.00

TEST AND REPLACE BATTERY AND REPLACE AS NEEDED.
BATTERY FAILED LOAD TEST, REPLACE AS NEEDED.
REPLACED BATTERY AS RECOMMENDED. NORMALIZED WINDOWS AND SET
CLOCK.

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	LIST PRICE-UNIT PRICE-	
	1	004-541-86-01	BATTERY (DO NO	264.50 264.50	264.50
			BILL BATTERY DISPOSAL FEE		
	-1	004-541-86-01	CORE RETURN	24.50 24.50	-24.50
				TOTAL - PARTS	240.00

MISC-----	CODE-----	DESCRIPTION-----	CONTROL NO-----	
	HAB	BATTERY WASTE DISPOSAL FEE		1.01
			TOTAL - MISC	1.01

JOB# 2 TOTALS-----

LABOR 203.00
PARTS 240.00
MISC 1.01

JOB# 2 JOURNAL PREFIX MBXS JOB# 2 TOTAL 444.01

JOB# 3 CHARGES-----

LABOR-----
J# 3 40MBZ-0-INFLAT CAL LAW TIRE CHECK TECH(S):2640 INTERNAL

B.A.R. # AK041274
EPA # CAD 982021008
EPA # CAC 002584953
EPA # CAL 000258049

SERVICE INVOICE



Mercedes-Benz

Mercedes-Benz of San Francisco

1480 FOLSOM STREET
SAN FRANCISCO, CALIFORNIA 94103
(415) 673-1700 • FAX (415) 553-9912
www.sfbenz.com

695989

SF
Benz

695989



0101IMBCS695989

24 HOURS

ROADSIDE ASSISTANCE SERVICE
1-800-222-0100

CUSTOMER NO. 108923	ADVISOR JON KEARNS	TAG NO. 2432	INVOICE DATE 08/21/19	INVOICE NO. MBCS695989
	LICENSE NO. SLSGLW	MILEAGE 20,904	COLOR AMG TMOLA G	STOCK NO.
	YEAR / MAKE / MODEL 11/MERCEDES-BENZ/SLS AMG/2DR CPE		DELIVERY DATE 07/20/10	DELIVERY MILES
	VEHICLE I.D. NO. WDDRJ7HA8BA001717		SELLING DEALER NO.	PRODUCTION DATE 05/31/10
	P.T.E. NO.	P.O. NO.	R.O. DATE 08/13/19	
	COMMENTS E# 15998060001729			MO: 20906

COMMENTS-----
RECOMMENDED NOT DONE/ DECLINED SERVICES-----

TOTALS-----

PLEASE CALL 415-673-1700 TO SCHEDULE YOUR NEXT APPOINTMENT!

MERCEDES BENZ OF SAN FRANCISCO THANKS YOU FOR YOUR BUSINESS
*****DRIVE SAFELY AND HAVE A GREAT DAY*****

[]CASH []CHECK#.....[]CHARGE[]VISA[]MC[]AMX[]DISCOVER

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN
THE ORIGINAL ESTIMATE PRICE.

CLIENT SIGNATURE

TOTAL LABOR.... 235.00
TOTAL PARTS.... 0.00
TOTAL SUBLET... 0.00
TOTAL G.O.G.... 0.00
TOTAL MISC CHG. 0.00
TOTAL MISC DISC 0.00
TOTAL TAX..... 0.00

TOTAL INVOICE \$ 235.00

FAIT
AUG 22 2019

BY: _____

B.A.R. # AK041274

EPA # CAD 982021008

EPA # CAC 002584953

EPA # CAL 000258049

SERVICE INVOICE

[END OF INVOICE] 02:13pm



Mercedes-Benz

Mercedes-Benz of San Francisco

1480 FOLSOM STREET
SAN FRANCISCO, CALIFORNIA 94103
(415) 673-1700 • FAX (415) 553-9912
www.sfbenz.com

695989

SF
Benz

686989



0101IMBCS695989

24 HOURS

ROADSIDE ASSISTANCE SERVICE
1-800-222-0100

CUSTOMER NO. 108923	ADVISOR JON KEARNS	TAG NO. 2432 069	INVOICE DATE 08/21/19	INVOICE NO. MBCS695989
	LICENSE NO. SLSGLW	MILEAGE 20,904	COLOR AMG IMOLA G	STOCK NO.
	YEAR / MAKE / MODEL 11/MERCEDES-BENZ/SLS AMG/2DR CPE		DELIVERY DATE 07/20/10	DELIVERY MILES
	VEHICLE I.D. NO. WDDRJ7HA8BA001717		SELLING DEALER NO.	PRODUCTION DATE 05/31/10
	F.T.E. NO.	P.O. NO.	R.O. DATE 08/13/19	
COMMENTS E# 15998060001729				

MO: 20906

PERFORM MANDATORY CALIFORNIA STATE LAW AB32 "TIRE INFLATION CHECK AND CORRECTION"

Notice to our guests; We will check and correct your front and rear tire pressures when inflated with air. Nitrogen is unavailable at this service center; tire pressures will not be corrected on any vehicle that is identified as Nitrogen inflated. Nitrogen inflated tires are identified by a green valve stem cap. Green valve stems caps is the industrial identification standard for Nitrogen inflated tires.
AS PER AB32, CHECK AND CORRECTED TIRE INFLATION TO MANUFACTURE SPECIFICATIONS.
TIRES INFLATED TO (PSI);
FRONT 31
REAR 35

JOB# 4 TOTALS-----
JOB# 4 JOURNAL PREFIX MBCS JOB# 4 TOTAL 0.00

JOB# 5 CHARGES-----
LABOR-----
J# 5 08MBZ-WASH CAR WASH EXTERI. ONLY TECH(S):002 INTERNAL
PERFORM COMPLIMENTARY CAR WASH - VALUE \$19.95
WASHED AND VACUUMED VEHICLE

JOB# 5 TOTALS-----
JOB# 5 JOURNAL PREFIX MBCS JOB# 5 TOTAL 0.00

JOB# 6 CHARGES-----
LABOR-----
J# 6+96MBZZ03 NO QUOTE FT TIRES TECH(S):2230 INTERNAL
Added Operation (JONK @ 08/15/2019 16:24)
FRONT TIRES MAY NEED ATTENTION NEXT VISIT
WILL RECHECK FRONT TIRES AND ADVISE NEXT VISIT

JOB# 6 TOTALS-----
JOB# 6 JOURNAL PREFIX MBCS JOB# 6 TOTAL 0.00

JOB# 7 CHARGES-----
LABOR-----
J# 7+96MBZZ04 NO QUOTE RR TIRES TECH(S):2230 INTERNAL
Added Operation (JONK @ 08/15/2019 16:24)
REAR TIRES MAY NEED ATTENTION NEXT VISIT
WILL RECHECK REAR TIRES AND ADVISE NEXT VISIT

JOB# 7 TOTALS-----
JOB# 7 JOURNAL PREFIX MBCS JOB# 7 TOTAL 0.00

ESTIMATE-----
CLIENT HEREBY ACKNOWLEDGES RECEIVING
ORIGINAL ESTIMATE OF \$235.00 (+TAX)

B.A.R. # AK041274

EPA # CAD 982021008

EPA # CAC 002584953

EPA # CAL 000258049

SERVICE INVOICE



Mercedes-Benz

Mercedes-Benz of San Francisco

1480 FOLSOM STREET
SAN FRANCISCO, CALIFORNIA 94103
(415) 673-1700 • FAX (415) 553-9912
www.sfbenz.com

695989

SF
Benz

695989



0101IMBCS695989

24 HOURS

ROADSIDE ASSISTANCE SERVICE
1-800-222-0100

CUSTOMER NO. 108923	ADVISOR JON KEARNS	TAG NO. 2432	INVOICE DATE 08/21/19	INVOICE NO. MBCS695989
	LICENSE NO. SLSGLW	20,904	COLOR AMG IMOLA G	STOCK NO.
	YEAR / MAKE / MODEL 11/MERCEDES-BENZ/SLS-AMG/2DR CPE		DELIVERY DATE 07/20/10	DELIVERY MILES
	VEHICLE ID NO. WDDRJ7HA8BA001717		SELLING DEALER	PRODUCTION DATE 05/31/10
	COMMENTS E# 15998060001729		R.O. DATE 08/13/19	

JOB# 1 CHARGES-----

LABOR-----

J# 1 40MBZ-ALIGN *CK ALIGNMENT ADJ TO TECH(S):2230 235.00

CLIENT REQUEST CHECK WHEEL ALIGNMENT, ADJUST TOE IF NECESSARY. CAMBER/CASTER BOLT KITS PARTS & LABOR TO INSTALL ARE ADDITIONAL IF REQUIRED.

CLIENT REQUEST CHECK WHEEL ALIGNMENT

Performed four wheel alignment. Test drove OK.

JOB# 1 TOTALS-----

LABOR 235.00

JOB# 1 JOURNAL PREFIX MBCS JOB# 1 TOTAL 235.00

JOB# 2 CHARGES-----

LABOR-----

J# 2 19MBZ2019030017 REPL DR/PASS-SIDE AB TECH(S):2230 WARRANTY

PERFORM OPEN RECALL CAMPAIGN 2019030017, REPLACE DRIVER-SIDE AND FRONT PASSENGER-SIDE AIRBAG. MODEL 204, X204 AND 197, MODEL YEAR 2011 - 2015.

DC# 91 940 017, LOP:02-2942 (W204) 1.4, 02-2942 (X204) 1.0 OR 02-2942 (197) ZM.

Replaced driver and passenger's airbags. Cleared DTCs. No SRS light on before or after repair. (NON 0.5, 0.4, 0.5, 0.3, 3.4, 4.7, 3.2)068178

PARTS	QTY	FP-NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	
1	000-860-55-02-9116	DRIVER S AIRBA				WARRANTY
1	197-860-00-00-05	FRONT PASSENGE				WARRANTY
TOTAL - PARTS					0.00	

JOB# 2 TOTALS-----

JOB# 2 JOURNAL PREFIX MBCS JOB# 2 TOTAL 0.00

JOB# 3 CHARGES-----

LABOR-----

J# 3 12MBZ-MPI-A MULTI-POINT INSPECT TECH(S):2230 INTERNAL

PERFORM COURTESY MULTI-POINT INSPECTION - VALUE \$79.95

COMPLETED MULTI-POINT INSPECTION.

REFER TO INSPECTION SHEET

JOB# 3 TOTALS-----

JOB# 3 JOURNAL PREFIX MBCS JOB# 3 TOTAL 0.00

JOB# 4 CHARGES-----

LABOR-----

J# 4 40MBZ-0-INFLAT CAL LAW TIRE CHECK TECH(S):2230 INTERNAL

B.A.R. # AK041274

EPA # CAD 982021008

EPA # CAC 002584953

EPA # CAL 000258049

SERVICE INVOICE

MERCEDES-BENZ OF SAN FRANCISCO

Customer Name

Phone: (H)

Service Advisor: JON KEARNS

Vehicle Year/Model: 11 MERCEDES-BENZ SLS AI Date/Time: 08/21/2019 14:13:54

VIN: WDDRJ7HA8BA001717

Technician: SETH C CALLAHAN

Odometer: 20904

RO: 695989

Tag: 069

INSPECTION RESULT - OK

WILL REQUIRE FURTHER ATTENTION

REQUIRES IMMEDIATE ATTENTION

Green Yellow Red

Serviced

<input checked="" type="checkbox"/>	<input type="checkbox"/>	Window Washer	
<input type="checkbox"/>	<input type="checkbox"/>	Transmission (if equipped with dipstick)	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Brake Reservoir	
<input type="checkbox"/>	<input type="checkbox"/>	Power steering fluid	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Coolant Recovery Reservoir	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Engine oil	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Operation of horn, interior lights, exterior lights, turn signals, hazard and brake lamps	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Windshield washer spray, wiper operations and wiper blades	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Warning lights	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Interior	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Air cleaner element	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Drive belts and hoses	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	Auxiliary/ISM battery (if equipped)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Under hood	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Front /rear differential and transfer case (leaks)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Axles/driveshaft(s) and boots/driveline flex couplers	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Exhaust system (leaks/damage/loose parts)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Brake system (including lines, hoses, and parking brake)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Cooling system (leaks/wear/damage)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Heating and air conditioning operation	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Steering and steering linkages	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Front suspension components (leaks/damage)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rear suspension components (leaks/damage)	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	Air suspension (if equipped)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Transmission (leaks)/clutch operation (if equipped)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Engine (leaks)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Fuel system (leaks/damage)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Recommended scheduled maintenance services	<input type="checkbox"/>

Brake Lining Measurements: LF: 7 mm RF: 7 mm LR: 8 mm RR: 8 mm

Tire Tread Measurements: LF: 7 mm RF: 6 mm LR: 4 mm RR: 5 mm

Front / Rear Brake Linings

LF	<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	RF	<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red
LR	<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	RR	<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red

☐ Inspection Not Taken

Over 7mm Remaining

4mm to 6mm

3mm or Less

Check Tires / Tread Depth

LF	<input type="checkbox"/> Green	<input checked="" type="checkbox"/> Yellow	<input type="checkbox"/> Red	RF	<input type="checkbox"/> Green	<input checked="" type="checkbox"/> Yellow	<input type="checkbox"/> Red
LR	<input type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	RR	<input type="checkbox"/> Green	<input checked="" type="checkbox"/> Yellow	<input type="checkbox"/> Red

Spare: ☐ Green ☐ Yellow ☐ Red

8mm or Greater

4mm to 7mm

3mm or Less

Check Battery 1 Performance



☒ Good
☐ Fair
☐ Bad

Actual Cold Cranking Amps

Factory Cold Cranking Amps

Check Battery 2 Performance



☐ Good
☐ Fair
☐ Bad

Actual Cold Cranking Amps

Factory Cold Cranking Amps



Chassis Alignment Test Sheet



Branch Agency -- Firm no.

Customer

JEFFREY HELLER
MB OF SF

Vehicle ident no.

WDDRJ7HA8BA001717

Repair order no.

695989

Measurement carried out: Name
2230

Date/Time

21.8.19 10:16

Odometer reading: km/miles

20904

License plate no.
SLSGWLW

First reg. date Model

Mercedes-Benz 2011 197 (Self-leveling
Suspension) -08.2012 (Modified Specification)

Complaints or reason for alignment check

Tire make

Tire designation

Tire performance: km/miles

		Front left	Front right	Rear left	Rear right
Tire air pressure (cold tires) bar/psi/kPa					
Tire tread depth (mm)	outside				
	center				
	inside				
		Before correction	Target Data	After correction	
Front axle vehicle level ready for driving (mm/°)	left	-8mm/-4.6° *	-2.9° +/-1.4°	-8mm/-4.6° *	
	right	-7mm/-4.5° *		-7mm/-4.5° *	
Shock tube length (mm)	left				
	right				
Ball point location (mm)	left				
	right				
Rear axle vehicle level ready for driving (mm/°)	left	2mm/6.4°	7.2° +/-1.1°	2mm/6.4°	
	right	2mm/6.4°		2mm/6.4°	
Control point with level control (mm/°)					
Rear axle	Camber +/- (°)	left	-1°58'	+/-0°10'	-1°59'
		right	-1°54'		-1°55'
	Caster (°)	left			
		right			
	total		0°18'	+/-0°07'	0°19'
					0°10'
	Toe +/- (°)	left	0°08'	+/-0°07'	0°09'
		right	0°10'		0°00'
	Geometrical driving axis		0°00'	+/-0°07'	0°00'
Front axle	Camber +/- (°)	left	-1°50'	+/-0°15'	-1°48'
		right	-2°10'		-2°10'
	Caster (°)	left	10°56'	+/-0°30'	10°56'
		right	11°01'		11°02'
	Track diff. right wheel lock 20°		-1°37'	+/-0°30'	-1°36'
			-1°38'		-1°38'
	angle +/- (°) left wheel lock 20°		0°02'		0°04'
	Setback		-0°27'		-0°29'
	Unpressed	total	-0°27'	+/-0°07'	-0°29'
	Pressed	left	-0°16'	+/-0°04'	-0°14'
		right	-0°11'		-0°15'
	Maximum steering lock on curve inside wheel (°)	left			
		right			

ed = manually entered

* Measurement is out of tolerance.

d = exceeds cross-tolerance

HTA-MB-R-PA

WinAlign 14.4.2

MB Version 2.0

Spec: 5.01b

Daimler AG Vertrieb Personenwagen
D-70322 StuttgartAll rights reserved, including reprinting,
reproduction, or translation, in whole or in part.

CHASE
 08/10/2019
 14:55:55
 XXXXXXXXXXXXXXXX
 12V 24V
 CREDIT CARD

Invoice # 28012
 MILLBRAE TIRE & AUTO REPAIR
 184 EL CAMINO REAL - MILLBRAE, CA 94030
 650-689-5110 MILLBRAETIRE@YAHOO.COM
 BAR# ARD259593 EPA# CAL000346398
 DATE 7-10-2019

NAME: JEFFREY HELLER
 MILLBRAE, CA 94030
 TAG: SLSGLW
 YR: 2011 MAKE: MERSEDES
 MODEL: SLS AMG
 MILEAGE: 20884
 MOTOR:
 VIN: WDDRJ7HA8BA001717
 HPHONE: 415-730-5707
 WPHONE: 650-
 TECH: AK
 NOTES:
 MANAGER: VA
 PO NUMBER:
 MANUF:

PART#	DESCRIPTION	QTY	PRICE	DISC	TOTAL
P	P265/35R19 MICHELIN PILOT SUPPER SPORT (98Y) XL 59800	2.00	339.00	0	678.00
BT	BALANCE TIRE UP TO 17 INCH	2.00	25.00	0	50.00
VS	VALVE CORE	2.00	3.25	0	6.50
WW	WEIGHT WHEIGHTS	2.00	4.00	0	8.00
TDF	TIRE DISPOSAL FEE	2.00	3.50	0	7.00
CATIRETAX	STATE OF CA TIRE TAX	2.00	1.75	0	3.50
RM	** TIRES REQUIRE ROTATION EVERY 6 MONTHS OR 6,000 MILES	1.00	0.00	0	0.00
RM1	TIRE WARRANTY IS LIMITED TO MANUFACTURES WARRANTY	1.00	0.00	0	0.00
RM2	TIRES DO NOT HAVE ROAD HAZARD WARRANTY	1.00	0.00	0	0.00

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle for the purposes of testing and inspection. An express mechanics lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

Parts 703.00
 Labor 50.00
 Subtotal 753.00
 CA SALES TAX 65.03

 Total 818.03
 Mc/Visa 818.03

Signature X _____



Mercedes-Benz

24 HOURS
ROADSIDE ASSISTANCE
CALL 1-800-222-0100

Mercedes-Benz of San Francisco

1480 FOLSOM ST. - CORNER 11th
SAN FRANCISCO, CALIFORNIA 94103
PHONE (415) 673-1700 FAX (415) 553-9912
www.sfbenz.com



B.A.R. # AK041274
EPA # CAD 982021008

RECOMMENDED SERVICES

OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL	OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL
91MBZ-SEATBELT	REP/REPL SEAT BELT	RN	0.00				

SERVICE HISTORY

DATE	REPAIR ORDER	MILEAGE	ADVISOR	TECHNICIAN	TYPE	OPERATION	OPERATION DESCRIPTION
08/13/19	695989	20904	2432	2230 2230 2230 2230 002 2230	C W I I I I	40MBZ-ALIGN 19MBZZ2019030017 12MBZ-MPI-A 40MBZ-O-INFLAT 08MBZ-WASH 96MBZZ03	*CK ALIGNMENT ADJ TO REPL DR/PASS-SIDE AB MULTI-POINT INSPECT CAL LAW TIRE CHECK CAR WASH EXTERI. ONLY NO QUOTE FT TIRES

SALESPERSON NO. you may choose another licensed facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary. STATE REG# 4291

C.S.I. CALLED	VEHICLE I.D. NO.	YEAR/MAKE/MODEL	PRODUCTION DATE	STOCK NO.	LICENSE NO.	R.O. NO.
	WDDRJ7HA8BA001717	11/MERCEDES-BENZ/SLS AMG/2DR CPE	05/31/10		SLSGLW	709710
DATE		CUSTOMER NO.	SERVICE CONTRACT	DELIVERY DATE	DELIVERY MILES	SELLING DEALER NO.
		108923		07/20/10		R.O. DATE
		COLOR	MILEAGE OUT	EXPIRATION DATE	EXPIRATION MILES	TAG NO.
		AMG IMOLA GREY/CL				425
TIME		TURBO	M/MC	AIR COND.	P. S.	TRANS
		N	MBZZ	Y	Y	A
		MILEAGE	ADVISOR NO.	ADVISOR		
		21,143	2432	JON KEARNS		
		THIS CONTRACT LIMITS OUR LIABILITY-READ IT: I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on the streets, highways or elsewhere for the purpose of testing and/or inspection. MERCEDES BENZ OF SAN FRANCISCO and its agents, employees and representatives are not responsible for any loss, theft or destruction of the vehicle described herein or of any personal property left in vehicles, left on the premises of MERCEDES BENZ OF SAN FRANCISCO for servicing and/or repair. Customer represents that no articles of personal property have been left in the vehicle and MERCEDES BENZ OF SAN FRANCISCO is not responsible for inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs and attorney fees thereto. A \$75.00 maximum daily storage fee may be charged the day after repairs are completed. SUBJECT TO CONDITIONS OF REVERSE SIDE OF THIS CONTRACT. Customer acknowledges that he/she has read all provisions of this contract, agrees to be bound thereby and has received a copy. ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE. ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE PRIOR TO REPAIR.				
APPOINTMENT	X Yes E# 15998060001729					
JOB	X CUSTOMER SIGNATURE					

5 I * 08MBZ-WASH CAR WASH EXTERI. ONLY
PERFORM COMPLIMENTARY CAR WASH - VALUE \$19.95

REVISED ESTIMATE (1) \$	REVISED ESTIMATE (2) \$	REVISED ESTIMATE (3) \$
DATE		
TIME		
PERSON CONTACTED		
PHONE #		

I HEREBY ACKNOWLEDGE THAT I WAS NOTIFIED & GAVE ORAL APPROVAL OF THE ABOVE REVISED ESTIMATES:

X CUSTOMER SIGNATURE

NOTICE TO CUSTOMERS
WE MAKE A SEPARATE CHARGE FOR THE STORAGE AND DISPOSAL OF TOXIC WASTES. RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR TO ALL OF OUR SERVICE CUSTOMERS. WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE ON REQUEST.

VEHICLE CHECK-IN	
C - Chips	Spare Tire
S - Scratch	Radio
D - Dent	CB
M - Missing	Fuel
T - Tear	F 1/2 E
G - Glass Damage	
Customer Signature	
HAZ. WASTE CHARGE	
GALS. GAS/DIESEL	
QTS. OIL	
GEAR OIL	
A.T.F.	
FREON BR. FLUID	

MONDAY THRU FRIDAY 7:30 A.M. - 5:30 P.M. CLOSED SATURDAY AND SUNDAY



Mercedes-Benz

24 HOURS
ROADSIDE ASSISTANCE
CALL 1-800-222-0100

Mercedes-Benz of San Francisco

1480 FOLSOM ST. - CORNER 11th
SAN FRANCISCO, CALIFORNIA 94103
PHONE (415) 673-1700 FAX (415) 553-9912
www.sfbenz.com



B.A.R. # AK041274
EPA # CAD 982021008

RECOMMENDED SERVICES

OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL	OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL
91MBZ-SEATBELT	REP/REPL SEAT BELT	RN	0.00				

SERVICE HISTORY

DATE	REPAIR ORDER	MILEAGE	ADVISOR	TECHNICIAN	TYPE	OPERATION	OPERATION DESCRIPTION
08/13/19	695989	20904	2432	2230 2230 2230 2230 002 2230	C W I I I I	40MBZ-ALIGN 19MBZ2019030017 12MBZ-MPI-A 40MBZ-O-INFLAT 08MBZ-WASH 96MBZ203	*CK ALIGNMENT ADJ TO REPL DR/PASS-SIDE AB MULTI-POINT INSPECT CAL LAW TIRE CHECK CAR WASH EXTERI. ONLY NO QUOTE FT TIRES

SALESPERSON NO. you may choose another licensed facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary. STATE REG# 4291

C.S.I. CALLED DATE TIME	VEHICLE I.D. NO. WDDRJ7HA8BA001717	YEAR/MAKE/MODEL 11/MERCEDES-BENZ/SLS	PRODUCTION DATE 05/31/10	STOCK NO.	LICENSE NO. SLSGLW	R.O. NO. 709710	
	CUSTOMER NO. 108923		SERVICE CONTRACT 07/20/10	DELIVERY MILES	SELLING DEALER NO.	R.O. DATE 03/03/20	
	COLOR AMG IMOLA GREY/CL		MILEAGE OUT	EXPIRATION DATE	EXPIRATION MILES	TAG NO. 425	
	TURBO N	M/MC MBZZ	AIR COND. Y	P.S. Y	TRANS A	MILEAGE 21,143	ADVISOR NO. 2432
PHONE		<small>THIS CONTRACT LIMITS OUR LIABILITY-READ IT: I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on the streets, highways or elsewhere for the purpose of testing and/or inspection. MERCEDES BENZ OF SAN FRANCISCO and its agents, employees and representatives are not responsible for any loss, theft or destruction of the vehicle described herein or of any personal property left in vehicles, left on the premises of MERCEDES BENZ OF SAN FRANCISCO for servicing and/or repair. Customer represents that no articles of personal property have been left in the vehicle and MERCEDES BENZ OF SAN FRANCISCO is not responsible for inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs and attorney fees thereto. A \$75.00 maximum daily storage fee may be charged the day after repairs are completed. SUBJECT TO CONDITIONS OF REVERSE SIDE OF THIS CONTRACT. Customer acknowledges that he/she has read all provisions of this contract, agrees to be bound thereby and has received a copy. ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE. ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE PRIOR TO REPAIR.</small>					
TIME RECEIVED 11:50am		DATE/TIME PROMISED 03/04/20 05:00pm		PRIORITY 5			
APPOINTMENT <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	E# 15998060001729						
JOB		X CUSTOMER SIGNATURE					

PLEASE, SAVE PARTS ☐

ORIGINAL CLIENT ESTIMATE: TOTAL

650.00

X _____

1 C* 06MBZ-SLSLOF SLS OIL AND FILTER
CUSTOMER REQUEST TO PERFORM ENGINE OIL AND FILTER CHANGE ONLY.

2 C 42MBZ-FLUSH *BRAKE FLUID FLUSH
CUSTOMER REQUEST TO FLUSH BRAKE FLUID SYSTEM.

3 I* 12MBZ-MPI-A MULTI-POINT INSPECT
PERFORM COURTESY MULTI-POINT INSPECTION - VALUE \$79.95


4 C* 40MBZ-O-INFLAT CAL LAW TIRE CHECK
PERFORM CALIFORNIA STATE LAW AB32 MANDATORY "TIRE INFLATION CHECK AND CORRECTION"
Notice to our guests; We will check and correct your front and rear tire pressures when inflated with air. Nitrogen is unavailable at this service center; tire pressures will not be corrected on any vehicle that is identified as Nitrogen inflated. Nitrogen inflated tires are identified by a green valve stem cap. Green valve stems caps is the industrial identification standard for Nitrogen inflated tires.

REVISED ESTIMATE (1) \$	REVISED ESTIMATE (2) \$	REVISED ESTIMATE (3) \$
DATE		
TIME		
PERSON CONTACTED		
PHONE #		

I HEREBY ACKNOWLEDGE THAT I WAS NOTIFIED & GAVE ORAL APPROVAL OF THE ABOVE REVISED ESTIMATES.

X
CUSTOMER SIGNATURE

NOTICE TO CUSTOMERS
WE MAKE A SEPARATE CHARGE FOR THE STORAGE OF TOXIC WASTES. RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE ON REQUEST.



C - Chips
S - Scratch
D - Dent
M - Missing
T - Tear
G - Glass Damage

Spare Tire _____
Radio _____
CB _____
Fuel ☐ F ☐ 1/2 ☐ E

Customer Signature _____

	HAZ. WASTE CHARGE		
	GALS. GAS/DIESEL		
	QTS. OIL		
	GEAR OIL		
	A.T.F.		
	FREON BR. FLUID		

MONDAY THRU FRIDAY 7:30 A.M. - 5:30 P.M. CLOSED SATURDAY AND SUNDAY



Mercedes-Benz

24 HOURS
ROADSIDE ASSISTANCE
CALL 1-800-222-0100

Mercedes-Benz of San Francisco

1480 FOLSOM ST. - CORNER 11th
SAN FRANCISCO, CALIFORNIA 94103
PHONE (415) 673-1700 FAX (415) 553-9912
www.sfbenz.com



B.A.R. # AK041274
EPA # CAD 982021008

RECOMMENDED SERVICES

OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL	OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL
91MBZ-SEATBELT	REP/REPL SEAT BELT	RN	0.00				

SERVICE HISTORY

DATE	REPAIR ORDER	MILEAGE	ADVISOR	TECHNICIAN	TYPE	OPERATION	OPERATION DESCRIPTION
07/03/19	693149	20867	2432	2640 2640 2640 002	W C I I	19MBZ2019030017 54MBZ-BATT 40MBZ-O-INFLAT 08MBZ-WASH	REPL DR/PASS-SIDE AB *REPAIR/REPL BATTERY CAL LAW TIRE CHECK CAR WASH EXTERI. ONLY
02/14/19	683362	20475	2432	2198 2432	C C	06MBZ-SLS60K 53MBZ-SMOG	SLS 60K STATE SMOG CHECK

SALESPERSON NO. 11/10, you may choose another licensed facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary. STATE REG# 4291

C.S.I. CALLED	VEHICLE I.D. NO. WDDRJ7HA8BA001717	YEAR/MAKE/MODEL 11/MERCEDES-BENZ/SLS AMG/2DR CPE	PRODUCTION DATE 05/31/10	STOCK NO.	LICENSE NO. SLSGLW	R.O. NO. 695989
DATE	CUSTOMER NO. 108923	SERVICE CONTRACT	DELIVERY DATE 07/20/10	DELIVERY MILES	SELLING DEALER NO.	R.O. DATE 08/13/19
TIME	COLOR AMG IMOLA GREY/CL	MILEAGE OUT	EXPIRATION DATE	EXPIRATION MILES	TAG NO. 069	
	TURBO N	M/MC MBZZ	AIR COND. Y	P.S. Y	TRANS A	MILEAGE 20,904
	S PHONE	ADVISOR NO. 2432	ADVISOR JON KEARNS			
	TIME RECEIVED 04:43pm	DATE/TIME PROMISED 08/13/19 06:00pm	PRIORITY 5	THIS CONTRACT LIMITS OUR LIABILITY-READ IT: I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on the streets, highways or elsewhere for the purpose of testing and/or inspection. MERCEDES BENZ OF SAN FRANCISCO and its agents, employees and representatives are not responsible for any loss, theft or destruction of the vehicle described herein or of any personal property left in the vehicle and MERCEDES BENZ OF SAN FRANCISCO for servicing and/or repair. Customer represents that no articles of personal property have been left in the vehicle and MERCEDES BENZ OF SAN FRANCISCO is not responsible for inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs and attorney fees thereto. A \$75.00 maximum daily storage fee may be charged the day after repairs are completed. SUBJECT TO CONDITIONS OF REVERSE SIDE OF THIS CONTRACT. Customer acknowledges that he/she has read all provisions of this contract, agrees to be bound thereby and has received a copy. ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE. ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE PRIOR TO REPAIR.		
APPOINTMENT	E# 15998060001729					
JOB	PLEASE, SAVE PARTS					

caps is the industrial identification standard for Nitrogen inflated tires.

5 I * 08MBZ-WASH CAR WASH EXTERI. ONLY
PERFORM COMPLIMENTARY CAR WASH - VALUE \$19.95

REVISED ESTIMATE (1) \$	REVISED ESTIMATE (2) \$	REVISED ESTIMATE (3) \$
DATE		
TIME		
PERSON CONTACTED		
PHONE #		

I HEREBY ACKNOWLEDGE THAT I WAS NOTIFIED & GAVE ORAL APPROVAL OF THE ABOVE REVISED ESTIMATES:

X CUSTOMER SIGNATURE

NOTICE TO CUSTOMERS

WE MAKE A SEPARATE CHARGE FOR THE STORAGE AND DISPOSAL OF TOXIC WASTES. RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE ON REQUEST.



VEHICLE CHECK-IN

Mercedes-Benz



C - Chips
S - Scratch
D - Dent
M - Missing
T - Tear
G - Glass Damage

Spare Tire _____
Radio _____
CB _____
Fuel

F	1/2	E
---	-----	---

Customer Signature _____

	HAZ. WASTE CHARGE		
	GALS. GAS/DIESEL		
	QTS. OIL		
	GEAR OIL		
	A.T.F.		
	FREON BR. FLUID		

MONDAY THRU FRIDAY 7:30 A.M. - 5:30 P.M. CLOSED SATURDAY AND SUNDAY



Mercedes-Benz

24 HOURS
ROADSIDE ASSISTANCE
CALL 1-800-222-0100

Mercedes-Benz of San Francisco

1480 FOLSOM ST. - CORNER 11th
SAN FRANCISCO, CALIFORNIA 94103
PHONE (415) 673-1700 FAX (415) 553-9912
www.sfbenz.com



B.A.R. # AK041274
EPA # CAD 982021008

RECOMMENDED SERVICES

OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL	OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL
91MBZ-SEATBELT	REP/REPL SEAT BELT	RN	0.00				



SERVICE HISTORY

DATE	REPAIR ORDER	MILEAGE	ADVISOR	TECHNICIAN	TYPE	OPERATION	OPERATION DESCRIPTION
07/03/19	693149	20867	2432	2640 2640 2640 002	W C I I	19MBZ2019030017 54MBZ-BATT 40MBZ-O-INFLAT 08MBZ-WASH	REPL DR/PASS-SIDE AB *REPAIR/REPL BATTERY CAL LAW TIRE CHECK CAR WASH EXTERI. ONLY
02/14/19	683362	20475	2432	2198 2432	C C	06MBZ-SLS60K 53MBZ-SMOG	SLS 60K STATE SMOG CHECK

SALESPERSON NO. you may choose another licensed facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary. STATE REG# 4291

C.S.I. CALLED	VEHICLE I.D. NO.	YEAR/MAKE/MODEL	PRODUCTION DATE	STOCK NO.	LICENSE NO.	R. O. NO.
	WDDRJ7HA8BA001717	11/MERCEDES-BENZ/SLS AMG/2DR CPE	05/31/10		SLSGLW	695989
DATE		CUSTOMER NO.	SERVICE CONTRACT	DELIVERY DATE	DELIVERY MILES	SELLING DEALER NO.
		108923		07/20/10		
TIME		COLOR	MILEAGE OUT	EXPIRATION DATE	EXPIRATION MILES	TAG NO.
		AMG IMOLA GREY/CL				069
		TURBO	M/MC	AIR COND.	P. S.	TRANS
		N	MBZZ	Y	Y	A
		PHONE		MILEAGE	ADVISOR NO.	ADVISOR
				20,904	2432	JON KEARNS
APPOINTMENT	TIME RECEIVED	DATE/TIME PROMISED	PRIORITY	THIS CONTRACT LIMITS OUR LIABILITY-READ IT: I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on the streets, highways or elsewhere for the purpose of testing and/or inspection. MERCEDES BENZ OF SAN FRANCISCO and its agents, employees and representatives are not responsible for any loss, theft or destruction of the vehicle described herein or of any personal property left in the vehicle and MERCEDES BENZ OF SAN FRANCISCO is not responsible for inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs and attorney fees thereto. A \$75.00 maximum daily storage fee may be charged the day after repairs are completed. SUBJECT TO CONDITIONS OF REVERSE SIDE OF THIS CONTRACT. Customer acknowledges that he/she has read all provisions of this contract, agrees to be bound thereby and has received a copy.		
	04:43pm	08/13/19 06:00pm	5	ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE. ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE PRIOR TO REPAIR.		
	E# 15998060001729			PLEASE, SAVE PARTS		

ORIGINAL CLIENT ESTIMATE: TOTAL	235.00
X	
1 C * 40MBZ-ALIGN	*CK ALIGNMENT ADJ TO CLIENT REQUEST CHECK WHEEL ALIGNMENT, ADJUST TOE IF NECESSARY. CAMBER/CASTER BOLT KITS PARTS & LABOR TO INSTALL ARE ADDITIONAL IF REQUIRED.
2 W * 19MBZ2019030017	REPL DR/PASS-SIDE AB PERFORM OPEN RECALL CAMPAIGN 2019030017, REPLACE DRIVER-SIDE AND FRONT PASSENGER-SIDE AIRBAG. MODEL 204, X204 AND 197, MODEL YEAR 2011 - 2015.
3 I * 12MBZ-MPI-A	MULTI-POINT INSPECT PERFORM COURTESY MULTI-POINT INSPECTION - VALUE \$79.95
4 I * 40MBZ-O-INFLAT	CAL LAW TIRE CHECK PERFORM MANDATORY CALIFORNIA STATE LAW AB32 "TIRE INFLATION CHECK AND CORRECTION" Notice to our guests; We will check and correct your front and rear tire pressures when inflated with air. Nitrogen is unavailable at this service center; tire pressures will not be corrected on any vehicle that is identified as Nitrogen inflated. Nitrogen inflated tires are identified by a green valve stem cap. Green valve stems

REVISED ESTIMATE (1) \$	REVISED ESTIMATE (2) \$	REVISED ESTIMATE (3) \$
DATE		
TIME		
PERSON CONTACTED		
PHONE #		
I HEREBY ACKNOWLEDGE THAT I WAS NOTIFIED & GAVE ORAL APPROVAL OF THE ABOVE REVISED ESTIMATES:		
X CUSTOMER SIGNATURE		
NOTICE TO CUSTOMERS WE MAKE A SEPARATE CHARGE FOR THE STORAGE AND DISPOSAL OF TOXIC WASTES, RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR TO ALL OF OUR SERVICE CUSTOMERS. WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES. THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE ON REQUEST.		
 Mercedes-Benz		
		
C - Chips	S - Scratch	D - Dent
M - Missing	T - Tear	G - Glass Damage
Spare Tire		Radio
CB		Fuel
Customer Signature		
HAZ. WASTE CHARGE		
GALS. GAS/DIESEL		
QTS. OIL		
GEAR OIL		
A.T.F.		
FREON BR. FLUID		

MONDAY THRU FRIDAY 7:30 A.M. - 5:30 P.M. CLOSED SATURDAY AND SUNDAY