



Mercedes-Benz

Mercedes-Benz of San Francisco

1480 FOLSOM STREET
SAN FRANCISCO, CALIFORNIA 94103
(415) 673-1700 • FAX (415) 553-9912
www.sfbenz.com

709710
SF
Benz

709710



0101IMBCS709710

24 HOURS

ROADSIDE ASSISTANCE SERVICE
1-800-222-0100

CUSTOMER NO.	108923	ADVISOR	JON KEARNS	TAG NO.	425	INVOICE DATE	03/05/20	INVOICE NO.	MBCS709710
		LICENSE NO.	2432	MILEAGE	21,143	COLOR	AMG IMOLA G	STOCK NO.	
		YEAR / MAKE / MODEL	SLSGLW			DELIVERY DATE	07/20/10	DELIVERY MILES	
		VEHICLE ID. NO.	11/MERCEDES-BENZ/SLS AMG/2DR CPE			SELLING DEALER NO.		PRODUCTION DATE	05/31/10
		P.T.E. NO.	W D D R J 7 H A 8 B A 0 0 1 7 1 7	P.O. NO.		R.O. DATE	03/03/20		
		COMMENTS	E# 15998060001729						

MO: 21145

JOB# 7 TOTALS-----

JOB# 7 JOURNAL PREFIX MBCS JOB# 7 TOTAL 0.00

ESTIMATE-----

CLIENT HEREBY ACKNOWLEDGES RECEIVING

ORIGINAL ESTIMATE OF \$650.00 (+TAX)

APPROVED ADDITIONAL COST OF \$45.00 FOR TOTAL ESTIMATE OF \$695.00 (+TAX) ON 03/03/20 AT 11:50am

BY JEFFREY HELLER COMMENTS

COMMENTS-----

RECOMMENDED NOT DONE/ DECLINED SERVICES-----

TOTALS-----

PLEASE CALL 415-673-1700 TO SCHEDULE YOUR NEXT APPOINTMENT!

MERCEDES BENZ OF SAN FRANCISCO THANKS YOU FOR YOUR BUSINESS

*****DRIVE SAFELY AND HAVE A GREAT DAY*****

[]CASH []CHECK#.....[]CHARGE[]VISA[]MC[]AMX[]DISCOVER

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN
THE ORIGINAL ESTIMATE PRICE.

CLIENT SIGNATURE

TOTAL LABOR.... 551.95
TOTAL PARTS.... 122.13
TOTAL SUBLET... 0.00
TOTAL G.O.G.... 0.00
TOTAL MISC CHG. 6.89
TOTAL MISC DISC 0.00
TOTAL TAX..... 10.39

TOTAL INVOICE \$ 691.36

MAR 10 2020

BY: _____

B.A.R. # AK041274

EPA # CAD 982021008

EPA # CAC 002584953

EPA # CAL 000258049

Mercedes-Benz

Mercedes-Benz of San Francisco

1480 FOLSOM STREET

SAN FRANCISCO, CALIFORNIA 94103

(415) 673-1700 • FAX (415) 553-9912

www.sfbenz.com

709710
SF
Benz

709710



0101IMBCS709710

24 HOURS

ROADSIDE ASSISTANCE SERVICE
1-800-222-0100

CUSTOMER NO. 108923	ADVISOR JON KEARNS	TAG NO. 2432	INVOICE DATE 03/05/20	INVOICE NO. MBCS709710
	LICENSE NO. SLSGLW	MILEAGE 21,143	COLOR AMG IMOLA G	STOCK NO.
	YEAR / MAKE / MODEL 11/MERCEDES-BENZ/SLS AMG/2DR CPE		DELIVERY DATE 07/20/10	DELIVERY MILES
	VEHICLE I.D. NO. WDDRJ7HA8BA001717		SELLING DEALER NO.	PRODUCTION DATE 05/31/10
	P.T.E. NO.	P.O. NO.	R.O. DATE 03/03/20	
COMMENTS E# 15998060001729			MO: 21145	

JOB# 3 TOTALS-----

JOB# 3 JOURNAL PREFIX MBCS JOB# 3 TOTAL 0.00

JOB# 4 CHARGES-----

LABOR-----

J# 4 40MBZ-0-INFLAT CAL LAW TIRE CHECK TECH(S):2634 4.00

PERFORM CALIFORNIA STATE LAW AB32 MANDATORY "TIRE INFLATION CHECK AND CORRECTION"

Notice to our guests; We will check and correct your front and rear tire pressures when inflated with air. Nitrogen is unavailable at this service center; tire pressures will not be corrected on any vehicle that is identified as Nitrogen inflated. Nitrogen inflated tires are identified by a green valve stem cap. Green valve stems caps is the industrial identification standard for Nitrogen inflated tires.

AS PER AB32, CHECK AND CORRECTED TIRE INFLATION TO MANUFACTURE SPECIFICATIONS.

TIRES INFLATED TO (PSI);

FRONT 31

REAR 35

JOB# 4 TOTALS-----

LABOR 4.00

JOB# 4 JOURNAL PREFIX MBCS JOB# 4 TOTAL 4.00

JOB# 5 CHARGES-----

LABOR-----

J# 5 08MBZ-WASH CAR WASH EXTERI. ONLY TECH(S):002 INTERNAL

PERFORM COMPLIMENTARY CAR WASH - VALUE \$19.95

WASHED AND VACUUMED VEHICLE

JOB# 5 TOTALS-----

JOB# 5 JOURNAL PREFIX MBCS JOB# 5 TOTAL 0.00

JOB# 6 CHARGES-----

LABOR-----

J# 6+96MBZZ03 NO QUOTE FT TIRES TECH(S):2634 0.00

Added Operation (JONK @ 03/04/2020 15:32)

FRONT TIRES MAY NEED ATTENTION NEXT VISIT

WILL RECHECK FRONT TIRES AND ADVISE NEXT VISIT

JOB# 6 TOTALS-----

JOB# 6 JOURNAL PREFIX MBCS JOB# 6 TOTAL 0.00

JOB# 7 CHARGES-----

LABOR-----

J# 7+96MBZZ04 NO QUOTE RR TIRES TECH(S):2634 0.00

Added Operation (JONK @ 03/04/2020 15:32)

REAR TIRES MAY NEED ATTENTION NEXT VISIT

WILL RECHECK REAR TIRES AND ADVISE NEXT VISIT

B.A.R. # AK041274

EPA # CAD 982021008

EPA # CAC 002584953

EPA # CAL 000258049

SERVICE INVOICE

Mercedes-Benz of San Francisco

1480 FOLSOM STREET

SAN FRANCISCO, CALIFORNIA 94103

(415) 673-1700 • FAX (415) 553-9912

www.sfbenz.com



0101IMBCS709710

24 HOURS

ROADSIDE ASSISTANCE SERVICE
1-800-222-0100

CUSTOMER NO. 108923	ADVISOR JON KEARNS	TAG NO. 425	INVOICE DATE 03/05/20	INVOICE NO. MBCS709710
	LICENSE NO. SLSGLW	MILEAGE 21,143	COLOR AMG IMOLA G	STOCK NO.
	YEAR / MAKE / MODEL 11/MERCEDES-BENZ/SLS AMG/2DR CPE		DELIVERY DATE 07/20/10	DELIVERY MILES
	VEHICLE I.D. NO. W D D R J 7 H A 8 B A 0 0 1 7 1 7		SELLING DEALER NO.	PRODUCTION DATE 05/31/10
	F.T.E. NO.	P.O. NO.	R.O. DATE 03/03/20	
COMMENTS E# 15998060001729				

MO: 2114

JOB# 1 CHARGES-----

LABOR-----
J# 1 06MBZ-SLSLOF SLS OIL AND FILTER TECH(S):2634 360.00
 CUSTOMER REQUEST TO PERFORM ENGINE OIL AND FILTER CHANGE ONLY.
 PERFORMED OIL AND FILTER CHANGE ONLY AS REQUESTED.

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	LIST PRICE	UNIT PRICE-	PRICE-
	1	000-180-30-09	FILTER ELEMENT	19.50	19.50	19.50
	9	000-989-79-02-19BIFU	229.5 SAE 5W-4	6.24	6.24	56.16
	1	007603-018101	SEAL RING,VLRU	2.99	2.99	2.99
	1	007603-014106	SEAL RING,VLRU	5.99	5.99	5.99
	1	012-997-56-48	SEAL RING.INJC	13.99	13.99	13.99
TOTAL - PARTS						98.63

MISC-----	CODE-----	DESCRIPTION-----	CONTROL NO-----	
	HA	HAZARDOUS WASTE DISPOSAL FEE		1.54
TOTAL - MISC				1.54

JOB# 1 TOTALS-----

LABOR	360.00
PARTS	98.63
MISC	1.54

JOB# 1 JOURNAL PREFIX MBCS JOB# 1 TOTAL 460.17

JOB# 2 CHARGES-----

LABOR-----
J# 2 42MBZ-FLUSH *BRAKE FLUID FLUSH TECH(S):2634 187.95
 CUSTOMER REQUEST TO FLUSH BRAKE FLUID SYSTEM.
 PERFORM BRAKE SYSTEM FLUID FLUSH.

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	LIST PRICE	UNIT PRICE-	PRICE-
	1	000-989-08-07-01	BRAKE FLUID	23.50	23.50	23.50
TOTAL - PARTS						23.50

MISC-----	CODE-----	DESCRIPTION-----	CONTROL NO-----	
	HABF	BRAKE FLUID WASTE DISPOSAL FEE		5.35
TOTAL - MISC				5.35

JOB# 2 TOTALS-----

LABOR	187.95
PARTS	23.50
MISC	5.35

JOB# 2 JOURNAL PREFIX MBCS JOB# 2 TOTAL 216.80

JOB# 3 CHARGES-----

LABOR-----
J# 3 12MBZ-MPI-A MULTI-POINT INSPECT TECH(S):2634 INTERNAL
 PERFORM COURTESY MULTI-POINT INSPECTION - VALUE \$79.95
 COMPLETED MULTI-POINT INSPECTION.
 REFER TO INSPECTION SHEET

B.A.R. # AK041274
EPA # CAD 982021008
EPA # CAC 002584953
EPA # CAL 000258049

SERVICE INVOICE

MERCEDES-BENZ OF SAN FRANCISCO

Phone: (H) [Redacted]

Service Advisor: JON KEARNS

Vehicle Year/Model: 11 MERCEDES-BENZ SLS AI Date/Time: 03/05/2020 06:51:49

VIN: WDDRJ7HA8BA001717

Odometer: 21143

Technician: KARL HASELBACH

RO: 709710

Tag: 425

INSPECTION RESULT - OK

WILL REQUIRE FURTHER ATTENTION

REQUIRES IMMEDIATE ATTENTION

Green Yellow Red

Serviced

☒	☐	Window Washer	
☒	☐	Transmission (if equipped with dipstick)	
☒	☐	Brake Reservoir	
☒	☐	Power steering fluid	
☒	☐	Coolant Recovery Reservoir	
☒	☐	Engine oil	
☒	☐	BATTERY DATE CODE	
☒	☐	Operation of horn, interior lights, exterior lights, turn signals, hazard and brake lamps	☐
☒	☐	Windshield washer spray, wiper operations and wiper blades	☐
☒	☐	Warning lights	☐
☒	☐	Interior	☐
☒	☐	Air cleaner element	☐
☒	☐	Drive belts and hoses	☐
☒	☐	Auxiliary/ISM battery (if equipped)	☐
☒	☐	Under hood	☐
☒	☐	Front /rear differential and transfer case (leaks)	☐
☒	☐	Axles/driveshaft(s) and boots/driveline flex couplers	☐
☒	☐	Exhaust system (leaks/damage/loose parts)	☐
☒	☐	Brake system (including lines, hoses, and parking brake)	☐
☒	☐	Cooling system (leaks/wear/damage)	☐
☒	☐	Heating and air conditioning operation	☐
☒	☐	Steering and steering linkages	☐
☒	☐	Front suspension components (leaks/damage)	☐
☒	☐	Rear suspension components (leaks/damage)	☐
☒	☐	Air suspension (if equipped)	☐
☒	☐	Transmission (leaks)/clutch operation (if equipped)	☐
☒	☐	Engine (leaks)	☐
☒	☐	Fuel system (leaks/damage)	☐
☒	☐	Recommended scheduled maintenance services	☐

Brake Lining Measurements: LF: 10 mm RF: 10 mm LR: 10 mm RR: 10 mm

Tire Tread Measurements: LF: 7 mm RF: 7 mm LR: 5 mm RR: 5 mm

Front / Rear Brake Linings

LF	☒ Green	☐ Yellow	☐ Red	RF	☒ Green	☐ Yellow	☐ Red
LR	☒ Green	☐ Yellow	☐ Red	RR	☒ Green	☐ Yellow	☐ Red

☐ Inspection Not Taken

Over 7mm Remaining

4mm to 6mm

3mm or Less

Check Tires / Tread Depth

LF	☐ Green	☒ Yellow	☐ Red	RF	☐ Green	☒ Yellow	☐ Red
LR	☐ Green	☒ Yellow	☐ Red	RR	☐ Green	☒ Yellow	☐ Red

Spare: ☐ Green ☐ Yellow ☐ Red

8mm or Greater

4mm to 7mm

3mm or Less

Check Battery 1 Performance



- ☒ Good
☐ Fair
☐ Bad

Actual Cold Cranking Amps

Factory Cold Cranking Amps

Check Battery 2 Performance



- ☐ Good
☐ Fair
☐ Bad

Actual Cold Cranking Amps

Factory Cold Cranking Amps