

Porsche Palm Springs

**Porsche Palm Springs**  
3737 E Palm Canyon Dr  
Palm Springs, California, 92264, US  
Phone: (760) 610-0432  
www.porschepalmsprings.com

Repair Order #: **106466**  
Tag #: **T3091**  
Advisor: **Danielle Brian**  
Advisor No. #: **57**  
Order Open Date: **2023-12-19**

Customer Information

Vehicle Information

2023 PORSC 911

VIN #: **WP0AF2A94PS278085**  
Color #: **SILVER**  
Mileage In/Out #: **768/769**

Job # A

**Labor Total: No Charge**

**Re-code Airbag control unit**

Cause:

Correction(s):

APB3\_2 Re-code Airbag control unit  
Tech Number: 600166 Labor Type: W

No Charge

Part Number Part Description Qty List

**Parts Total: No Charge**

768 70 Performed Campaign APB3. Verified during coding proper voltage of 13.6 volts minimum and created Post-VAL after coding.

**Misc Total: No Charge**

**Job # A Total**

**\$ 0.00**

Job # B

**Labor Total: No Charge**

**Replacing oil filler neck**

Cause:

Correction(s):

WPE9\_3 Replacing oil filler neck  
Tech Number: 600166 Labor Type: IPS

No Charge

Part Number Part Description Qty List

**Parts Total: No Charge**

768

**Misc Total: No Charge**

\* OEM means Original Equipment Manufacturer (factory) Parts | \*\* All parts are New unless specified otherwise.

12/22/2023 9:38 AM

~~ Thank you for your business ~~

Porsche Palm Springs

**Porsche Palm Springs**  
3737 E Palm Canyon Dr  
Palm Springs, California, 92264, US  
Phone: (760) 610-0432  
www.porschepalmsprings.com

Repair Order #: 106466  
Tag #: T3091  
Advisor: Danielle Brian  
Advisor No. #: 57  
Order Open Date: 2023-12-19

**Job # B Total \$ 0.00**

**Job # C Labor Total: No Charge**

**Replacing rear wing circlips**  
Cause:  
Correction(s):  
WPG4\_1 Replacing rear wing circlips  
Tech Number: 600166 Labor Type: W

No Charge

Part Number	Part Description	Qty	List	Parts Total:	No Charge
9GT-898-533	1 SET CIRCLIPS	1			
768 78 Performed campaign WPG4 Replaced 14 wing clips.					

**Misc Total: No Charge**

**Job # C Total \$ 0.00**

**Job # D Labor Total: \$ 0.00**

**REPLACE FRONT WINDHSIELD**  
Cause:  
Correction(s):  
00 GENERAL REPAIR  
Tech Number: 999 Labor Type: CP

\$0.00

Part Number	Part Description	Qty	List	Parts Total:	\$ 2,801.93
992-845-011-AN	WINDSCREEN	1	\$ 2,667.92	\$ 2,667.92	
9A7-955-609-20	ADHESIVE FILM	1	\$ 134.01	\$ 134.01	

**Misc Total: \$ 480.00**

**Job # D Total \$ 3,281.93**

\* OEM means Original Equipment Manufacturer (factory) Parts | \*\* All parts are New unless specified otherwise.

Porsche Palm Springs

**Porsche Palm Springs**  
3737 E Palm Canyon Dr  
Palm Springs, California, 92264, US  
Phone: (760) 610-0432  
www.porschepalmsprings.com

Repair Order #: 106466  
Tag #: T3091  
Advisor: Danielle Brian  
Advisor No. #: 57  
Order Open Date: 2023-12-19

Job # E				Labor Total:	No Charge
<b>PORSCHE PALM SPRINGS COMPLEMENTARY MULTI-POINT INSPECTION</b>					
<b>Cause:</b>					
<b>Correction(s):</b>					
PMPI PORSCHE PALM SPRINGS COMPLEMENTARY MULTI-POINT INSPECTION				No Charge	
Tech Number: 600166 Labor Type: IPS					
Part Number	Part Description	Qty	List	Parts Total:	No Charge
768 Performed complimentary multi-point inspection. Tires 5mm front 5mm rear brakes 8mm front 8mm rear.					
				Misc Total:	No Charge
<b>Job # E Total</b>					<b>\$ 0.00</b>

Job # F				Labor Total:	No Charge
<b>CHECK AND RECORD TIRE PRESSURES PER CALIFORNIA STATE LAW, ADJUST AS NEEDED</b>					
<b>Cause:</b>					
<b>Correction(s):</b>					
TIREC COMPLETED TIRE PRESSURE CHECK				No Charge	
Tech Number: 600166 Labor Type: IPS					
Part Number	Part Description	Qty	List	Parts Total:	No Charge
768 Front 31psi Rear 32psi					
				Misc Total:	No Charge
<b>Job # F Total</b>					<b>\$ 0.00</b>

Job # G				Labor Total:	No Charge
<b>PERFORM COURTESY WASH &amp; VACUUM UPON CUSTOMER REQUEST.</b>					
<b>Cause:</b>					
<b>Correction(s):</b>					
WASH PERFORM COURTESY WASH & VACUUM UPON CUSTOMER				No Charge	

Porsche Palm Springs

**Porsche Palm Springs**

3737 E Palm Canyon Dr  
Palm Springs, California, 92264, US  
Phone: (760) 610-0432  
www.porschepalmsprings.com

Repair Order #: 106466  
Tag #: T3091  
Advisor: Danielle Brian  
Advisor No. #: 57  
Order Open Date: 2023-12-19

REQUEST.

Tech Number: 999 Labor Type: IPS

Part Number	Part Description	Qty	List	Parts Total:	No Charge
				Misc Total:	No Charge
<b>Job # G Total</b>					<b>\$ 0.00</b>

Job # H

Labor Total: No Charge

**CUSTOMER REQUESTS 10000 MILE SERVICE**

Cause: SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE

Correction(s):

10K CUSTOMER REQUESTS 10000 MILE SERVICE

No Charge

Tech Number: 600166 Labor Type: WPSMP

Part Number	Part Description	Qty	List	Parts Total:	No Charge
0PB-115-351	OIL FILTER	1			
PAF-013-844	SEAL RING	1			
9GT-115-647-B	END CAP	1			
0W40ESPQTX3	MOBIL1 ESP 0W40 QT X3	5			
768 208 Performed vehicle 10,000 mile service, Adjusted tire pressures, Drained engine oil , changed oil filter, filled engine oil to 75 percent level, inputted into service booklet of the vehicle. Oil tank drain plug needed to be reused, part was not in stock approved by The shop foreman.				Misc Total:	No Charge
<b>Job # H Total</b>					<b>\$ 0.00</b>

Miscellaneous

Job #	PO #	Description
D	9999	REMOVE AND REPLACE FRONT WINDSHIELD

Miscellaneous Total: \$ 480.00

Porsche Palm Springs

**Porsche Palm Springs**  
3737 E Palm Canyon Dr  
Palm Springs, California, 92264, US  
Phone: (760) 610-0432  
www.porschepalmsprings.com

Repair Order #: **106466**  
Tag #: **T3091**  
Advisor: **Danielle Brian**  
Advisor No. #: **57**  
Order Open Date: **2023-12-19**

RO Comments

**Amount Totals**

Total Labor: **\$ 0.00**

Total Parts: **\$ 2,801.93**

Miscellaneous + Discounts: **\$ 3,061.11**

Sales Tax: **\$ 259.18**

Shop Supplies: **\$ 0.00**

**Customer Total: \$ 0.00**

Terms and Acceptance

Customer acknowledges approval of work described in this Repair Order Summary. Any Warranties on the product sold herein are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

Please look for a survey on your service experience. The manufactures survey will be sent to you by email. If you are not sure if your current email address is on file please check with your service advisor.

We're working hard to make customers for life!



Customer acknowledges receipt of copy

THE THERMAL CLUB

61980 Tyler Street  
THERMAL CA 92274  
760-674-0088

12/21/2023 3:22 PM

page 1

Invoice #15991

Vehicle : 2023 Porsche 911 GT3 RS  
VIN : WP0AF2A94PS278085  
Created : 12/1/2023 11:30:52 AM  
Complete : 12/21/2023 3:22:53 PM  
Invoiced : 12/21/2023 3:22:53 PM  
Srv Writer : DS

Color : Silver  
Odometer In : 0  
Odometer Out : 0

Labor/Notes

Qty	Code/Tech*	Reference	Description	Unit Price	Price
-	-	NOTE	NO LABOR CHARGE PER ALLEN		
1	AI*	OIL CHANGE	PERFORM OIL CHANGE SERVICE	\$0.00	\$0.00

Parts

Qty	Code/Tech*	Reference	Description	Condition	Unit Price	Price
1	-	OPB115351	PORSCHE OIL FILTER	New	\$74.93	\$74.93
1	-	PAF-013-844	SEAL RING	New	\$2.88	\$2.88
1	-	9GT-115-647-B	END CAP	New	\$31.65	\$31.65
10	-	MOB 112628	MOBIL 1 0W40	New	\$19.54	\$195.40

Labor	\$0.00
Parts	\$304.86
Sublet/Misc.	\$0.00
Shop Supplies/Hazard	\$0.00
Charges	\$0.00
Sales Tax	Tax @ \$304.86 * 7.7500%
	\$23.63

Total Due **\$328.49**

Tech Certification #  
AI

Repair Order only. See your monthly Thermal Club statement for invoice and payment.

