

Name	
Addr.	
Phone	
B- Name	
B-Addr.	
B-Phone	
Prod Date	12/80 E26/S38/
V.I.N. #	4301343

Inv. Date	12/18/23	Year	1981
S.O. Date	10/07/21	Make	BMW
QC'd by	7	Model	M1
Salesman	GC	Color	ORANGE
Division	SS	Miles	52362
		Lic.#	MRLASER

Service Description	Hrs.	Lab\$
PERFORM VEHICLE CHECK	11.30	2147.00
CHANGE OIL AND FILTER		
REPLACE BATTERY		
INITIAL COMPRESSION TEST COLD- 50/165/155/160/150/150		
CONFIRMED CRANKING OIL PRESSURE AT 80 PSI		
REPLACE BOTH BELLOWS FROM FUEL FILLERS TO TANKS		
CRANK, NO START. CHECK SPARK PLUGS, OIL PRESSURE,		
REPLACE COOLANT BLEEDER HOSE WITH TEMPORARY		
REPLACE ALL FUSES		
DRAIN RESIDUAL FUEL, INSTALL NEW FUEL WITH INJECTION		
CLEANER.		
REPLACE FUEL PUMP, FILTER, FUEL LINES AS NEC		
REPLACE FUEL PUMP RELAY, ADD INJECTOR CLEANER TO TANK		
RAN ENGINE, STALLED- FUEL PUMP FAILED		
REPLACE FUEL PUMP AGAIN- ADD PRE-FILTER BEFORE PUMP		
NOTE: ENGINE RUNS, HAVE NOT TEST DRIVEN		
WATER PUMP LEAKS HEAVILY- NOT AVAILABLE		
ENGINE FUEL HOSES IN POOR SHAPE- NOT AVAILABLE		
OTHER SMALLER ISSUES NOTED ON VEHICLE CHECK		

Qty	Part Number	Part Description	Price
1	61-21-2-353-806	BMW BATTERY 70AH	150.00
1	61-21-8-353-010	HOLD-DOWN	12.84
1	13-32-1-270-039	FUEL FILTER	50.64
1	11-42-1-304-423	OIL FILTER OC54	47.50
2	16-12-2-161-436	FUEL HOSE	177.60
1	16-11-2-161-383	FUEL HOSE- TANK TO PUMP	194.91
1	16-11-2-161-381	FUEL HOSE- FILTER TO ENG	195.33
1	13-53-7-563-456	FUEL HOSE 8x13mm 6BAR	77.59
1	12-63-1-277-245	GAS PUMP RELAY *	198.17
2	16-12-2-160-628	FUEL PUMP M1	1150.00
2	51-21-1-809-735	BUFFER *	11.08
2	LM 22076	LM DIJECTRON FUEL CLEANER	49.00
1	MRG 9748	INLINE FUEL FILTER	38.95
7	83-21-2-365-946 P	PENNZOIL EURO 5W40 LL-01	69.93
6	6681	NGK 6681 SPARK PLUG	145.20
1	11-53-1-304-334	HOSE EURO	51.85
1	13-51-1-304-360	BELT {M-1}	208.59
4	17-12-2-160-162	8-HOSE EURO	135.76
1	17-12-2-160-442	HOSE EURO	57.38
1	17-12-2-160-443	HOSE EURO	241.50

Additional Items	Sublet or Add'l Services
	GASOLINE
	M1 ELEC DIAGRAMS
	GAS
	20.00
	99.50
	17.70
Total Items	Total Sublets
	137.20

Notes

Next service due on: ???

Totals	
Labor	2147.00
Parts	3325.31
Supplies	0.00
Sublets	137.20
Addl. Items	0.00
Subtotal	5609.51
Tax	282.10
Total	5891.61

(Page 1 of 2)

Thank you for giving us the opportunity to service your vehicle. If you notice any problems or have any concerns about these repairs, please call us immediately. Bar No. AD159774

rus

te
#

Date
Date
d by
esman
vision

12/80 E26/S38/
4301343

1 2/18/23
06/15/23
41,33
OWNER
SS

Year 1981
Make BMW
Model M1
Color ORANGE
Miles 52362
Lic.# MRLASER

Service Description	Hrs.	Lab\$
REPLACE WATER PUMP, THERMOSTAT, COOLANT HOSES #41 AS NEC REPLACE BELTS RECHECK COMPRESSION AFTER RUNNING- 130/130/130/130/130/125	20.20	3838.00
BRAKE FLUID FLUSH #41 R/F OUTER BLEEDER WAS CLOGGED, REMOVED AND CLEANED, GOOD NOW R/R WILL NOT BLEED PROPERLY- POSSIBLE HOSE OR CALIPER OTHER 3 CALIPERS BLED NORMALLY	2.00	380.00
MOUNT AND BALANCE 4 TIRES #33	1.00	190.00
PERFORM 4 WHEEL ALIGNMENT #7	1.00	190.00

Qty	Part Number	Part Description	Price
1	07-11-9-906-322	O-RING	2.97
1	11-53-1-275-881	BLEEDER	4.37
1	99-91-9-209-750	BELT 10 x 725	13.79
1	11-53-1-307-737	O.E. ONLY T/STAT	68.38
1	13-X1-0-50	13 X 1050	24.16
1	11-51-1-401-537	GASKET	15.34
1	11-51-1-401-538	GASKET	10.51
1	17-12-1-712-736	NEW COOLANT HOSE	134.36
2	11-51-7-729-587	7-O-RING	15.60
2	23-41-1-666-133	RUB RING	16.14
2	12-31-1-305-037	3PK980 BELT	158.08
1	40718A	WIPER BLADE 18"	25.95
1	11-51-9-065-550	WATER PUMP EURO	2450.50
1	11-53-1-304-331	8-HOSE	49.50
1	82-14-1-467-704Q	COOLANT(QUARTS)	45.60
12	61-31-2-160-338	OIL PRESS SWITCH 14x1.5	93.75
1	HYD FLUID	ATE SL.6 DOT 4 LITER	42.20
2	205/55/16 CONTI 91W	CONTI EXTRCONT SPT 02	378.00
2	225/50/16 SPORT 02	CONTI EXTRCNT SPT 02 92W	378.00
8	WEIGHTS	WHEEL WEIGHTS	16.00

Additional Items	Sublet or Add'l Services
Total Items	Total Sublets 0.00

Notes
Next service due on: ???

Totals	
Labor	4598.00
Parts	3963.60
Supplies	0.00
Sublets	0.00
Addl. Items	0.00
Subtotal	8561.60
Tax	335.17
Total	8896.77

(Page 1 of 2)

Thank you for giving us the opportunity to service your vehicle. If you notice any problems or have any concerns about these repairs, please call us immediately. Bar No. AD159774

1641 Jackson Street, San Francisco, CA. 94109 415-567-8000

