

# 1989 PORSCHE 911 TURBO CABRIOLET

10/6/18

w/ SLANTNOSE - OPTION CODE M505

- GUARDS RED w/ CASHMERE, 282HP, 3.3L,
- FACTORY CERTIFICATE OF AUTHENTICITY
- 1989 FACTORY BROCHURE w/ FINISH OPTIONS
- G50 FIVE SPEED - ONE YEAR ONLY - 1989
- MULTIPLE SETS OF FACTORY KEYS
- TWO OWNERS, NORTHERN CALIFORNIA
- 45,000 MILES
- OPTIONAL EQUIPMENT: STEER WHEEL w/ RAISED HUB  
TUNNEAU COVER  
AMPLIFIER SYSTEM  
HEATED SEAT - LEFT  
SLANT NOSE  
LIMITED SLIP DIFFERENTIAL  
"CD-2" CD PLAYER w/ RADIO  
SHORTER GEAR SHIFT LEVER  
LUGGAGE COMPARTMENT  
BLACK VELOUR
- TOOL ROLL, JACK, SPARE TIRE, TIRE COMPRESSOR
- BOOKS,
- AIR CONDITIONING - DOES NOT WORK CURRENTLY
- SLIGHTEST WEAR ON DRIVER SEAT LEFT BOLSTER
- SLIGHT CHIP/CRACK IN WIND SHIELD, AT LEAST 14 YRS
- ONE OF 20 BUILT IN 1989
- PRICE NEW: 85,060 FOR TURBO CABRIOLET  
IN 1989      29,555 FOR SLANT NOSE  
\$114,615
- WITH BATTERY TENDER
- ALARM SYSTEM
- SEKURIFLEX WINDSHIELD w/ BUILT IN ANTENNA
- ORIGINAL PAINT, TOP, LEATHER,
- CORRECT BLAUPUNKT RADIO



1989 PORSCHE 911 TURBO  
 CABRIOLET SLANTNOSE WPOEB0932K507052

DATE	MILEAGE	COST	DESCRIPTION	VENDOR
3-19-05	42,402	-	PURCHASE IN WALNUT CREEK	PRESTIGE AUTOHAUS
3-15-06*	41,112	410.13	CHANGE OIL, MISC. REPAIRS	"
5-9-07	43,739	50.25	SMOG TEST	SAVE ON SMOGS
5-1-08	44,090	1062.81	NEW BATTERY, OIL/BRAKE SERVICE	PRESTIGE AUTOHAUS
5-7-09	44,173	75.00	SMOG TEST	AAAAA SMOG CNTR
4-21-11	44,470	75.00	" "	"
5-13-13	44,780	85.00	" "	"
9-4-14		223.05	NEW BATTERY	AUTOS INTL.
4-18-15	44,971	61.75	FAILED SMOG TEST	AAAAA
4-20-15	44,996	655.28	OIL CHANGE, ADJUSTED IDLE	EUROPEAN AUTOTECH
4-21-15	44,996	INCL.	PASSED SMOG TEST	" " "
4-19-17	45,245	80.00	SMOG TEST	PACHECO SMOG
3-23-18	45,415	292.94	MINOR SERVICE, FLUID CHANGE	EUROPEAN AUTOTECH

\* MILEAGE INCORRECT ON SERVICE DOCUMENT



ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

\*CODE N-NEW U-USED R-REBUILT

QTY.	*	PART NO. OR DESCRIPTION	SALE AMOUNT
11		QTS HELIX SYNTHETIC 5W-40	211 20
1		OIL FILTER	28 87
TOTAL PARTS			240 07
OUTSIDE-SUBLET REPAIRS			

*PAID C/C  
OMER*

# PRESTIGE AUTOHAUS

2259 North Main Street  
Walnut Creek, California 94596  
Phone (925) 937-5400  
BAR# AA 075111 -- EPA# CAL 000163257

020503  
**REPAIR  
ORDER**

NAME	DATE	LABOR CHARGE PER HR.
ADDR	3-15-06	MAINTENANCE INSPECTION <input type="checkbox"/>
CITY		LUBRICATION <input type="checkbox"/>
PHON	YEAR	MAKE
RES.	89	PORSCHE
BUS.		930
VEH. I.D.#	W P O E B O 9 3 2 K \$ 0 7 0 5 2 4	TYPE OR MODEL
MILEAGE	041,112	LIC. #
		5MEM588
TIME REC'D	TIME PROM.	GROSS VEH. WT.
A.M.	A.M.	ORD. WRITTEN BY
P.M.	P.M.	CUST. ORDER NO.
OPER. NO.	REPAIR ORDER - DESCRIPTION OF WORK	
OMER	REPAIR FRONT SEAT	
	CHARGE BATTERY, CHECK CHARGING SYSTEM, INSTALL TANAU COVER CLIP	
	1.25HR	150 00
	NOTE: BRAKE FLUID SYSTEM NEEDS TO BE FLUSHED	
	TRANSAXLE OIL NEEDS TO BE CHANGED	

PLEASE INITIAL HERE \_\_\_\_\_ TOTAL SUBLET REPAIRS  
FOLLOWING REPAIRS RECOMMENDED

ORIGINAL ESTIMATE \$	390.00	DATE	3-15-06	IN PERSON BY	J. CABER	TOTAL LABOR	150 00
REVISED ESTIMATE \$		DATE		PH #		TOTAL PARTS	240 07
REVISED ESTIMATE \$		DATE		PH #		GAS, OIL, GREASE	
I acknowledge notice and oral approval of an increase in the original estimated price.						HAZARDOUS WASTE DISPOSAL	8 25
Tel. _____ Best time to call _____						SUBLET REPAIRS	
Replaced parts requested by customer YES <input type="checkbox"/> NO <input type="checkbox"/>						SMOG CERTIFICATE	
I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read and understand the above and acknowledge receipt of an estimate. "BY LAW YOU MAY CHOOSE ANOTHER LICENSED SMOG FACILITY TO PERFORM ANY NEEDED REPAIRS OR ADJUSTMENTS WHICH THE SMOG CHECK TEST INDICATES ARE NECESSARY."						SUB TOTAL	398 32
						TAX	19 81
						PAY THIS AMOUNT	418 13

**WARRANTY:** From date of delivery for a period of 4,000 miles or 90 days, whichever comes first. This firm will repair free of charge any defects in material and workmanship to the repairs stated on this invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts.  
\$\_\_\_\_\_ per day storage fee will be charged 24 hours after notification of work completed.

TERMS ARE CASH UNLESS OTHER PRIOR ARRANGEMENTS ARE MADE  
SEE IMPORTANT INFORMATION ON BACK



Vehicle Information

Model Year... 1989 Make... PORSCHE Model... 911 CARRERA
License... 5MEM588 State... California VIN... WPOEB0932KS070524
Engine Size... 3.2 Liters Type... Passenger Transmission... Manual
GVWR... N/A Test Weight... 3000 lbs. Cylinders... 6
Odometer... 43739 Certification... California VLT Record #... 10758
Fuel Type... Gasoline Exhaust... Single Inspection Reason... 1.9% RND
Engine Year... N/A Engine Make... N/A Bar Number... N/A
Fleet BAR File #... N/A

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection..(Pass) Functional Check..(Pass) Emissions Test..(Pass)

DMV ID Number..(2132Q159M154)
Smog Check Certificate Number..(MQ990367)

Your Smog Check certificate has been electronically transmitted to the DMV. This certificate is valid for ninety (90) days from the date of issuance.

Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist the identification of oxides of nitrogen, crankcase, and cold start emissions which are not measured during the idle tests)

Table with 6 columns: ECS, Result, ECS, Result, ECS, Result. Rows include PCV, Catalytic Converter, Pump Air Injection, Vacuum lines sensors/switches, Fuel Cap Integrity Test, Thermostatic Air Cleaner, Spark Controls, Oxygen Sensor, Other related emis. components, Fuel Cap Visual, Fuel Evaporative Controls, Fuel Injection, Wiring to Sensors, Liquid Fuel Leak, Ignition Timing (26 BTDC).

SMOG CHECK VEHICLE INSPECTION REPORT

(05/09/2007 @ 9:16:00 am)

Page # 2 VIN..... WPOEB0932KS070524 License.. 5MEM588

ASM Emission Test Results

Table with 14 columns: Test, RPM, %CO2, %O2, HC (PPM), CO (%), NO (PPM), Result. Rows include M1: 15 MPH, M2: 25 MPH.

MAX = Maximum Allowed Emissions AVE = Average Emissions For Passing Vehicles MEAS = Amount Measured

Smog Check Station Information

SAVE ON SMOGS INC Technician Name/Number..... TEIFEL THOMAS ALLEN/EA137545
1250 CONTRA COSTA BLVD #107 Repair Tech Name/Number..... N/A
PLEASANT HILL, CA 94523 Software Version/EIS Number... 0311/SX980135
925 691 1045 Station Number..... TC232873



022084

# PRESTIGE AUTOHAUS

2259 North Main Street  
Walnut Creek, California 94596  
Phone (925) 937-5400  
BAR# AA 075111 -- EPA# CAL 000163257

**REPAIR INVOICE**

LABOR CHARGE PER HR. \_\_\_\_\_

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

\* CODE = N-NEW U-USED R-REBUILT O-OEM A-AFTERMARKET C-CUSTOMER SUPPLIED

* QTY	PART NO. & DESCRIPTION	AMOUNT
1	MEGA INTERSTATE BATTERY	193.73
1	OIL FILTER 930-107-764-01	34.10
11	QTS HELIX ULTRA SYNTHETIC OIL 5W/40	242.00
2	COPPER DRAIN PLUG SEALS	5.00
4	QTS SYNTHETIC GEAR OIL	88.00
2	COPPER DRAIN PLUG SEALS FOR TRANSAXLE	5.00
4	PTS BRAKE FLUID DOT-4	44.00

DATE	5-1-08	<input type="checkbox"/> MAINTENANCE INSPECTION
STATE	ZIP	<input type="checkbox"/> LUBRICATION
HC		<input type="checkbox"/> CHANGE OIL GRADE
		<input type="checkbox"/> CHANGE OIL FILTER CART.
PHONE WHEN READY	ORDER WRITTEN BY	LICENSE PLATE #
<input type="checkbox"/> YES <input type="checkbox"/> NO	MIKI/OMER	5MEM588
MAKE	MODEL	YEAR
PORSCHE	930 TURBO	1989
		ODOMETER
		44,090
V.I.N.	CUST. PO #	
W P O E B 0 9 3 2 K S 0 7 0 5 2 4		

OPR. #	REPAIR ORDER • DESCRIPTION OF LABOR		
	CAR TOWED IN. BATTERY COMPLETELY DEAD. CAR IS STORED MOSTLY.		
	CHARGE OLD BATTERY, CHECK CHARGING SYSTEM. BATTERY IS DEAD.	.5	65.00
	INSTALL NEW MEGA BATTERY.		
	INSTALL CUSTOMERS SUPPLIED CONECTOR FOR AUTO BATT. CHARGER. N/C		
	SERVICE TRANSAXLE AND REPLACE NEW GEAR OIL.	.5	65.00
	FLUSH BRAKE SYSTEM, BLEED IT AND RENEW BRAKE FLUID	1.0	130.00
	OIL, FILTER, LUBRICATION SERVICE & SAFETY INSPECTION	1.0	130.00
	HAND WASH AND VACUM		N/C

**TOTAL PARTS 611.83**

**OUTSIDE-SUBLET REPAIRS**

*PAID VISA 5-10-08*

INITIAL TO AUTHORIZE SUBLET REPAIRS \_\_\_\_\_ **TOTAL SUBLET REPAIRS**

**FOLLOWING REPAIRS RECOMMENDED**

**WARRANTY:** FROM DATE OF DELIVERY FOR A PERIOD OF 4,000 MILES OR 90 DAYS, WHICHEVER COMES FIRST, THIS FIRM WILL REPAIR FREE OF CHARGE ANY DEFECTS IN MATERIAL AND WORKMANSHIP TO THE REPAIRS STATED ON THIS INVOICE. ALL WORK TO BE DONE IN THIS SHOP ONLY. THIS DOES NOT INCLUDE TOWING OR CUSTOMER SUPPLIED PARTS.

ORIGINAL ESTIMATE \$	DATE	TIME	PHONE/CONTACT	<input type="checkbox"/> BY PHONE <input type="checkbox"/> EMAIL <input type="checkbox"/> IN PERSON <input type="checkbox"/> FAX	TOTAL LABOR	390.00	
I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT, DYNAMOMETER TESTING OR ANY OTHER CAUSE BEYOND YOUR CONTROL. IN THE EVENT LEGAL ACTION IS NECESSARY TO ENFORCE THIS CONTRACT, I UNDERSTAND THAT I AM SOLELY RESPONSIBLE FOR ALL COSTS INCLUDING ATTORNEY'S FEES AND COURT COSTS. I HAVE READ AND UNDERSTAND THE ABOVE. I ACKNOWLEDGE RECEIPT OF AN ESTIMATE. SMOG CHECK CUSTOMERS: BY LAW YOU MAY CHOOSE ANOTHER SMOG CHECK STATION TO PERFORM NEEDED REPAIRS, INSTALLATIONS, ADJUSTMENTS OR SUBSEQUENT TESTS.							
REVISSED ESTIMATE \$	DATE	TIME	PHONE/CONTACT	<input type="checkbox"/> BY PHONE <input type="checkbox"/> EMAIL <input type="checkbox"/> IN PERSON <input type="checkbox"/> FAX	TOTAL PARTS	611.83	
REASON	I ACKNOWLEDGE NOTICE AND APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE.					AUTH. BY	REC'D BY
REVISSED ESTIMATE \$	DATE	TIME	PHONE/CONTACT	<input type="checkbox"/> BY PHONE <input type="checkbox"/> EMAIL <input type="checkbox"/> IN PERSON <input type="checkbox"/> FAX	GAS, OIL, GREASE		
REASON	I ACKNOWLEDGE NOTICE AND APPROVAL OF AN INCREASE IN THE REVISED ESTIMATED PRICE.					HAZARDOUS WASTE DISPOSAL	10.50
					SUBLET REPAIRS		
					SMOG CERTIFICATE		
					SUBTOTAL		
					TAX	50.48	

REPLACED PARTS REQUESTED BY CUSTOMER?  YES  NO

TERMS:  CASH  CHECK  CHARGE  DEBIT CARD  CREDIT CARD

**PLEASE PAY THIS AMOUNT 1,062.81**

TERMS ARE CASH UNLESS PRIOR ARRANGEMENTS ARE MADE SEE IMPORTANT INFORMATION ON BACK



# SMOG CHECK VEHICLE INSPECTION REPORT

(05/07/2009 @ 9:14:57 am)

## Vehicle Information

Model Year..... 1989	Make..... PORSCHE	Model..... 911 CARRERA
License..... 5MEM588	State..... California	VIN..... WP0EB0932KS070524
Engine Size..... 3.2 Liters	Type..... Passenger	Transmission..... Manual
GVWR..... N/A	Test Weight..... 3000 lbs.	Cylinders..... 6
Odometer..... 44173	Certification..... California	VLT Record #..... 10758
Fuel Type..... Gasoline	Exhaust..... Single	Inspection Reason.... 1.9% RND
Engine Year..... N/A	Engine Make..... N/A	Bar Number..... N/A
Fleet BAR File #..... N/A		

## Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection..(Pass) Functional Check..(Pass) Emissions Test..(Pass)

DMV ID Number..(2872K050N194)  
Smog Check Certificate Number..(NK164888)

Your Smog Check certificate has been electronically transmitted to the DMV.  
This certificate is valid for ninety (90) days from the date of issuance.

Please keep this copy for your records.

## Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist the identification of oxides of nitrogen, crankcase, and cold start emissions which are not measured during the idle tests)

<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>
PCV.....	Pass	Fuel Evaporative Controls.....	Pass	Catalytic Converter.....	Pass
EGR (Visual).....	Pass	Spark Controls.....	Pass	Fuel Injection.....	Pass
Pump Air Injection.....	Pass	Oxygen Sensor.....	Pass	Wiring to Sensors.....	Pass
Vacuum lines sensors/switches..	Pass	Other related emis. components.	Pass	Liquid Fuel Leak.....	Pass
Fuel Cap Integrity Test.....	Pass	Fuel Cap Visual.....	Pass	Malfunction Indicator Light....	Pass

# SMOG CHECK VEHICLE INSPECTION REPORT

(05/07/2009 @ 9:14:57 am)

Page # 2

VIN..... WP0EB0932KS070524

License.. 5MEM588

## ASM Emission Test Results

Test	RPM			%CO2			HC (PPM)			CO (%)			NO (PPM)			Result
	MEAS	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
M1: 15 MPH	1327	11.7	4.4	121	31	42	0.76	0.10	0.17	807	237	778	Pass			
M2: 25 MPH	2180	11.0	5.1	96	20	16	0.65	0.09	0.11	746	199	365	Pass			

MAX = Maximum Allowed Emissions    AVE = Average Emissions For Passing Vehicles    MEAS = Amount Measured

## Smog Check Station Information

AAAAA SMOG CENTER INC  
2134 MARKET ST  
CONCORD, CA 94520  
707.925.6973

Technician Name/Number..... ALVAREZ, RODOLFO/EA153089  
Repair Tech Name/Number..... N/A  
Software Version/EIS Number... 0311/SX091079  
Station Number..... TC257273



# SMOG CHECK VEHICLE INSPECTION REPORT

(04/21/2011 @ 9:00:43 am)

## Vehicle Information

Model Year..... 1989	Make..... PORSCHE	Model..... 911 CARRERA TURBO
License..... 5MEM588	State..... California	VIN..... WFOEB0932KS070524
Engine Size..... 3.3 Liters	Type..... Passenger	Transmission..... Manual
GVWR..... N/A	Test Weight..... 3375 lbs.	Cylinders..... 6
Odometer..... 44470	Certification..... California	VLT Record #..... 21476
Fuel Type..... Gasoline	Exhaust..... Single	Inspection Reason..... 1.9% RND
Engine Year..... N/A	Engine Make..... N/A	Bar Number..... N/A
Fleet BAR File #..... N/A		

### Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection..(Pass) Functional Check..(Pass) Emissions Test..(Pass)

DMV ID Number..(2674C0500294)  
Smog Check Certificate Number..(OC510340)

Your Smog Check certificate will be electronically transmitted to DMV  
This certificate is valid for ninety (90) days from the date of issuance.

Please keep this copy for your records.

### Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist the identification of oxides of nitrogen, crankcase, and cold start emissions which are not measured during the idle tests)

<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>
PCV.....	Pass	Fuel Evaporative Controls.....	Pass	Catalytic Converter.....	Pass
Spark Controls.....	Pass	Fuel Injection.....	Pass	Pump Air Injection.....	Pass
Oxygen Sensor.....	Pass	Wiring to Sensors.....	Pass	Vacuum lines sensors/switches..	Pass
Other related emis. components.	Pass	Liquid Fuel Leak.....	Pass	Fuel Cap Visual.....	Pass
Ignition Timing (27 BTDC).....	Pass				

### ASM Emission Test Results

Test	RPM		%CO <sub>2</sub>			HC (PPM)			CO (%)			NO (PPM)			Result
	MEAS	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS			
M1: 15 MPH	1350	11.8	4.2	114	31	50	0.73	0.10	0.19	785	237	784	Pass		
M2: 25 MPH	2163	11.1	4.8	88	20	21	0.61	0.09	0.13	724	199	388	Pass		


MAX = Maximum Allowed Emissions    AVE = Average Emissions For Passing Vehicles    MEAS = Amount Measured

### Smog Check Station Information

AAAAA SMOG CENTER INC  
2134 MARKET ST  
CONCORD, CA 94520  
1 925 687 7664

Technician Name/Number..... ALVAREZ, RODOLFO/EA153089  
Repair Tech Name/Number..... N/A  
Software Version/EIS Number... 1003/SX091079  
Station Number..... TC257273

I certify under penalty of perjury under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and correct.

  
 \_\_\_\_\_  
 Date

  
 \_\_\_\_\_  
 Technician's Signature



# SMOG CHECK VEHICLE INSPECTION REPORT

(05/13/2013 @ 2:22:55 pm)

## Vehicle Information

Model Year..... 1989	Make..... PORSCHE	Model..... 911 CARRERA TURBO
License..... 5MEM588	State..... California	VIN..... WPOEB0932KS070524
Engine Size..... 3.3 Liters	Type..... Passenger	Transmission..... Manual
GVWR..... N/A	Test Weight..... 3375 lbs.	Cylinders..... 6
Odometer..... 44780	Certification..... California	VLT Record #..... 21476
Fuel Type..... Gasoline	Exhaust..... Single	Inspection Reason..... HEP
Engine Year..... N/A	Engine Make..... N/A	Bar Number..... N/A
Fleet BAR File #..... N/A		

### Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection..(Pass) Functional Check..(Pass) Emissions Test..(Pass)

DMV ID Number..(2012W1560534)  
Smog Check Certificate Number..(OW237480)

Your Smog Check certificate has been electronically transmitted to the DMV.  
This certificate is valid for ninety (90) days from the date of issuance.

Please keep this copy for your records.

### Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist the identification of oxides of nitrogen, crankcase, and cold start emissions which are not measured during the idle tests)

<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>
PCV.....	Pass	Fuel Evaporative Controls.....	Pass	Catalytic Converter.....	Pass
Spark Controls.....	Pass	Fuel Injection.....	Pass	Pump Air Injection.....	Pass
Oxygen Sensor.....	Pass	Wiring to Sensors.....	Pass	Vacuum lines sensors/switches..	Pass
Other related emis. components.	Pass	Liquid Fuel Leak.....	Pass	Fuel Cap Integrity Test.....	Pass
Fuel Cap Visual.....	Pass	Ignition Timing (27 BTDC).....	Pass		

### ASM Emission Test Results

Test	RPM			%CO2			HC (PPM)			CO (%)			NO (PPM)			Result
	MEAS	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
M1: 15 MPH	1363	11.7	4.0	114	27	47	0.73	0.09	0.17	785	255	784				Pass
M2: 25 MPH	1588	11.5	4.3	88	18	31	0.61	0.07	0.11	724	223	602				Pass

MAX = Maximum Allowed Emissions    AVE = Average Emissions For Passing Vehicles    MEAS = Amount Measured

### Smog Check Station Information

GREEN STAR SMOG CHECK TEST ONLY  
2134 MARKET ST  
CONCORD, CA 94520  
1 925 687 7664

Technician Name/Number..... ALVAREZ, RODOLFO/EA153089  
Repair Tech Name/Number..... N/A  
Software Version/EIS Number... 1201/SX061113  
Station Number..... TC271756

I certify under penalty of perjury under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and correct.

Date

Technician's Signature

5-11-13

[Signature]



**Autos International**

2201 Commerce Ave  
 Concord, CA. 94520  
 Phone - 925-676-0440 Fax - 925-676-4286  
 TRUSTED FOR OUTSTANDING SERVICE

INVOICE

**2427**

Org. Est. # 003029  
 ARD 276078  
 EO637210

**INVOICE**

Print Date : 09/04/2014

0 -  
 Lic # : - Odometer In : 1  
 Unit # : Odometer Out : 1  
 Vin # :  
 Hat # : Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
WARRANTY 85 MO WARRANTY MTP49/H8	1.00	189.95	189.95		
WARRANTY CORE CHARGE BCC	1.00	16.00	16.00	<i>Credited 9/12/14</i>	

Estimate \$ 223.05 Revisions \$ 0.00 Current Estimate \$ 223.05

Labor:	0.00
Parts:	205.95
Sublet:	\$0.00
Sub:	205.95
Tax:	17.10
Total:	223.05
Bal Due:	\$223.05

By: \_\_\_\_\_ Date: \_\_\_\_\_ Time: \_\_\_\_\_  
 I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.



# SMOG CHECK VEHICLE INSPECTION REPORT

(04/18/2015 @ 4:21:08 pm)

## Vehicle Information

Model Year..... 1989	Make..... PORSCHE	Model..... 911 CARRERA TURBO
License..... 5MEM588	State..... California	VIN..... WPOEB0932KS070524
Engine Size..... 3.2 Liters	Type..... Passenger	Transmission..... Manual
GVWR..... N/A	Test Weight..... N/A	Cylinders..... 6
Odometer..... 44971	Certification..... California	VLT Record #..... 21475
Fuel Type..... Gasoline	Exhaust..... Single	Inspection Reason..... HEP
Engine Year..... N/A	Engine Make..... N/A	Bar Number..... N/A
Fleet BAR File #..... N/A		

### Overall Test Results

**ABORTED TEST**  
Engine RPM too high

### Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist the identification of oxides of nitrogen, crankcase, and cold start emissions which are not measured during the idle tests)

<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>
------------	---------------	------------	---------------

### Smog Check Station Information

GREEN STAR SMOG CHECK TEST ONLY  
2134 MARKET ST  
CONCORD, CA 94520  
1 925 687 7664

Technician Name/Number..... SAEPHANH, KYLE/EO631958  
Repair Tech Name/Number..... N/A  
Software Version/EIS Number... 1401/SX061113  
Station Number..... TC271756

I certify under penalty of perjury under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and correct.

4/18/15  
Date



\_\_\_\_\_  
Technician's Signature

**ONE FREE RETEST  
WITHIN 30 DAYS**



authorize the repair work listed herein, including sublet work, to be done along with any materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

# European Autotech Inc.

31-J Beta Court  
 San Ramon, CA 94583  
 (925) 820-6460

BAR # ARD272122, EPA # CAL000021453  
 EUROPEANAUTOTECHSR.COM

X

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

**Invoice # 37085**

**1989 Porsche 911 Turbo Carrera**  
 VIN: WP0EB0932KS070524  
 Engine: H6 3.3L, 3294cc, SOHC, GAS, FI, B  
 Trans: M/T

License # 5MEM588  
 ODO In:44996 Out: 44999  
 Color: Red  
 Mfg. Date: 3/89  
 Unit #

Inv Date: 4/20/2015  
 Service Writer:  
 Status: Complete  
 Driver:  
 PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
<b>Customer states that: diagnose failed smog</b>						
Labor Service - diagnose failed [ aborted ] smog, factory under hood sticker says timing should be at 26 degrees before at 4000 rpm, book says 3 atdc to 1 befor at 900 rpm plus or minus 50 with vacuum lines disconnected and plugged, timing is within specs we lowered the idle to 875. 3			2.00		135.00	270.00
Labor Service - Smog inspection 3 New SC State smog cert.			1.00	1.00	80.00 8.25	80.00 8.25

**Notes: install customers trickle charger**

Labor Service - Install customers trickle charger, cut wire ends and hook to battery 3	0.50		135.00		67.50
--	------	--	--------	--	-------

**Notes: radio code, 45532**

**Notes: service**

Labor Service - Minor service porsche 911 & carreras to 89-change oil and filter, check and top off all fluids, inspect all tire pressures, and a complete safety inspection (belts-brakes-lights). 3	0.50		135.00		67.50
New 930-107-764-01 Oil Filter		1.00	20.34		20.34
New 20W50 B.P. Brad Penn, contains high levels of zinc and phosphorous, for cars with solid lifters		12.00	10.75		129.00

Front brake linings aprox 6 mm remain [ squeak ],  
 rear brake linings aprox 8 mm remain

Revisions of Original Estimate - Original Estimate of Services and Parts \$512.27							
Rev#	Date and Time	Who Contacted	Method	Contact #	Cont. By	Revise By	Total
1	4/22/2015 10:36AM				ADMIN	143.01	655.28
oil,battery							

X

Customer accepts revision to the invoice and agrees to pay revised amount.

**Recommended Repairs and Services:**

- check a/c if easy fix, needs retrofit to r134a 724.64
- Car leaks engine oil [ minor ] from lower timing chain covers and housings, Car needs vacuum hoses replaced to distributor [ brittle ], air filter, belts, recommend new ignition wires or boots on dist end, # 1 was falling off when car came in, needs rear deck shock

**Vehicle Tire Information**

Check Performed.

	Left Front	Right Front	Left Rear	Right Rear	Checked By
Tire Pressure PSI	36	36	38	38	3



**European Autotech Inc.**

31-J Beta Court

San Ramon, CA 94583

(925) 820-6460

BAR # ARD272122, EPA # CAL000021453

EUROPEANAUTOTECHSR.COM

... amount of repair...  
... damage to vehicle or articles left in vehicle...  
... beyond your control...  
... if vehicle is returned to customer without repair...  
... have read and understand the above and do hereby acknowledge receipt of an estimate

X

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

**Invoice # 37085**

**1989 Porsche 911 Turbo Carrera** License # 5MEM588

Inv Date: 4/20/2015

Continued from previous page

<p><b>Warranty</b> 2 YEAR OR 24 -K MILE WARRANTY WHICHEVER COMES FIRST, PARTS AND LABOR GOOD AT THIS REPAIR FACILITY ONLY.</p>		<p><b>Invoice Summary</b></p> <table border="0"> <tr><td>Parts</td><td>157.59</td></tr> <tr><td>Labor</td><td>485.00</td></tr> <tr><td><b>Sub Total</b></td><td><b>642.59</b></td></tr> <tr><td>Sales Tax (CA)</td><td>12.69</td></tr> <tr><td><b>Total</b></td><td><b>655.28</b></td></tr> </table>	Parts	157.59	Labor	485.00	<b>Sub Total</b>	<b>642.59</b>	Sales Tax (CA)	12.69	<b>Total</b>	<b>655.28</b>
Parts	157.59											
Labor	485.00											
<b>Sub Total</b>	<b>642.59</b>											
Sales Tax (CA)	12.69											
<b>Total</b>	<b>655.28</b>											
X	Customer acknowledges receipt of merchandise and services.											
Page 2 of 2	Discard old parts	Original Estimate: 512.27										



# Smog Check Vehicle Inspection Report (VIR)

## Vehicle Information

Test Date/Time: 04/21/2015 @ 13:01

Model Year: 1989	Make: PORSCHE	Model: 911 CARRERA TURBO
License: 5MEM588	State: CA	VIN: WPOEB0932KS070524
Engine Size: 3.3 L	Type: Passenger	Transmission: Manual
GVWR: N/A	Test Weight: 3375	Cylinders: 6
Odometer: 44996	Certification: California	VLT Record #: 21476
Fuel Type: Gasoline	Exhaust: Single	Inspection Reason: High Emitter Profile

## Overall Test Results

Thank you for performing the needed emissions-related repairs to your vehicle. These repairs help California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air.

Smog Check Certificate Number: PQ275302  
DMV ID Number: **2892Q255P954**

Your Smog Check certificate has been electronically transmitted to DMV.  
Your certificate is valid for 90 days from date of issuance.  
Please keep this copy for your records.

## Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	N/A	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	N/A	OBD System Checks
N/A	EGR Visual	Pass	Vacuum Lines to Sensors/ Switches	Pass	Carb./Fuel Injection
N/A	EGR Functional		Ignition Timing: 26 BTDC	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Pass	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	N/A			
N/A	Fuel Evaporative Controls Functional				

## ASM Emission Test Results

Test	RPM	%CO <sub>2</sub>		HC (PPM)			CO (%)			NO (PPM)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
15 mph	1540	11.3	4.5	114	27	108	0.73	0.09	0.57	785	255	664	PASS
25 mph	1566	11.2	4.6	89	18	50	0.61	0.07	0.24	724	223	384	PASS

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

### Repair Actions

Initial Timing (Secondary)      Ok  
Other-Ignition System (Secondary)      Ok

### Repair Costs

Total Repair Time: 2.0 hours  
Emission-Related Repairs (Parts): \$0  
Emission-Related Repairs (Labor): \$270  
Tamper Repairs (Parts and Labor): \$0  
Estimated Costs of Additional Repairs: \$0  
Hourly Labor Rate: \$135  
Emission-Related Repairs (Parts - LIRAP): \$0  
Emission-Related Repairs (Labor - LIRAP): \$0

## Smog Check Inspection Station Information

European Autotech  
31-J Beta Ct San Ramon, CA 94583  
(925) 820-6460  
Station Number: RC272122

Technician Name/Number: MURAD, CHRISTOPHER/EO305306  
Repair Tech Name/Number: MURAD, CHRISTOPHER/EO305306  
Software Version/EIS Number: 1301/ES315295

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate. Pretest repairs performed on this vehicle were not tamper related.

Date

Technician's Signature



# Smog Check Vehicle Inspection Report (VIR)

## Vehicle Information

Test Date/Time: 04/19/2017 @ 11:05

Model Year: 1989	Make: PORSCHE	Model: 911 CARRERA TURBO
License: 5MEM588	State: CA	VIN: WPOEB0932KS070524
Engine Size: 3.3 L	Type: Passenger	Transmission: Manual
GVWR: N/A	Test Weight: 3375	Cylinders: 6
Odometer: 45245	Certification: California	VL Record #: 21476
Fuel Type: Gasoline	Exhaust: Single	Inspection Reason: High Emitter Profile

## Overall Test Results

**Congratulations!** Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: ZT437081  
DMV ID Number: **2828T052Z494**

Your Smog Check certificate has been electronically transmitted to DMV.  
Your certificate is valid for 90 days from date of issuance.  
Please keep this copy for your records.

## Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test)

<u>Result</u>	<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>	<u>ECS</u>
Pass	PCV	N/A	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	N/A	OBD System Checks
N/A	EGR Visual	Pass	Vacuum Lines to Sensors/	Pass	Carb./Fuel Injection
N/A	EGR Functional		Switches	Pass	Other Emission Related
Pass	Fuel Cap Functional	N/A	Ignition Timing:		Components
Pass	Fuel Cap Visual	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Spark Controls	N/A	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Fuel Evaporative Controls Functional				

## ASM Emission Test Results

Test	RPM	%CO <sub>2</sub>		HC (PPM)			CO (%)			NO (PPM)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
15 mph	1343	11.3	4.6	114	27	66	0.73	0.09	0.49	785	255	771	PASS
25 mph	2155	10.8	5.1	89	18	34	0.61	0.07	0.32	724	223	542	PASS

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured


## Smog Check Inspection Station Information

PACHECO SMOG  
5301 PACHECO BLVD. PACHECO, CA 94553  
925-682-7664  
Station Number: TC262992

Technician Name/Number: MARTELLE, ANTONIO/EO639531  
Repair Tech Name/Number:  
Software Version/EIS Number: 1301/ES315029

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

4-19-17  
Date

  
Technician's Signature



I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

# European Autotech Inc.

31-J Beta Court  
 San Ramon, CA 94583  
 (925) 820-6460

BAR # ARD272122, EPA # CAL000021453  
 EUROPEANAUTOTECHSR.COM

X

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

Invoice # 42113

## 1989 Porsche 911 Turbo Carrera

VIN: WP0EB0932KS070524

Engine: H6 3.3L, 3294cc, SOHC, GAS, FI, B  
 Trans: M/T

License # 5MEM588

ODO In:45415 Out: 45417

Color: Red

Mfg. Date: 3/89

Unit #

Inv Date: 3/23/2018

Service Writer: Chris Murad

Status: Complete

Driver:

PO #

Vehicle Problems	Requests for Service	Services Performed	Qty	Price	Ext
------------------	----------------------	--------------------	-----	-------	-----

### Customer states that: 10.30 oil service

Labor Service - Minor service porsche 911 & carreras to 89-change oil and filter, check and top off all fluids, inspect all tire pressures, and a complete safety inspection (belts-brakes-lights). 3					72.50
New	20W50 B.P.	Brad Penn, contains high levels of zinc and phosphorous, for cars with solid lifters	12.00	11.95	143.40
New	930 107 764 03	Oil Filter Spin-On	1.00	15.44	15.44

### Notes: test battery

Labor Service - Check charging system and battery. Hook up battery tender wires, installed battery mount, battery tested good. Charging system is working properly at this time. 3					72.50
--	--	--	--	--	-------

### Front brake linings aprox 6 mm remain, Rear brake linings aprox 8 mm remain

#### Recommended Repairs and Services:

- check a/c if easy fix, needs retrofit to r134a 724.64
- Car leaks engine oil [ minor ] from lower timing chain covers and housings, Car needs vacuum hoses replaced to distributor [ brittle ], air filter, belts, recommend new ignition wires or boots on dist end, # 1 was falling off when car came in, needs rear deck shock
- car needs front and rear hood shocks, rear engine pad is starting to fall down on corners, Recommend fuel filter replacement

#### Add On Charges Breakdown

Oil/Filter Disp 6.00

#### Vehicle Tire Information

Check Performed.

Tire Pressure PSI	Left Front	Right Front	Left Rear	Right Rear	Checked By
	32	32	38	38	

#### Warranty

2 YEAR OR 24 MONTHS WHATEVER COMES FIRST, PARTS & LABOR ONLY.

#### Invoice Summary

Parts	158.84
Labor	145.00
Labor Discount	-30.00
Add On Charges	6.00

Sub Total 279.84  
 Sales Tax (CA) 13.10

**Total 292.94**

Customer Use

THANK YOU!

services.

Discard old parts

Original Estimate: 360.74