

HUDSON AUTO CARE
 495 EL CAMINO REAL
 MENLO PARK, CA 94025
 (650) 324-4561 BAR # ARD 085462
 EPA# CAL000006804

SEQ NO. 6940	REF NO. 69408
DATE 7/26/2017	PHONE CELL (650) 465-4408
ACCOUNT I.D. COUCH JOHN	PHONE
VEHICLE I.D. 6NRR349	ODOMETER IN 9834
LICENSE NO. 6NRR349	ODOMETER OUT 9834
VIN SAJWA4FC2BMB40597	EMPLOYEE I.D. WILSON
YEAR/MAKE 2011 JAGUAR	
REMARKS/RECOMMENDATIONS	

WORK ORDER

Printed On: 7/26/2017 9:31:39 AM

QUANTITY	WORK TO BE PERFORMED/PARTS REQUIRED	N = NEW S = SUBCONTRACTED W = WARRANTY U = USED R = REBUILT	PARTS PRICE	JOB	LABOR	EMP
	SMOG SMOG INSPECTION	L		1.00	49.95	ELI
	FREE RETEST IF ADDITIONAL INSPECTIONS AND REPAIRS FOR FAILED SMOG ARE DONE HERE.					
	\$30.00 REINSPECTION FEE FOR ALL OTHER RETEST PLUS CERT FEE OF \$8.25.					
1.00	SMOG CERT SMOG CERTIFICATE	N	8.25			
	PASS					
	SMOG CERT # ZZ529556C					
	DMV ID # 9449Z251Z367					

You are entitled to an estimate of the cost of repairs or services which you have requested. Your bill will not be higher than the estimate unless additional work and cost have been authorized by you. Should the original estimate be found to be insufficient to cover the cost of repairs we will not proceed until your approval has been secured.

REVISED ESTIMATE:	PARTS	LABOR	TOTAL REVISED ESTIMATE
PHONE APPROVAL	CUST. INITIAL	TIME	DATE

I, the registered owner, authorize you to perform the above repairs and furnish necessary materials. I understand any cost quoted heretofore is an estimate only. Your employees may operate vehicle for inspection, testing, delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. An express Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto, including those from any prior work or repair contract on this vehicle. In the event an attorney is retained to foreclose this lien or to bring suit for collection of any sums due, I agree to pay costs of collection and any reasonable attorney fees. Receipt of a copy of this order is hereby acknowledged.

- Diagnose problems discussed - advise of work needed. Work may be sublet where necessary as explained to me.
 I do not want replaced parts. Return replaced parts, except parts returned to supplier for credit

X

SUBTOTAL	8.25	49.95	
TOTAL	58.20		CALIFORNIA ONLY: By law you may choose another facility to perform any needed repairs or adjustments which the Smog Check Test indicates are necessary.
GAS	0.00		
TAX	0.00		
PLEASE PAY THIS AMOUNT	58.20 x		initials

SHOULD YOU FAIL TO AUTHORIZE COMPLETION OF REPAIRS OR SERVICES AT THE TIME YOUR APPROVAL IS REQUESTED, A CHARGE MAY BE IMPOSED FOR VEHICLE DISASSEMBLY, REASSEMBLY OR PARTIALLY COMPLETED WORK.

A DAILY STORAGE CHARGE MAY BE ADDED FOR VEHICLES NOT PICKED UP AFTER NOTIFICATION OF COMPLETION OF REPAIRS COMMENCING HOURS/DAYS AFTER NOTIFICATION.

Smog Check Vehicle Inspection Report ()

Vehicle Information

Test Date/Time: 07/26/2017 @ 9:17 AM

Model Year: 2011	Vehicle Make: JAGUAR	Vehicle Model: XKR
VIN (scanned from vehicle): SAJWA4FC2BMB40597	License State: CA	Fuel Type: Gasoline
License Plate: 6NRR349	Odometer: 9834	
Certification Type: California		

Overall Test Result

PASS

Congratulations! Your vehicle passed the Smog Check inspection, which helps California reach its daily goal of removing smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection: PASS Functional Inspection: PASS

Smog Check Certificate Number: ZZ529556C

DMV ID Number: 9449Z251Z367

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance.

Please keep this copy for your records.

Visual Inspection Result Information

Result	Inspection Category	Result	Inspection Category
NOTAPPLICABLE	Air Injection System	PASS	Catalyst
PASS	Computers, Sensors, Switches, and Wiring	PASS	Crankcase Emission Controls
NOTAPPLICABLE	Exhaust Gas Recirculation (EGR)	PASS	Fuel Evaporative System (EVAP)
PASS	Fuel Metering System	PASS	Other Emission Related Components/Systems
PASS	Turbocharger/Supercharger	PASS	Vacuum Lines to Sensors/Switches

Emission Control Systems Functional Check Results

Result	Inspection Category	Result	Inspection Category
PASS	Liquid Fuel Leak Check	PASS	OBDII
PASS	Smoke Check		

Smog Check Inspection Station Information

Station ID: RC085462	Inspector Name/ID: LAMARQUE, ELIZARDO/EO147280
HUDSON AUTO CARE	Software Version/OIS ID: 6 8.996.0/CV006246
495 EL CAMINO REAL	
MENLO PARK, CA 94025	
(650) 324-4561	
(650) 324-0100	
HUDSONAUTOCARE1@GMAIL.COM	

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

07-26-17

Date

Inspector's Signature



OUR VALUED CUSTOMER

Jose Pepe Cortez
Service Consultant

F. Varillas
Certified Technician

YOUR VEHICLE

Year 2011	Make Jaguar	Model XKR	Engine Type 5.0L V8 DOHC (MFI)
Odometer 11,667	VIN # SAJWA4FC2BMB40597	License # 6NRR349	Date 8/8/2018

Vehicle Care Commitment

It's about "Peace of Mind..."

Thank you for choosing our service department to handle your vehicle's service needs. In order to provide the quality service you deserve, we have invested in the latest diagnostic equipment and information systems. These help us fully understand your vehicle's service and maintenance requirements so that we can service your vehicle in the most comprehensive and economical way possible.



We are pleased to present to you a "Know Your Vehicle" report today. It's important to us that you leave our dealership with peace of mind, so we take the extra time necessary to analyze your vehicle's health to make sure it is operating at its optimum levels. This bumper-to-bumper inspection report will help you better understand your vehicle's performance and health. Staying on top of your vehicle's health is vitally important to ensuring your safety on the road.



Thank you for this opportunity to assist you. We appreciate your business. Please feel free to contact your service advisor if you have any questions or concerns. We will do everything we can to put your mind at ease and keep you and your family safe on the road.



How we give you "Peace of Mind..."

To help you understand what your vehicle needs to stay in top operating condition, we:

- Perform a world class visual inspection on your vehicle every visit
- Review your vehicle's maintenance schedules and search our extensive database to uncover anything we believe you should know about your vehicle based on its odometer reading and time on the road
- Make recommendations and complete a Treatment Plan for your vehicle
- Offer a complete easy to read and understand report that enables you to make an educated decision for your vehicle's service needs. Items on the report will be classified as follows:
 - Pass - Items are new or "like new" and do not require service at this time
 - Caution - Items that are dirty or showing signs of wear and would benefit from being serviced soon
 - Fail - Items that have either worn below minimum specifications or are no longer doing what it was designed to do and need to be repaired immediately

DISCLAIMER: Addressing any identified issues listed by the report, should improve the safety and performance of your vehicle. However, please remember that the inspection is limited to a visual inspection of the items listed on the report without disassembling or test driving your vehicle. Therefore, it is not possible for the technician to see or identify all potential defects, especially those that are internal to the engine, transmission, driveline, electrical system or other components. The cleanliness of the vehicle both inside and out at the time of the actual inspection may reduce the accuracy of the inspection. Your vehicle may have conditions that are not evident at the time of the inspection or otherwise not presented or noticed during the inspection process. Therefore, the inspection and condition report does not provide any guarantee or warranty that the vehicle will not break down in the future, or have conditions that were undetected during the inspection or were omitted from the report.



Original Customer Requests

The following is what you requested we perform or investigate regarding your vehicle:

- ✓ A. PERFORM COMPLIMENTARY MULTI POINT INSPECTION
- ✓ B. Service - 105,000 Miles
- ✓ C. CUSTOMER WILL WAIT WHILE CAR IS INSPECTED



Package Results

Jaguar Land Rover San Jose MultiPo1nt Inspection

Passed Task	Observation	Recommendation	Done
Fill windshield washer fluid	Found washer fluid level low: Filled to proper level		
Measure rear brake pads	7 mm or greater: Inspect brakes next service		
Measure front brake pads	7 mm or greater: Inspect brakes next service		
Left front tire tread depth	Left front tire tread measures 7/32" or greater: Inspect tire next service		
Left rear tire tread depth	Left rear tire tread measures 7/32" or greater: Inspect tire next service		
Right front tire tread depth	Right front tire tread measures 7/32" or greater: Inspect tire next service		
Right rear tire tread depth	Right rear tire tread measures 7/32" or greater: Inspect tire next service		

Passed Tasks

- | | | |
|---|--|--|
| ✓ Inspect exhaust system for leaks, damage, and loose parts | ✓ Inspect axles, driveshaft and CV joints/boots | ✓ Inspect engine mounts |
| ✓ Inspect transmission mounts | ✓ Inspect fuel tank, lines, and connections | ✓ Inspect air filter |
| ✓ Fill windshield washer fluid | ✓ Check power steering fluid level and condition | ✓ Check engine oil level and condition |
| ✓ Check engine coolant level and condition | ✓ Check brake fluid level and condition | ✓ Check transmission fluid level and condition (if applicable) |
| ✓ Inspect hazard light operation | ✓ Inspect brake light operation | ✓ Inspect reverse light operation |

- ✓ Inspect taillight, turn signal, side marker, and license plate lights
- ✓ Inspect wiper and washer operation
- ✓ Inspect dash and interior lights
- ✓ Inspect brake system components
- ✓ Inspect battery terminals and cables
- ✓ Inspect steering components
- ✓ Inspect engine for oil leaks
- ✓ Inspect cooling system for leaks
- ✓ Inspect sway bar components
- ✓ Right front tire tread depth
- ✓ Check power window operation
- ✓ Inspect LED daytime running lights (If equipped)
- ✓ Inspect rear differential fluid level, condition and check for leaks
- ✓ Tire recommendations based on overall tire wear and condition
- ✓ Check and adjust LF Tire Pressure
- ✓ Check and adjust RR Tire Pressure
- ✓ Inspect taillight, turn signal, and side marker assemblies for cracks and damage
- ✓ Check horn operation
- ✓ Measure rear brake pads
- ✓ Inspect instrument cluster warning lamps
- ✓ Inspect drive belts
- ✓ Inspect front suspension components
- ✓ Inspect transmission for leaks
- ✓ Inspect fog/driving lights (if equipped)
- ✓ Left front tire tread depth
- ✓ Right rear tire tread depth
- ✓ Check power locking system operation
- ✓ Inspect lower engine cover
- ✓ Inspect wiper blades
- ✓ Time and Mileage based recommendations
- ✓ Check and adjust LR Tire Pressure
- ✓ Inspect headlight low and high beam operation
- ✓ Inspect heat and air conditioning operation
- ✓ Measure front brake pads
- ✓ Perform battery performance test
- ✓ Inspect all hoses and clamps
- ✓ Inspect rear suspension components
- ✓ Inspect brake system for leaks
- ✓ Inspect steering system for leaks
- ✓ Left rear tire tread depth
- ✓ Inspect wheels for damage
- ✓ Check hood strut(s)
- ✓ Inspect windshield for cracks, chips and pitting
- ✓ Check engine performance
- ✓ Inspect cabin air (HEPA/micro) filter (in applicable vehicles)
- ✓ Check and adjust RF Tire Pressure



Recommended Services

Our technicians recommend the following services for your vehicle.

Original Customer Requests	Status	Deferred	Approved
A. PERFORM COMPLIMENTARY MULTI POINT INSPECTION			X
B. Service - 105,000 Miles			X
C. CUSTOMER WILL WAIT WHILE CAR IS INSPECTED			X
Subtotal			



Recommended Services

Our technicians recommend the following services for your vehicle.

Original Customer Requests	Status	Cost	Deferred	Approved
A. PERFORM COMPLIMENTARY MULTI POINT INSPECTION		\$0.00		X
B. Service - 20,000 Miles		\$625.07		X
C. Wheels - Rotate		\$80.00		X
D. PROVIDE CLIENT WITH UBER		\$0.00		X
Subtotal		\$705.07		\$705.07
Totals, Taxes and Fees		Cost	Deferred	Approved
Estimate Subtotal		\$705.07	\$0.00	\$705.07
Tax		\$0.00		\$0.00
Estimate Total		\$705.07		\$705.07

CUSTOMER #: J1217045

146476



INVOICE

JAGUAR LAND ROVER STEVENS CREEK

4040 Stevens Creek Boulevard
San Jose, CA 95129

(408) 246-7600

FAX # (408) 249-9136

PAGE 2

SERVICE ADVISOR: 2403 JOSE CORTEZ

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
UBLK	11	JAGUAR	SAJWA4FC2BMB40597	6NRR349	11667/11667	T346
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
21AUG10 DD			WAIT 08AUG18		0.00 CASH	08AUG18
R.O. OPENED	DATE CUST. NOTIFIED	OPTIONS: STK:20939 DLR:0518 AXL:2 1)SOP PARTS HERE PAINTED LOOVERS 4.15.11 SEE MIKE G...				
08AUG18	08AUG18					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
0116	IN	Inspect	Horn				
		3637	CMJ			0.00	0.00
00001	R	Replace	Engine Oil			0.00	0.00
		3637	CMJ			0.00	0.00
0123	IN	Inspect	Window Washer Fluid Level			0.00	0.00
		3637	CMJ			0.00	0.00
0125	IN	Inspect	Function of All Lights			0.00	0.00
		3637	CMJ			0.00	0.00
0138	IN	Inspect	for Fluid Leaks			0.00	0.00
		3637	CMJ			0.00	0.00
0157	IN	Inspect	Warning and Indicator Lamps			0.00	0.00
		3637	CMJ			0.00	0.00
0160	IN	Inspect	Windshield Wiper Operation			0.00	0.00
		3637	CMJ			0.00	0.00
0192	IN	Inspect	Window Washer Operation			0.00	0.00
		3637	CMJ			0.00	0.00
00003	R	Replace	Engine Oil Filter			0.00	0.00
		3637	CMJ			0.00	0.00
00005	M	Road	Test			0.00	0.00
		3637	CMJ			0.00	0.00
00054	R	Replace	Pollen Air Filter			0.00	0.00
		3637	CMJ			0.00	0.00
00119	R	Replace	Spark Plugs			0.00	0.00
		3637	CMJ			0.00	0.00
00124	R	Replace	Supercharger Belt			0.00	0.00
		3637	CMJ			0.00	0.00
0021	IN	Inspect	Brake Lines, Hoses and Connections			0.00	0.00
		3637	CMJ			0.00	0.00
0022	IN	Inspect	Power Steering Lines and Hoses			0.00	0.00
		3637	CMJ			0.00	0.00

11667 as required 105,000 mile interval service maintenance executed successfully

C CUSTOMER WILL WAIT WHILE CAR IS INSPECTED

	ORIGINAL ESTIMATE \$		FINAL REVISED ESTIMATE \$		DESCRIPTION	TOTALS
	DATE	TIME	PHONE # OR IN PERSON	AUTHORIZED BY	LABOR AMOUNT	
	REASON		ADDITIONAL AMOUNT \$		PARTS AMOUNT	
	REASON		REVISED TOTAL \$		GAS, OIL, LUBE	
DATE		TIME	PHONE # OR IN PERSON	AUTHORIZED BY	ADDITIONAL AMOUNT \$	SUBLET AMOUNT
REASON		REASON		REVISED TOTAL \$		MISC. CHARGES
DATE		TIME	PHONE # OR IN PERSON	AUTHORIZED BY	ADDITIONAL AMOUNT \$	TOTAL CHARGES
REASON		REASON		REVISED TOTAL \$		DEDUCTIONS
I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE.		I ACKNOWLEDGE RECEIPT OF VEHICLE AND I HAVE RECEIVED A COPY OF THIS INVOICE.		PLEASE PAY THIS AMOUNT		SALES TAX
X		X				


ALL PARTS ENDING IN "WP" ARE NOT SOURCED FROM JAGUAR LAND ROVER. SEE PARTS MANAGER FOR WARRANTY. NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

BAR # ARD 278146

EPA# CAL 000401166

CUSTOMER #: J1217045

146476



INVOICE

JAGUAR LAND ROVER STEVENS CREEK
4040 Stevens Creek Boulevard
San Jose, CA 95129
(408) 246-7600
FAX # (408) 249-9136

PAGE 3

SERVICE ADVISOR: 2403 JOSE CORTEZ

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG	
UBLK	11	JAGUAR	SAJWA4FC2BMB40597	6NRR349	11667/11667	T346	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE	
21AUG10 DD			WAIT 08AUG18		0.00 CASH	08AUG18	
R.O. OPENED	DATE CUST. NOTIFIED	OPTIONS: STK:20939 DLR:0518 AXL:2 1)SOP PARTS HERE PAINTED LOOVERS 4.15.11 SEE MIKE G...					
08AUG18	08AUG18						
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
							(N/C)
WAIT CUSTOMER WILL WAIT WHILE CAR IS INSPECTED							
3637 ISR							

EST: 1,927.39 08AUG18 08:35 SA: 2403

THANK YOU FOR YOUR PATRONAGE, YOUR BUSINESS IS VERY MUCH APPRECIATED!

WE HOPE WE HAVE EARNED YOUR FUTURE BUSINESS AND RECOMENDATIONS TO FAMILY AND FRIENDS! COMMENTS WELCOMED AT MREYES@LANDROVERSJ.COM
MANUEL REYES, PARTS & SERVICE DIRECTOR.

ORIGINAL ESTIMATE \$		FINAL REVISED ESTIMATE \$		DESCRIPTION	TOTALS
DATE	TIME	PHONE # OR IN PERSON	AUTHORIZED BY	LABOR AMOUNT	1238.40
REASON				PARTS AMOUNT	601.17
REASON				GAS, OIL, LUBE	0.00
REASON				SUBLET AMOUNT	0.00
REASON				MISC. CHARGES	0.00
REASON				TOTAL CHARGES	1839.57
REASON				DEDUCTIONS	0.00
REASON				SALES TAX	55.61
I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE.				PLEASE PAY THIS AMOUNT	
I ACKNOWLEDGE RECEIPT OF VEHICLE AND I HAVE RECEIVED A COPY OF THIS INVOICE.				1895.18	

ALL PARTS ENDING IN "WP" ARE NOT SOURCED FROM JAGUAR LAND ROVER. SEE PARTS MANAGER FOR WARRANTY. NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

BAR # ARD 278146 EPA# CAL 000401166



OUR VALUED CUSTOMER

Jose Pepe Cortez
Service Consultant

K. Su
Certified Technician

YOUR VEHICLE

Year 2011	Make Jaguar	Model XKR	Engine Type 5.0L V8 DOHC (MFI)
Odometer 10,734	VIN # SAJWA4FC2BMB40597	License # 6NRR349	Date 2/7/2018

Vehicle Care Commitment

It's about "Peace of Mind..."

Thank you for choosing our service department to handle your vehicle's service needs. In order to provide the quality service you deserve, we have invested in the latest diagnostic equipment and information systems. These help us fully understand your vehicle's service and maintenance requirements so that we can service your vehicle in the most comprehensive and economical way possible.



We are pleased to present to you a "Know Your Vehicle" report today. It's important to us that you leave our dealership with peace of mind, so we take the extra time necessary to analyze your vehicle's health to make sure it is operating at its optimum levels. This bumper-to-bumper inspection report will help you better understand your vehicle's performance and health. Staying on top of your vehicle's health is vitally important to ensuring your safety on the road.



Thank you for this opportunity to assist you. We appreciate your business. Please feel free to contact your service advisor if you have any questions or concerns. We will do everything we can to put your mind at ease and keep you and your family safe on the road.



How we give you "Peace of Mind..."

To help you understand what your vehicle needs to stay in top operating condition, we:

- Perform a world class visual inspection on your vehicle every visit
- Review your vehicle's maintenance schedules and search our extensive database to uncover anything we believe you should know about your vehicle based on its odometer reading and time on the road
- Make recommendations and complete a Treatment Plan for your vehicle
- Offer a complete easy to read and understand report that enables you to make an educated decision for your vehicle's service needs. Items on the report will be classified as follows:
 - Pass - Items are new or "like new" and do not require service at this time
 - Caution - Items that are dirty or showing signs of wear and would benefit from being serviced soon
 - Fail - Items that have either worn below minimum specifications or are no longer doing what it was designed to do and need to be repaired immediately

DISCLAIMER: Addressing any identified issues listed by the report, should improve the safety and performance of your vehicle. However, please remember that the inspection is limited to a visual inspection of the items listed on the report without disassembling or test driving your vehicle. Therefore, it is not possible for the technician to see or identify all potential defects, especially those that are internal to the engine, transmission, driveline, electrical system or other components. The cleanliness of the vehicle both inside and out at the time of the actual inspection may reduce the accuracy of the inspection. Your vehicle may have conditions that are not evident at the time of the inspection or otherwise not presented or noticed during the inspection process. Therefore, the inspection and condition report does not provide any guarantee or warranty that the vehicle will not break down in the future, or have conditions that were undetected during the inspection or were omitted from the report.



Original Customer Requests

The following is what you requested we perform or investigate regarding your vehicle:

- ✓ A. Service - 90,000 Miles- 6TH YEAR SERVICE
- ✓ B. PERFORM COMPLIMENTARY MULTI POINT INSPECTION
- ✓ C. CUSTOMER WILL WAIT WHILE CAR IS INSPECTED
- ✓ D. Complimentary Car Wash (includes exterior wash, vacuum front seating area, clean and dry outside)



Package Results

Jaguar Land Rover San Jose MultiPo1nt Inspection

Failed Task	Observation	Recommendation	Done
Right rear tire tread depth	Right rear tire tread measures 3/32"		

Cautioned Task	Observation	Recommendation	Done
Measure rear brake pads	5 mm		
Left front tire tread depth	Left front tire tread measures 5/32"		
Left rear tire tread depth	Left rear tire tread measures 4/32"		
Right front tire tread depth	Right front tire tread measures 5/32"		
Tire recommendations based on overall tire wear and condition	Found front tires abnormally worn		

Passed Task	Observation	Recommendation	Done
Fill windshield washer fluid	Found washer fluid level low: Filled to proper level		
Measure front brake pads	7 mm or greater: Inspect brakes next service		
Check and adjust LF Tire Pressure	Set tire pressures to 36 psi - Check tire pressures monthly		
Check and adjust LR Tire Pressure	Set tire pressures to 36 psi - Check tire pressures monthly		
Check and adjust RF Tire Pressure	Set tire pressures to 36 psi - Check tire pressures monthly		

RO#: 140823

Jaguar Land Rover San Jose
4040 Stevens Creek Blvd San Jose, CA • (408) 246-7600

Passed Task	Observation	Recommendation	Done
Check and adjust RR Tire Pressure	Set tire pressures to 36 psi - Check tire pressures monthly		

Passed Tasks		
✓ Inspect exhaust system for leaks, damage, and loose parts	✓ Inspect axles, driveshaft and CV joints/boots	✓ Inspect engine mounts
✓ Inspect transmission mounts	✓ Inspect fuel tank, lines, and connections	✓ Inspect air filter
✓ Fill windshield washer fluid	✓ Check power steering fluid level and condition	✓ Check engine oil level and condition
✓ Check engine coolant level and condition	✓ Check brake fluid level and condition	✓ Inspect hazard light operation
✓ Inspect brake light operation	✓ Inspect reverse light operation	✓ Inspect taillight, turn signal, side marker, and license plate lights
✓ Inspect taillight, turn signal, and side marker assemblies for cracks and damage	✓ Inspect headlight low and high beam operation	✓ Inspect wiper and washer operation
✓ Check horn operation	✓ Inspect heat and air conditioning operation	✓ Inspect dash and interior lights
✓ Measure front brake pads	✓ Inspect brake system components	✓ Inspect instrument cluster warning lamps
✓ Perform battery performance test	✓ Inspect battery terminals and cables	✓ Inspect drive belts
✓ Inspect all hoses and clamps	✓ Inspect steering components	✓ Inspect front suspension components
✓ Inspect rear suspension components	✓ Inspect engine for oil leaks	✓ Inspect transmission for leaks
✓ Inspect brake system for leaks	✓ Inspect cooling system for leaks	✓ Inspect steering system for leaks
✓ Inspect sway bar components	✓ Inspect wheels for damage	✓ Check power window operation
✓ Check power locking system operation	✓ Check hood strut(s)	✓ Inspect LED daytime running lights (if equipped)
✓ Inspect lower engine cover	✓ Inspect windshield for cracks, chips and pitting	✓ Inspect rear differential fluid level, condition and check for leaks
✓ Inspect wiper blades	✓ Check engine performance	✓ Time and Mileage based recommendations
✓ Inspect cabin air (HEPA/micro) filter (in applicable vehicles)	✓ Check and adjust LF Tire Pressure	✓ Check and adjust LR Tire Pressure
✓ Check and adjust RF Tire Pressure	✓ Check and adjust RR Tire Pressure	

Additional Observations	Recommendation
TIRES WORN INSIDE, FUTURE	FUTURE REC. 4 TIRES WITH ALIGNMENT CHECK.



Recommended Services

Our technicians recommend the following services for your vehicle.

RO#: 140823

Jaguar Land Rover San Jose
4040 Stevens Creek Blvd San Jose, CA • (408) 246-7600

Original Customer Requests	Status	Cost	Deferred	Approved
A. Service - 90,000 Miles- 6TH YEAR SERVICE		\$636.24		X
B. PERFORM COMPLIMENTARY MULTI POINT INSPECTION		\$0.00		X
C. CUSTOMER WILL WAIT WHILE CAR IS INSPECTED		\$0.00		X
D. Complimentary Car Wash (includes exterior wash, vacuum front seating area, clean and dry outside)		\$0.00		X
Subtotal		\$636.24		\$636.24
Totals, Taxes and Fees		Cost	Deferred	Approved
Estimate Subtotal		\$636.24	\$0.00	\$636.24
Tax		\$0.00		\$0.00
Estimate Total		\$636.24		\$636.24

CUSTOMER #: J1217045

140823



INVOICE

JAGUAR LAND ROVER STEVENS CREEK
4040 Stevens Creek Boulevard
San Jose, CA 95129

PAGE 1

(408) 246-7600
FAX # (408) 249-9136

SERVICE ADVISOR: 2403 JOSE CORTEZ

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
UBLK	11	JAGUAR	SAJWA4FC2BMB40597	6NRR349	10734/10735	T961
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
21AUG10 DD			WAIT 07FEB18		0.00 CASH	07FEB18
R.O. OPENED	DATE CUST. NOTIFIED	OPTIONS: STK:20939 DLR:0518 AXL:2 1)SOP PARTS HERE PAINTED LOOVERS 4.15.11 SEE MIKE G...				
07FEB18	07FEB18					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	Service	-	90,000 Miles-	6TH YEAR SERVICE			
	B011A090000	Service	-	90,000 Miles-	6TH YEAR SERVICE		
		6059	CJ			378.95	378.95
	1	C2D3670	FILTER-OIL		49.53	49.53	49.53
	8	06333	CASTROL EDGE SPT		10.50	10.50	84.00
	2	C2P16933	ELEMENT-AIRCLEAN		39.02	39.02	78.04
	1	C2P2410	FILTER-AIR PARTI		74.86	74.86	74.86
0023IN	Inspect Brake Pads and/or Linings, Rotors and/or Drums	6059	CJ			0.00	0.00
0032IN	Inspect Drive Belt(s)	6059	CJ			0.00	0.00
0050IN	Inspect Fuel Line and Hoses	6059	CJ			0.00	0.00
0057IN	Inspect Parking Brake Operation	6059	CJ			0.00	0.00
0059IN	Inspect Power Steering Fluid Level	6059	CJ			0.00	0.00
0079IN	Inspect Tires and Adjust Air Pressures, Including Spare Tire	6059	CJ			0.00	0.00
0087IN	Inspect Windshield Wiper Blades	6059	CJ			0.00	0.00
0110IN	Inspect Brake Fluid Level	6059	CJ			0.00	0.00
0113IN	Inspect Engine Coolant Level	6059	CJ			0.00	0.00
0116IN	Inspect Horn	6059	CJ			0.00	0.00
00001R	Replace Engine Oil	6059	CJ			0.00	0.00
0123IN	Inspect Window Washer Fluid Level	6059	CJ			0.00	0.00



ORIGINAL ESTIMATE \$	FINAL REVISED ESTIMATE \$	DESCRIPTION	TOTALS			
DATE	TIME	PHONE # OR IN PERSON	AUTHORIZED BY	ADDITIONAL AMOUNT \$	LABOR AMOUNT	
REASON					REVISED TOTAL \$	PARTS AMOUNT
REASON					REVISED TOTAL \$	GAS, OIL, LUBE
REASON					REVISED TOTAL \$	SUBLET AMOUNT
REASON					REVISED TOTAL \$	MISC. CHARGES
REASON					REVISED TOTAL \$	TOTAL CHARGES
REASON					REVISED TOTAL \$	DEDUCTIONS
REASON					REVISED TOTAL \$	SALES TAX
<input checked="" type="checkbox"/> I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE.					<input checked="" type="checkbox"/> I ACKNOWLEDGE RECEIPT OF VEHICLE AND I HAVE RECEIVED A COPY OF THIS INVOICE.	
					PLEASE PAY THIS AMOUNT	

ALL PARTS ENDING IN "WP" ARE NOT SOURCED FROM JAGUAR LAND ROVER. SEE PARTS MANAGER FOR WARRANTY. NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

BAR # ARD 278146 EPA# CAL 000401166

CUSTOMER #: J1217045

140823



INVOICE

JAGUAR LAND ROVER STEVENS CREEK

4040 Stevens Creek Boulevard
San Jose, CA 95129

(408) 246-7600

FAX # (408) 249-9136

PAGE 2

SERVICE ADVISOR: 2403 JOSE CORTEZ

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
UBLK	11	JAGUAR	SAJWA4FC2BMB40597	6NRR349	10734/10735	T961
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
21AUG10 DD			WAIT 07FEB18		0.00 CASH	07FEB18
R.O. OPENED	DATE CUST. NOTIFIED	OPTIONS: STK:20939 DLR:0518 AXL:2 1)SOP PARTS HERE PAINTED LOOVERS 4.15.11 SEE MIKE G...				
07FEB18	07FEB18					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
0125	IN						
						0.00	0.00
0127	IN						
						0.00	0.00
0138	IN						
						0.00	0.00
0157	IN						
						0.00	0.00
0160	IN						
						0.00	0.00
0192	IN						
						0.00	0.00
00002	M						
						0.00	0.00
00003	R						
						0.00	0.00
00005	M						
						0.00	0.00
00007	R						
						0.00	0.00
00054	R						
						0.00	0.00
0021	IN						
						0.00	0.00
0022	IN						
						0.00	0.00
10735	PERFORM 90,000 MILES SERVICE AS PER CHECK LIST.						

B PERFORM COMPLIMENTARY MULTI POINT INSPECTION
FMPI PERFORM COMPLIMENTARY MULTI POINT INSPECTION
6059 ISR

(N/C)

10734 PERFORM MULTI POINT INSPECTION.



ORIGINAL ESTIMATE \$	FINAL REVISED ESTIMATE \$	DESCRIPTION	TOTALS
DATE	TIME	PHONE # OR IN PERSON	AUTHORIZED BY
REASON	ADDITIONAL AMOUNT \$	LABOR AMOUNT	
REASON	REVISED TOTAL \$	PARTS AMOUNT	
DATE	TIME	PHONE # OR IN PERSON	AUTHORIZED BY
REASON	ADDITIONAL AMOUNT \$	GAS, OIL, LUBE	
REASON	REVISED TOTAL \$	SUBLET AMOUNT	
I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE.		MISC. CHARGES	
I ACKNOWLEDGE RECEIPT OF VEHICLE AND I HAVE RECEIVED A COPY OF THIS INVOICE.		TOTAL CHARGES	
X		DEDUCTIONS	
X		SALES TAX	
		PLEASE PAY THIS AMOUNT	

ALL PARTS ENDING IN "WP" ARE NOT SOURCED FROM JAGUAR LAND ROVER. SEE PARTS MANAGER FOR WARRANTY. NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

BAR # ARD 278146

EPA# CAL 000401166

CUSTOMER #: J1217045

140823



INVOICE

JAGUAR LAND ROVER STEVENS CREEK

4040 Stevens Creek Boulevard
San Jose, CA 95129

(408) 246-7600

FAX # (408) 249-9136

PAGE 3

SERVICE ADVISOR: 2403 JOSE CORTEZ

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
UBLK	11	JAGUAR	SAJWA4FC2BMB40597	6NRR349	10734/10735	T961
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
21AUG10 DD			WAIT 07FEB18		0.00 CASH	07FEB18

R.O. OPENED	DATE CUST. NOTIFIED	OPTIONS:
07FEB18	07FEB18	STK:20939 DLR:0518 AXL:2 1)SOP PARTS HERE PAINTED LOOVERS 4.15.11 SEE MIKE G...

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

C CUSTOMER WILL WAIT WHILE CAR IS INSPECTED
 WAIT CUSTOMER WILL WAIT WHILE CAR IS INSPECTED
 6059 ISR (N/C)

D Complimentary Car Wash (includes exterior wash, vacuum front seating area, clean and dry outside)
 WASH Complimentary Car Wash (includes exterior wash, vacuum front seating area, clean and dry outside)
 6059 ISR (N/C)

EST: 636.24 07FEB18 08:48 SA: 2403

THANK YOU FOR YOUR PATRONAGE, YOUR BUSINESS IS VERY MUCH APPRECIATED!

WE HOPE WE HAVE EARNED YOUR FUTURE BUSINESS AND RECOMENDATIONS TO FAMILY AND FRIENDS! COMMENTS WELCOMED AT MREYES@LANDROVERSJ.COM
MANUEL REYES, PARTS & SERVICE DIRECTOR.



ORIGINAL ESTIMATE \$	FINAL REVISED ESTIMATE \$	DESCRIPTION	TOTALS
		LABOR AMOUNT	378.95
		PARTS AMOUNT	286.43
		GAS, OIL, LUBE	0.00
		SUBLET AMOUNT	0.00
		MISC. CHARGES	0.00
		TOTAL CHARGES	665.38
		DEDUCTIONS	0.00
		SALES TAX	26.49
		PLEASE PAY THIS AMOUNT	691.87

ALL PARTS ENDING IN "WP" ARE NOT SOURCED FROM JAGUAR LAND ROVER. SEE PARTS MANAGER FOR WARRANTY. NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

BAR # ARD 278146

EPA# CAL 000401166

CUSTOMER #: J1217045

156967



INVOICE

JAGUAR LAND ROVER STEVENS CREEK
4040 Stevens Creek Boulevard
San Jose, CA 95129

PAGE 1

(408) 246-7600
FAX # (408) 249-9136

SERVICE ADVISOR: 6657 SAMUEL MOSES

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
UBLK	11	JAGUAR	SAJWA4FC2BMB40597	6NRR349	13023/13025	T2779
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
21AUG10 DD			17:00 30MAY19		0.00 CASH	04JUN19
R.O. OPENED	DATE CUST. NOTIFIED	OPTIONS: STK:20939 DLR:0518 AXL:2 1)SOP PARTS HERE PAINTED LOOVERS 4.15.11 SEE MIKE G...				
30MAY19	04JUN19					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A PERFORM COMPLIMENTARY MULTI POINT INSPECTION
 FMPI PERFORM COMPLIMENTARY MULTI POINT INSPECTION
 6059 ISJ (N/C)
 13025 PERFORM MULTI POINT.

B CHECK TIRES BASED ON TIME, WORRIED ABOUT DRY ROT.
 GENERAL SEE LINE E
 6059 ISR (N/C)
 13025 CHECK AND FOUND ALL TIRES OLD AND RUBBERS OFF TIRES IS HARD
 AND WORN. REC. 4 TIRES AND ALIGNMENT CHECK.

C CLIENT STATES THAT THE AC SEEMS WEAK.
 DIAG DIAGNOSIS
 6059 CJ 510.00 510.00

13026 CHECK AND CONFIRM A/C SYSTEM BLOW WARN AIR, HOOK UP A/C
 MACHINE TO CHECK FOUND A/C COMPRESSOR IS WEAK CAUSE A/C SYSTEM NOT BLOW
 COLD AIR. REC. NEW COMPRESSOR ASSEMBLY AND RECHECK. REPLACE A/C
 COMPRESSOR ASSEMBLY ON LINE G AS PER CUSTOMER AUTHORIZATION, FILL UP
 FREON AND RETEST SYSTEM OP NORMALLY AT THIS TIME. FUTURE REC. RECHECK.

D Service - 120,000 Miles
 B011A120000 Service - 120,000 Miles
 6059 CJ 586.50 586.50
 1 C2D3670 FILTER-OIL 46.20 46.20 46.20
 1 C2P2410 FILTER-AIR PARTI 83.52 83.52 83.52
 2 C2C36093 FILTER-HEATED CO 83.72 83.72 167.44
 8 12083 0W20CASTROL 13.95 13.95 111.60
 0023IN Inspect Brake Pads and/or Linings, Rotors
 and/or Drums 6059 CJ 0.00 0.00
 0032IN Inspect Drive Belt(s) 6059 CJ 0.00 0.00
 0050IN Inspect Fuel Line and Hoses 6059 CJ 0.00 0.00

PAID
PAID JUN 05 2019
 BY: *Ma Usa*
 3941



ORIGINAL ESTIMATE \$	FINAL REVISED ESTIMATE \$	DESCRIPTION	TOTALS
		LABOR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
		TOTAL CHARGES	
		DEDUCTIONS	
		SALES TAX	
<input type="checkbox"/> I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE.		<input type="checkbox"/> I ACKNOWLEDGE RECEIPT OF VEHICLE AND I HAVE RECEIVED A COPY OF THIS INVOICE.	
		PLEASE PAY THIS AMOUNT	

ALL PARTS ENDING IN "WP" ARE NOT SOURCED FROM JAGUAR LAND ROVER. SEE PARTS MANAGER FOR WARRANTY.
 NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

BAR # ARD 278146

EPA# CAL 000401166

CUSTOMER #: J1217045

156967



INVOICE

JAGUAR LAND ROVER STEVENS CREEK

4040 Stevens Creek Boulevard
San Jose, CA 95129

(408) 246-7600

FAX # (408) 249-9136

PAGE 2

SERVICE ADVISOR: 6657 SAMUEL MOSES

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
UBLK	11	JAGUAR	SAJWA4FC2BMB40597	6NRR349	13023/13025	T2779
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
21AUG10 DD			17:00 30MAY19		0.00 CASH	04JUN19
R.O. OPENED	DATE CUST. NOTIFIED	OPTIONS: STK:20939 DLR:0518 AXL:2 1)SOP PARTS HERE PAINTED LOOVERS 4.15.11 SEE MIKE G...				
30MAY19	04JUN19					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
0057	IN	Inspect	Parking Brake Operation			0.00	0.00
		6059	CJ				
0059	IN	Inspect	Power Steering Fluid Level			0.00	0.00
		6059	CJ				
0079	IN	Inspect	Tires and Adjust Air Pressures, Including Spare Tire			0.00	0.00
		6059	CJ				
0087	IN	Inspect	Windshield Wiper Blades			0.00	0.00
		6059	CJ				
0110	IN	Inspect	Brake Fluid Level			0.00	0.00
		6059	CJ				
0113	IN	Inspect	Engine Coolant Level			0.00	0.00
		6059	CJ				
0116	IN	Inspect	Horn			0.00	0.00
		6059	CJ				
00001R		Replace	Engine Oil			0.00	0.00
		6059	CJ				
0123	IN	Inspect	Window Washer Fluid Level			0.00	0.00
		6059	CJ				
0125	IN	Inspect	Function of All Lights			0.00	0.00
		6059	CJ				
0127	IN	Inspect	and Correct Battery Electrolyte Level			0.00	0.00
		6059	CJ				
0138	IN	Inspect	for Fluid Leaks			0.00	0.00
		6059	CJ				
0157	IN	Inspect	Warning and Indicator Lamps			0.00	0.00
		6059	CJ				
0160	IN	Inspect	Windshield Wiper Operation			0.00	0.00
		6059	CJ				
0192	IN	Inspect	Window Washer Operation			0.00	0.00
		6059	CJ				
00002M		Apply	Windscreen Paste			0.00	0.00
		6059	CJ				



ORIGINAL ESTIMATE \$	FINAL REVISED ESTIMATE \$	DESCRIPTION	TOTALS
DATE	TIME	PHONE # OR IN PERSON	AUTHORIZED BY
REASON	ADDITIONAL AMOUNT \$	LABOR AMOUNT	PARTS AMOUNT
REASON	REVISED TOTAL \$	GAS, OIL, LUBE	SUBLET AMOUNT
DATE	TIME	PHONE # OR IN PERSON	AUTHORIZED BY
REASON	ADDITIONAL AMOUNT \$	MISC. CHARGES	TOTAL CHARGES
REASON	REVISED TOTAL \$	DEDUCTIONS	SALES TAX
I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE.		I ACKNOWLEDGE RECEIPT OF VEHICLE AND I HAVE RECEIVED A COPY OF THIS INVOICE.	
X		X	
		PLEASE PAY THIS AMOUNT	

ALL PARTS ENDING IN "WP" ARE NOT SOURCED FROM JAGUAR LAND ROVER. SEE PARTS MANAGER FOR WARRANTY.
NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

BAR # ARD 278146

EPA# CAL 000401166

CUSTOMER #: J1217045

156967



INVOICE

JAGUAR LAND ROVER STEVENS CREEK
4040 Stevens Creek Boulevard
San Jose, CA 95129

PAGE 3

(408) 246-7600
FAX # (408) 249-9136

SERVICE ADVISOR: 6657 SAMUEL MOSES

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
UBLK	11	JAGUAR	SAJWA4FC2BMB40597	6NRR349	13023/13025	T2779
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
21AUG10 DD			17:00 30MAY19		0.00 CASH	04JUN19
R.O. OPENED	DATE CUST. NOTIFIED	OPTIONS: STK:20939 DLR:0518 AXL:2 1)SOP PARTS HERE PAINTED LOOVERS 4.15.11 SEE MIKE G...				
30MAY19	04JUN19					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
	00003R						
						0.00	0.00
	00005M						
						0.00	0.00
	00054R						
						0.00	0.00
	00108R						
						0.00	0.00
	0021IN						
						0.00	0.00
	0022IN						
						0.00	0.00

13024 PERFORM 120,000 MILE SERVICE AS PER CHECK LIST.

E** TECH RECOMMENDS TIRE REPLACEMENT

TIRE4 MOUNT AND BALANCE FOUR TIRES

6059 CR

2	265040735	DUNLOP SPORT MAX	297.50	297.50	440.00	440.00
2	TIRE	California Tire Fee	1.75	1.75		3.50
2	265040736	DUNLOP SPORT MAX	356.25	356.25	712.50	712.50
2	TIRE	California Tire Fee	1.75	1.75		3.50
8	9002	WHEEL WEIGHTS	1.35	1.35	10.80	10.80

13024 REPLACE ALL 4 DUNLOP TIRES AS PER CUSTOMER AUTHORIZATION.

F** PERFORM 4-WHEEL ALIGNMENT

4WA PERFORM 4-WHEEL ALIGNMENT

6059 CJ

399.95 399.95

13024 PERFORM 4-WHEEL ALIGNMENT AS PER CUSTOMER AUTHORIZATION SEE PRINT OUT.

G** TECH RECOMMENDS AIR CONDITIONING COMPRESSOR REPLACEMENT

010132 AIR CONDITIONING COMPRESSOR -
COMMISSIONING PROCEDURE

6059 CJ

1530.00 1530.00

 	ORIGINAL ESTIMATE \$		FINAL REVISED ESTIMATE \$		DESCRIPTION	TOTALS
	DATE		PHONE # OR IN PERSON	AUTHORIZED BY	LABOR AMOUNT	
	REASON		ADDITIONAL AMOUNT \$		PARTS AMOUNT	
	DATE		PHONE # OR IN PERSON	AUTHORIZED BY	GAS, OIL, LUBE	
	REASON		ADDITIONAL AMOUNT \$		SUBLET AMOUNT	
	DATE		PHONE # OR IN PERSON	AUTHORIZED BY	MISC. CHARGES	
	REASON		ADDITIONAL AMOUNT \$		TOTAL CHARGES	
	DATE		PHONE # OR IN PERSON	AUTHORIZED BY	DEDUCTIONS	
	REASON		ADDITIONAL AMOUNT \$		SALES TAX	
	I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE.		I ACKNOWLEDGE RECEIPT OF VEHICLE AND I HAVE RECEIVED A COPY OF THIS INVOICE.		PLEASE PAY THIS AMOUNT	

ALL PARTS ENDING IN "WP" ARE NOT SOURCED FROM JAGUAR LAND ROVER. SEE PARTS MANAGER FOR WARRANTY. NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

BAR # ARD 278146

EPA# CAL 000401166

CUSTOMER #: J1217045

156967



INVOICE

JAGUAR LAND ROVER STEVENS CREEK
4040 Stevens Creek Boulevard
San Jose, CA 95129

PAGE 4

(408) 246-7600
FAX # (408) 249-9136

SERVICE ADVISOR: 6657 SAMUEL MOSES

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
UBLK	11	JAGUAR	SAJWA4FC2BMB40597	6NRR349	13023/13025	T2779
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
21AUG10 DI			17:00 30MAY19		0.00 CASH	04JUN19
R.O. OPENED	DATE CUST. NOTIFIED	OPTIONS: STK:20939 DLR:0518 AXL:2 1)SOP PARTS HERE PAINTED LOOVERS 4.15.11 SEE MIKE G...				
30MAY19	04JUN19					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	C2D38105	ASSEMBLY-COMPRES			964.78	964.78	964.78
2	R134A	REFRIGERANT			16.95	16.95	33.90

13024 PERFORM AIR CONDITIONING COMPRESSOR ASSEMBLY REPLACEMENT WITH
PROCEDURE AS PER CUSTOMER AUTHORIZATION. FILL UP 1LB AND 8OZ FREON,
RETEST A/C SYSTEM OP NORMALLY AT THIS TIME. FUTURE REC. RECHECK.

H** JAGUAR/LAND ROVER LOANER (4 DAYS MAX), VEHICLE TO BE RETURNED UPON
DEALERS REQUEST AT ANY TIME. CLIENT IS FULLY RESPONSIBLE/LIABLE
FOR THE FUEL LEVEL, ANY DAMAGE ,PARKING TICKETS, TOLL
VIOLATIONS, EXCESSIVE USE, ETC.....

CAUSE: JAGUAR LAND ROVER LOANER

RLC JAGUAR/LAND ROVER LOANER (4 DAYS MAX),
VEHICLE TO BE RETURNED UPON DEALERS REQUEST
AT ANY TIME. CLIENT IS FULLY
RESPONSIBLE/LIABLE FOR THE FUEL LEVEL, ANY
DAMAGE ,PARKING TICKETS, TOLL VIOLATIONS,
EXCESSIVE USE, ETC.....

99 ISR

(N/C)

I** RECONDITION FOUR ROAD WHEELS
RECON4 RECONDITION FOUR ROAD WHEELS

99 CR

127.50 127.50

SUBL REPAIRED ALL FOUR WHEELS
PO#61445

CR

840.00 840.00

FC: 1234

13025 All 4 wheels have been refinished.

EST: 1,458.11 30MAY19 09:08 SA: 6657



ORIGINAL ESTIMATE \$	FINAL REVISED ESTIMATE \$	DESCRIPTION	TOTALS
		LABOR AMOUNT	
DATE TIME PHONE # OR IN PERSON AUTHORIZED BY ADDITIONAL AMOUNT \$		PARTS AMOUNT	
REASON	REVISED TOTAL \$	GAS, OIL, LUBE	
DATE TIME PHONE # OR IN PERSON AUTHORIZED BY ADDITIONAL AMOUNT \$		SUBLET AMOUNT	
REASON	REVISED TOTAL \$	MISC. CHARGES	
		TOTAL CHARGES	
		DEDUCTIONS	
		SALES TAX	
I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE. X		I ACKNOWLEDGE RECEIPT OF VEHICLE AND I HAVE RECEIVED A COPY OF THIS INVOICE. X	
		PLEASE PAY THIS AMOUNT	

ALL PARTS ENDING IN "WP" ARE NOT SOURCED FROM JAGUAR LAND ROVER. SEE PARTS MANAGER FOR WARRANTY.
NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

BAR # ARD 278146 EPA# CAL 000401166

CUSTOMER #: J1217045

156967



INVOICE

JAGUAR LAND ROVER STEVENS CREEK
4040 Stevens Creek Boulevard
San Jose, CA 95129

PAGE 5

(408) 246-7600
FAX # (408) 249-9136

SERVICE ADVISOR: 6657 SAMUEL MOSES

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
UBLK	11	JAGUAR	SAJWA4FC2BMB40597	6NRR349	13023/13025	T2779
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
21AUG10 DD			17:00 30MAY19		0.00 CASH	04JUN19
R.O. OPENED	DATE CUST. NOTIFIED	OPTIONS: STK:20939 DLR:0518 AXL:2 1)SOP PARTS HERE PAINTED LOOVERS 4.15.11 SEE MIKE G...				
30MAY19	04JUN19					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
<p>THANK YOU FOR YOUR PATRONAGE, YOUR BUSINESS IS VERY MUCH APPRECIATED!</p> <p>WE HOPE WE HAVE EARNED YOUR FUTURE BUSINESS AND RECOMENDATIONS TO FAMILY AND FRIENDS! COMMENTS WELCOMED AT MREYES@LANDROVERSJ.COM MANUEL REYES, PARTS & SERVICE DIRECTOR.</p>							



ORIGINAL ESTIMATE \$	FINAL REVISED ESTIMATE \$	DESCRIPTION	TOTALS
		LABOR AMOUNT	3593.95
DATE	TIME	PHONE # OR IN PERSON	AUTHORIZED BY
REASON			
DATE	TIME	PHONE # OR IN PERSON	AUTHORIZED BY
REASON			
I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE.		I ACKNOWLEDGE RECEIPT OF VEHICLE AND I HAVE RECEIVED A COPY OF THIS INVOICE.	
X		X	
		PARTS AMOUNT	2725.74
		GAS, OIL, LUBE	0.00
		SUBLET AMOUNT	840.00
		MISC. CHARGES	7.00
		TOTAL CHARGES	7166.69
		DEDUCTIONS	0.00
		SALES TAX	252.13
		PLEASE PAY THIS AMOUNT	7418.82

ALL PARTS ENDING IN "WP" ARE NOT SOURCED FROM JAGUAR LAND ROVER. SEE PARTS MANAGER FOR WARRANTY.
NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

BAR # ARD 278146

EPA# CAL 000401166

MENLO-ATHERTON AUTO REPAIR

Ph. (650) 325-1280

BAR# AA50797 EPA# CAL982334161
1279 El Camino Real • Menlo Park, CA 94025

www.menloathertonautorepair.com
service@menloathertonautorepair.com



INVOICE

108911

Org. Est. # 160404

INVOICE

Date: 01/06/2021

2011 Jaguar - XKR - 5L, V8 (305CI) VIN(C)


Lic # : 6NRR349

Odometer In : 14465

Odometer Out : 14465

VIN # : SAJWA4FC2 BMB40597

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Interstate 60 Month Battery MTP-49/H8 49 (H8)	1.00	264.95	264.95	CHARGING SYSTEM - Check - All Applicable Models - [Includes: Check Battery, Regulator and Alternator output.] Found battery failed load test.	127.80
Oil Filter Oil/filter	1.00	23.95	23.95	Check charging system	n/c
Synthetic 5/20 Motor oil 5/20	7.66	14.95	114.52	Check charging system for proper output to battery and starter. Load test battery and starter. Check all wiring. Inspect belt and adjust as required. Test for current draw on electrical system and record findings. Battery failed load test	
Washer fluid wash	1.00	3.25	3.25	Courtesy Check -No charge	n/c
				Check fluids-service due	
				Check Tires- All @ 7/32	
				Visual brake check-All @ 6mm	
				Check wipers-ok	
				Oil Change Service---Reset car maintenance information system with scan tool to proper specification	99.95
				Check filters	
				Check fluids:transmission,washer,powersteering,brake, coolant	
				Check battery	
				Check belts/hoses	
				Check tune up	
				Check shocks/struts	
				Check wipers	
				Check all lights	
				Check tire wear-	
				Check tire rotation	
				Visual brakes check-	
				Tire pressure:	
				Psi (left/front) 36	Psi (right/front) 36
				Psi (Left/rear) 36	Psi (right/rear) 36
				Alignment:	
				Inspect headlights fading:	
				Oil change light reset:	
				Check engine light:	
				Gas left in tank: %left	
				HAZARDOUS WASTE: A charge will be added when fluids removed from your vehicle must be disposed of in compliance with federal state and local government. Such fluids are engine oil,transmission fluid,fuel,gear oils,coolant,and brakes,etc...	6.50
				Fluid Capacity:	
				Engine Oil - Volume: 7.66 QTS. (7.2L) - Castrol SLK Professional OE SAE 5W-20 meeting Specification: WSS M2C925-A; w/Filter - (Note: In an emergency, if the oil is unavailable, the engine can be topped-up using a maximum of 2 US pints of 5W-20 oil meeting spec ILSACGF-4 API SM.)	
				[Recommendations]	
				As of 1/6/2021 Rear shocks starting to seep, recommend to monitor next service.	



MENLO-ATHERTON AUTO REPAIR
 Ph. (650) 325-1280
 BAR# AA50797 EPA# CAL982334161
 1279 El Camino Real • Menlo Park, CA 94025
 www.menloathertonautorepair.com
 service@menloathertonautorepair.com



INVOICE

108911

Org. Est. # 160404

INVOICE

Date: 01/06/2021

2011 Jaguar - XKR - 5L, V8 (305CI) VIN(C)

Lic # : 6NRR349

Odometer In : 14465

Odometer Out : 14465

VIN # : SAJWA4FC2 BMB40597

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
---------------------------	-----	------	-----	-------------------	-----



CERTIFIED MECHANICS

Org. Estimate 389.95 Revisions 261.28 Current Estimate 651.23

Revision # 1, Previous Estimate Amount: 389.95, Additional Cost: 261.28, Revised Estimate: 651.23, Parts: \$14172 Labor: \$106.45 Sublet: \$0.00
 Taxes & Fees: \$13.11 Authorized by - Couch, John, Date - 1/6/2021, Time - 12:36 PM, Initiated By - Shop, Phone Number - Home: 650-387-3166xCell

Labor:	234.25
Parts:	406.67
SubTotal:	640.92
Tax:	37.62
Total:	678.54
Bal Due:	\$678.54

[Payments -]

Vehicle Received: 1/6/2021

Customer Number : 206814

An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. All Parts are New unless otherwise designated. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

Visit us on the web: <https://www.menloathertonautorepair.com/>

Email Address: Service@menloathertonautorepair.com

Service Advisor : Gomez, Mario, Tech : Quezada, Marco 14; Edgar, Gonzalezs; G.

MENLO SMOG
 1110 MARSH ROAD
 MENLO PARK, CA 94025

MENLOSMOG@SBCGLOBAL.NET
 WWW.MENLOSMOG.NET
 650 473-6977 650 473-6915

BAR# RC247384
 EPA# CAL000316025

Invoice

Due Date 6/14/2021
 Ship date 6/14/2021

Invoice #
39410

YEAR / MAKE	2011 JAGUAR
MODEL	XKR
ODOMETER	14646
LICENSE #	6NRR349

Remarks/Recomendations

TIRE PRESURE
 LF ___ RF ___ LR ___ RR ___

Item	Description	Qty	Price	Amount
smog check certificate			59.75	59.75
			8.25	8.25

By law, you may choose another facility to perform needed repairs or adjustments which the smog test indicicates are necessary

A daily storage charge maybe added for vehicles not picked up after notification of completion of repairs commencing _____ hours/days after notification

REVISED ESTIMATE \$ _____ DATE _____ TIME _____
 PHONE# _____ PHONE OR IN PERSON _____
 REASON _____
 ADDITIONAL COST _____
 I acknowledge notice and oral approval of an increase in the original estimated price.
 X _____

I hereby authorize you to perform the above repairs and furnish necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection and delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of this invoice. You will not be held responsible for loss or damage to vehicle due to fire, theft, accident, dynamometer testing or any other cause beyound your control. In the event legal action is necessary to enforce this contract, I understand that i am solely responsible for all cost including attorney's fees and court costs. I have read and understand the above and acknowledge receipt of an estimate.

X _____ DATE _____

LABOR TOTAL =

PARTS TOTAL =

Subtotal	\$68.00
Sales Tax (9.25%)	\$0.00
Total	\$68.00
Payments /Credits	\$0.00
Balance Due	\$68.00

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 06/14/2021 @ 10:38 AM

Model Year: 2011	Vehicle Make: JAGUAR	Vehicle Model: XKR
VIN (scanned from vehicle): SAJWA4FC2BMB40597		
VIN (manually entered or from DMV document): SAJWA4FC2BMB40597		
License Plate: 6NRR349	License State: CA	Fuel Type: Gasoline
Certification Type: California	Odometer: 14646	

Overall Test Result

PASS

Congratulations! Your vehicle passed the Smog Check inspection, which helps California reach its daily goal of removing smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection: PASS Functional Inspection: PASS

Smog Check Certificate Number: IL428722C

DMV ID Number: 9931L8511897

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance.

Please keep this copy for your records.

Visual Inspection Result Information

<u>Result</u>	<u>Inspection Category</u>	<u>Result</u>	<u>Inspection Category</u>
NOT APPLICABLE	Air Injection System	PASS	Catalyst
PASS	Computers, Sensors, Switches, and Wiring	PASS	Crankcase Emission Controls
NOT APPLICABLE	Exhaust Gas Recirculation (EGR)	PASS	Fuel Evaporative System (EVAP)
PASS	Fuel Metering System	PASS	Other Emission Related Components/Systems
PASS	Turbocharger/Supercharger	PASS	Vacuum Lines to Sensors/Switches

Emission Control Systems Functional Check Results

<u>Result</u>	<u>Inspection Category</u>	<u>Result</u>	<u>Inspection Category</u>
PASS	Liquid Fuel Leak Check	PASS	OBDII
PASS	Smoke Check		

Smog Check Inspection Station Information

Station ID: RC247384
MENLO SMOG
1110 MARSH RD
MENLO PARK, CA 94025
(650) 473-6977

Inspector Name/ID:
Software Version/OIS ID:

PRASAD, SALEN/EO142882
21.1.1227.0/CV004839

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with the requirements, and that the information listed on this vehicle inspection report is true and accurate.


Date


Inspector's Signature

Menlo Atherton Auto Repair

79 El Camino Real, Menlo Park, CA
Menlo Park, CA. 94025
Phone: 650-325-1280 Fax: 650-325-6853

ESTIMATE #

174050

Estimate for Services

Estimate Date : 6/8/2023

2011 Jaguar - XKR - 5L, V8 (305CI) VIN(C)

Lic # : 6NRR349 - CA

Odom. In: 0

VIN # : SAJWA4FC2 BMB40597

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
Oil Filter <i>Oil/filter</i>	1.00	24.95	24.95	VEHICLE PICK UP -620 SANDHILL RD - Comprehensive checkup and servicing. The car has only about 15,000 miles on the odometer so it should be a least equivalent to the manufacturers - Oil Change Service--Reset car maintenance information system with scan tool to proper specification Check filters Check fluids:transmission,washer,powersteering,brake, coolant Check battery Check belts/hoses Check tune up Check shocks/struts Check wipers Check all lights Check tire wear Check tire rotation Visual brakes check- Tire pressure: Psi (left/front) Psi (right/front) Psi (Left/rear) Psi (right/rear) Alignment: Inspect headlights fading: Oil change light reset: Check engine light: Gas left in tank: %left HAZARDOUS WASTE: A charge will be added when fluids removed from your vehicle must be disposed of in compliance with federal state and local goverment.Such fluids are engine oil,transmission fluid,fuel,gear oils,coolant,and brakes,etc... CABIN AIR FILTER - Remove & Replace Exchanged brake fluid.	
Drain plug washer <i>washer</i>	1.00	3.75	3.75		99.95
Oil Filter Kit w/ O-Ring <i>Wp</i>	1.00	42.02	42.02		
Full Synthetic Motor Oil 5W-20 Group V - 1 Qt <i>wp</i>	8.00	17.95	143.60		
Cabin Air Filter <i>Wp</i>	1.00	74.82	74.82		
Brake fluid <i>kw</i>	2.00	6.83	13.66		6.50
					129.50
					179.95
<p>[Recommendations] As of 1/6/2021 Rear shocks starting to seep, recommend to monitor next service.</p>					

Parts/Supplies: 302.80

Labor: 415.90

HazMat/Fees: 0.00

Tax: 28.39

Total : \$ 747.09

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle described for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. SMOG: I understand that I can have emission service and/or adjustments done elsewhere. I hereby waive this right. All Parts New unless otherwise designated. TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

Menlo Atherton Auto Repair 650-325-1280

Signature _____ Date _____ Time _____

MENLO-ATHERTON AUTO REPAIR

Ph. (650) 325-1280
 BAR# AA50797 EPA# CAL982334161
 1279 El Camino Real • Menlo Park, CA 94025
 www.menloathertonautorepair.com



INVOICE

120971

Org. Est. # 174050

INVOICE

Printed Date: 06/09/2023

Work Completed: 06/09/2023

2011 Jaguar - XKR - 5L, V8 (305CI) VIN(C)

Lic # : 6NRR349

Odometer In : 15460

Odometer Out : 15464

VIN # : SAJWA4FC2 BMB40597

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Oil Filter <i>Oil/filter</i>	1.00	24.95	24.95	15K Service	n/c
Drain plug washer <i>washer</i>	1.00	3.75	3.75	VEHICLE PICK UP -620 SANDHILL RD - Comprehensive checkup and servicing. The car has only about 15,000 miles on the odometer so it should be a least equivalent to the manufacturers -	
Oil Filter Kit w/ O-Ring <i>Wp</i>	1.00	42.02	42.02	Oil Change Service---Reset car maintenance information system with scan tool to proper specification	99.95
Full Synthetic Motor Oil 5W-20 Group V - 1 Qt <i>wp</i>	8.00	17.95	143.60	Check filters	
Cabin Air Filter <i>Wp</i>	1.00	74.82	74.82	Check fluids:transmission,washer,powersteering,brake, coolant	
Brake fluid <i>kw</i>	2.00	6.83	13.66	Check battery	
Brake Pad Sensor-Rear <i>FST</i>	1.00	69.78	69.78	Check belts/hoses	
Brake Pad Set <i>FST</i>	1.00	101.55	101.55	Check tune up	
Brake Disc <i>FST</i>	2.00	185.01	370.02	Check shocks/struts	
				Check wipers	
				Check all lights	
				Check tire wear - F & R @ 7/32	
				Check tire rotation	
				Visual brakes check - F @ 5mm R @ 3mm	
				Tire pressure:	
				36 Psi (left/front) 36 Psi (right/front)	
				36 Psi (Left/rear) 36 Psi (right/rear)	
				Alignment:	
				Inspect headlights fading:	
				Oil change light reset:	
				Check engine light:	
				Gas left in tank: %left	
				HAZARDOUS WASTE: A charge will be added when fluids removed from your vehicle must be disposed of in compliance with federal state and local government.Such fluids are engine oil,transmission fluid,fuel,gear oils,coolant,and brakes,etc...	6.50
				CABIN AIR FILTER - Remove & Replace	129.50
				Exchanged brake fluid.	179.95
				Install rear new brake pads,rotors and re pack wheel bearing where applicable,road test.	442.89
				Brake hazardous waste: A charge will be added when fluids removed from your vehicle must be disposed of in compliance with federal state and local government.Such fluids are engine oil,transmission fluid,fuel,gear oils,coolant,and brakes,etc	3.50
				[Recommendations]	
				As of 1/6/2021Rear shocks starting to seep, recommend to monitor next service.	

INVOICE

120971

Org. Est. # 174050

MENLO-ATHERTON AUTO REPAIR

Ph. (650) 325-1280

BAR# AA50797 EPA# CAL982334161

1279 El Camino Real • Menlo Park, CA 94025

www.menloathertonautorepair.com



INVOICE

Printed Date: 06/09/2023

Work Completed: 06/09/2023

menloautorepair.com

2011 Jaguar - XKR - 5L, V8 (305CI) VIN(C)

Lic # : 6NRR349

Odometer In : 15460

Odometer Out : 15464

VIN # : SAJWA4FC2 BMB40597

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
---------------------------	-----	------	-----	-------------------	-----



CERTIFIED MECHANICS

Org. Estimate 747.09 Revisions 1,038.49 Current Estimate 1,785.58

Revision# 1, Previous Estimate Amount: 747.09, Additional Cost: 1038.49, Revised Estimate: 1785.58, Parts: \$541.35 Labor: \$446.39 Sublet: \$0.00 Taxes & Fees: \$350.75 Authorized by - Couch, John, Date - 6/8/2023, Time - 6:03 PM, Initiated By - Shop Phone Number - Home: 650-387-3166xCell

Labor:	862.29
Parts:	844.15
SubTotal:	1,706.44
Tax:	79.14
Total:	1,785.58
Bal Due:	\$1,785.58

[Payments -]

Vehicle Received: 6/9/2023

Customer Number : 206814

An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. All Parts are New unless otherwise designated. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

Visit us on the web: <https://www.menloathertonautorepair.com/>

Email Address: Service@menloathertonautorepair.com

Service Advisor : Bajada, Ryan, Tech : Diaz, Diego, Brian, Brian

MENLO SMOG
 1110 MARSH ROAD
 MENLO PARK, CA 94025

MENLOSMOG@SBCGLOBAL.NET
 WWW.MENLOSMOG.NET
 650 473-6977 650 473-6915

BAR# RC247384
 EPA# CAL000316025

Invoice

Due Date 6/23/2023
 Ship date 6/23/2023

Invoice #
44188

YEAR / MAKE	2011 JAGUAR
MODEL	XKR
ODOMETER	15522
LICENSE #	6NRR349

Remarks/Recomendations

TIRE PRESURE
 LF ___ RF ___ LR ___ RR ___

Item	Description	Qty	Price	Amount
smog check certificate			59.75	59.75
			8.25	8.25

By law, you may choose another facility to perform needed repairs or adjustments which the smog test indicates are necessary

A daily storage charge maybe added for vehicles not picked up after notification of completion of repairs commencing _____ hours/days after notification

REVISED ESTIMATE \$ _____ DATE _____ TIME _____
 PHONE# _____ PHONE OR IN PERSON _____
 REASON _____
 ADDITIONAL COST _____

I acknowledge notice and oral approval of an increase in the original estimated price.
 X _____

I hereby authorize you to perform the above repairs and furnish necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection and delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of this invoice. You will not be held responsible for loss or damage to vehicle due to fire, theft, accident, dynamometer testing or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that i am solely responsible for all cost including attorney's fees and court costs. I have read and understand the above and acknowledge receipt of an estimate.

X _____ DATE _____

LABOR TOTAL =

PARTS TOTAL =

Subtotal	\$68.00
Sales Tax (9.25%)	\$0.00
Total	\$68.00
Payments/Credits	\$0.00
Balance Due	\$68.00

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 06/23/2023 @ 1:58 PM

Model Year: 2011	Vehicle Make: JAGUAR	Vehicle Model: XKR
VIN (scanned from vehicle): SAJWA4FC2BMB40597		
VIN (manually entered or from DMV document): SAJWA4FC2BMB40597		
License Plate: 6NRR349	License State: CA	Fuel Type: Gasoline
Certification Type: California	Odometer: 15522	

Overall Test Result

PASS

Congratulations! Your vehicle passed the Smog Check inspection, which helps California reach its daily goal of removing smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection: PASS Functional Inspection: PASS

Smog Check Certificate Number: TI984962C

DMV ID Number: 99391854T997

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance. Please keep this copy for your records.

The Bureau of Automotive Repair helps consumers with Smog Check repairs, vehicle retirement, collision repair inspections, and more.
www.bar.ca.gov

Visual Inspection Result Information

<u>Result</u>	<u>Inspection Category</u>	<u>Result</u>	<u>Inspection Category</u>
NOT APPLICABLE	Air Injection System	PASS	Catalyst
PASS	Computers, Sensors, Switches, and Wiring	PASS	Crankcase Emission Controls
NOT APPLICABLE	Exhaust Gas Recirculation (EGR)	PASS	Fuel Evaporative System (EVAP)
PASS	Fuel Metering System	PASS	Other Emission Related Components/Systems
PASS	Turbocharger/Supercharger	PASS	Vacuum Lines to Sensors/Switches

Emission Control Systems Functional Check Results

<u>Result</u>		<u>Result</u>	
PASS	Liquid Fuel Leak Check	PASS	OBDII
PASS	Smoke Check		

Smog Check Inspection Station Information

Station ID: RC247384
MENLO SMOG
1110 MARSH RD
MENLO PARK, CA 94025
(650) 473-6977

Inspector Name/ID: PRASAD, SALEN/EO142882
Software Version/OIS ID: 23.1.1665.0/CV004839

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

06/23/23
Date

[Signature]
Inspector's Signature

CUSTOMER #: J1217045

230510



JAGUAR LAND ROVER SAN JOSE

4040 Stevens Creek Boulevard
San Jose, CA 95129
(408) 246-7600
FAX # (408) 249-9136
www.jaguarsanjose.com
www.landroversanjose.com

INVOICE

PAGE 1

B.A.R. REG.# ARD299238

EPA# CAL000461089

SERVICE ADVISOR: 40031 ADRIAN SADLER


COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
UBLK	11	JAGUAR XKRCP	SAJWA4FC2BMB40597	6NRR349	16025/16025	T6342	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
21AUG10 DD			17:00 19OCT24		325.00	CASH	17OCT24
R.O. OPENED	READY	OPTIONS: DLR:0518 AXL:2 1)SOP PARTS HERE PAINTED L OOVERS 4.15.11 SEE MIKE G...					
10:09 07OCT24	10:50 17OCT24						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A PERFORM COMPLIMENTARY MULTI POINT INSPECTION ON VEHICLE (VALUED AT \$89.95) AND ADVISE ON ANY NEEDS.
 CAUSE: PERFORM COMPLIMENTARY MULTI POINT INSPECTION ON VEHICLE (VALUED AT \$89.95) AND ADVISE ON ANY NEEDS.
 FMPI PERFORM COMPLIMENTARY MULTI POINT INSPECTION ON VEHICLE (VALUED AT \$89.95) AND ADVISE ON ANY NEEDS.
 40017 GARCIA, ITZAMADUL L LIC#: 40017
 ISPL
 16025 PERFORMED MPI

11/5/24 1199 LK
PAID
 16000
 OCT 17 2024 (N/C)

B REPLACE REMOTE BATTERY
 CAUSE: REMOTE BATTERY REPLACE
 RBATT REPLACE REMOTE BATTERY
 40017 GARCIA, ITZAMADUL L LIC#: 40017
 CJ
 2 CR2032 REMOTE BATTERY
 16025 REPLACED KEY FOB REMOTE BATTERY



C CUSTOMER REQUESTS SCHEDULED MAINTENANCE PER ATTACHED MENU CHECKLIST - PREFERRED SERVICE - CUSTOMER ACKNOWLEDGES RECEIPT OF LIST OF OPERATIONS TO BE PERFORMED
 CAUSE: SCHEDULED MAINTENANCE
 K3 CUSTOMER REQUESTS SCHEDULED MAINTENANCE PER ATTACHED MENU CHECKLIST - PREFERRED SERVICE - CUSTOMER ACKNOWLEDGES RECEIPT OF LIST OF OPERATIONS TO BE PERFORMED
 40017 GARCIA, ITZAMADUL L LIC#: 40017
 CJ
 8 12083 0W20CASTROL 31.00 31.00 248.00
 1 C2D3670 FILTER-OIL 87.00 87.00 87.00
 2 C2P16933 ELEMENT-AIRCLEAN 105.00 105.00 210.00
 1 C2P2410 FILTER-AIR PARTI 165.00 165.00 165.00
 8 C2P23089 SPARK PLUG 65.92 65.92 527.36

PAID
 4199.20
 OCT 17 2024
 ck 104 LK

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By
\$	\$			<input type="checkbox"/> In Person Approval <input type="checkbox"/> Telephone <input type="checkbox"/> Text <input type="checkbox"/> Email/Fax (See Attached)
Revised Estimate	\$			<input type="checkbox"/> In Person Approval <input type="checkbox"/> Telephone <input type="checkbox"/> Text <input type="checkbox"/> Email/Fax (See Attached)

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
WASTE DISPOSAL COSTS *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

Tire pressure check/inflation service was performed.
 RF _____ psi LF _____ psi RR _____ psi LR _____ psi
 Customer declined tire pressure check/inflation service. Initials _____

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.

DATE _____ CUSTOMER SIGNATURE _____ AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE _____

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.
 Some Parts Not Returnable

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

CUSTOMER #: J1217045

230510



JAGUAR LAND ROVER SAN JOSE

4040 Stevens Creek Boulevard
San Jose, CA 95129

(408) 246-7600

FAX # (408) 249-9136

www.jaguarsanjose.com

www.landroversanjose.com

B.A.R. REG.# ARD299238

EPA# CAL000461089

INVOICE

PAGE 2

SERVICE ADVISOR: 40031 ADRIAN SADLER

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
UBLK	11	JAGUAR XKRCP	SAJWA4FC2BMB40597	6NRR349	16025/16025	T6342	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
21AUG10 DD			17:00 19OCT24		325.00	CASH	17OCT24
R.O. OPENED	READY	OPTIONS: DLR:0518 AXL:2 1)SOP PARTS HERE PAINTED L OOVERS 4.15.11 SEE MIKE G...					
10:09 07OCT24	10:50 17OCT24						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	C2D39175	BELT-DRIVE			104.00	104.00	104.00
1	T2R16360	BELT-DRIVE			105.63	105.63	105.63
1	BG9822RSC	WASHER CONCENTRATE			13.65	13.65	13.65
1	BG7073	FRIGI FRESH			29.12	29.12	29.12
1	BG6579	ENGINE PERFORMANCE KIT			47.05	47.05	47.05
1	BG208	FUEL ADDITIVE			49.50	49.50	49.50
1	BG2913	ETHANOL DEF KIT			44.32	44.32	44.32
1	BG546	SUPER COOL			40.95	40.95	40.95
1	BG4073	MASS AIR FLOW SENSOR CLEANER			28.12	28.12	28.12
1	BG83532	BRAKE FLUSH			48.87	48.87	48.87
2	BG750	75W-90 ULTRA GUARD			50.69	50.69	101.38
1	BG328	LS AXLE ADDITIVE			26.57	26.57	26.57
1	BG5901	COOLING SYSTEM FLUSH			52.05	52.05	52.05
1	LRN2279	FLUID - COOLING			37.85	37.85	37.85
1	BG3348	POWER STEERING KIT			105.47	105.47	105.47
1	C2P13476WP	FUEL FILTER			125.00	91.24	91.24

16025

PERFORMED JAGUAR SERVICE ON VEHICLE AND TOPPED OFF BASIC FLUIDS.
THANK YOU FOR YOUR BUSINESS.

E CUSTOMER REQUEST TO P/A TIRES...
GENERAL P&A

40017 GARCIA, ITZAMADUL L LIC#: 40017
ISPL

(N/C)

40120 Guerrero, Emilio LIC#: 40120
ISPL

(N/C)

F PROVIDE CLIENT WITH UBER

UBER PROVIDE CLIENT WITH UBER

40017 GARCIA, ITZAMADUL L LIC#: 40017
ISPL

(N/C)

G** MOUNT AND BALANCE FOUR TIRES

TIRE4 MOUNT AND BALANCE FOUR TIRES

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By <input type="checkbox"/> In Person Approval <input type="checkbox"/> Telephone <input type="checkbox"/> Text (For Use Attached)	*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
\$	\$					LABOR AMOUNT	
Revised Estimate	\$			<input type="checkbox"/> In Person Approval <input type="checkbox"/> Telephone <input type="checkbox"/> Text (For Use Attached)		PARTS AMOUNT	
<input type="checkbox"/> Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi <input type="checkbox"/> Customer declined tire pressure check/inflation service. Initials _____						GAS, OIL, LUBE	
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.						SUBLET AMOUNT	
DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE				WASTE DISPOSAL COSTS *	
						TOTAL CHARGES	
						LESS INSURANCE	
						SALES TAX	
						PLEASE PAY THIS AMOUNT	

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

CUSTOMER #: J1217045

230510



JAGUAR LAND ROVER SAN JOSE

4040 Stevens Creek Boulevard
San Jose, CA 95129

(408) 246-7600

FAX # (408) 249-9136

www.jaguarsanjose.com

www.landroversanjose.com

B.A.R. REG.# ARD299238

EPA# CAL000461089

INVOICE

PAGE 3

SERVICE ADVISOR: 40031 ADRIAN SADLER

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
UBLK	11	JAGUAR XKRCP	SAJWA4FC2BMB40597	6NRR349	16025/16025	T6342	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
21AUG10 DD			17:00 19OCT24		325.00	CASH	17OCT24

R.O. OPENED	READY	OPTIONS:
10:09 07OCT24	10:50 17OCT24	DLR:0518 AXL:2 1)SOP PARTS HERE PAINTED L OOVERS 4.15.11 SEE MIKE G...

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
	40101	AGUIER, CARLOS	LIC#:	40101			
		CJ				340.00	340.00
2	10241M	MICHELIN PILOT SPORT			415.00	415.00	830.00
2	TIRE	California Tire Fee			1.75	1.75	3.50
2	35654				465.82	465.82	931.64
2	TIRE	California Tire Fee			1.75	1.75	3.50
8	9002	WHEEL WEIGHTS			3.76	3.76	30.08

16025

MOUNTED AND BALANCED 2 TIRES PER CUSTOMER REQUEST. SET ALL TIRES TO 36 PSI AND TORQUED WHEELS TO SPECS ON VEHICLE. TEST DROVE TO VERIFY CORRECT OPERATION OF VEHICLE AND THAT THE TIRE LIGHT IS NOT ILLUMINATED. OK AT THIS TIME.

THANK YOU FOR YOUR BUSINESS!

H** PERFORM 4-WHEEL ALIGNMENT

CAUSE: ALIGNMENT

4WA PERFORM 4-WHEEL ALIGNMENT

40101 AGUIER, CARLOS LIC#: 40101

CJ

16025

PERFORMED 4 WHEEL ALIGNMENT ON VEHICLE AND ADJUSTED TO MANUFACTURE SPECIFICATIONS. TEST DROVE VEHICLE AND VERIFIED STEERING WHEEL IS STRAIGHT AND DRIVES STRAIGHT ON THE ROAD. OK AT THIS TIME. THANK YOU FOR YOUR BUSINESS!

I** RECONDITION FOUR ROAD WHEELS

RECON4 RECONDITION FOUR ROAD WHEELS

99 CR

0.00 0.00

SUBL RECONDITION 4 ROAD WHEELS

PO#76556

CR

1000.00 1000.00



Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By	Date & Time	Authorization Obtained By	*HAZARDOUS WASTE DISPOSAL COSTS: We have added this charge to cover costs associated with the handling, management and disposal of toxic wastes or hazardous substances under California and Federal Law.	DESCRIPTION	TOTALS
\$	\$			<input type="checkbox"/> In Person Approval <input type="checkbox"/> Telephone <input type="checkbox"/> Text <input type="checkbox"/> Email/Fax (See Attached)		LABOR AMOUNT	
Revised Estimate	\$			<input type="checkbox"/> In Person Approval <input type="checkbox"/> Telephone <input type="checkbox"/> Text <input type="checkbox"/> Email/Fax (See Attached)		PARTS AMOUNT	
<input type="checkbox"/> Tire pressure check/inflation service was performed. RF _____ psi LF _____ psi RR _____ psi LR _____ psi <input type="checkbox"/> Customer declined tire pressure check/inflation service. Initials _____						GAS, OIL, LUBE	
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you.						SUBLET AMOUNT	
DATE	CUSTOMER SIGNATURE		AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE			WASTE DISPOSAL COSTS *	
						TOTAL CHARGES	
					<input type="checkbox"/> ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. <input type="checkbox"/> Some Parts Not Returnable	LESS INSURANCE	
						SALES TAX	
						PLEASE PAY THIS AMOUNT	

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

Multi-Point Inspection Summary

Thursday, October 17, 2024 11:09 AM

RO# 230510



CUSTOMER INFORMATION


CAR INFORMATION

SERVICE ADVISOR INFO






Jaguar
2011 XKR
SAJWA4FC2BMB40597
Mileage: 16025
Tag # T6342

Adrian Sadler
(408) 762-3922
TECHNICIAN
Itzamadul Lombera Garcia

ORIGINAL CUSTOMER REQUESTS RECOMMENDATIONS

 CUSTOMER REQUEST TO P/A TIRES... Michelin PILOT SPORT CUP 2 R CONNECT NO	Original Approved:	\$0.00
	Total Approved:	\$2,699.25
	Repair Estimate:	\$2,699.25

OTHER

 REPLACE REMOTE BATTERY	Original Approved:	\$22.59
	Total Approved:	\$22.59
 CUSTOMER REQUESTS SCHEDULED MAINTENANCE PER ATTACHED MENU CHECKLIST - PREFERRED SERVICE - CUSTOMER ACKNOWLEDGES RECEIPT OF LIST OF OPERATIONS TO BE PERFORMED	Original Approved:	\$6,345.36
	Total Approved:	\$6,345.36
 MOUNT AND BALANCE FOUR TIRES	Original Approved:	\$340.00
	Total Approved:	\$340.00
 PERFORM 4-WHEEL ALIGNMENT	Original Approved:	\$399.99
	Total Approved:	\$399.99
 RECONDITION FOUR ROAD WHEELS	Original Approved:	\$1,000.00
	Total Approved:	\$1,000.00

31 Passed Inspection

GENERAL

- ✔ Lighting (internal/external)
- ✔ Wiper Blades & Wiper Blade Operation
- ✔ Inspect Windshield for Cracks

INSPECT UNDER VEHICLE COMPONENTS

- ✔ Lower engine cover
- ✔ Fuel tank, lines and connections
- ✔ Exhaust system for leaks, damage and loose parts
- ✔ Engine mounts
- ✔ Transmission mounts
- ✔ Steering components
- ✔ Suspension components
- ✔ Sway bar components
- ✔ Axles, drive shaft and CV joints / boots

MEASURE AND INSPECT TIRES

- ✔ Front Tires
 - Left front - 6/32"
 - Right front - 6/32"
 - Rear Right - 6
 - Rear Left - 6
- ✔ Wheel Alignment Recommended
Tire Wear - Pass
- ✔ Overall wheels condition

INSPECT UNDER HOOD COMPONENTS

- ✔ Perform battery performance test
- ✔ Battery terminals and cables
- ✔ Engine Oil
- ✔ Brake Fluid
- ✔ Engine Coolant
- ✔ Hood strut(s)
- ✔ Engine Performance
- ✔ Drive belts
- ✔ All hoses and clamps

INSPECT FOR FLUID LEAKS

- ✔ Engine for oil leaks
- ✔ Cooling system for leaks
- ✔ Brake system for leaks
- ✔ Transmission for leaks

INSPECT BRAKE PADS AND COMPONENTS

- ✔ Front Brakes
Front Pads - 7mm
- ✔ Rear Brakes
Rear Pads - 6mm
- ✔ Braking system components

OTHER COMMENTS

Tire pressures
Front PSI per Factory Specs - YESpsi

SUMMARY OF VISIT:

Total Estimate: \$10,807.19

	Approved	Declined	Undecided
Pre-approved amount:	\$8,106.01	-	-
Recommended amount:	\$2,531.72	\$0.00	\$0.00
Taxes:	\$169.46	\$0.00	\$0.00
Total:	\$10,807.19	\$0.00	\$0.00